919 733-659Z (NC CONSTRUCTION)

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01

(X3) DATE SURVEY COMPLETED

HAL012001

B. WING

03/13/2015

PRINTED: 04/14/2015 FORM APPROVED

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Report of Blennial Construction Survey by Frank Strickland on 03/13/2015:  Information obtained from the DHSR database indicates that this facility was either first licensed or submitted for licensure on 02/01/1980 for 24 residents. Based on this information, we are requiring the facility to meet the 1977 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm, the applicable portions of the 2005 Regulations for Adult Care Homes, and the 1978 Edition of the North Carolina State Building Code-Section 409.1(c) Institutional Occupancy.  A deficiency has been cited and A Plan of	C 000	CONSTRUCTION SECTION  APR 27 2015  RECEIVED	. 4
C 189	Correction is required.  Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.	C 189	WE ARE BONTACTING COBSTRUCTION MAN & ELECTRICIAN AND THEY HAVE TO ORDER I SHOKE DAMPER MOTORIZED TYPE" INSTALL" TIED TO FIRE ACARM SYSTEM	6/15/2
	This Rule is not met as evidenced by:  1-Besed on observations, the facility has failed to maintain the building fire safety features. This could effect the safety of staff and all residents by not containing smoke and/or fire in the compartment of origin.			

STATE FORM (

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

5Y0021

TITLE ADMINIST PAROR (X8) DATE, 4/27/2015 If continuation street 1 of 2 (828) 433-5875

PRINTED: 04/14/2015 FORM APPROVED

Division of Health Service Regulation STATEMENT OF DEFICIENCIÉS (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING HAL012001 03/13/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, SYATE, ZIP CODE 125 CAMELLIA GARDEN STREET BURKE LONG TERM CARE MORGANTON, NC 28655 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE PREFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) C 189 Continued From page 1 C 189 Findings on 03/13/2015: a. The facility has return-air grilles in the cellings. of the exit access corridor that do not have any fire dampers (ceiling radiation dampers) in place for the openings at the time of survey. ELECTRICIAN & GASTR 2-Based on observations, currently the facility is using the exit access corridor as a return-air -UCTION MAN WILL plenum that can effect the safety of staff and all IDSTALL BY BROWN residents by not containing smoke and/or fire in the compartment of origin. THE CUSTOMIZED UNIT Findings on 03/13/2015: TO MEET YOUR 4/27/2015 The facility is using the exit access corridor as a return-air plenum making it likely that smoke REQUIREM ENT. will migrate into the exit access corridor if the system is moving air during a fire/smoke event. At the time of survey, it was not determined whether or not the HVAC shuts down and stops moving air upon activation of the fire alarm. system. Division of Haulth Service Regulation

\*\*\*\*

STATE FORM

5Y0021

If continuation sheet 2 of 2

828 433-5875