PRINTED: 07/20/2015 FORM APPROVED

Division of Health Service Regulation (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA COMPLETED STATEMENT OF DEFICIENCIES IDENTIFICATION NUMBER: A. BUILDING: 01 AND PLAN OF CORRECTION 07/02/2015 B. WING FCL092080 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 5818 POOLE ROAD POOLE ROAD FAMILY CARE HOME RALEIGH, NC 27610 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES COMPLETE (EACH CORRECTIVE ACTION SHOULD BE PREFIX (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL DATE CROSS-REFERENCED TO THE APPROPRIATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) TAG 8-30-15 - Correction C 000 C 000 Initial Comments This report is of a biennial construction survey done by Bob Getchell on July 2, 2015. This facility was first licensed as a Family Care Home for six (6) ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency) on January 01, 1984. With amendment of the 1978 NCSBC effective February 1, 1983, and the revision of the 1977 Licensure Rules effective April 1, 1984, FCHs were allowed to increase capacity to six all ambulatory residents. Based on this we are requiring the home to be in compliance with the 1977, 1984, and the applicable portions of the 2005 Rules (10A NCAC 13G) for the Licensing of Family Care Homes, the 1968 North Carolina Uniform Residential Building Code (Volume I-B), and, the 1978 North Carolina State Building Code Section 409.1(g), Residential Care Facilities. Deficiencies were noted which will require a new plan of correction. C 101 C 101 Existing Licensed-No Less than '71 Rules SECTION .0300 - THE BUILDING CONSTRUCTION SECTION 10A NCAC 13G .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each family care home shall be applied as follows: Except where otherwise specified, existing licensed homes or portions of existing licensed homes shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation or alteration; however, in no case shall the requirements for any licensed home, where no addition or renovation has been made, be less (X6) DATE Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Division of Health Service Regulation (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING: 01 B. WING 07/02/2015 FCL092080 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 5818 POOLE ROAD POOLE ROAD FAMILY CARE HOME RALEIGH, NC 27610 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH CORRECTIVE ACTION SHOULD BE COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) 130K C 101 C 101 Continued From page 1 Inche Outictor installed august 30,2015 than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Family Care Homes", copies of which are available at the Division of Health Service Regulation - Construction Section, 701 Barbour Drive, Raleigh, North Carolina 27603 at no cost: This Rule is not met as evidenced by: Based on observation, the building fire protection equipment was not installed in accordance with the Licensure Rules and Building Code in effect when the facility was first licensed. This would affect all residents by not detecting smoke, activating the fire alarm, and directing residents from the building. Findings include: a. There is no smoke detector installed in the immediate vicinity outside the staff bedroom. The smoke detection R.30-15 will be installed This is not in accordance with 1997 (1999) Revision) North Carolina State Residential Building Code requiring smoke detectors be installed in each sleeping room, and in the immediate vicinity outside of each sleeping room. C 137 C 137 Bathroom-Mechanical Ventilation Expansed by Ougust 30,2015 SECTION .0300 - THE BUILDING 10A NCAC 13G .0309 BATHROOM (g) The bathrooms shall be lighted to provide 30 foot candles of light at floor level and have mechanical ventilation at the rate of two cubic feet per minute for each square foot of floor area. These vents shall be vented directly to the outdoors.

This Rule is not met as evidenced by:

CTV321

Division of Health Service Regulation

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

POOLE ROAD FAMILY CARE HOME

5818 POOLE ROAD RALEIGH, NC 27610

RALEIGH, NC 27610			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (X5) (EACH CORRECTIVE ACTION SHOULD BE COMPLETE DATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE COMPLETE DATE
C 137	Continued From page 2 1. Based on observation, the bathroom window was not maintained operable. Findings include: a) back right bathroom window can not be opened for fresh air. Provide mechanical ventilation. b) The back right bathroom window has broken glass.	C 137	Will bevieranced 8-30-15 by august 30-2015
C 148	Outside Entrances/Exits-Free of Obstructions SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (e) All entrances/exits shall be free of all obstructions or impediments to allow for full instant use in case of fire or other emergency. This Rule is not met as evidenced by: 1. Based on observation, the facility was not maintained in a safe manner by having a path of egress blocked.	C 148	
C 149	Findings include: a) The front porch has an awning on the left side that hangs down to about 5'6", blocking egress off the porch in an emergency. b) The corridor door at the front entrance, in the path of egress, has locking hardware. Outside Entrances/Exits-Handrails At Porches SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (f) All steps, porches, stoops and ramps shall be provided with handrails and guardrails.	C 149	auing will be repaired by august 30, 2015
50.000 211	salth Canrice Degulation		

FORM APPROVED Division of Health Service Regulation (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING 07/02/2015 FCL092080 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 5818 POOLE ROAD POOLE ROAD FAMILY CARE HOME RALEIGH, NC 27610 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5) COMPLETE (X4) ID EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PRÉFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) C 149 Continued From page 3 C 149 everaged by This Rule is not met as evidenced by: Based on observation, the facility was not maintained in a safe manner by having a handrail missing. Findings include: a) The front porch has steps down the left side which have only one handrail C 151 C 151 Laundry Room Saundry Clamper Will be replaced by august 30,2015

10A NCAC 13G .0313 LAUNDRY ROOM The laundry equipment in a family care home shall be located out of the living, dining, and bedroom areas.

SECTION .0300 - THE BUILDING

This Rule is not met as evidenced by: Based on observation, the dryer exhaust duct was not maintained operable.

Findings include: The backdraft damper on the dryer exhaust is stopped up with lint, and coming loose from the side of the house.

C 152 Floors

10A NCAC 13G .0314 FLOORS (a) All floors in a family care home shall be of smooth, non-skid material and so constructed as to be easily cleanable.

(b) Scatter or throw rugs shall not be used. (c) All floors shall be kept in good repair.

This Rule is not met as evidenced by: Based on observation, the floor in the main corridor was not maintained safe

CTV321

C 152

Division of Health Service Regulation (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: COMPLETED AND PLAN OF CORRECTION A. BUILDING: 01 B. WING 07/02/2015 FCL092080 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 5818 POOLE ROAD POOLE ROAD FAMILY CARE HOME RALEIGH, NC 27610 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH CORRECTIVE ACTION SHOULD BE COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PRÉFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) 7-15-16 C 152 C 152 | Continued From page 4 Ibready bion repaired Findings include: The grate for the floor furnace has broken causing it to shift when stepped on and exposing residents to a trip hazard Oll Bidroom end tallis Krolis have rein replaced Bedrooms 4,3,2 C 153 C 153 Houskeeping And Furnishings-Clean, Repaired SECTION .0300 - THE BUILDING 10A NCAC 13G .0315 HOUSEKEEPING AND FURNISHINGS (a) Each family care home shall: have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors: (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing homes. This Rule is not met as evidenced by: Based on observation, the resident furnishings were not maintained in good repair. Findings include: a) Bedroom 4 has an end table that is missing a drawer handle. b) Bedroom 3 has a chest of drawers that is missing handles. Bedroom 2 has an end table that is missing a 7-15-15 drawer handle. C 168 C 168 Fire Extinguishers SECTION .0300 - THE BUILDING 10A NCAC 13G .0316 FIRE SAFETY AND DISASTER PLAN (a) Fire extinguishers shall be provided which

care home:

meet these minimum requirements in a family

CTV321

Division of Health Service Regulation (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING: 01 07/02/2015 FCL092080 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 5818 POOLE ROAD POOLE ROAD FAMILY CARE HOME RALEIGH, NC 27610 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID: EACH CORRECTIVE ACTION SHOULD BE COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) C 168 The tago porthe extinguisher haue wen Digwed and well continued to C 168 | Continued From page 5 one five pound or larger (net charge) "A-B-C" type centrally located: (2) one five pound or larger "A-B-C" or CO/2 type located in the kitchen; and (3) any other location as determined by the code Whichecked lack enforcement official. This Rule is not met as evidenced by: Based on observation, the building fire protection equipment was not maintained in a safe manner. This would affect all residents by not having fire protection equipment operable for use in an emergency. Findings include: The inspection tags on the fire extinguishers indicate that required monthly checks are not being performed per NFPA 10 C 174 C 174 Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical. mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (i) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: Based on observation, the back exterior The brace will be post to skilling the porches and steps were not maintained safe. Findings include: a) The back deck has no cross bracing on the

4x4 posts to stabilize the structure.

b) The steps on the exit door have no cross

CTV321

PRINTED: 07/20/2015 FORM APPROVED Division of Health Service Regulation (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING FCL092080 07/02/2015 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 5818 POOLE ROAD POOLE ROAD FAMILY CARE HOME RALEIGH, NC 27610 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) . Dtersounda C 174 C 174 15-16 Continued From page 6 which they word bracing to stabilize the structure roest, ext no suc Based on observation, egress from all areas was not maintained in a safe manner by having bedroom windows that are stuck shut. This would affect the residents by not allowing free egress in an emergency. Findings include: The window is stuck shut in the Staff bedroom 3. Based on observation, the facility components were not maintained operable by having doors that did not close completely and latch. This could affect a residents privacy. Starty heaveous deer 17-15-15 The following doors have issues: a) Front right bedroom door won't close and latch, b) Front right bedroom closet door will not close and latch, c) Bedroom 1 has a closet door with no hardware, d) The front bathroom door has no latch, e) The Staff bedroom door has the latch installed saraluxxx has wen backwards. tuplaced in bedroom Based on observation, the facility showers teant liadrucem were not maintained safe. nas luen Findings include: The back shower has no hand grip. Based on observation, the facility interior building components were not maintained.

Findings include:

following locations:

There are walls and ceilings damaged in the

b) Bedroom 1 has wall damage.

a) Front right bedroom ceiling has damage from

Division of Health Service Regulation (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING: 01 B. WING. 07/02/2015 FCL092080 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 5818 POOLE ROAD POOLE ROAD FAMILY CARE HOME RALEIGH, NC 27610 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES (X4) ID EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PRÉFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) C 174 Junction box will be inclaited by C 174 Continued From page 7 Based on observation, the facility electrical system was not maintained in a safe manner by not using acceptable wiring methods. Findings include: a) There are three wiring junctions in the attic that are not contained inside of a mounted junction box.