Division of Health Service Regulation

PRINTED: 07/13/2017 FORM APPROVED

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPL A. QUILDING:	∭ ÇONSTRUCTION 01	(X8) DATE SURVEY COMPLETED				
		HAL001028	B. WING		06/27/2017			
NAME OF PROVIDER OR SUPPLIER STREET ADD				STATE, ZIP CODE				
SPRING	SPRINGVIEW - CROUSE BUILDING 613 W WHITSETT STREET GRAHAM, NO. 27253							
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIVE (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRODEFICIENCY)	D BE COMPLETE			
C 128	Report of Construct by Ed Miller on Juni Records indicate hi a Home for the Age residents on 05/01/ must meet the 1996 of the 2005 Rules fi Homes, and, the 16 Building Code - Sec Residential Care Fa Deficiencies were of Correction. Bathrooms-Minimul SECTION .0300 - F 10A NCAC 13F .03 ENVIRONMENT (e) The requirement rooms are:	s facility was first licensed as id serving 12 ambulatory 2000. Therefore the facility 3 and the applicable portions or the Licensing of Adult Care 296 North Carolina State 2100 419.5 for Large acility- Group R. Sitted that require a Plan of am Facilities	C 000		he shower			
CMVIsion of H	include a toilet and residents and a tub residents and a tub residents or portion. This Rule is not med. Based on obse Menager, the facility minimum plumbing required by the Rule residents who must fixtures. Findings on June 2 a. Shower Room	a hand lavatory for each 5 or shower for each 10 othereof; et as evidenced by: rvation and interview with y feiled to maintain the fixture to resident ratio e. This deficiency affects all t wait to have access to these 7, 2017: - this room is out of order, is and is acheduled to be		A resident broke to chair and it had to out to be welded to complete the vi- The shower chair was repaired fre-in by end of day I	louck-together gair trelt nstalled one 27th			

Division of Health Service Regulation							
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/SCLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPLE GONSTRUCTION A. BUILDING: 61		(X3) DATE SURVEY COMPLETED			
		A. BOILDING: VI					
		HAL001026	B' MING		06/2	7/2017	
NAME OF	PROVIDER OR SUPPLIER			STATE, ZIP GODE			
SPRING	VIEW - CROUSE BUIL	DING	NC 27263	ALL I			
(X4) (D PREFIX TAG	(EACH DEFICIENCY		PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROVIDENCY)	DBE	(X5) COMPLETE DATE	
C 186	Continued From page 1		C 166				
C 166	Housekeeping-Mair	Housekeeping-Maintained Free of Hazards					
				The vent cover and o were both cleared of dust and lint.		per	

Division of Health Service Regulation STATE FORM

MDXD21

Division of Health Service Regulation STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X3) DATE SURVEY COMPLETED (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 HALOO400C h Wind. 00/97/9047 STREET ADDRESS, GITY, STATE, ZIP GODE NAME OF PROVIDER OR SUPPLIER 613 W WHITSETT STREET SPRINGVIEW - CROUSE BUILDING GRAHAM, NC 27263 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION ΙĐ (X5) COMPLETE DATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE PREFIX REGULATORY OR LEC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) C 185 Continued From page 2 C 186 Usenior manager have gotten with the Rices and explained the Importance of move detail on the five drill This Rule is not met as evidenced by: 1. Based on Record review and Interview with Executive Director/Administrator/Maintenance Director/Manager the facility failed to document all aspects of the fire plan rehearsals. This deficiency affects all by not finding weakness or opportunities for improving evacuation responses. Findings on June 27, 2017: 104. a. The fire plan rehearsal records included date, time, shift, and staff members present but little to no description of what the rehearsal involved. C 189 Building Equipment Mainteined Safe, Operating C 189 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing. facilities with the exception of Paragraph (e) which shall not apply to existing facilities. The five alarm system is tested annually and working properly. We have replaced the smake detector in the closet. This Rule is not met as evidenced by: Based on observation, the Fire Alarm system. was not maintained in a safe and operating condition. This would affect residents, staff, and visitors by not providing early detection and activating the fire alarm system. Findings on June 27, 2017: Bedroom 3 Window Closet - the fire alarm system's smoke detector is missing. Based on observation, the Building Sprinkler System was not maintained in a safe and operating condition. This could affect all

MDXD21

Division of Health Service Regulation								
STATEMENT OF DEFICIENCIES (X1) ((X1) PROVIDER/SUPPLIER/GLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED			
		HAL001028	B. WING		06/27/2017			
NAME OF I	PROVIDER OR SUPPLIER	STREET AD	ODRESS, CITY, STATE, ZIP CODE					
		613 W WH	IITSETT STE	REET				
	/IEW - CROUSE BUIL	.DING GRAHAM	NC 27253					
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFIGIENCIES MUST BE PRECEDED BY FULL BG IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROVIDENCY)	D BE COMPLETE PRIATE DATE			
C 189	contained in the Ro Findings on June 2 a. Bedroom 4 - in sprinkler head is ble obstructing the fire b. Activity Closet - plate had dropped of fire-resistance-rate that allows the spre c. Bedroom 6 - a debris-loaded. 3. Based on obse not maintained in a Findings on June 2 a. Kitchen - the oc ita frame when clos 4. Based on obse emergency equipm safe and in operatir residents, staff, and promptly find their v emergency. Findings on June 2 a. Med Room - th emergency light did power when the tes 5. Based on obse safety was not make condition. This coul not contained in Ro Findings on June 2 a. Beauty Shop - 1	d visitors if smoke/fire is not som or compartment of origin. 7, 2017: the window side closet the fire coked with a big bag of cloths, sprinkler spray pattern the fire sprinkler escutcheon down from the discilling exposing an opening ad of smoke and heat. fire sprinkler head was reation, the interior doors were safe and operating condition. 7, 2017: pridor door did not latch into led. revation, the building's ent was not maintained in a sign condition. This would affect it visitors if they could not way to an exit during an an exit	(F)	A,3,C) We have clear loaded sprinkler head throughout the low and pushed all down escutcheon cups to the correct position. The doors have been to ensure proper the battery was very the embroyency light wor king properly. The hole was filled the proper fire plants.	adjusted latching. laced in anditis			
	6. Based on obse	rvation, the Facility failed to						

Division of Health Service Regulation							
STATEMEN	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/QUPPLIER/CLIA IDENTIFICATION NUMBER:	1	E CONSTRUCTION	(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER:	A. BUILDING: 01		COMPLETED		
		HAL001025	B. WING		06/2	7/2017	
NAME OF F	PROVIDER OR SUPPLIER	STREET AC	DRESS, CITY, S	STATE, ZIP CODE			
SPRING	/IEW - CROUSE BUIL		HITSETT ST	REET			
		GRAHAM	I, NC 27283				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	MUST BE PRECEDED BY FULL	PREF(X TAG	PROVIDER'S PLAN OF CORRECTION (BACH CORRECTIVE ACTION SHOULD CROSS-REPERENCED TO THE APPROVIDENCY)	D BE	(XB) COMPLETE DATE	
C 189	Continued From pa	ge 4	C 189				
C 189	SUMMARY STATEMENT OF DEFICIENCIES (RACH DEFICIENCY MUST BE PRECEDED BY PULL REQULATORY OR LSG IDENTIFYING INFORMATION) Continued From page 4 maintain the electrical system in a safe and operating condition. Findings on June 27, 2017: a. Exterior Storage - a box is stored in front of the electrical panel, limiting the required 36-inches minimum clear working space. This prevents quick eccess in any emergency. Deficiency corrected before Construction Surveyor departed the site.		C 189				