

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL036006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/09/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER WOODLAWN HAVEN	STREET ADDRESS, CITY, STATE, ZIP CODE 301 CRAIG STREET MOUNT HOLLY, NC 28120
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report of Construction Section Biennial Survey by Dennis Harrell on 11-9-2017.</p> <p>Records indicate this facility was first licensed on 11-30-1989, for 80 beds. Therefore, the facility is required to meet the 1987 Homes for the Aged and Infirm Minimum Desired Standards and Regulations; the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds; and the 1978 North Carolina State Building Code, Revision 8, Section 409- Institutional Occupancy- Group I2.</p>	C 000		
C 140	<p>Linen Storage-Separate Clean & Soiled</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (f) The requirements for storage rooms and closets are: (2) Linen Storage. Storage areas shall be adequate in size and number for separate storage of clean linens and separate storage of soiled linens. Access to soiled linen storage shall be from a corridor or laundry room;</p> <p>This Rule is not met as evidenced by: Based on observation, the door between the soiled linen room and the laundry would not close completely.</p>	C 140		
C 164	<p>Housekeeping and Furnishings-Clean, Repaired</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor</p>	C 164		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL036006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/09/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER WOODLAWN HAVEN	STREET ADDRESS, CITY, STATE, ZIP CODE 301 CRAIG STREET MOUNT HOLLY, NC 28120
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 1 coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: Based on observation, floor tiles were broken or missing in the dining room.	C 164		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building was not maintained in a safe manner by not properly handling portable medical oxygen cylinders. This could affect all residents, staff and visitors if cylinders fall, breaking their valves, propelling the cylinder and turning it into a dangerous projectile. Findings include: Several (15) portable medical oxygen cylinders were stored in unapproved beverage crates in the oxygen storage room. 2. Based on observation, the hoses on both of the shower wands in the Beauty Salon were long enough to reach the sink basins and there were no vacuum breakers provided. Hoses on water fixtures that are long enough to reach the flood	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL036006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/09/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER WOODLAWN HAVEN	STREET ADDRESS, CITY, STATE, ZIP CODE 301 CRAIG STREET MOUNT HOLLY, NC 28120
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 2 rim of the fixture present the possibility of siphoning contaminated water into the water system unless a vacuum breaker is installed. 3. Based on observation, a lamp cord type extension cord was being used in place of permanent wiring in the employee break room. Extension cords are intended for temporary use only. 4. Based on observation, an exterior exit path was not maintained free of obstructions. Finding includes; There was a small concrete statue directly in the path of egress just outside the exit door from the dining room. The statue posed a trip hazard	C 166		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the facility was not maintained in a safe condition because of exit doors that were difficult to open. Exit doors that do not open freely could delay or prevent an evacuation in an emergency. Findings include; a. The exterior exit door from the dining room	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL036006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/09/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER WOODLAWN HAVEN	STREET ADDRESS, CITY, STATE, ZIP CODE 301 CRAIG STREET MOUNT HOLLY, NC 28120
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 3</p> <p>was difficult to open.</p> <p>b. The exit door near the laundry was difficult to open.</p> <p>2. Based on observation, many corridor doors are prevented from closing quickly and latching to resist the passage of fire and smoke. Corridor doors that do not close completely and latch present the possibility that a fire that begins in one space can quickly spread to the corridor and the remainder of the facility.</p> <p>Findings include;</p> <p>a. One of the fire doors near room B2 failed to latch when closed by the fire alarm system.</p> <p>b. One of the smoke barrier doors near room B5 failed to close completely when activated by the fire alarm system.</p> <p>c. The door to the living room would not latch when closed.</p> <p>d. The door from the kitchen to the dining room would not latch when closed.</p> <p>e. The door to the employee break room would not latch when closed.</p> <p>f. The door to room A6 would not latch when closed.</p> <p>g. The door to room B5 would not latch when closed.</p> <p>h.</p> <p>i. The double doors to the dining room will not close completely.</p> <p>j. There is a gap of about 1/2 inch between the double doors to the dining room.</p> <p>k. The latch strike was missing on the door to the phone room.</p> <p>l. The latch strike was missing on the door to the employee break room.</p> <p>m. The closer was broken on the 3/4 hour fire rated door to the laundry.</p> <p>n. The door to room B13 does not close properly to be resistant to the passage of smoke because</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL036006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/09/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER WOODLAWN HAVEN	STREET ADDRESS, CITY, STATE, ZIP CODE 301 CRAIG STREET MOUNT HOLLY, NC 28120
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 4</p> <p>the strike was installed wrong.</p> <p>o. There is a hole through the door to room A20 at the latchset.</p> <p>p. There is a hole through the door to room B7 at the latchset.</p> <p>q. There is a hole through the door to room B8 at the latchset.</p> <p>r. There is a hole through the door to room B12 at the latchset.</p> <p>s. There is a hole through the door to room A4 where a secondary latchset had been removed.</p> <p>t. There is a hole through the door to room B2 where a secondary latchset had been removed.</p> <p>u. One of the doors to the activity room was sagged and would not close and latch.</p> <p>3. Based on observation the required one-hour fire rated walls and/or ceilings were compromised in several locations. Holes and penetrations that are not sealed with materials approved for use in one-hour fire rated construction present the possibility that a fire that begins in one space can quickly spread to other areas of the facility. Findings include:</p> <p>a. Crack in the ceiling of the activity storage room,</p> <p>b. Holes in the ceiling of the boiler room,</p> <p>c. A large portion of the ceiling, about 8 feet by 8 feet, had sagged down from the ceiling joists in the storage room on B Hall.</p> <p>d. The surface mounted light fixture had fallen down from the ceiling in the storage room on B Hall.</p> <p>4. Based on observation, there was no access door provided for the duct mounted smoke detector in the boiler room for maintenance and cleaning. Sampling tubes that are not periodically inspected and cleaned can endanger all residents and staff because the duct detector may fail to</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL036006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/09/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER WOODLAWN HAVEN	STREET ADDRESS, CITY, STATE, ZIP CODE 301 CRAIG STREET MOUNT HOLLY, NC 28120
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 operate properly.	C 189		