

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/01/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER BROOKDALE CONCORD PARKWAY	STREET ADDRESS, CITY, STATE, ZIP CODE 2452 ROCK HILL CHURCH ROAD NW CONCORD, NC 28027
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report of a Construction Section Biennial Survey by Ed Miller and Frank Strickland conducted on November 1, 2017.</p> <p>Records indicate this facility was first licensed on 10-9-1996, for 112 beds, including 25 Special Care (SCU) beds. Based on this information, we are requiring the facility to meet the 1996 Homes for the Aged and Disabled - Minimum Standards and Regulations, the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds, and the 1996 Edition of the North Carolina State Building Code, Section 409.1, Group I Unrestrained Occupancy.</p> <p>Note: This facility consists of 2 separate buildings. One for Assisted Living and the other Memory Care Unit.</p> <p>Deficiencies were cited that require a Plan of Correction.</p>	C 000		
C 101	<p>Existing Licensed Fac- No less than '71 Rules</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and</p>	C 101		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/01/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER BROOKDALE CONCORD PARKWAY	STREET ADDRESS, CITY, STATE, ZIP CODE 2452 ROCK HILL CHURCH ROAD NW CONCORD, NC 28027
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	<p>Continued From page 1</p> <p>Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost;</p> <p>This Rule is not met as evidenced by:</p> <p>1. Based on observation, the facility failed to meet the Code requirements in effect at the time of construction by not having all of the required components for doors equipped with Special Locking Arrangements. This could affect all occupants who would need to evacuate through the door(s) if the exit were obstructed.</p> <p>Findings on November 1, 2017:</p> <p>a. MC Bldg Courtyard Gate - the existing emergency release switch at the "Special Locking" locked gate requires a metal key to operate. This key cannot be removed from the switch without reenergizing the lock. This is not in accordance with the NC State Building Code's requirement that the emergency release switch be an on/off switch.</p> <p>b. MC Bldg Front Door - the existing emergency release switch at the "Special Locking" locked door requires a metal key to operate. This key cannot be removed from the switch without reenergizing the lock. This is not in accordance with the NC State Building Code's requirement that the emergency release switch be an on/off switch.</p> <p>c. MC Bldg - the "Special Locking" system did not have a central on/off emergency release switch located at a staff station serving the locked unit and any other control situation responsible for the evacuation of the occupants of the locked units that are staffed 24 hours.</p> <p>d. MC Bldg both Back Exit - the "Special Locking" system at these doors did not have an on/off emergency release switch located within three feet of the door.</p>	C 101		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/01/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER BROOKDALE CONCORD PARKWAY	STREET ADDRESS, CITY, STATE, ZIP CODE 2452 ROCK HILL CHURCH ROAD NW CONCORD, NC 28027
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 2 e. Fire Alarm Control Panel - the special locking system does not have a wiring diagram and a system components location map posted at the FACP. Wiring diagram must also provide the electrical panel name/location and circuit breaker number that energizes the system.	C 101		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building mechanical systems are not kept clean and in good repair. Findings on November 1, 2017: a. AL Bldg Kitchen Mop Closet - the ventilation grille with its radiation damper had an excessive accumulation of dust/lint. b. MC Bldg Soiled Utility inside Laundry Room - the ventilation grille with its radiation damper had an excessive accumulation of dust/lint. c. MC Bldg Bedroom 76 - the HVAC return grille with its radiation damper had an excessive accumulation of dust/lint. 2. Based on Observation, the facility failed to keep walls, ceilings, floors or floor coverings and furniture clean and in good repair. Findings on November 1, 2017:	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/01/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER BROOKDALE CONCORD PARKWAY	STREET ADDRESS, CITY, STATE, ZIP CODE 2452 ROCK HILL CHURCH ROAD NW CONCORD, NC 28027
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 3 a. MC Bldg Public Restroom - the ceiling is stained and mold was starting to grow.	C 164		
C 189	<p>Building Equipment Maintained Safe, Operating</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS</p> <p>(a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition.</p> <p>(k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <p>1. Based on observation, the building's emergency equipment was not maintained in a safe and operating condition. This would affect all if they could not promptly find their way to an exit during an emergency.</p> <p>Findings on November 1, 2017:</p> <p>a. AL Bldg Corridor near Med - the exit sign on the Smoke Barrier did not illuminate on backup power when tested.</p> <p>b. AL Bldg Intersecting Corridors near Bistro - the exit sign had no chevron directional indicators punch-outs removed, indicating that you should go straight and exit out the buildings side door, which is not a marked exit. The exits are in the front and back of the building and the chevron directional indicators punch-outs on the exit sign must indicated that. .</p> <p>2. Based on observation, the Fire Alarm system was not maintained in a safe and operating condition. This would affect all by not providing</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/01/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER BROOKDALE CONCORD PARKWAY	STREET ADDRESS, CITY, STATE, ZIP CODE 2452 ROCK HILL CHURCH ROAD NW CONCORD, NC 28027
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 4</p> <p>early detection and activating the fire alarm system.</p> <p>Findings on November 1, 2017:</p> <p>a. AL Bldg Mech Room in Nurse Office - the sample tubes for the HVAC duct mounted smoke detectors are dirty and must be cleaned.</p> <p>3. Based on observations, the Building fire safety was not maintained in a safe and operating condition. This could expose all to fire/smoke if not contained in Room or compartment of origin.</p> <p>Findings on November 1, 2017:</p> <p>a. AL Bldg Mech Room/Office - there is a gap around a cable bundle not firestopped as it penetrates the fire-resistance-rated ceiling assembly.</p> <p>b. MC Bldg Sprinkler Riser Room - the escutcheon plate around the sprinkler riser has dropped down from the fire-resistance-rated ceiling exposing an opening that allows the spread of smoke and heat.</p> <p>4. Based on observation, the Facility failed to maintain the electrical system in a safe and operating condition.</p> <p>Findings on November 1, 2017:</p> <p>a. AL Bldg Reception Desk - a power tap (power strip) is plugged into an extension cord. Power taps must connect directly to permanently installed branch circuit electrical power receptacles.</p> <p>b. AL Bldg Dining - at the coffee counter the ground-fault circuit-interrupter (GFCI) electrical power receptacle was not secure to the wall.</p> <p>5. Based on observation, the interior doors were not maintained in a safe and operating condition.</p> <p>Findings on November 1, 2017:</p> <p>a. MC Bldg Bedroom 68 - the corridor door did not latch into its frame when closed.</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/01/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER BROOKDALE CONCORD PARKWAY	STREET ADDRESS, CITY, STATE, ZIP CODE 2452 ROCK HILL CHURCH ROAD NW CONCORD, NC 28027
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 b. MC Bldg Program Director - the corridor door had a kick down device holding the door open. This prevents the rapid release of the door with a light push or pull of the door, to close and latch.	C 189		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff, and visitors by preventing the exhausting of odors. Findings on November 1, 2017: a. MC Bldg Housekeeping across from Bedroom 71 - the required exhaust ventilation system did not work, and there is odor. b. MC Bldg Spa across from Bedroom 72 - the required exhaust ventilation system did not work, and there is odor. c. MC Bldg Public Restroom - the required	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/01/2017
--	--	---	---

NAME OF PROVIDER OR SUPPLIER BROOKDALE CONCORD PARKWAY	STREET ADDRESS, CITY, STATE, ZIP CODE 2452 ROCK HILL CHURCH ROAD NW CONCORD, NC 28027
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 6 exhaust ventilation system did not work, and there is odor.	C 199		