

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report of a Construction Section Biennial Survey by Ed Miller, conducted on October 12, 2018. A Biennial Follow up Construction Survey was performed at the same time.</p> <p>Records indicate this facility was first licensed as a Home for the Aged on March 11, 1998. The facility is currently licensed as a Forty-Eight (48) bed Special Care Unit. Based on this information, we are requiring the facility to meet the 1996 Homes for the Aged and Disabled - Minimum Standards and Regulations, the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds, and the 1996 Edition of the North Carolina State Building Code, Section 409.1, Group I Unrestrained Occupancy.</p> <p>Deficiencies were cited that require a Plan of Correction.</p>	C 000		
C 150	<p>Corridors-Free of equipment and Obstructions</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions.</p> <p>This Rule is not met as evidenced by: 1. Based on observation, corridors are not free of obstructions. This would affect all residents, staff, and visitors by slowing or obstructing egress during an emergency. Findings on October 12, 2018: a. Exit near Bedroom A9-A10 - the exit is blocked from opening with a ladder positioned behind the door.</p>	C 150		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 1	C 164		
C 164	<p>Housekeeping and Furnishings-Clean, Repaired</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS</p> <p>(a) Adult care homes shall:</p> <p>(1) have walls, ceilings, and floors or floor coverings kept clean and in good repair;</p> <p>(2) have no chronic unpleasant odors;</p> <p>(3) have furniture clean and in good repair;</p> <p>(e) This Rule shall apply to new and existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <p>1. Based on observation, the building mechanical systems are not kept clean and in good repair.</p> <p>Findings on October 12, 2018:</p> <p>a. Women - the ventilation system with its radiation damper has an excessive accumulation of dust/lint.</p> <p>b. A Wing Restroom - the ventilation system with its radiation damper has an excessive accumulation of dust/lint.</p> <p>c. B Wing Laundry - the ventilation system with its radiation damper has an excessive accumulation of dust/lint.</p> <p>d. C Wing Laundry - the ventilation system with its radiation damper has an excessive accumulation of dust/lint.</p> <p>e. D Wing Laundry - the ventilation system with its radiation damper has an excessive accumulation of dust/lint.</p> <p>2. Based on observation, the building ceiling are not kept clean and in good repair.</p> <p>Findings on October 12, 2018:</p> <p>a. Beauty Shop - there is an acoustical ceiling</p>	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 2 tile stained from a past leak.	C 164		
C 188	<p>Electrical Outlets in Wet Locations</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters.</p> <p>This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to provide electrical outlets in wet locations at sinks, with ground fault interrupters. This would affect residents, staff, and visitors by not providing ground fault protection to these devices. Findings on October 12, 2018: a. A & B Beauty Shop - there is an electrical power receptacle within six feet of the sink, and it is not providing ground fault protection. b. C & D Beauty Shop - there is an electrical power receptacle within six feet of the sink, and it is not providing ground fault protection.</p>	C 188		
C 189	<p>Building Equipment Maintained Safe, Operating</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

C 189	<p>Continued From page 3</p> <p>This Rule is not met as evidenced by:</p> <ol style="list-style-type: none"> 1. Based on observation, the Fire Alarm system was not maintained in a safe and operating condition. This would affect all by not providing early detection and activating the fire alarm system. Findings on October 12, 2018: <ol style="list-style-type: none"> a. A & B Janitor - the fire alarm system's smoke detector is dangling from the ceiling by its power/operational wires. 2. Based on observations, the Building fire safety was not maintained in a safe and operating condition. This could expose all to fire/smoke if not contained in room of origin. Findings on October 12, 2018: <ol style="list-style-type: none"> a. Lobby - there is a gap around a plastic tube not sealed as it penetrates the smoke tight assembly. b. A & B Panel Room - there are gaps around two conduits not firestopped as they penetrate the fire-resistance-rated ceiling assembly. c. Exit Corridor near Bedroom A9 - A10 - the attic door is open, allowing fire and smoke access through the fire-resistance-rated ceiling assembly. d. B Wing Panel Room near Bedroom B4 - B5 - there is an open-ended sleeve with a cable bundle not firestopped as it penetrates the fire-resistance-rated ceiling assembly. e. A & B Maintenance Shop Room - there are gaps around two conduits not firestopped as they penetrate the fire-resistance-rated ceiling assembly. f. C & D Panel Room - there is a gap around a conduit not firestopped as it penetrates the fire-resistance-rated ceiling assembly. 3. Based on Observation, fire rated doors of hazardous or Incidental areas are not being 	C 189		
-------	--	-------	--	--

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 4</p> <p>maintained in a safe and operating condition. By not maintaining the fire and smoke resistance of doors, keeping rooms the NC State Building Code defines as "Hazardous or Incidental Area" separated from the rest of the Building. This could affect residents, staff and visitors if smoke/fire is not contained in Room of origin. Findings on October 12, 2018:</p> <p>a. C & D Soiled Linen - the corridor door was not self-closing or automatic closing by smoke detection.</p> <p>4. Based on Observation, corridor door of Incidental areas are not being maintained in a safe and operating condition. This could affect residents, staff and visitors if smoke/fire is not contained in Room of origin. Findings on October 12, 2018:</p> <p>a. Kitchen - under its own power, the self-closing corridor door did not latch into its frame.</p> <p>b. C & D Soiled Linen - the corridor door a self-closing 45 minute fire rated door has a wedge holding the door open</p> <p>5. Based on observation, the Facility failed to maintain the electrical system in a safe and operating condition. Findings on October 12, 2018:</p> <p>a. Kitchen - a rack is stored in front of the electrical panel, limiting the required 36-inches by 30-inches minimum clear working space to 24-inches.</p> <p>6. Based on observation, the Building was not maintained in a safe and operating condition, because of required periodic testing requirements, some fire sprinkler head have been removed and submitted to a testing laboratory for evaluation. This has left some areas without fire</p>	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 5</p> <p>sprinkler protection. This would affect all, by not providing the required protection that fire sprinklers provide.</p> <p>Findings on October 12, 2018:</p> <p>a. B Wing Panel Room near Bedroom B4 - B5 - the escutcheon plate on the fire sprinkler does not cover the complete hole through the fire-resistance-rated ceiling that allows the spread of smoke and heat.</p> <p>7. Based on Observation, the corridor doors are not maintained in a safe and operating condition. This affects all by not containing smoke and fire in the room of origin.</p> <p>Findings on October 12, 2018:</p> <p>a. Bedroom B1 - the corridor door has a shoe holding the door open. This prevents the rapid release of the door with a light push or pull of the door, to close and latch.</p> <p>b. Bedroom C9 - C10 - the corridor door has a wedge holding the door open. This prevents the rapid release of the door with a light push or pull of the door, to close and latch.</p>	C 189		
C 191	<p>Unvented & Portable Elec. Heaters Prohibited</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS</p> <p>(b) There shall be a heating system sufficient to maintain 75 degrees F (24 degrees C) under winter design conditions. In addition, the following shall apply to heaters and cooking appliances.</p> <p>(2) Unvented fuel burning room heaters and portable electric heaters are prohibited.</p> <p>(k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.</p>	C 191		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 191	Continued From page 6 This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to prevent the use of portable electric heaters in an Adult Care Home. This could affect residents, staff, and visitors if heater is the ignition source of a fire. The danger increases if used by resident or combustible material is near. Findings on October 4, 2018: a. Receptionist - a portable electric heater is in this space.	C 191		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff, and visitors by preventing the exhausting of odors. Findings on October 12, 2018:	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041078	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/12/2018
--	--	---	---

NAME OF PROVIDER OR SUPPLIER THE ARBORETUM AT HERITAGE GREENS	STREET ADDRESS, CITY, STATE, ZIP CODE 709 MEADOWOOD STREET GREENSBORO, NC 27409
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 7 a. A Wing Laundry - the required exhaust ventilation system did not work b. B Wing Laundry - the required exhaust ventilation system did not work	C 199		