Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 HAL045126 03/07/2019 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **1825 PISGAH DRIVE** CAROLINA RESERVE OF LAUREL PARK HENDERSONVILLE, NC 28791 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DATE CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) C 000 Initial Comments C 000 The following is a summary of the Plan of Correction for Carolina Reserve of Laurel Report of Construction Section Biennial Survey Park. This Plan of Correction is in regards by Dennis Harrell on 3-7-2019. to the Corrective Action Report dated March 18, 2019. This Plan of Correction is not to Records indicate this facility was first licensed on be construed as an admission of or 5-1-1998, for 48 beds. Therefore, this facility is agreement with the findings and conclusions required to meet the 1996 Minimum and Desired in the Statement of Deficiencies, or any Standards and Regulations for Homes for the related sanction or fine. Rather, it is Aged and Disabled; the applicable portions of the submitted as confirmation of our ongoing 2005 Rules for Adult Care Homes of Seven or efforts to comply with statutory and More Beds; and the 1996 North Carolina State regulatory requirements. In this document, Building Code Section 409.1- Institutional we have outlined specific actions in Occupancy (Group I) Unrestrained. response to identified issues. We have not provided a detailed response to each C 164 Housekeeping and Furnishings-Clean, Repaired C 164 allegation or finding, nor have we identified mitigating factors. SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND **FURNISHINGS** 10A NCAC 13F .0306 Housekeeping and (a) Adult care homes shall: **Furnishings** (1) have walls, ceilings, and floors or floor (a) Adult care homes shall: coverings kept clean and in good repair: (1) have walls, ceilings, and floors or floor (2) have no chronic unpleasant odors: coverings kept clean and in good repair; (3) have furniture clean and in good repair; (2) have no chronic unpleasant odors; (e) This Rule shall apply to new and existing (3) have furniture clean and in good facilities. repair; (e) This Rule shall apply to new and This Rule is not met as evidenced by: existing facilities. Based on observation, a building surface was not Designated laminate counter top was kept in good repair. repaired by 3/8/19 Finding on 3-7-2019: Portions of the trim on a laminate countertop were broken or not firmly fastened in place. C 189 Building Equipment Maintained Safe, Operating C 189 10A NCAC 13F .0311 Other SECTION .0300 - PHYSICAL PLANT Requirements 10A NCAC 13F .0311 OTHER

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

(X6) DATE

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 HAL045126 03/07/2019 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **1825 PISGAH DRIVE** CAROLINA RESERVE OF LAUREL PARK HENDERSONVILLE, NC 28791 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) DATE TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) C 189 Continued From page 1 C 189 10A NCAC 13F .0311 Other REQUIREMENTS Requirements (a) The building and all fire safety, electrical, (a) The building and all fire safety, mechanical, and plumbing equipment in an adult electrical, mechanical, and plumbing care home shall be maintained in a safe and equipment in an adult care home shall be operating condition. maintained in a safe and operating (k) This Rule shall apply to new and existing condition. facilities with the exception of Paragraph (e) (k) This Rule shall apply to new and which shall not apply to existing facilities. existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: Indicated conduit sleeves and ceiling 1. Based on observation, the required one-hour penetrations will be sealed with approved fire rated walls and/or ceilings were compromised fire seal material by 3/8/19 in several locations. Holes and penetrations that Designated smoke barrier door was repaired are not sealed with materials approved for use in assuring proper closure by 3/8/19. one-hour fire rated construction present the Designated door wedge was removed on possibility that a fire that begins in one space can 3/8/19. quickly spread to other areas of the facility. Designated sprinkler escutcheon's were Findings on 3-7-2019: a. Unsealed conduit sleeves (2) through the repaired on 3/8/19. ceiling in the main electrical room. Designated room with combustible b. Unsealed penetration in the ceiling of the 300 storage that is not designated as a Hall mechanical room, storage room per regulations will be c. Two ceiling penetrations sealed with unrated cleared of noted items by 4/2/19. foam in the mechanical room off the laundry. d. Unsealed penetration in the ceiling of the other mechanical room off the laundry, e. Unsealed penetration in the ceiling of the kitchen at a gas line. f. A ceiling penetration sealed with unrated foam in the sprinkler riser room. 2. . Based on observation, corridor doors are prevented from closing quickly and latching to resist the passage of fire and smoke. Corridor doors that do not close completely and latch present the possibility that a fire that begins in one space can quickly spread to the corridor and the remainder of the facility. Findings on 3-7-2019;

Division of Health Service Regulation

Sterrie Simmons

 $\mathcal{E}_{\mathcal{I}}^{\mathfrak{s}\mathfrak{s}\mathfrak{s}}$

L6Q621

4/1/2019

If continuation sheet 2 of 4

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING _ HAL045126 03/07/2019 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **1825 PISGAH DRIVE** CAROLINA RESERVE OF LAUREL PARK HENDERSONVILLE, NC 28791 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX COMPLETE PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) C 189 Continued From page 2 C 189 a. The smoke barrier doors on the 100 Hall do not close completely when activated by the fire alarm system. b. A wedge was found at the 20 minute fire rated door to the mop sink room on the 200 Hall. The wedge indicates the door is sometimes wedged open. Note; This deficiency was corrected during the survey. 3. Based on observation the required one-hour fire rated ceilings were compromised in locations because of sprinkler escutcheons missing or not tightly fitted to the ceiling. Sprinkler escutcheons that are not properly mounted present the possibility that a fire that begins in one space can quickly spread to other areas of the facility. Improperly mounted escutcheons were found in: a. Both closets in room 117. b. Dining room. Oxygen storage room. 4. Based on observation, the facility failed to be maintained in a safe manner by allowing large quantities of combustible storage to be kept in an area that is not designed and equipped as a storage room in accordance with the NC State Building Code. This situation could result in a fire growing larger than the construction's ability to contain it. Finding on 3-7-2019; Former bedroom 221 is now being used as the maintenance area. Combustible storage was found consisting of at least the following: 46 plastic storage containers, 30 upholstered chairs. 6 wood chests, 4 wood bed frames and 14 wood framed mirrors. 5. Based on observation, the facility was not maintained in a safe condition because of improper storage too close to a fire sprinkler

Division of Health Service Regulation

Sherrie Simmons,

E۵

-6Q621 4/1/2019 If continuation sheet 3 of 4

FORM APPROVED Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING HAL045126 03/07/2019 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **1825 PISGAH DRIVE** CAROLINA RESERVE OF LAUREL PARK HENDERSONVILLE, NC 28791 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID PREFIX (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DATE **DEFICIENCY**) C 189 Continued From page 3 C 189 head. Storage that is not kept at least 18 inches below the sprinkler head could negate the ability of the fire sprinkler system to extinguish a fire. Finding on 3-7-2019; Items had been stacked to within 4 inches of the ceiling in the dry storage room. Note; This deficiency was corrected during the survey. 6. Based on observation, there was no documentation of the required in house/owner's monthly inspections provided on the inspection tag at the range hood fire suppression system since October of last year. Range hood fire suppression systems must be inspected monthly and the inspections must be documented somewhere such as on the tag provided at the system pull.

Division of Health Service Regulation

STATE FORM

Dherrie Simmons, ED

L6Q621 4/1/2019 If continuation sheet 4 of 4