

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL098036	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 01/10/2024
--	--	---	---

NAME OF PROVIDER OR SUPPLIER COMPASSIONATE CARE HOME AT FOXCROFT	STREET ADDRESS, CITY, STATE, ZIP CODE 2413 FOXCROFT RD WILSON, NC 27893
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report by Jonathan Gamsey</p> <p>DHSR Construction Section conducted a Biennial Survey on January 10, 2023 from 11:35 AM to 01:10 PM at the above referenced facility. DHSR records indicate the home was first licensed on August 24, 2021 as a Family Care Home for six (3) non-ambulatory Residents (unable to respond and evacuate without any physical or verbal assistance during a fire or other emergency). Based on this we are requiring the home to be in compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes the applicable portions of the 2018 North Carolina Building Code - Section 428.2 - Residential Care Homes</p> <p>NOTES:</p> <p>1.) At the time of our visit, we cited deficiencies that require an acceptable plan of correction. All deficiencies listed were discussed with on-site staff during the exit interview.</p> <p>2.) Take actions to correct all listed deficiencies, once completed provide verification in the form of photos, receipts, invoices, etc. for all work performed.</p> <p>3.) At the time of the survey, it was identified that the home hasn't served any residents in the past 10 months.</p> <p>The cited deficiencies are as follows:</p>	C 000		
C 105	<p>Initial Licensure-Meet NCSBC</p> <p>SECTION .0300 - THE BUILDING 10A NCAC 13G .0302 DESIGN AND</p>	C 105		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL098036	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 01/10/2024
--	--	---	---

NAME OF PROVIDER OR SUPPLIER COMPASSIONATE CARE HOME AT FOXCROFT	STREET ADDRESS, CITY, STATE, ZIP CODE 2413 FOXCROFT RD WILSON, NC 27893
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 105	<p>Continued From page 1</p> <p>CONSTRUCTION</p> <p>(a) Any building licensed for the first time as a family care home shall meet the applicable requirements of the North Carolina State Building Code. All new construction, additions and renovations to existing buildings shall meet the requirements of the North Carolina State Building Code for One and Two Family Dwellings and Residential Care Facilities if applicable. All applicable volumes of The North Carolina State Building Code, which is incorporated by reference, including all subsequent amendments, may be purchased from the Department of Insurance Engineering Division located at 322 Chapanoke Road, Suite 200, Raleigh, North Carolina 27603 at a cost of three hundred eighty dollars (\$380.00).</p> <p>(b) Each home shall be planned, constructed, equipped and maintained to provide the services offered in the home.</p> <p>This Rule is not met as evidenced by:</p> <p>1.) At the time of the survey, it was observed that the laundry room does not have a GFCI. Per 210.8(A) states " Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified in 210.8(A)(1) through (10) shall have ground-fault circuit-interrupter protection for personnel. " This is not compliant with the rule. Take the necessary steps to reach out to a certified professional to install a GFCI in the laundry room for the washer.</p> <p>2.) At the time of the survey, it was observed that the staff bathroom does not have a GFCI. Per 210.8(A) states " Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified in 210.8(A)(1)</p>	C 105		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL098036	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 01/10/2024
--	--	---	---

NAME OF PROVIDER OR SUPPLIER COMPASSIONATE CARE HOME AT FOXCROFT	STREET ADDRESS, CITY, STATE, ZIP CODE 2413 FOXCROFT RD WILSON, NC 27893
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 105	Continued From page 2 through (10) shall have ground-fault circuit-interrupter protection for personnel. " This is not compliant with the rule. Take the necessary steps to reach out to a certified professional to install a GFCI in the laundry room to replace the current receptacle 3.) At the time of the survey, it was observed that DHSR does not have a proper layout of the facility. This is not compliant with the rule. Take the necessary steps to properly update a floor plan and send to DHSR dictating proper room usage.	C 105		
C 115	Construction-Consult Local BI for Permits SECTION .0300 - THE BUILDING 10A NCAC 13G .0302 DESIGN AND CONSTRUCTION (l) The local code enforcement official shall be consulted before starting any construction or renovations for information on required permits and construction requirements. This Rule is not met as evidenced by: 1.) At the time of the survey, it was observed that the garage in the facility had had alterations without approval from the DHSR construction section. This is not compliant with the rule. Take the necessary steps to follow up with the local official jurisdiction to provide a permit to DHSR and if a permit is not needed provide documentation to DHSR.	C 115		
C 147	Outside Entrances/Exits-Single Hand Motion SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS	C 147		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL098036	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 01/10/2024
--	--	---	---

NAME OF PROVIDER OR SUPPLIER COMPASSIONATE CARE HOME AT FOXCROFT	STREET ADDRESS, CITY, STATE, ZIP CODE 2413 FOXCROFT RD WILSON, NC 27893
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 147	Continued From page 3 (d) All exit door locks shall be easily operable, by a single hand motion, from the inside at all times without keys. Existing deadbolts or turn buttons on the inside of exit doors shall be removed or disabled. This Rule is not met as evidenced by: 1.) At the time of the survey, it was observed that the front and rear storm doors do not meet the rule above. This is not compliant with the rule. Take the necessary steps to alter the door to meet the rule.	C 147		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1.) At the time of the survey it was observed that the hallway bathroom near the rear exit had a loose toilet at the base causing a potential for leaks to happen and also for residents to be injured when using the facilities. This is not compliant with the rule. Take the necessary steps to secure the toilets to prevent any leaks or possible injuries. 2.) At the time of the survey, it was observed that bedroom #4 had an extension cord. This is not compliant with the rule. Take the necessary steps	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL098036	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 01/10/2024
--	--	---	---

NAME OF PROVIDER OR SUPPLIER COMPASSIONATE CARE HOME AT FOXCROFT	STREET ADDRESS, CITY, STATE, ZIP CODE 2413 FOXCROFT RD WILSON, NC 27893
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 4 to remove the extension cord from the facility and utilize a surge protector if needed. 3.) At the time of the survey, it was observed that the rear ramp leading to the gate sidewalk needs the grading built back up. This could potentially lead to a tripping hazard. This is not compliant with the rule. Take the necessary steps to build the grading back up.	C 174		