Division of Health Service Regulation (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING: 01 R WING 06/19/2024 HAL007025 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 143 SWAMP ROAD PANTEGO REST HOME PANTEGO, NC 27860 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES IВ (X4) ID COMPLETE DATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX **PREFIX** CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) {C 000} {C 000} Initial Comments Report of a Biennial Follow Up Construction Survey by Suzanna Fay conducted on June 19, 2024. There are deficiencies from the Biennial Construction Survey that remain to be corrected. {C 160} {C 160} Outside Premises-Clean, Safe SECTION .0300 - PHYSICAL PLANT Administrator had Housekeeper to clean debris and spider webs from screen/ 10A NCAC 13F .0305 PHYSICAL **ENVIRONMENT** (m) The requirements for outside premises are: (1) The outside grounds of new and existing facilities shall be maintained in a clean and safe condition: vindous on 6/19/24.
Manager will ensure
that Housekeeping
teop clean all window
tals and etc. weekly This Rule is not met as evidenced by: 1. Observations revealed that the outside grounds were not maintained in a clean and safe condition. Findings on June 19, 2024: a. A 30" section of the exterior soffit at the right front side of the facility has rotted and is hanging Of as needed. all other repairs have been started by down. b. A 24" section of the exterior soffit left of the front entry has deteriorated and is no longer b. Enclosed Porch - the left front window glass is maintenance. Facility broken. c. There is a pattern of torn or damaged window manager will ensure screens around the facility. There is a heavy accumulation of debris and spider webs between the screens and the windows. e. Grounds left of facility - there is one rotting ietion correction post and a section of broken concrete laying in the middle of the side yard. There are multiple Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

PRINTED: 07/05/2024 FORM APPROVED Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 R HAL007025 B. WING 06/19/2024 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 143 SWAMP ROAD PANTEGO REST HOME PANTEGO, NC 27860 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) {C 160} Continued From page 1 {C 160} holes and ruts that are creating trip hazards. There is ongoing work with the drainage system that has left holes full of water and piles of dirt around this side of the building. {C 164} Housekeeping and Furnishings-Clean, Repaired {C 164} SECTION .0300 - PHYSICAL PLANT Facility manager Will ensured facility is kept clean at all times. 10A NCAC 13F .0306 HOUSEKEEPING AND **FURNISHINGS** (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: Observations revealed that the furniture and furnishings were not kept in good repair. Findings on June 19, 2024: c. Room 9 - there is a 3" hole in the closet door. monitor daily to 2. Observations revealed that the walls and ceilings were not kept in good repair. Findings on June 19, 2024: a. Room 13 - there is a crack in the ceiling where an old patch is opening up. There is a 24" diameter area near the closets that has a yellow water stain and the finish within the stain is

bubbling and flaking.

chipping and flaking off.

b. There is a 6" x 12" hole knocked into the corridor wall outside of the kitchen door. The paint finish on the wall across from the hole is

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 R B. WING HAL007025 06/19/2024 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 143 SWAMP ROAD PANTEGO REST HOME PANTEGO, NC 27860 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (X5) (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX PREFIX (EACH CORRECTIVE ACTION SHOULD BE COMPLETE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG DEFICIENCY) {C 164} Continued From page 2 {C 164} c. Kitchen - the wall by the handwashing sink is flaking and peeling. d. Kitchen - there is an accumulation of grease and dirt on the HVAC grille in front of the hood. (C 166) Housekeeping-Maintained Free of Hazards {C 166} SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND **FURNISHINGS** (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation the facility was not maintained free from hazards. Oxygen bottles were improperly stored. Oxygen bottles without any means of restraint to prevent them from falling or being knocked over may present a danger to the occupants of the facility. Findings on June 6, 2024: a. Oxygen Supply Room - there are oxygen bottles unsecured in a shallow plastic crate. Interview with staff revealed that these were purchased by a previous resident's family and they have been unable to locate a vendor to Plan of Completion Correction: 6/21/24 remove the bottles. New Deficiency: b. Nurse Station - there is a shallow plastic crate full of oxygen bottles without any means of restraint to prevent the bottles from falling or

getting knocked over.

NPSK22

Division	of Health Service Ro	egulation			TOTALL
STATEMENT OF DEFICIENCIES		(X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIP	LE CONSTRUCTION	(X3) DATE SURVEY
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:	A. BUILDING		COMPLETED
				. •	_
		HAL007025	B. WING		R
		HAL00/025			06/19/2024
NAME OF	PROVIDER OR SUPPLIER	STREET AD	DRESS, CITY,	STATE, ZIP CODE	
DANTEC	0.0007.110445	143 SWA	MP ROAD		
PANTEG	O REST HOME		D, NC 27860	1	
(X4) ID	SUMMARY STA	TEMENT OF DEFICIENCIES			TION
PREFIX		MUST BE PRECEDED BY FULL	ID PREFIX	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO	
TAG				CROSS-REFERENCED TO THE APPR	
			:	DEFICIENCY)	
(C 186)	Duilding Equipment	Maintained Code Conserving	. (0.400)		
(C 103)	; building Equipment	Maintained Safe, Operating	{C 189}		
	SECTION .0300 - F	SUVEICAL DI ANT		,	
	10A NCAC 13F .03			(maintanance)	Stringer
	REQUIREMENTS	II OTHER		That wer were	nu ka
		d all fire safety, electrical,		1000 min no 7/10/	เดน
	morphopical and all	iu ali life salety, electrical,	i	Japana or mil	Ø7
	opro homo chell ha	umbing equipment in an adult maintained in a safe and		and front to Ma	Ontag
	operating condition		1	UNA TACHIY MA	rajer
	1 .			will proposed -	⊬ ∑
		apply to new and existing		maintenance repairs on 71191 and facility Ma will continue	
		ception of Paragraph (e)		manital MOMAN	<i>'</i> †)
	willon shall not app	ly to existing facilities.		menitor repaired Theoritor all are a Plan of Comple Correction; 8/19/	10
				Thouga 111 ADO	moleta
	This Bula is not me	at as avidonased by		erome ace was	7
	This Rule is not me	vation there is a failure to			
	1			01 - 1 0	
		g's fire safety systems in a es or gaps at penetrations		YIAN DE COMPCE	710
		nt rated ceilings could allow		21	,
		pread beyond the area of		(Decretion ' X 1191	QU
	origin.	pread beyond the area of	'	Corr (Caron) (3/1 /p	^7
	origin.				
	Findings on June 19	9. 2024:			
		- one of the grille vents is not			
		p in the fire resistant rated			
	ceiling.	p " ino mo robiotant ratoa			
	•	cover in the right back corner			
		g a gap in the fire resistant			İ
	rated ceiling.	g a gap in the net recipient	:		
		an unsealed cable bundle in	i		
	the front corner of t				
		ealed cable penetration in the	· ·		
		ency light outside of Room 1.	İ		
		nel above the water heater			
		e perimeter and the water			
		sealed where they penetrate			
	the ceiling.	The second secon	!	* 1	}
		small holes in the ceiling			*
	outside of Room 16		!		
		there are two unsealed			
		ne ECO Smart panel.			

Division	of Health Service R	egulation			FORM APPRO	VED
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED	
		HAL007025	B. WING	PR-14-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	R 06/19/2024	ļ
NAME OF	PROVIDER OR SUPPLIER	STREET AD	DRESS, CITY,	STATE, ZIP CODE		
PANTEG	O REST HOME	143 SWAI		_		
(V4) ID	CIRALADY STA	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~), NC 2786			
(X4) ID PREFIX TAG	(EACH DEFICIENCY		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE COMPLI	ETE
{C 189}	Continued From pa	ge 4	{C 189}			
	REGULATORY OR LSC IDENTIFYING INFORMATION)			Rm 2 latch Pla Repaired on 6/19 Repaired on 4/19 Rm 10 door do the floor Repair 6/19/24 All other fur are being repair by maintenance Plan of Compo Correction: 8/19	rdip ived	

NPSK22

FORM APPROVED Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 R HAL007025 **B. WING** 06/19/2024 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 143 SWAMP ROAD **PANTEGO REST HOME** PANTEGO, NC 27860 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DATE TAG DEFICIENCY) {C 189} Continued From page 5 {C 189} relief valve has not been piped. 5. Observations revealed that the mechanical equipment is not maintained in a safe and operating condition. Findings on March 26, 2024: a. There are two duct openings outside of Laundry for the dryer vents. Neither has a cover or cap to prevent pests from entering the facility. 6. Based on observation the facility's fire safety equipment is not maintained in operating condition. Failure to maintain fire safety equipment in operating condition could affect occupants of the facility if the equipment did not function during a fire. Findings on June 19, 2024: a. Clean Linen - the bottom plate on the heat detector is bent 90 degrees. b. Oxygen Supply Closet - the heat detector is dangling from its wires. 7. Based on observation, the electrical equipment is not being maintained in a safe operating condition. Missing or broken cover plates on electrical devices may cause injury to the occupants of the facility if wiring is exposed. Findings on June 19, 2024: b. The top of the cover plate on the outlet at the security panel is broken off. 8. Based on observation, the electrical equipment is not maintained in a safe and operating condition.

Findings on June 19, 2024:

a. Kitchen Pantry - the light lens is damaged and

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 HAL007025 B. WING 06/19/2024 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 143 SWAMP ROAD PANTEGO REST HOME PANTEGO, NC 27860 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) {C 189}: Continued From page 6 {C 189} hanging from the frame. (C 195) Hot Water System {C 195} SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (d) The hot water system shall be of such size to provide an adequate supply of hot water to the kitchen, bathrooms, laundry, housekeeping closets and soil utility room. The hot water temperature at all fixtures used by residents shall be maintained at a minimum of 100 degrees F (38 degrees C) and shall not exceed 116 degrees F (46.7 degrees C). (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations and testing revealed that the hot water temperature at all fixtures used by residents was not maintained between 100 degrees F and 116 degrees F. Findings on June 19, 2024: b. Tub Bath - the water temperature at the sink was 130 degrees F. A new water heater had just been installed. The thermostat on the water heater was adjusted. The door was secured and the water was left running to get the temperature to within the required range.

NPSK22