| | | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 | | | (X3) DATE SURVEY COMPLETED | |
|--------------------------|---|--|--|---|---|---|--|
| | | BENTH IOATION NOMBER. | | | R | | |
| | HAL018016 | | B. WING | B. WING | | 10/22/2024 | |
| IAME OF F | ROVIDER OR SUPPLIER | STREET | ADDRESS, CITY, ST | TATE, ZIP CODE | | | |
| BROOKD | ALE HICKORY NOR | THFAST | STH STREET N RY, NC 28601 | E | | | |
| (X4) ID PREFIX TAG | (EACH DEFICIENC) | ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION) | ID PREFIX TAG | ID PROVIDER'S PLAN OF CC PREFIX (EACH CORRECTIVE ACTIO | | ON SHOULD BE COMPLET IE APPROPRIATE DATE | |
| {C 000} | Initial Comments | | {C 000} | | | | |
| | Report of a Construction Section Biennial Follow Up Survey by Tod Hancock conducted on October 22, 2024. | | 1 | | | | |
| | an addition submitt current licensed ca on this information, the 1993 Rules for Homes (Homes for portions of the 2009 of Adult Care Home the 1991 NC State | ensed on May 13, 1994, with ed on June 12, 1997, with the pacity of 88 residents. Based this facility is required to men- the Licensing of Domiciliary the Aged), the applicable 5 10A NCAC 13F - Licensing es of Seven or More Beds, ar Building Code(s) for a Group strained Occupancy. | i et nd | | | | |
| | Deficiencies were o required. | cited and a Plan of Correction | | | | | |
| {C 189} | Building Equipment | t Maintained Safe, Operating | {C 189} | | | | |
| | mechanical, and pl care home shall be operating condition (k) This Rule shall facilities with the ex | 11 OTHER nd all fire safety, electrical, umbing equipment in an adul maintained in a safe and | t | | | | |
| vision of He | there is a failure to emergency fire alar equipment in a safe occupants of the fa | et as evidenced by: vation and review of records maintain the facility's rm system devices and e operating condition. All the cility could be affected if the alert the occupants in case of | of | | | | |

| Division of Health Service Regulation STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL018016 | | (X2) MULTIPLE CONSTRUCTION | | | (X3) DATE SURVEY COMPLETED | | |
|---|---|---|-------------------------|--|-------------------------------|-----------|--|
| | | IDENTIFICATION NOMBER. | A. BUILDING: 01 | | | R | |
| | | B. WING | | | 10/22/2024 | | |
| NAME OF F | ROVIDER OR SUPPLIER | STREET AL | DRESS, CITY, | STATE, ZIP CODE | | | |
| BROOKE | ALE HICKORY NOR | THEAST | H STREET (, NC 28601 | | | | |
| (X4) ID PREFIX TAG | (EACH DEFICIENCY | TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY) | SHOULD BE COMPLETE | | |
| {C 189} | Continued From page 1 a fire. Findings on October 22, 2024: a. The Fire Alarm Control Panel is showing trouble with the tamper switch. | | {C 189} | Fire panel corrected by Summit Fire alarm system; Maintenance manager to perform monthly testing to ensure fire alarm system operating properly. | | 11/01/202 | |
| | 2. Based on observation and review of records the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. This could affect occupants of the facility if egress paths and exits were not illuminated during a power outage. Findings on October 22, 2024: a. 1st Hall-Living Room- Review of the most recent inspection and test report of the fire alarm system, the sealed lead acid battery did not pass the voltage test. | | | New battery to installed by M manager; To be reinspected fire inspection | | 01/03/202 | |
| | equipment was not operating condition Findings on Octobe a. Mechanical/Main the area had the rate | | | Maintenance manager removitems that were holding vents Corrected and completed | | 11/01/202 | |
| | | | | | | | |

BNVD22