STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLI		egulation (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X3) DATE SURVEY COMPLETED	
				A. BUILDING: <b>01</b>		R
		FCL017056	B. WING		02/05/2025	
NAME OF F	PROVIDER OR SUPPLIER		DRESS, CITY, ST			
ABUNDA	NT LIVING # 2	3816 CHI ELON, N	ERRY GROVE C 27244	ROAD		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES WINT BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLET DATE
{C 000}	Initial Comments		{C 000}			
	Report by David Hi	ckman				
	DHSR Construction Section conducted a Biennial Follow-up February 5, 2025 from 10:40 AM to 11:20 AM at the above referenced facility. At the time of the survey, not all deficiencies were corrected therefore further action is required. Additional deficiencies were also observed.					
	NOTES:					
	that require an acce deficiencies listed v staff during the exit previous deficiencie from an open bienn	ur visit, we cited deficiencies eptable plan of correction. All vere discussed with onsite interview. There were es that were not closed out ial survey, these deficiencies rd from previous survey.				
	once completed pro	correct all listed deficiencies, ovide verification in the form of voices, etc. for all work				
C 105	Initial Licensure-Me	eet NCSBC	C 105			
	requirements of the Code. All new cons renovations to exist requirements of the Code for One and T Residential Care Fa	North Carolina State Building struction, additions and ting buildings shall meet the North Carolina State Building Two Family Dwellings and acilities if applicable. All of The North Carolina State				
ision of He		ch is incorporated by				

MB1822

	of Health Service Re	egulation	-			
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>		(X3) DATE SURVEY COMPLETED	
		FCL017056	B. WING		02	R / <b>05/2025</b>
NAME OF F	PROVIDER OR SUPPLIER	STREET A	DRESS, CITY, ST	TATE, ZIP CODE		
ABUNDA	NT LIVING # 2	3816 CH ELON, N	ERRY GROVE C 27244	ROAD		
(X4) ID	SUMMARY STA	TEMENT OF DEFICIENCIES	ID	PROVIDER'S PLAN OF	CORRECTION	(X5)
PRÉFIX TAG		Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREFIX TAG	(EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	HE APPROPRIATE	COMPLETE
C 105	Continued From pa	ge 1	C 105			
	reference, including all subsequent amendments, may be purchased from the Department of Insurance Engineering Division located at 322 Chapanoke Road, Suite 200, Raleigh, North Carolina 27603 at a cost of three hundred eighty dollars (\$380.00). (b) Each home shall be planned, constructed, equipped and maintained to provide the services offered in the home.					
	was hearing impaire alarm when sounde the rule and code. T install strobes that a system. These stro areas, bathrooms, a	served: e survey, one of the residents ed and could not hear the ed. This is not compliant with Fake the necessary steps to are connected to the alarm bes need to be in the common and in the resident's bedroom.				
{C 117}	SECTION .0300 - T 10A NCAC 13G .03 CONSTRUCTION (n) The home sha fire and building saf shall be maintained review.	02 DESIGN AND Il have current sanitation and fety inspection reports which in the home and available for	{C 117}			
	the most recent Fire were not on site and not compliant with t	et as evidenced by: e survey it was observed that e Alarm inspection reports d available for review. This is he rule. Take the necessary e reports for review. Copies of				

MB1822

Division of Health Service Regulation           STATEMENT OF DEFICIENCIES           AND PLAN OF CORRECTION           IDENTIFICATION NUMBER:			CONSTRUCTION		(X3) DATE SURVEY COMPLETED	
				A. BUILDING: <b>01</b>		R
		FCL017056	B. WING			05/2025
NAME OF F	PROVIDER OR SUPPLIER		DDRESS, CITY, ST			
ABUNDA	NT LIVING # 2		ERRY GROVE C 27244	ROAD		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES ' MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE AC' CROSS-REFERENCED TO DEFICIENC	TION SHOULD BE THE APPROPRIATE	(X5) COMPLET DATE
{C 117}	Continued From pa	ge 2	{C 117}			
	review by both Lice sections.	be kept on-site for periodic nsure and DHSR construction ne survey, the reports were no				
{C 126}	Bedrooms-Sufficier	nt In Number	{C 126}			
	number and size to according to age ar administrator or sup live-in staff and any family care home. F bedrooms with staff (b) Only rooms au					
	residents were in ro during the original t necessary steps to rooms and or utilize (2 residents), #8 ( 2 Residents) * At the time of th	et as evidenced by: e survey, it was observed that ooms that were not approved ransmittal in 2014. Take the submit a project for additional e the approved bedrooms of # e residents), and #9(2 me survey, the rooms were still d been no project submitted.	7			
{C 174}	Building Equipment	Maintained Safe, Operating	{C 174}			
	EQUIPMENT	THE BUILDING 17 BUILDING SERVICE nd all fire safety, electrical,				

STATE FORM

MB1822

If continuation sheet 3 of 5

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE A. BUILDING: (		(X3) DATE SURVEY COMPLETED		
						R	
		FCL017056	B. WING			05/2025	
AME OF F	PROVIDER OR SUPPLIER	STREET AL	DRESS, CITY, S	TATE, ZIP CODE			
BUNDA	NT LIVING # 2	3816 CHI ELON, N	ERRY GROVE C 27244	ROAD			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO DEFICIENC	TION SHOULD BE	(X5) COMPLE <sup>-</sup> DATE	
{C 174}	Continued From pa	ige 3	{C 174}				
	care home shall be operating condition	apply to new and existing					
	in bedroom #12 the the knob. This is no the necessary step door.	et as evidenced by: e survey, it was observed that e door was damaged around ot compliant with the rule. Take s to repair and or replace the had not been corrected.					
	2.) At the time of th bedroom #12 blinds potentially affect the room. This is not connecessary steps to blinds.	e survey, it was observed that s were damaged. This could e residents privacy in the ompliant with the rule. Take the repair and or replace the had not been corrected.					
	bedroom #9 cove b and or missing. Thi rule. Take the nece repair the cove bas	e survey, it was observed that basing on the floor is damaged, s is not compliant with the ssary steps to replace and or ing as needed. had not been corrected.					
	the hot water heater top of the water heater being properly secu						

MB1822

AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b> B. WING		(X3) DATE SURVEY COMPLETED	
		FCL017056				R 02/05/2025
NAME OF	PROVIDER OR SUPPLIER		DDRESS, CITY, ST	ATE, ZIP CODE		
ABUNDA	ANT LIVING # 2	3816 CHI ELON, N	ERRY GROVE C 27244	ROAD		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE HE APPROPRIATE	(X5) COMPLET DATE
{C 180}	Continued From pa	ge 4	{C 180}			
{C 180}	Building Service Eq	uipment-Call System	{C 180}			
	EQUIPMENT (f) Where the bedr located in a separat bedrooms, an elect shall be provided co bedroom to the live- resident call system can be activated wit on until deactivated activator shall be with his bed.	17 BUILDING SERVICE room of the live-in staff is the area from residents' rically operated call system onnecting each resident -in staff bedroom. The a activator shall be such that it th a single action and remain by staff. The call system ithin reach of resident lying on apply to new and existing				
	staff is sleeping in the compliant with the re- to install an electrical shall be provided co- bedroom to the live- resident call system can be activated with on until deactivated activator shall be with on his bed. For any approved, the base power, must recogn stop providing a sig according to the inter * The call system be programmed so	e survey, it was observed that he facility. This is not ule. Take the necessary steps ally operated call system that onnecting each resident in staff bedroom. The a activator shall be such that it th a single action and remain by staff. The call system thin reach of the resident lying wireless system to be unit must use the house nize when any of the activators nal, and must function				

MBI822