Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: (X3) DATE SURVEY A. BUILDING: 01 COMPLETED R HAL034104 B. WING 03/05/2025 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE TRANQUILITY CARE 5100 LANSING DRIVE WINSTON SALEM, NC 27105 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PRÉFIX PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG COMPLETE TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) {C 000} Initial Comments {C 000} Report of a Construction Section Biennial Follow Up Survey by Suzanna Fay conducted on March 5, 2025. Deficiencies remain uncorrected and a Plan of Correction is required. {C 189} Building Equipment Maintained Safe, Operating {C 189} SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 7. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. The occupants in the smoke compartment could be affected if the fire-resistant rated doors do not completely close and latch to help limit the spread of smoke and/or fire to the area of origin. Findings March 5, 2025: a. Room 12- The vertical latching bar, in the cross-corridor fire doors, does not engage the strike plate at the header jamb. Staff revealed that they had been unable to find someone to repair the door but had someone coming out next week. Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM