PRINTED: 07/05/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT C	OF OFFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A. BUILD	LTIPLE CONSTRUCTION DING	(X3) DATE SUI COMPLET	ED i
		345284	B. WNG			C 1/2012
NAME OF PR	OVIDER OR SUPPLIER		:	STREET ADDRESS, CITY, STATE, ZIP C 901 BETHESDA RD WINSTON SALEM, NC 27103	CODE	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN ((EACH CORRECTIVE A CROSS-REFERENCED TO DEFICIE	CTION SHOULD BE O THE APPROPRIATE	(X5) COMPLETION DATE
F 164 SS=D	PRIVACY/CONFIDENTHE resident has the confidentiality of his or records. Personal privacy inclumedical treatment, we communications, personal of family and does not require the froom for each resident received as provided in section, the resident release of personal a individual outside the The resident's right to and clinical records dresident is transferred institution; or record in the form or storage marelease is required by healthcare institution: contract; or the resident by: Based on observation record reviews, the faprivacy for 2 of 3 resident #39 an included:	right to personal privacy and or her personal and clinical addes accommodations, ritten and telephone sonal care, visits, and diresident groups, but this facility to provide a private ont. In paragraph (e)(3) of this may approve or refuse the nid clinical records to any facility. In refuse release of personal does not apply when the dito another health care release is required by law. In confidential all information dent's records, regardless of nethods, except when y transfer to another glaw; third party payment ent. It is not met as evidenced ons, staff interviews and accility failed to provide dents during wound and #257). The findings	F 1	The statements made on this not an admission to and do a greement with the alleged of the agreement with the actions set forth in this Plan of Correction constitutes the compliance such that all alle have been or will be corrected indicated. 483.10 (e), 483.75(I)(4) Perse Privacy/Confidentiality of R F Tag # 164 This requirement will be mean the facility has taken corrected and the action of Residents affected by this prace. Observation of Residents affected by this prace of the action of the confidence with wears and the action of the action	th all Federal and State aken or will take the of Correction. The Plane facility's allegation of ged deficiencies cited ed by the date or dates on all ecords that as follows: tive action for the actice by: sident #39 & #257 on alled that privacy has been bound treatment and care. counseled and educated by 012. The on July 9, 2012 by SDC as provided by wound a provided by the same are sidents were interviewed 2 for any issues with turing treatment and care, if no concerns regarding	07-13-12
LABORATORY	DIRECTOR'S OR PROVIDER/	SUPPLIER REPRESENTATIVE'S SIGNATUR	E	TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPI A. BUILDING	LE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
		345284	8. WNG		C 06/21/2012
NAME OF PR	OVIDER OR SUPPLIER	343284	STR	EET ADDRESS, CITY, STATE, ZIP CODE	06/21/2012
THE OAKS			90	01 BETHESDA RO VINSTON SALEM, NC 27103	
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE COMPLETION
F 164	During an observation wound care nurse(W s room. Resident #3 blanket fully clothed. pulled all the way bat were open to the fact and staff were seate blanket down to the up to the shoulder at entire back to the view windows in resident wheelchair height. The nurse was quest practices for ensuring Nurse confirmed that have been pulled and blind should have be wound care. During an interview Director of Nursing, that the expectation resident 's door, primary care was provided by proper procedures for type of care in accordance. 2. During an observation would be proper procedures for type of care in accordance. The privacy curtain staff Development (Continue) and care nurse erroom. Resident# 25 The privacy curtain staff Drivacy curtain s	on on 6/20/12 at 12:41PM, the /CN) entered Resident #39 '9 was lying in bed under a The privacy curtain was ck to the wall and the blinds illity patio where 3 residents d. The nurse pulled the resident 's brief and the shirt rea exposing the resident 's ew of the window. The room were at seated Itioned about the facility g privacy during wound care, at the privacy curtain should be concluded before doing the enclosed	F 164	The following measures/systemic change in place to ensure that the deficient practoccur: All nursing staff to include C N nurses were in-serviced by SDC 2012 regarding providing priva administering personal care and Any in-house staff who did not service training will not be allow until training is completed. This information has been integ standard orientation training and required in-service refresher colemployees and will be reviewed Quality Assurance Process to whomation will be reviewed Quality Assurance Process to whomation are achieved and sustained facility will evaluate the plan's effective. Using the QA Survey Auditing will be monitored by observing treatments on 2 residents daily through Friday for two weeks the for two months by SDC, Nurse designee. Any immediate concerns will be the DON or Administrator for action. Compliance will be monitored auditing program reviewed at the Quality of Life Meeting. The Comembers will include at a minimal Administrator, DON, SDC, Sum MDS nurses, Social Services, I other clinical team members as	As and staff C by July 13, bey while it reatments. receive in- wed to work grated into the d in the urses for all d by the erify that the e to ensure d. The ness by: Tool, privacy care and Monday hen weekly Manager, or be brought to appropriate and ongoing he Weekly Committee imum: pport Nurse, Dietary and

	F DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A, BUI		PLE CONSTRUCTION	COMPLETE	D
		345284	B. WIN	G		06/21	/2012
NAME OF PRO	OVIDER OR SUPPLIER		• • • • • • • • • • • • • • • • • • • •	9	REET ADDRESS, CITY, STATE, ZIP CODE 101 BETHESDA RD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	ILD BE	(X5) COMPLETION DATE
F 164	resident window. The care to resident 's he room were at seated. The nurse was quest practices for ensurin Nurse confirmed that have been pulled are blind should have be wound care. During an interview Director of Nursing, that the expectation resident 's door, privany care was provided During an interview Staff Development (expectation would be proper procedures for type of care in accordant and the staff of type of care in accordant and the staff of type of care in accordant authorities; and (2) Store, prepare, of under sanitary conditions.	atio area in view of the enurse was providing wound eel. The windows in resident wheelchair height. Itioned about the facility g privacy during wound care. It the privacy curtain should bund the resident and the een closed before doing the con 6/21/12 at 9:10AM, the Administrator both indicated was that staff closed the vacy curtain and blinds before ed to ensure privacy. on 6/21/12 at 12:23PM, the Coordinator indicated the e that all staff followed the or ensuring privacy during any redance with facility policy. OCURE, SERVE - SANITARY		164	483.35 (i) Food Procedure, Store/Prepa Sanitary F Tag # 371 This requirement will be met as follows	for the fied in the late or damaged Other items roperly in identifying y date". bottoms were ge rack for for those ed by the same	07-13-12

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MU A. BUILI	ILTIPLE CONSTRUCTION DING	(X3) DATE SUF COMPLET	
		345284	B. WING	3	1	1/2012
NAME OF PR	OVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZI 901 BETHESDA RD WINSTON SALEM, NC 2710)3	
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EACH CORRECTIV CROSS-REFERENCE	IN OF CORRECTION E ACTION SHOULD BE D TO THE APPROPRIATE CIENCY)	(X5) COMPLETION DATE
F 371	record review, the far dented cans from the 2) failed to ensure for walk-in refrigerator vof the original contain the expiration date, a lids/insulated bottom cart and clean racks. Findings include: During the initial tou area on 6/18/12 at 1 canned foods were dents at their rims a mandarins oranges, can of three-bean se stocked among and undamaged canned use. During the kitchen to the following items walk-in refrigerator: frozen dinner rolls, deli-roll ham dated container of mustare large container of Tidated use by 6/4/12 director of food servexpired. During an interview manager indicated to	ons, staff interviews, and cility failed to 1) remove 3 e kitchen's dry-storage area, and items in the one of one were labeled when taken out mer and were discarded past and 3) failed to air-dry dome as and stock them on a clean . Tof the kitchen's dry-storage 1:01 a.m., the following damaged with significant and/or seals: 1 can of 1 can of pasta sauce, and 1 calad. They were observed	F	in place to ensure that the occur: All cans will be receipt and furth audit process. To monitor for come. Ravioli, frozen cham, mustard, so products will be contents. All foods will be contents. All foods will be before expiration. Insulated dome will be allowed inspected for fo Storage racks for daily. Long term plans storage racks. An audit procese ensure complian and approved by Dietitian/CDM CDM beginning Service staff in Kitchen Superv Aids. This information standard orients included in the conducted by the Manager or deservices.	linner rolls, hot dogs, deli- alad dressing and like labeled with identification of e used or disposed on or n date. lids and insulated bottoms to air dry and will be od debris prior to stacking. or these items will be cleaned s include purchasing new s will be implemented to noe. An in-service developed y the Registered will be presented by the g July 9-13, 2012 for all Food cluding the Kitchen Manager, isors, Cooks and Dietary on has been integrated into the ation training and will be Kitchen survey that is ne Regional Food Service signee. If who did not receive in- g will not be allowed to work	

DEPARTMENT OF HEALTH AND HUMAN SERVICES

FORM APPROVED OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING С B. WNG 06/21/2012 345284 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 901 BETHESDA RD THE OAKS WINSTON SALEM, NC 27103 (X5) COMPLETION DATE PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (EACH CORRECTIVE ACTION SHOULD BE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX CROSS-REFERENCED TO THE APPROPRIATE **PREFIX** REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) The facility will monitor its performance to ensure F 371 Continued From page 4 F 371 that solutions are achieved and sustained. The and dated as to when they are opened and when facility will evaluate the plan's effectiveness by: This requirement will be met as follows: they should be used by before they are returned Using the QA Survey Auditing Tool, to the refrigerator/freezer. compliance will be monitored by inspection for dented cans, proper labeling, dating, and During kitchen observation on 6/18/12 at 11:10 expiration of items, and that lids/insulated a.m., 31 domed lids and 45 insulated bottoms bottoms are dry/free of food debris. Audits will be conducted four times weekly for two were observed stacked on top of each other, wet weeks then weekly for two months by or with food debris. Dietary Manager or designee. Any immediate concerns will be brought to During tray line observation on 6/20/12, at 11:08 the Dietary Manager, DON or Administrator for appropriate action. a.m., 20 domed lids were observed wet or with Compliance will be monitored and ongoing food particles on them, and 22 domed lids were auditing program reviewed at the Weekly observed on the drying rack with food particles Quality of Life Meeting. The Committee (the lids were identified by the dietay manager as members will include at a minimum: clean and ready to be used. The rack the domed Administrator, DON, SDC, Support Nurse, MDS nurses, Social Services, Dietary and lids were on and the cart had dried-up black and other clinical team members as needed. yellow matter on them. During an interview on 6/20/12 at 11:12 a.m. with the dietary manger, she indicated that the expectation is that the dietary aides who stack the dishes should check all the dishes for left-over food debris before stacking items on drying racks or in the drying area. The person assigned to check the stock or has retrieved food should label and date the foods before returning them to the refrigerator or freezer. Staff (7 staff members on duty between breakfast and lunch) have been informed and in-serviced on the expectations of the kitchen. During an interview on 6/21/12 on 9:10 a.m., the administrator indicated that the expectation was that the dietary manager ensures that all sanitary conditions in the kitchen are maintained, that foods are labeled and dated, that dishes was

cleaned and dried without food and debris, and that any broken dishes should be discarded.

PRINTED: 07/05/2012

, , , , , , , , , , , , , , , , , , , ,	A. BUILDING		!
345284		C	1
	B. WNG	06/21	1
NAME OF PROVIDER OR SUPPLIER THE OAKS	901 E	FADDRESS, CITY, STATE, ZIP CODE BETHESDA RD STON SALEM, NC 27103	
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL	ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE	(X5) COMPLETION DATE
PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION)	TAG	DEFICIENCY)	
F 441 SS=D The facility must establish and maintain an Infection Control Program designed to provide a safe, sanitary and comfortable environment and to help prevent the development and transmission of disease and infection. (a) Infection Control Program The facility must establish an Infection Control Program under which it - (1) Investigates, controls, and prevents infections in the facility; (2) Decides what procedures, such as isolation, should be applied to an individual resident; and (3) Maintains a record of incidents and corrective actions related to infections. (b) Preventing Spread of Infection (1) When the Infection Control Program determines that a resident needs isolation to prevent the spread of infection, the facility must isolate the resident. (2) The facility must prohibit employees with a communicable disease or infected skin lesions from direct contact will transmit the disease. (3) The facility must require staff to wash their hands after each direct resident contact for which hand washing is indicated by accepted professional practice. (c) Linens Personnel must handle, store, process and transport linens so as to prevent the spread of infection.	F 441	483.65 Infection Control, Prevent Spread, Linens F Tag # 441 This requirement will be met as follows: The facility has taken corrective action for the residents affected by this practice by: Resident #39 has had no ill effect and all wounds are documented without signs and symptoms of infection. Resident #257 is no longer a resident in the facility. Wound Care Nurse was counseled and educated by DON on wound care procedure and infection control on July 13, 2012. Observations of wound care on July 9, 2012 by SDC for technique to ensure compliance with all infection control practices during treatments. The facility will take corrective action for those residents having the potential to affected by the sams deficient practice: All residents have the potential to be affected by this alleged practice. Residents with wounds were assessed on July 13, 2012 by the Nurse Practioner with Physicians Eldercare and have no signs or symptoms of infection.	

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDI		(X3) DATE SUR COMPLETE	D /
		345284	B. WNG		06/21	1/2012
NAME OF PE	ROVIDER OR SUPPLIER		S	TREET ADDRESS, CITY, STATE, ZIP CODE 901 BETHESDA RD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	/EACH DEFICIE	STATEMENT OF DEFICIENCIES NCY MUST BE PRECEDED BY FULL PR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
F 441	by: Based on observareview, the facility wash hands before facility failed to cleequipment before provided for 2 of 3 wound care (Residual The findings included for Dressing Procepart: section: Genecontrol included # precautions or other as approved approhands before and gloves when approvall equipment used storage area. Hand 3/1/04, read in parperforming dressin any kind, after handling items por resident 's blood, Section noted gloves use of gloves doe 1. During an obset the wound care no cart to the side of	NT is not met as evidenced tion, staff interview and record failed to the facility failed to an after wound care, the an environmental surfaces and and after wound care was sampled residents receiving ent #39 and #257).	F 44	The following measures/systemic clin place to ensure that the deficient occur: An in-service was provide wound care C N A II on dechnique, and infection concluded use of gloves, has preparation of a clean surfinaterial and equipment, president so wound surface contaminated surfaces dure procedure. In-services we SDC and completed by Ju. Any in-house nursing staff C N A IIs who did not rectraining will not be allowed training is completed. This information has been standard orientation training required in-service refresh employees and will be revered Quality Assurance Processichange has been sustained. SDC will conduct and conskills Check List to include care demonstration on orientation and annually. C N A II who pwill also have to demonstration and annually. concerns with infection convil be reported to the DO action and follow up.	d for all nurses and ressing change ontrol. Training and washing, ace for dressing ositioning of the remain free from ing treatment are conducted by ly 13, 2012. If or wound care eive in-service do to work until the ing and in the lier courses for all iewed by the sto verify that the insplete a Nurses le wound and skin entation and rovide wound care rate competency on Any identified ontrol technique	

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIP	PLE CONSTRUCTION	(X3) DATE SUR COMPLETE	
			B. WNG		(·
		345284	B. WING		06/2 ⁻	1/2012
THE OAK	SUMMARY ST	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL	9	PROVIDER'S PLAN OF CORRECTION SHOULD BE STATE AND CORRECTION SHEET AND C		(X5) COMPLETION
PREFIX TAG		SC IDENTIFYING INFORMATION)	TAG	CROSS-REFERENCED TO THE APP DEFICIENCY)		DATE
F 441	nurse wash her hand #39 room. Nurse rem treatment supplies fro supplies on the tray to the surface area before the tray table. Nurse which had several off pair of black gloves. I from the resident 's to with the anti-septic syscissors from her pod applied the hydrocolliput the scissors back broke during the treat gel was on the nurse broke. The dressing while the nurse replat Nurse did not use an hands before or after Nurse exited Resider cart to treatment room and did not wash had to room without wash buring an observation wound care nurse erroom. Resident# 257 Nurse pulled treatmes #257 room. Nurse dilocated at the side of her hands before init #257. The nurse retifor the treatment and tray table. Nurse reaput on a clean set of dressing from the resident from the tray table.	is the nursing cart, nor did the as before entering Resident oved Resident #39 om the cart and placed the able. Nurse #1 did not clean are placing the supplies on reached into her pocket are items and pulled out a Nurse removed the bandage back, the area was sprayed oray, removed a pair of exet to cut the dressing, and in her pocket. The gloves at the transport of the transport of the transport of the broken gloves was placed on the tray table ced the broken gloves. It is a proceeded to next resident and the 1st man proceeded to next resident and Nurse went from room	F 441	The facility will monitor its performany that solutions are achieved and sustain facility will evaluate the plan's effective. Using the QA Survey Auditive care will be monitored by obe treatments on 2 residents dail through Friday for two weeks for two months by SDC or Not designee. Any immediate concerns will the DON or Administrator for action. Compliance will be monitore auditing program reviewed at Quality of Life Meeting. The members will include at a min Administrator, DON, SDC, SMDS nurses, Social Services other clinical team members.	red. The reness by: In Tool, wound rerving care and y Monday In then weekly are Manager or The be brought to a papropriate In and ongoing the Weekly Committee formum: In a proport Nurse, In Dietary and	

	OF DEFICIENCIES FCORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING	E CONSTRUCTION	(X3) DATE SU COMPLE	
		345284	B. WING	-	06/	C 21/2012
NAME OF PE	ROVIDER OR SUPPLIER		90	EET ADDRESS, CITY, STATE, ZIP CODE 1 BETHESDA RD INSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	(EACH DEFICIE	STATEMENT OF DEFICIENCIES NCY MUST BE PRECEDED BY FULL PR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE API DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
F 441	stough in the center the foot pedal that on it. She obtain so she did not clean, a marker. She cut the scissors obtained if dated. Nurse# place pocket without clear the wound heel on the She added that she treatment with the was up in the wheel the treatment in the She did not clean the before putting the retrieved the scisse her pocket and did and after the care. unaware of the new scissors before tree. During an interview Director of Nursing the expectation wotheir hands and/or hand sanitizer in be changes. DON indishould have been supplies was put of should clean the swhen treating an of Administrator furth follow the infection.	th white edges and some or, and placed the heel back on had dripping antiseptic spray cissors from her pocket that a flash light and sharpie e santyl gauze with the rom the pocket in 6 slits and ced the scissors back into her aning them. That she placed the opened foot pedal of the wheelchair. The would normally perform the resident in the bed, but she telchair so went ahead and did the position the resident was in, the surface of the tray table treatment supplies on it and tors, marker and pen light from the clean the scissors before She indicated she was the dot clean the surfaces or the atment was provided. The one of 21/12 at 9:10AM, the the and Administrator indicated build be that staff should wash the the etween glove and dressing icated that the resident area cleaned before treatment on the surface. The nurse cissors before and after use the pen wound. DON and the staff should the control protocol for hand the of surfaces and equipment	F 441			

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI	TIPLE CONSTRUCTION	(X3) DATE S COMPLE	URVEY ETED
		345284	B. WING_		06/	C 21/2012
NAME OF PR	ROVIDER OR SUPPLIER		s	TREET ADDRESS, CITY, STATE, ZIP COI 901 BETHESDA RD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE THE APPROPRIATE	(X5) COMPLETION DATE
F 441	During an interview o Staff Development Co the expectation would	n 6/21/12 at 12:23PM, the coordinator(SDC) indicated if be that all staff follow the res for hand washing and	F 44	1		

ARAM	ENT OF HEALTH	AND HUMAN SERVICES		OMB NO. 0	/
FERS	FOR MEDICARE F DEFICIENCIES CORRECTION	& MEDICAID SERVICES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A BUILDING	CONSTRUCTION (X9) DATE SUN 01 - MAIN BUILDING 01 2012 07/12	ED ,
		345284	B. WING		
	OVIDER OR SUPPLIER	<u> </u>	STREE	TADDRESONITA STATE OUT SODE IN	
			WIN	ISTON SALEM, NC 27103	(X5)
E OAKS		- resourticies	10	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE (EACH CORRECTIVE ACTION SHOULD BE	COMPLETION
(4) ID REFIX TAG	SUMMARY ST (EACH DEFICIENC REGULATORY OR	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	PREFIX TAG	(EACH CORRECTIVE ACTION SHOULD REPROPRIATE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	
	INITIAL COMMEN	•	K 000	NFPA 101 Life Safety Code Standard Tag # K 012 This requirement will be met as follows: The facility has taken corrective action for	8-24-12
K 012 \$\$=D	conducted as per at 42CFR 483.70 Care section of the publications. This construction, one automatic sprink The deficiencies are as follows: NFPA 101 LIFE	The Code of Federal Register (a); using the Existing Health ne LSC and its referenced s building is Type III(211) e story, with a complete	K 012	The following was repaired to the smoke resisting roof/ceiling: Sealed the pipe penetrations in phone equipment room ceiling Holes fixed in ceiling of mechanical room beside room 300 Holes fixed in ceiling of toilet beside 200 hall clerical station Holes fixed in ceiling of toilet near front entrance main nurses' station The facility will identify other life safety issues having the potential to affect residents by the same deficient practice: Assess all areas for holes or penetrations to the smoke resisting roof/ceiling Repair areas as needed The following measures/systemic changes will be put in place to ensure that the deficient	
	Surveyor: 0224 Based on obse approximately resisting roof/o facility due to t 1. unsealed pl equipment roo 2. holes in cel room 300.	9:00am onward, the smoke seiling is non compliant in the he following: pe penetrations in phone om ceiling. ling of mechanical room beside		Assess all areas for holes or penetrations to the smoke resisting roof/ceiling Repair areas as needed The facility will monitor its performance to ensure that solutions are achieved and sustained. The facility will evaluate the plan's effectiveness by: Maintenance Director will monitor for compliance monthly for the smoke resisting roof/ceiling to meet standard during preventative maintenance rounds. Corrective action taken if not compliant. Report will be made to the Quality Assurance Committee on a monthly basis	
-	station.	lling of tollet beside 200 hall cleric	cal	Assurance Committee on a monary for next 2 months	
	4. holes in ce	PROVIDER/SUPPLIER REPRESENTATIVE		TITLE	(X8) DAT クチーン-5

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days of the safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the above findings and plans of correction are disclosable 14 following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: 923497

PRINTED: 07/15/2012 FORM APPROVED OMB NO. 0938-0391

07/12/2012

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

345284

(X2) MULTIPLE CONSTRUCTION

A. BUILDING

B. WING __

01 - MAIN BUILDING 01

(X3) DATE SURVEY COMPLETED

NAME OF PROVIDER OR SUPPLIER

THE OAKS

STREET ADDRESS, CITY, STATE, ZIP CODE 901 BETHESDA RD WINSTON SALEM, NC 27103

THE OAK	(Signature)	j	WINSTON SALEM, NC 27103
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (X5) COMPLETION DATE
K 012 K 015 SS=D	main nurse's station. 42 CFR 483.70(a)	K 0	NFPA 101 Life Safety Code Standard Tag # K 015 This requirement will be met as follows: The facility has taken corrective action for the residents affected by this practice by: The following was repaired:
K 05 SS=	This STANDARD is not met as evidenced by: Surveyor: 02249 Based on observation, on July 12, 2012 at approximately 9:00am onward, there is flaking paint on the ceiling in the medication preparation room at station #3. 42 CFR 483.70(a) NFPA 101 LIFE SAFETY CODE STANDARD		The following measures/systemic changes will be put in place to ensure that the deficient practice does not recur: All medication preparation rooms assessed for flaking paint and painted if needed. Other areas within facility assessed for flaking pain and painted if needed. The facility will monitor its performance to ensure that solutions are achieved and sustained. The facility will evaluate the plan's effectiveness by: Maintenance Director will monitor for compliance by assessing areas monthly for compliance during preventative maintenance rounds. Corrective action taken if not compliant. Report will be made to the Quality Assurance Committee on a monthly basis for next 2 months.

PRINTED: 07/15/2012 FORM APPROVED DEPARTMENT OF HEALTH AND HUMAN SERVICES OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA COMPLETED STATEMENT OF DEFICIENCIES DENTIFICATION NUMBER: 01 - MAIN BUILDING 01 A. BUILDING AND PLAN OF CORRECTION 07/12/2012 345284 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 901 BETHESDA RD WINSTON SALEM, NC 27103 THE OAKS PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (X5) COMPLETION (D) SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL DATE (X4) ID PREFIX PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION) DEFICIENCY) TAG K 051 Continued From page 2 K 051 NFPA 101 Life Safety Code Standard nurse's stations. Pull stations are located in the Tag # K 051 path of egress. Electronic or written records of This requirement will be met as follows: tests are available. A reliable second source of The facility has taken corrective action for the residents affected by this practice by: power is provided. Fire alarm systems are maintained in accordance with NFPA 72 and The audible trouble signal repaired records of maintenance are kept readily available. to sound. There is remote annunciation of the fire alarm The facility will identify other life safety system to an approved central station. issues having the potential to affect residents 9.6 by the same deficient practice: Alarm will sound. The following measures/systemic changes will be put in place to ensure that the deficient practice does not recur: Facility will continue required inspections related to the fire panel. The facility will monitor its performance to ensure that solutions are achieved and ŧ

This STANDARD is not met as evidenced by: Surveyor: 02249
Based on observation, on July 12, 2012 at approximately 9:00am onward, the audible trouble signal did not resound with the main power breaker off to the fire alarm control panel after acknowledgement of signal by utilizing the trouble silence switch and then activating the control panel reset switch with the breaker remaining in the off position.

42 CFR 483.70(a) NFPA 101 LIFE SAFETY CODE STANDARD

Required automatic sprinkler systems have valves supervised so that at least a local alarm will sound when the valves are closed. NFPA 72, 9.7.2.1

-

K 061

NFPA 101 Life Safety Code Standard
Tag # K 061
This requirement will be met as follows:
The facility has taken corrective action for the residents affected by this practice by:

basis for next 2 months.

sustained. The facility will evaluate the

Maintenance Director will monitor for compliance by assessing audible

monthly preventative maintenance

Report will be made to the Quality Assurance Committee on a monthly

trouble signal standard during

Corrective action taken if not

plan's effectiveness by:

rounds.

compliant.

 Audible tamper switch signal has a local alarm that sounds when valves are closed on the dry-pipe sprinkler riser located on 400 hall. 8-2412

K 061

SS=D

DEPARTMENT OF HEALTH AND HUMAN SERVICES

PRINTED: 07/15/2012 FORM APPROVED OMB NO. 0938-0391

CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: STATEMENT OF DEFICIENCIES COMPLETED AND PLAN OF CORRECTION 01 - MAIN BUILDING 01 A. BUILDING B. WING 07/12/2012 345284 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 901 BETHESDA RD THE OAKS WINSTON SALEM, NC 27103 PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (X5) COMPLETION SUMMARY STATEMENT OF DEFICIENCIES ID (X4) ID PREFIX PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) The facility will identify other life safety issues K 061 K 061 | Continued From page 3 having the potential to affect residents by the same deficient practice: A local alarm will sound when valves are closed. This STANDARD is not met as evidenced by: The following measures/systemic changes will he put in place to ensure that the deficient Surveyor: 02249 practice does not recur: Based on observation, on July 12, 2012 at approximately 9:00am onward, the audible Facility will continue required tamper switch signal can be permanently silenced inspections related to the fire panel. with the valve in the closed position - main valve The facility will monitor its performance to ensure that solutions are achieved and for dry-pipe sprinkler riser located on 400 hall. sustained. The facility will evaluate the plan's effectiveness by: 42 CFR 483.70(a) Maintenance Director will monitor for K 062 NFPA 101 LIFE SAFETY CODE STANDARD K 062 compliance by assessing local alarm sound standard during preventative SS≖D maintenance rounds. Required automatic sprinkler systems are Corrective action taken if not continuously maintained in reliable operating compliant. condition and are inspected and tested Report will be made to the Quality periodically. 19.7.6, 4.6.12, NFPA 13, NFPA Assurance Committee on a monthly basis for next 2 months. 25, 9.7.5 NFPA 101 Life Safety Code Standard Tag# K 62 This requirement will be met as follows: The facility has taken corrective action for the This STANDARD is not met as evidenced by: residents affected by this practice by: Surveyor: 02249 Paint removed from the heat sensitive Based on observation, on July 12, 2012 at element of the sprinkler head or replaced in janitor's closet beside approximately 9:00am onward, the sprinkler room 309 and in the kitchen dishwash system is not maintain in accordance with NFPA 25 due to the following: Items revealed on inspection report dated 04/10/12 will be resolved. The facility will Identify other life safety issues 1. there is paint on the heat sensitive element of having the potential to affect residents by the sprinkler in the janitor's closet beside room 309. same deficient practice: All the heat sensitive element of the 2. there is paint on the heat sensitive element of sprinkler heads throughout the facility sprinkler in the kitchen dishwash area. assessed for compliance.

3, the sprinkler inspection report dated 4/10/2012

deficiencies with no documents to demonstrate

by Simplex-Grinnell revealed the following

Post indicator valve and valve below ground pit has audible signal when

Water motor gong function tests by

valves are closed.

sprinkler company.

PRINTED: 07/15/2012 FORM APPROVED OMB NO. 0938-0391

(X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 B. WING 07/12/2012 345284 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 901 BETHESDA RD THE OAKS WINSTON SALEM, NC 27103 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES ID (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE COMPLÉTION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX DATE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) The following measures/systemic changes will K 062 K 062 | Continued From page 4 be put in place to ensure that the deficient practice does not recur: corrective action: All the heat sensitive element of the sprinkler heads throughout the facility a. Post indicator valve did not sound an audible assessed for compliance. signal with the valve closed. Post indicator valve and valve below ground pit has audible signal when valves are closed. b. valves in below ground pit did not sound an Water motor gong function tests by audible alarm with the valves closed. sprinkler company. c. water motor gong did not function test by The facility will monitor its performance to ensure that solutions are achieved and sprinkler company. sustained. The facility will evaluate the plan's effectiveness by: 42 CFR 483.70(a) K 072 Maintenance Director will monitor for K 072 NFPA 101 LIFE SAFETY CODE STANDARD compliance monthly by assessing that SS=D sprinkler heads meet standard during Means of egress are continuously maintained free preventative maintenance rounds. of all obstructions or impediments to full instant Maintenance Director will assure that use in the case of fire or other emergency. No facility has documentation to furnishings, decorations, or other objects obstruct demonstrate follow-up of inspection exits, access to, egress from, or visibility of exits. reports. Corrective action taken if not 7.1.10 compliant. Report will be made to the Quality Assurance Committee on a monthly basis for next 2 months. NFPA 101 Life Safety Code Standard 8-24-12 This STANDARD is not met as evidenced by: Tag # K 072 This requirement will be met as follows: Surveyor: 02249 The facility has taken corrective action for the Based on observation, on July 12, 2012 at residents affected by this practice by: approximately 9:00am onward, the means of Furnishings and other objects removed from egress is obstructed by furnishings and other egress in corridor of restorative care sunroom and corridor of Business Office Manager. objects in the following areas: The facility will identify other life safety issues having the potential to affect residents by the same 1. corridor in front of restorative care sunroom. deficient practice: All means of egress assessed for obstruction and corridor area near business manager office objects removed as needed. The following measures/systemic changes will be 400 hall area. put in place to ensure that the deficient practice

K 076

42 CFR 483.70(a)

NFPA 101 LIFE SAFETY CODE STANDARD

K 076

does not recur:

All means of egress assessed for obstruction and

objects removed as needed.

PRINTED: 07/15/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

(X3) DATE SURVEY

A. BUILDING 01 - MAIN BUILDING 01 COMPLETED

345284

8. WING

07/12/2012

NAME OF P	ROVIDER OR SUPPLIER	\	STREET ADDRESS, CITY, STATE, ZIP CODE 901 BETHESDA RD
THE OAK	(8	444754	WINSTON SALEM, NC 27103
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (X5) COMPLETION DATE
SS=D	Continued From page 5 Medical gas storage and administration areas at protected in accordance with NFPA 99, Standards for Health Care Facilities. (a) Oxygen storage locations of greater than 3,000 cu.ft. are enclosed by a one-hour separation. (b) Locations for supply systems of greater than 3,000 cu.ft. are vented to the outside. NFPA 9 4.3.1.1.2, 19.3.2.4 This STANDARD is not met as evidenced by: Surveyor: 02249 Based on observation, on July 12, 2012 at approximately 9:00am onward, there is an unsupported oxygen cylinder on the countertop; in the medication preparation room near room 507. 42 CFR 483.70(a) NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordanc with NFPA 70, National Electrical Code. 9.1.2 This STANDARD is not met as evidenced by: Surveyor: 02249 Based on observation, on July 12, 2012 at approximately 9:00am onward, electrical wiring and equipment is not in accordance with NFPA	9 K1	facility will evaluate the plan's effectiveness by: Maintenance Director will monitor for compliance by assessing obstruction of egress during preventative maintenance rounds. Corrective action taken if not compliant. Report will be made to the Quality Assurance Committee on a monthly basis for next 2 months. NFPA 101 Life Safety Code Standard Tag # K 076 This requirement will be met as follows: The facility has taken corrective action for the residents affected by this practice by: Unsupported oxygen cylinder secured in the medication preparation room near room 507. The facility will identify other life safety issues having the potential to affect residents by the same deficient practice: All oxygen cylinders assessed for proper storage. The following measures/systemic changes will be put in place to ensure that the deficient practice does not recur: All oxygen cylinders assessed for proper storage. The facility will monitor its performance to

PRINTED: 07/15/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01

(X3) DATE SURVEY COMPLETED

345284

B. WING

1 - MAIN DOLLDING 01

07/12/2012

NAME OF PROVIDER OR SUPPLIER

THE OAKS

STREET ADDRESS, CITY, STATE, ZIP CODE 901 BETHESDA RD

WINSTON SALEM, NC 27103

THE OAKS		}	WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 147	Continued From page 6 70 due to the following: 1. liquid-tight flexible conduit is disconnected from fitting on food disposal in dishwash area of kitchen. 2. no thirty minute load test documented for emergency generator from January through June 2012. 3. broken ground fault interrupter receptacle in central bath near room 200. 4. emergency power system required greater than ten seconds to restore power during loss of normal power to the automatic transfer switch of the essential electrical system. Approximately sixteen seconds elapsed prior to restoral of power. 5. generator power light did not function on the annunciator panel located behind the main nurse's station - during loss of normal power to the automatic transfer switch of the essential electrical system. 6. exposed incandescent light fixture above shelf in storage room - across hall from central bath on 400 hall. 42 CFR 483.70(a)	K 14	NFPA 101 Life Safety Code Standard Tag # K 147 This requirement will be met as follows: The facility has taken corrective action for the residents affected by this practice by: Liquid-tight flexible conduit reconnected on fitting of food disposal in dishwasher area of kitchen Thirty minute load test documented July 30, 2012. Broken ground faulty interrupter receptacle in central bath near room 200 repaired. Emergency power system restores power within 10 seconds or less. Generator power light now functions on annunciator panel behind main nurse's station. Incandescent light fixture fixed above shelf in storage room across hall from central bath on 400 hall. The facility will identify other life safety Issues having the potential to affect residents by the same deficient practice: All electrical fittings/wiring assessed. Thirty minute load tests conducted monthly. All ground fault receptacles assessed for broken areas. Emergency power system checked monthly to assure power is restored to facility within 10 seconds or less. Generator power light checked for continued appropriate functioning. All incandescent light fixtures assessed for exposure.	8-24-12	
L			Forting accused the continuation of	ant Page 7 of 7	

PRINTED: 07/15/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01

(X3) DATE SURVEY COMPLETED

345284

B. WING

07/12/2012

NAME OF PROVIDER OR SUPPLIER

THE OAKS

STREET ADDRESS, CITY, STATE, ZIP CODE 901 BETHESDA RD WINSTON SALEM, NC 27103

TITE ATMIN			4411	WINSTON SALEM, NO 27 103		
PROFESY FACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL BC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
fitting on food disposition. 2. no thirty minute l	-	Κ1	147	The following measures/systemic changes will be put in place to ensure that the deficient practice does not recur: All electrical fittings/wiring assessed. Thirty minute load tests conducted monthly. All ground fault receptacles assessed for broken areas. Emergency power system checked monthly to assure power is restored to facility within 10 seconds or less. Generator power light checked for continued appropriate functioning. All incandescent light fixtures assessed for exposure. The facility will monitor its performance to ensure that solutions are achieved and sustained. The facility will evaluate the plan's effectiveness by: Maintenance Director will monitor for compliance of electrical fittings, appropriate load test documentation, ground fault receptacles, appropriate timing of emergency power restoration, functioning of generator power light, and light fixtures. Corrective action taken if not compliant. Report will be made to the Quality Assurance Committee on a monthly basis for next 2 months.		
4. emergency power than ten seconds to normal power to the the essential electrosixteen seconds eleptower.	ault interrupter receptacle in com 200. er system required greater or restore power during loss of e automatic transfer switch of ical system. Approximately apsed prior to restoral of					
annunciator panel nurse's station - du the automatic trans electrical system. 6. exposed incande	located behind the main ring loss of normal power to sfer switch of the essential escent light fixture above shelf across hall from central bath on					
42 CFR 483.70(a)		Name of the Control o				