STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL051-173			(X2) MULTIPLE C		(X3) DATE SURVEY COMPLETED	
			A. BUILDING:			
		MHL051-173	B. WING		R 05/17/2018	
NAME OF PF	ROVIDER OR SUPPLIER	STREET	ADDRESS, CITY, STATE	, ZIP CODE		
SAVIN GR	ACE II		DAM ROAD NC 27576			
						(X5)
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EACH CORRECTIVE ACTIC CROSS-REFERENCED TO TH DEFICIENCY	D TO THE APPROPRIATE	
V 000	INITIAL COMMENTS		V 000			
	An annual and follow-up survey was completed on May 17, 2018. There were deficiencies cited.					
	This facility is licensed for the following service category: 10A NCAC 27G. 1700 Residential Treatment Staff Secure for Children					
	or Adolescents					
V 108	27G .0202 (F-I) Pers	onnel Requirements	V 108			
	<ul><li>10A NCAC 27G .0202 PERSONNEL</li><li>REQUIREMENTS</li><li>(f) Continuing education shall be documented.</li><li>(g) Employee training programs shall be</li></ul>					
	provided and, at a m following: (1) general organiza	inimum, shall consist of the				
	<ul> <li>(2) training on client rights and confidentiality as delineated in 10A NCAC 27C, 27D, 27E, 27F and 10A NCAC 26B;</li> </ul>					
	· · ·	the mh/dd/sa needs of the the treatment/habilitation				
	<ul><li>(4) training in infecti bloodborne pathoger</li><li>(b) Except as permitt</li></ul>					
	.5602(b) of this Subc	hapter, at least one staff ilable in the facility at all				
	member shall be train including seizure ma	-				
	trained in the Heimlic	ch maneuver or other first aid hose provided by Red Cross,				
	equivalence for reliev (i) The governing bo	ving airway obstruction.				
		ng and controlling infectious				

R8UG11

## PRINTED: 05/21/2018 FORM APPROVED

Division of Health Service Regulation TATEMENT OF DEFICIENCIES ND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL051-173			(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED	
		B. WING		R 05/17/2018		
			ADDRESS, CITY, STATE, ZIP CODE			
AVIN GR	ACE II		DAM ROAD NC 27576			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OI (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIEN	ACTION SHOULD BE COM TO THE APPROPRIATE DA	
V 108	Continued From page 1		V 108			
	and communicable d clients.	iseases of personnel and				
	This Rule is not met as evidenced by: Based on record review and interview the facility failed to ensure one of three audited staff (#2) had current training in First Aid and Cardiopulmonary Resuscitation (CPR). The findings are:					
	revealed: -Hired date: 1/16/12. -Position: Paraprofes -First Aid and CPR et					
	First Aid/CPR. -Staff #2 worked vari -There was always tw shifts with clients.					
	This deficiency const and must be correcte	itutes a re-cited deficiency d within 30 days.				
V 736	27G .0303(c) Facility	and Grounds Maintenance	V 736			
	10A NCAC 27G .030 EXTERIOR REQUIR					

STATE FORM

R8UG11

## PRINTED: 05/21/2018 FORM APPROVED

Division of Health Service Regulation           STATEMENT OF DEFICIENCIES           AND PLAN OF CORRECTION           (X1) PROVIDER/SUPPLIER/CLIA           IDENTIFICATION NUMBER:		(X2) MULTIPLE C			(X3) DATE SURVEY COMPLETED	
			A. BUILDING:		R	
		MHL051-173	B. WING		05	5/17/2018
AME OF PF	ROVIDER OR SUPPLIER	STREET	DDRESS, CITY, STATE	, ZIP CODE		
AVIN GR	ACE II		DAM ROAD NC 27576			
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN C (EACH CORRECTIVE AC CROSS-REFERENCED TC DEFICIEI	ACTION SHOULD BE CC	
V 736	Continued From page 2		V 736			
	(c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.					
	This Rule is not met as evidenced by: Based on observation and interview, the facility failed to ensure facility grounds were maintained in a safe and attractive manner. The findings are:					
	-In the shared bedroo bed frame was broke -The first bedroom to	/18 at 11:00 a.m. revealed: om, one of the beds bottom en. o the left of the front door: vas broken causing the				
	mattress to be on the -the closet door off track.					
	bedrooms.	d: eported issues in client's				
	repairing all maintena	sible for monitoring and ance issues or concerns. ofessional and completed all				

R8UG11