## Division of Health Service Regulation

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED	
		MHL043059	B. WIN	B. WING		07/29/2019
NAME OF	F PROVIDER OR SUPPLI	ER STRE	EET ADDRES	S, CITY, STATE, ZIP CODE		
PROFESS	SIONAL FAMILY CARE		SIE CIRCLI	Ξ.		
·		CAM	ERON, NC 2			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
V114	27G .0207 Emergency Plans and Supplies 10A NCAC 27G .0207 EMERGENCY PLANS AND SUPPLIES  (a) A written fire plan for each facility and area-wide disaster plan shall be developed and shall be approved by the appropriate local authority.  (b) The plan shall be made available to all staff and evacuation procedures and routes shall be posted in the facility.  (c) Fire and disaster drills in a 24-hour facility shall be held at least quarterly and shall be repeated for each shift. Drills shall be conducted under conditions that simulate fire emergencies.  (d) Each facility shall have basic first aid supplies accessible for use.		V114	Residential Manager developed quarterly schedule to address e completing the Fire and Disaste	e to address each shift	
				Professional Family Care Services QP will conduct an in-service training to all group home staff on policies and procedures of conducting and ensuring fire and disaster drills are conducted at least quarterly on each shift. Written documentations will be recorded by the staff conducting the drills. QP check logs monthly and monitor all drills quarterly to ensure they are carried out according to company policy.		09.15.19
V736	EXTERIOR REQUI (c) Each facility and maintained in a safe orderly	03 LOCATION AND	V736	AUG 1 3 2019 Lic. & Cert. Section		
violo617	alth Service Regulation		190	,		

Div

Signature:

Leon Robinson, MA, QP Residential Manager

Date: 08/09/2019

## Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:  B. WING		(X3) DATE SURVEY COMPLETED 07/29/2019	
		MHL043059				
NAME O	F PROVIDER OR SUPPLIE	ER STRE	ET ADDRES	SS, CITY, STATE, ZIP CODE		
PROFESS	SIONAL FAMILY CARE		SIE CIRCLI	Ε		
	1. 47 (D.1) 200 (484 ) 48 (C.0) (D.1) (M.1) (M.1	CAMI	ERON, NC 2		<u> </u>	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
V736	Continued from pa	ge 2	V736			
	#1's bedroom reveal -Window blinds we	9/19 at 11:50 A.M. of client aled: re missing holding clip to the ne off after trying to be	-PFCS reattached the sink can drawer and replace window be educating the consumer and changing linens multiple time and personal hygiene.	-PFCS has extended hooks to prevent the blinds from falling		08.01.19
	Observation on 7/2 #1's bathroom reve	d sink was missing top			08.01.19	
	-Window blinds beh Observation on 7/29 #2's bedroom revea -Strong musky odor -There was a a bas near the wall and be	nind tub were bent/broken. 9/19 at 12:00 P.M. of client aled:		Hole was patched and covered.		08.01.19
	Observation on 7/29 hallway bathroom re	9/19 at 12:05 P.M. of the		-PFCS to replace the mirror		09.15.19
	-Mirror on top of sin opaque on the botto	k was tarnished and		-PFCS replaced the panel next t shower area	o the	08.01.19
	empty room reveale	9/19 at 12:10 P.M. of the d: missing door frame from		-PFCS attached a new door fran the walk-in closet	ne to	08.01.19
	the door.	s not finished. Drywall and		-PFCS to paint the drywall inside closet	e of	09.15.19
	back/side porch reve	0/19 at 12:13 P.M. of the ealed:		-PFCS discarded the broken tab	le	08.01.19
	Observation on 7/29 front porch revealed	9/19 at 12:18 P.M. of the		-PFCS replaced 4 of 5 poles		08.05.19
eion of II		nns were rotten on the		-PFCS to replace the last pole (5	of 5)	09.15.19