	of Health Service Re IT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPI F	CONSTRUCTION	(X3) DATE SURVEY		
AND PLAN OF CORRECTION IDENTIFICATION NUMBER:			A. BUILDING:		COMPLETED		
		B. WING			R 10/21/2019		
NAME OF F	PROVIDER OR SUPPLIER	STREET A	DDRESS, CITY, ST	TATE, ZIP CODE			
VOCA - E	DELLINGER		DELLINGER F VILLE, NC 28				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES (MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE HE APPROPRIATE	HOULD BE COMPLET	
∨ 000	INITIAL COMMENTS		V 000				
	An annual and follow up survey was completed on 10-21-19. A deficiency was cited.						
	This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disabilities.						
	27G .0303(c) Facili	ty and Grounds Maintenance	V 736				
	EXTERIOR REQUI (c) Each facility and maintained in a safe	803 LOCATION AND IREMENTS d its grounds shall be e, clean, attractive and orderly e kept free from offensive					
		and observation, the facility I in a safe, clean, and					
	10:15am of the exte -Old dryer on the ex- grass underneath, f and rust on top; -Broken wooden pie nails pointing upwa -Decayed wooden t garage;	trim around the corners of the					
	, .	bed wooden handrail on the ading to the front door.					
	1:00pm of the interi	21-19 at approximately ior of the facility revealed: iner with torn and worn					

178Z11

AND PLAN OF CORRECTION IDENTIFICATION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		CONSTRUCTION		(X3) DATE SURVEY COMPLETED	
			A. BUILDING:				
		MHL036-091	B. WING			R 10/21/2019	
AME OF F	PROVIDER OR SUPPLIER	STREET AL	DDRESS, CITY, ST	TATE, ZIP CODE			
OCA - E	DELLINGER		DELLINGER F VILLE, NC 28				
(X4) ID PREFIX	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT			
TAG	REGULATORY OR L	SC IDENTIFYING INFORMATION)	TAG	CROSS-REFERENCED TO		DATE	
V 736	Continued From page 1		V 736				
	upholstery in the living room;						
		nditioning return vent in the					
	hallway was completely covered in dust; -A broken curtain rod on right hand side window						
	in Client #1's bedroom resulted in the draperies						
	hanging on the floor;						
	-Cobwebs located on the top of the walls, at						
	ceiling, throughout Client #1's bedroom;						
	-Black markings located on the exterior of Client #1's bedroom door;						
	-2-inch hole located in the exterior of Client #3's						
	bedroom door.						
	Interview on 10-21- revealed:	19 with the House Manager					
	-New maintenance company started on 10-4-19						
	and have not made any visits to the facility yet;						
	-She drives a truck and will be hauling the dryer						
	and the picnic table to the dump;						
	-She will be completing work orders to have the						
	bedroom doors repaired, curtain rod repaired, and the handrail repaired;						
		ent #1's bedroom and					
		ting and air conditioning return					
	vent will be comple	ted immediately.					
	Intonviow on 10 21	19 with the Program Manager					
	revealed:	T9 with the Frogram wanager					
		e concerns will be followed up					
	on by the new main	itenance department;					
		er will have the interior					
	cleaning handled as	s soon as possible.					

178Z11