	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	. ,	CONSTRUCTION		E SURVEY PLETED
MHL092-755			A. BUILDING:		R-C	
		B. WING			12/23/2019	
AME OF F	PROVIDER OR SUPPLIER	STREET A	DDRESS, CITY, ST	ATE, ZIP CODE		
BSOLU	TE HOME AND COM	MUNITY SERVICE	LRACE RD H, NC 27606			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE THE APPROPRIATE	(X5) COMPLE DATE
{V 000}	INITIAL COMMEN	TS	{V 000}			
	A Follow Up Survey Deficiencies were o	y was completed 12/23/19. cited.				
		sed for the following service C 27G .5600A Supervised th Mental Illness.				
V 114	27G .0207 Emerge	ency Plans and Supplies	V 114			
	AND SUPPLIES	207 EMERGENCY PLANS				
	shall be approved l authority.	plan shall be developed and by the appropriate local be made available to all staff				
	and evacuation pro posted in the facilit (c) Fire and disaste shall be held at lea repeated for each s under conditions th	ocedures and routes shall be y. er drills in a 24-hour facility st quarterly and shall be shift. Drills shall be conducted at simulate fire emergencies.				
	accessible for use.	all have basic first aid supplies				
	Based on record re failed to assure fire	et as evidenced by: eview and interview, the facility and disaster drills were quarterly on each shift. The				
	Review on 12/16/1 revealed no fire or	9 of the facility's records disaster drills				
	During interview or she:	n 12/16/19, staff #1 reported				

6L8U12

	NT OF DEFICIENCIES	egulation (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		CONSTRUCTION		E SURVEY PLETED
MHL092-755		B. WING		R-C <b>12/23/2019</b>		
AME OF	PROVIDER OR SUPPLIER	STREET A	DDRESS, CITY, ST	TATE, ZIP CODE		
BSOLU	JTE HOME AND COM	MUNITY SERVICE				
	SUMMARY STA	TEMENT OF DEFICIENCIES	H, NC 27606	PROVIDER'S PLAN OF		(YE)
(X4) ID PREFIX TAG	(EACH DEFICIENC)	( MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EACH CORRECTIVE ACT CROSS-REFERENCED TO DEFICIENC	TION SHOULD BE	(X5) COMPLE <sup>-</sup> DATE
V 114	Continued From pa	ige 1	V 114			
{V 736}	2019, but she did n -received pape the Qualified Profes -was not sure h should be complete -was not familia simulate/conduct fin drills be conducted 27G .0303(c) Facili	now often fire/disaster drills ed ar with how to re and disaster drills. "Should at each exit?" ty and Grounds Maintenance 803 LOCATION AND	{V 736}			
	(c) Each facility and maintained in a saf	d its grounds shall be e, clean, attractive and orderly e kept free from offensive				
	review the facility fa	et as evidenced by: ion, interview and record ailed to maintain the home in a manner. The findings are:				
	maintained by the I Regulation (DHSR) Deficiency (SOD) F from Mental Health Section of recited v following regulatory -emergency pla documenting drills -facility grounds	ans and supplies (staff not were conducted) s and maintenance (evidence in reference to client and staff				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION       (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:       (X2) MULTIPLE CONSTRUCTION A. BUILDING:       (X3) DATE SURVEY COMPLETED         MHL092-755       MHL092-755       B. WING       R-C 12/23/2019         NAME OF PROVIDER OR SUPPLIER       STREET ADDRESS, CITY, STATE, ZIP CODE       T2/23/2019         ABSOLUTE HOME AND COMMUNITY SERVICE       STREET ADDRESS, CITY, STATE, ZIP CODE       5628 MILLRACE RD RALEIGH, NC 27606         (X4) ID PREFIX       SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL       ID PREFIX       PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE       (X5) COMPLE	Division	of Health Service Re	aulation			FORM APPROVED	
MHL092-755         B. WING         12/23/2019           NAME OF PROVIDER OR SUPPLIER         STREET ADDRESS, CITY, STATE, ZIP CODE         Stabular Lance         Stabular Lance <t< th=""><th>STATEMEN</th><th>IT OF DEFICIENCIES</th><th>(X1) PROVIDER/SUPPLIER/CLIA</th><th></th><th></th><th></th></t<>	STATEMEN	IT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA				
ABSOLUTE HOME AND COMMUNITY SERVICE         5628 MILLPACE RD RALEIGH, NC 27606           (Y4)10 PREFIX TAG         SUMMARY STATEMENT OF DEFICIENCES (EACH DEFICIENCY MUST BE PRECEDED BY FULL FAG         PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG         PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG         PREFIX TAG         PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG         PREFIX         COMPLE (EACH CORRECTIVE ACTION SHOULD BE (EACH CORRECTIVE ACTION SHOULD BE DEFICIENCY)         COMPLE (CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)         COMPLE (V 736)           (V 736)         Continued From page 2 over stove/hood/range as well as countertops, living room facility grounds) safety-(trip hazards in client areas either by cable wires or trainate floors, exposed nails or screws, weak or rotted wood related to structural areas of the property) maintenance of electrical system- (inadequate lighting throughout the home)         Observation and tour of the facility on 12/16/19 between 9:30AN-11:30AM of the three level facility revealed the following; (Note an Asterisk (°) = cited 617/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: master bedroom occupied by clients #1 & #6		MHL092-755		B. WING			
ABSOLUTE HOME AND COMMUNITY SERVICE       RALEIGH, NC 27606         (X) ID PREFIX TAG       SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC DENTIFYING INFORMATION)       ID PREFIX PAG       ID PROVIDERS PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC DENTIFYING INFORMATION)       ID PREFIX PAG       ID PROVIDERS PLAN OF CORRECTION (EACH DEFICIENCY)       ID PROVIDEFIS PLAN OF CORRECTION (EACH DEFICIENCY)	NAME OF F	PROVIDER OR SUPPLIER	STREET AL	DRESS, CITY, S	STATE, ZIP CODE		
Přěčív TAG       (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION)       PŘĚTX TAG       (CACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)       COMPLE DEFICIENCY         {V 736}       Continued From page 2       (V 736)       (V 736)         over stové/hood/range as well as countertops, living room facility grounds)       -safety-(trip hazards in client areas either by cable wires or laminate floors, exposed nails or screws, weak or rotted wood related to structural areas of the property)       -maintenance of electrical system- (inadequate lighting throughout the home)       Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey)       -master bedroom occupied by clients #1 & #6       *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential tip hazard         with water stains & dirt.       *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *binds dirty in bathroom *dirt and mold noted in shower *"bathroom closet door frame wood broken       **dust noted in shower *"dust noted in ceiling paare repeing." Thaking", or	ABSOLU	TE HOME AND COM	MUNITY SERVICE				
TAG     REGULATORY OR LSC IDENTIFYING INFORMATION)     TAG     CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)       [V 736]     Continued From page 2 over stove/hood/range as well as countertops, living room facility grounds) -safety-(trip hazards in client areas either by cable wires or laminate floors, exposed nails or screws, weak or rotted wood related to structural areas of the property) -maintenance of electrical system- (inadequate lighting throughout the home)     (V 736)       Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (') = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: -master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam "laminate floors not "flush" together with potential trip hazard "broken molding notedtub dirty with water stains & dirt. "Vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower *"bathroom closet door frame wood broken bathroom closet wall contained offensive language and words *"dust noted in ceiling near exhaust *"dust noted in ceiling near exhaust *"dust noted in ceiling near exhaust *"dust noted in ceiling near exhaust     Image inside *"dust noted in ceiling near exhaust							
<pre>over stove/hood/range as well as countertops, living room facility grounds) -safety-(trip hazards in client areas either by cable wires or laminate floors, exposed nails or screws, weak or rotted wood related to structural areas of the property) -maintenance of electrical system- (inadequate lighting throughout the home) Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 &amp; 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: -master bedroom occupied by clients #1 &amp; #6</pre>					CROSS-REFERENCED TO THE APPRO		
living room facility grounds) -safety-(trip hazards in client areas either by cable wires or laminate floors, exposed nails or screws, weak or rotted wood related to structural areas of the property) -maintenance of electrical system- (inadequate lighting throughout the home) Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard with potential trip hazard toroken molding notedtub dirty with water stains & dirt *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *binds dirty in bathroom *dirt and mold noted in shower **bathroom closet wall contained offensive language and words **dust noted in celling near exhaust **celling plaster peeling, "flaking", or	{V 736}	Continued From pa	ge 2	{V 736}			
safety-(trip hazards in client areas either by cable wires or laminate floors, exposed nails or screws, weak or rotted wood related to structural areas of the property) maintenance of electrical system- (inadequate lighting throughout the home) Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *Taminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *binds dirty in bathroom *dirt and mold noted in shower **bathroom closet wall contained offensive language and words *dust noted in ceiling near exhaust *toeling plaster peeling, "flaking", or							
cable wires or laminate floors, exposed nails or screws, weak or rotted wood related to structural areas of the property) maintenance of electrical system- (inadequate lighting throughout the home) Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and waped) *binds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken 							
areas of the property) -maintenance of electrical system- (inadequate lighting throughout the home) Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: -master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *binds dirty in bathroom *dirt and mold noted in shower *trabhroom closet wall contained offensive language and words **dust noted in ceiling near exhaust *toelling plaster peeling, "flaking", or		cable wires or lamir	nate floors, exposed nails or				
-maintenance of electrical system- (inadequate lighting throughout the home) Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: -master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wall.mold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
<pre>(inadequate lighting throughout the home) Observation and tour of the facility on 12/16/19 between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 &amp; 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: -master bedroom occupied by clients #1 &amp; #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains &amp; dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words *dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or</pre>							
between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
between 9:30AM-11:30AM of the three level facility revealed the following: (Note an Asterisk (*) = cited 6/17/19 & 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey) A. Top Level: master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or		Observation and to	ur of the facility on 12/16/19				
<pre>(*) = cited 6/17/19 &amp; 9/4/19, ** = cited 9/4/19, no asterisk = newly identified during 12/16/19 survey)</pre>		between 9:30AM-11:30AM of the three level					
asterisk = newly identified during 12/16/19 survey) A. Top Level: -master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
A. Top Level: -master bedroom occupied by clients #1 & #6 *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or		asterisk = newly ide					
& #6     *closet- wire clothes hanging rack not fully attached to wallmold noted in door jam     *laminate floors not "flush" together with potential trip hazard     *broken molding notedtub dirty with water stains & dirt.     *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped)     *blinds dirty in bathroom     *dirt and mold noted in shower     **bathroom closet door frame wood broken     bathroom closet wall contained offensive language and words     **dust noted in ceiling near exhaust     **ceiling plaster peeling, "flaking", or							
*closet- wire clothes hanging rack not fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or			droom occupied by clients #1				
fully attached to wallmold noted in door jam *laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt. *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower *tathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or			wire clothes hanging rack not				
*laminate floors not "flush" together with potential trip hazard *broken molding notedtub dirty with water stains & dirt *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
*broken molding notedtub dirty with water stains & dirt *vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or		*lamina	ate floors not "flush" together				
with water stains & dirt   *vanity sink cabinet (door   brokeninside cabinet evidence of water   damage inside and warped)   *blinds dirty in bathroom   *dirt and mold noted in shower   **bathroom closet door frame wood   broken   bathroom closet wall contained   offensive language and words   **dust noted in ceiling near exhaust   **ceiling plaster peeling, "flaking", or							
*vanity sink cabinet (door brokeninside cabinet evidence of water damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
damage inside and warped) *blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
*blinds dirty in bathroom *dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
*dirt and mold noted in shower **bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
**bathroom closet door frame wood broken bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
bathroom closet wall contained offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
offensive language and words **dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or			and the set of the set of the				
**dust noted in ceiling near exhaust **ceiling plaster peeling, "flaking", or							
**ceiling plaster peeling, "flaking", or							
separating in both bathroom and bedroom areas		**ceilin	g plaster peeling, "flaking", or				
cracks noted in the ceiling							
mattress indented in the middle on client #1's bedcomforter torn							

	NT OF DEFICIENCIES OF CORRECTION	egulation (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		CONSTRUCTION	СОМ	E SURVEY PLETED	
		MHL092-755	B. WING			R-C 12/23/2019	
NAME OF I	PROVIDER OR SUPPLIER	STREET A	DDRESS, CITY, S	TATE, ZIP CODE			
ABSOLU	ITE HOME AND COM	MUNITY SERVICE	LRACE RD H, NC 27606				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE THE APPROPRIATE	(X5) COMPLET DATE	
{V 736}	Continued From pa	age 3	{V 736}				
	-single bed with exit door	Iroom occupied by client #3					
		ate flooring not "flush" together gency escape-railing remained					
	*tri-folo *semi-	Iroom occupied by client #4 I closet holes inside circle marking embedded in with closet door being opened					
	**windo noted in areas betv	on light fixture ow sill dirty and thick cobwebs veen double paned window ng separated					
	construction section -since 9/4/19, r	n 12/16/19, the DHSR n consultant reported: repairs had been made to the le deck hand railing required for stability.					
	ceiling in several ar	circular stains noted on the					
		en-Countertops chipped naterialgrease build up					
	-laundry ar *peelin	ea g around floor molding					
		am rotting e over head gate panels not ating)					

Division of Health Service STATE FORM

6L8U12

	of Health Service Re					
	NT OF DEFICIENCIES OF CORRECTION			(X2) MULTIPLE CONSTRUCTION A. BUILDING:		SURVEY PLETED
м		MHL092-755	B. WING			-C 23/2019
NAME OF I	PROVIDER OR SUPPLIER	STREET A	DDRESS, CITY, ST		•	
		5628 MII				
ABSOLU	ITE HOME AND COM		H, NC 27606			
(X4) ID		ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL	ID	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT		(X5) COMPLET
PREFIX TAG		SC IDENTIFYING INFORMATION)	PREFIX TAG	CROSS-REFERENCED TO T DEFICIENC	THE APPROPRIATE	DATE
{V 736}	Continued From pa	age 4	{V 736}		,	
	-the Administra spoken with some countertops and ca landlord did not wa -the facility's m the grease build up stove. The black m described as mold removed. C. Lower Level -room occu *light fi both client beds	a 12/16/19, staff #1 reported: tor/Registered Nurse (RN) had one about replacing the ubinets in the kitchen. The nt to assist with the cost aintenance man had cleaned o underneath the range of the arkings on the hood she and indicated it could not be : upied by client #2 and client #5 xture missing light bulb over am rotted outside of exit door				
	*thresh replaced) crack mattre occupied by client # -hallway	old broken (need to be s noted in the ceiling ss indented in middle on bed	ı			
		ng bulb in vanity on ceiling near exhaust vent				
	*thresh top (can be lifted w **light	ocated near bathroom hold lift up when foot placed or ith footnot secure door) bulbs missing which leaves no ay leading to outside				
vision of L	-she had not se both tours on 6/17/	12/16/19, staff #1 reported: een the SODs but participated 19 and 9/4/19 with DHSR ental Health Licensure				

Division of Health Service Regulation STATE FORM

6899

6L8U12

If continuation sheet 5 of 6

	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		CONSTRUCTION		E SURVEY PLETED
	OF CONNECTION	IDENTIFICATION NOWBER.	A. BUILDING: B. WING		R-C 12/23/2019	
		MHL092-755				
IAME OF I	PROVIDER OR SUPPLIER	STREET A	DDRESS, CITY, ST	TATE, ZIP CODE		
BSOLU	TE HOME AND COM	MUNITY SERVICE	LRACE RD			
	STINWARY ST		H, NC 27606	PROVIDER'S PLAN OF		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE HE APPROPRIATE	(X5) COMPLET DATE
{V 736}	Continued From pa	age 5	{V 736}			
	-did not noticed the mattresses needed to be replaced					
	Surveyor reported: -since June 20 follow up surveys a -the Administra 9/4/19 SOD. In Nov to the 6/17/19 SOD both the Administra Professional. -although some been corrected., th substantially out of -follow up activ most of these viola Little efforts have b violations in the 46 -concerns rega facility's structure re increase in cracks, maintenance upkee Review on 12/16/19 maintained by the I both Mental Health Sections between -a total of 13 tir facility maintenance -identified area of safety of the dec	19, he had conducted three at this location ator/RN did not respond to the vember 2019, she did respond b. The SODs were emailed to ator/RN and the Qualified e previously cited items had e facility still remained compliance. rities have been ongoing for tions identified since 2016. been made to correct the month period. arding the integrity of the emained as evident by the rotten wood and overall ep of the facility's public file DHSR of SOD Reports from Licensure and Construction 11/13/15 and 6/17/19 revealed: mes the facility was cited for e concerns. Is of non compliance inclusive ck/railing, structural issues with vorking condition of the garage				

6L8U12