Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY COMPLETED						
AND LAN OF CONNECTION		IDEITH IO, WORK HOMBER.	A. BUILDING:		001111						
MI		MHL020-082	B. WING		08/04/2021						
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE											
THE RIVER HOUSE 284 SMOKEFORD ROAD MURPHY, NC 28906											
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPF DEFICIENCY)	TION SHOULD BE THE APPROPRIATE						
	An annual and complaint survey was completed on August 4, 2021. The complaint was unsubstantiated (Intake #00178970). A deficiency was cited. This facility is licensed for the following service category: 10A NCAC 27G .5600C: Supervised Living for Adults with Developmental Disabilities. 27G .0303(c) Facility and Grounds Maintenance 10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.		V 000	At Appalachian Community Services, we strive to maintain our facilities to the highest standard possible. At times, we recognize that we have failed to meet this standard and we work towards remediation as soon as possible. Historically, coordinating repairs and maintenance with the landlord has proven to be a challenging and length process. In regards to the handicap accessible ramp and overhang eave, the landlord has been notified and will be on site to inspect the damages and repairs. In regards to the mold in bathroom #2, the walls were sprayed with a bleach solution to remove. Staff will spray the walls daily with bleach solution to prevent recurrence. In regards to the missing outlet cover in bedroom #4, the new outlet cover was installed. In regards to the hornet nest on the back porch, Terminex was contacted and removed the nest. Terminex is currently contracted to inspect and treat the facility for any infestations. To prevent any future facility and maintenance deficiencies, the IDD Residential Manager will conduct biweekly safety and maintenance inspections. Residential staff will required to reporany safety or maintenance issues to the IDD Residential Manager when they are discovered.							
	failed to ensure facilit in a clean, safe and a findings are: Observation on 8/2/2 of the home revealed -The base of the hand broken board in the n approximately 12 inct -The underside of the porch had been repla appeared to have wa	a and interview, the facility y grounds were maintained ttractive manner. The 1 at 11:00 AM of the exterior dicap accessible ramp had a hiddle of the ramp hes by 4 inches in size. overhang eave of the front ced with newer plywood but									

Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Director IDD Services

TITLE

08/23/2021

(X6) DATE

If continuation sheet 1 of 2 UURR11

PRINTED: 08/06/2021 FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:		, , ,	(X3) DATE SURVEY COMPLETED					
MHL020-082			B. WING	B. WING							
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE											
THE RIVER HOUSE 284 SMOKEFORD ROAD MURPHY, NC 28906											
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE THE APPROPRIATE	(X5) COMPLETE DATE					
V 736	-In bathroom #2, blace above the shower on -In bedroom #4, an or one outlet that was actelevisionOn the back porch to nest attached to the lither of the room one outlet that was actelevisionOn the back porch to nest attached to the lither of the room o	k-like substance on the wall two walls. utlet cover was missing on ctively being used for a the right, an active hornet ght fixture on the ceiling. Ind handicap accessible ailing pickets were loose or of the railing. 11:40 am with the Director velopmental Disabilities ed: In home where the clients consible for repairs and will ves, hire a handyman, or the landlord to fix any issues. In are some issues with the could be in better condition. In the process of the clients. In the process of the clients the process of the clients. In the process of the process of the clients. In the process of	V 736								

Division of Health Service Regulation

STATE FORM UURR11 If continuation sheet 2 of 2