

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL092-805	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 06/23/2022
--	---	---	---

NAME OF PROVIDER OR SUPPLIER LIVING WITH AUTISM, INC	STREET ADDRESS, CITY, STATE, ZIP CODE 2817 TOBERMORY LANE RALEIGH, NC 27606
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual and follow up survey was completed on 6/23/22. Deficiencies were cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disabilities.</p> <p>The facility is licensed for 3 and currently has a census of 3. The survey sample consisted of audits of 3 current clients.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT</p> <p>(b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors.</p> <p>(4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interview the facility failed to ensure the water temperature was maintained between 100-116 degrees Fahrenheit. The findings are:</p> <p>Observation on 6/22/2 at 10:45 AM revealed water temperature in the kitchen was 85 degrees Fahrenheit. The water temperature in client #1's bathroom was 90 degrees in the sink and 85 degrees in the shower. The hallway bathroom water temperature was 85 degrees in the sink and 90 degrees in the shower.</p>	V 752		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL092-805	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 06/23/2022
--	---	---	---

NAME OF PROVIDER OR SUPPLIER LIVING WITH AUTISM, INC	STREET ADDRESS, CITY, STATE, ZIP CODE 2817 TOBERMORY LANE RALEIGH, NC 27606
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	Continued From page 1 During interview on 6/22/22, the Director stated: -This had been an ongoing issue with the water temperatures. -When the dishwasher and washing machine were on the temperature would be in the correct range -The plumber was out and installed the scald guards (This deficiency constitutes a re-cited deficiency and must be corrected within 30 days.)	V 752		
V 753	27G .0304(b)(5) Indoor Lighting 10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT (b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors. (5) All indoor areas to which clients have routine access shall be well-lighted. Lighting shall be adequate to permit occupants to comfortably engage in normal and appropriate daily activities such as reading, writing, working, sewing and grooming. This Rule is not met as evidenced by: Based on observation and interview, the facility failed to ensure all indoor areas were well-lighted. The findings are: Observation on 6/23/22 at 11:00 AM of the group home revealed: -Upstairs living area 2 out of 6 track lighting light bulbs were	V 753		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL092-805	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 06/23/2022
--	---	---	---

NAME OF PROVIDER OR SUPPLIER LIVING WITH AUTISM, INC	STREET ADDRESS, CITY, STATE, ZIP CODE 2817 TOBERMORY LANE RALEIGH, NC 27606
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 753	<p>Continued From page 2</p> <p>not working, area was dim unable to see well</p> <p>Interview on 6/23/22, the staff reported: -The lights "don't put out a lot of light." -"Those are the new light-emitting diode (LED) light bulbs."</p> <p>Interview on 6/23/22, the Director reported: -The lighting upstairs had been dimmed -They had tried the LED lights and "it's not working"</p>	V 753		