

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL076019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/25/2015
NAME OF PROVIDER OR SUPPLIER HUDSON'S FAMILY CARE #2		STREET ADDRESS, CITY, STATE, ZIP CODE 4028 OLD NC HWY 49 ASHEBORO, NC 27203		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments This report is of a biennial construction survey done by Bob Getchell on June 25, 2015. This facility was first licensed as a Family Care Home for six (6) ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). on April 16, 1993. Based on this we are requiring the home to be in compliance with the 1992 and the applicable portions of the 2005 Rules 10A NCAC 13G for the Licensing of Family Care Homes, and, the 1991 (93 Revision) North Carolina State Building Code - Section 514.1 Exception #1 - Residential Care Homes. Deficiencies were noted which will require a new plan of correction.	C 000	Section .0300 -10A NCAC 13G.0311 The Building Corridor 1. The locking hardware on the back door from the living room has been replaced with and interior non locking knob for a hall. Photo provided. If a doorknob in the path of egress needs to be replaced the supervisor will assure that an interior non locking knob will always be used.	7-20-15
C 143	Corridor-Free of Obstructions SECTION .0300 - THE BUILDING 10A NCAC 13G .0311 CORRIDOR (c) Corridors shall be free of all equipment and other obstructions. This Rule is not met as evidenced by: 1. Based on observation, the facility was not maintained in a safe manner by having corridors obstructed. Findings include: a) The back door from the Living Room, in the path of egress, has locking hardware.	C 143		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE	C 174		

CONSTRUCTION SECTION
AUG 20 2015
RECEIVED

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6880

N08H21

If continuation sheet 1 of 2

Susie Hudson

Administrator

7-27-15

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL076019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/25/2015
NAME OF PROVIDER OR SUPPLIER HUDSON'S FAMILY CARE #2		STREET ADDRESS, CITY, STATE, ZIP CODE 4028 OLD NC HWY 49 ASHEBORO, NC 27203		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	<p>Continued From page 1</p> <p>EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes.</p> <p>This Rule is not met as evidenced by: 1. Based on observation, the electrical system was not maintained safe.</p> <p>Findings include: a) The left bathroom outlet is not GFCI protected, b) The right bathroom outlet has a GFCI outlet that will not trip. c) The electrical panel in the Laundry Room has an open space exposing energized contacts.</p>	C 174	<p>Section .0300 - 10ANCAC 123G.0317 The Building Service</p> <p>1. The left bathroom outlet GFCI protection will be installed 8-4-15</p> <p>The right bathroom outlet GFCI will be repaired 8-4-15</p> <p>The open space in the electrical panel in the laundry room will be repaired with a blank breaker 8-4-15</p> <p>A picture and the invoice will be provided upon completion of the needed repairs.</p> <p>The supervisor will monitor the electrical system to assure safety .</p>	8-4-15

Hoyt Russell

ELECTRIC CONTRACTOR

DEPENDABLE - EXPERIENCED - REPAIRING
 5221 US Hwy. 220 Bus. S. • Phone (336) 629-3523 • Asheboro, NC 27205

Customer's Order No. _____ Date 8-4 20 15
 M Hudsons Family Care No-2
 Address 4028 Old N.C. Hwy - 49
 City Asheboro Zip 27203 State N.C.


QUAN.	DESCRIPTION	PRICE	AMOUNT
	Replaced outlet in Left Bathroom GFCI outlet		
	Replaced Right Bathroom with GFCI outlet		
	Install Breaker Cover in Electric Panel in Laundry Room		
	Material		25.00
	Labor		100.00
	Total	\$	125.00


ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL

Received By Paul

A Service Charge of 1½% Per Month Will Be Charged on All Past Due Accounts.







1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

200A

MAIN

REVERSE