	IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING		COM	(X3) DATE SURVEY COMPLETED R 08/06/2015	
OF CORRECTION						
	HAL075010					
ROVIDER OR SUPPLIER	STREET AI	DDRESS, CITY, S	TATE, ZIP CODE			
WOODS						
(X4) IDSUMMARY STATEMENT OF DEFICIENCIESPREFIX(EACH DEFICIENCY MUST BE PRECEDED BY FULLTAGREGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO 1	TION SHOULD BE	(X5) COMPLET DATE	
Initial Comments		{C 000}				
Report of Follow-up Survey by Dennis Harrell on 8-6-2015.						
Not all deficiencies action is required.	were corrected. Further					
Must Have Current San. & Fire Safety Reports		{C 111}				
10A NCAC 13F .03 CONSTRUCTION(f) The facility shall fire and building sat shall be maintained review.	02 DESIGN AND have current sanitation and fety inspection reports which I in the home and available for					
2. Based on a revie recent Fire Safety I year ago. Failure to systems inspected could result in syste	ew of documents, the most nspection was more than a b have the building and safety and approved as required ems not operating properly in					
	(EACH DEFICIENCY REGULATORY OR L Initial Comments Report of Follow-up 8-6-2015. Not all deficiencies action is required. Must Have Current SECTION .0300 - F 10A NCAC 13F .03 CONSTRUCTION(f) The facility shall fire and building sat shall be maintained review. This Rule is not me 2. Based on a revie recent Fire Safety I year ago. Failure to systems inspected could result in syste the event of an actu Finding on 8-6-2018	ROVIDER OR SUPPLIER STREET AI 1062 WE COLUME NOODS SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) Initial Comments Report of Follow-up Survey by Dennis Harrell on 8-6-2015. Not all deficiencies were corrected. Further action is required. SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(1) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 2. Based on a review of documents, the most recent Fire Safety Inspection was more than a year ago. Failure to have the building and safety systems inspected and approved as required could result in systems not operating properly in the event of an actual fire. Finding on 8-6-2015: A new Fire Safety Inspection has not yet been completed.	TRECTION 0 STREET ADDRESS, CITY, S NOODS STREET ADDRESS, CITY, S SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) ID PREFIX TAG Initial Comments (C 000) Report of Follow-up Survey by Dennis Harrell on 8-6-2015. Not all deficiencies were corrected. Further action is required. Must Have Current San. & Fire Safety Reports (C 111) SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION((The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 2. Based on a review of documents, the most recent Fire Safety Inspection was more than a year ago. Failure to have the building and safety systems inspected and approved as required could result in systems not operating properly in the event of an actual fire. Finding on 8-6-2015: A new Fire Safety Inspection has not yet been completed.	Interview Interview Interview STREET ADDRESS, CITY, STATE, ZIP CODE MOODS 1062 WEST MILLS STREET COLUMBUS, NC 28722 SUMMARY STATEMENT OF DEFICIENCIES ID (EACH DEFICIENCY WIST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) ID (PREPRIX TAG PROVIDER'S PLAN OF (EACH CORRECTIVE ACI (COSS-REFERENCED TO TO DEFICIENCY Not all deficiencies were corrected. Further action is required. Not all deficiencies were corrected. Further action is required. (C 111) SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(1) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 2. Based on a review of documents, the most recent Fire Safety Inspection was more than a year ago. Failure to have the building and safety systems inspected and approved as required could result in systems not operating properly in the event of an actual fire. Finding on 8-6-2015: A new Fire Safety Inspection has not yet been completed.	HAL075010 B. WING Og ROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE MOODS 1062 WEST MILLS STREET SUMMARY STATEMENT OF DEFICIENCIES (EACH CORFCIENCY MIST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) ID PROVIDERS PLAN OF CORRECTION (EACH CORFCIENCY MIST BE PRECEDED BY FULL TAG ID PROVIDERS PLAN OF CORRECTION (EACH CORFCIENCY MIST BE PRECEDED BY FULL TAG ID PROVIDERS PLAN OF CORRECTION (EACH CORFCIENCY MIST BE PRECEDED BY FULL TAG Initial Comments (C 000) Report of Follow-up Survey by Dennis Harrell on 8-6-2015. (C 000) Not all deficiencies were corrected. Further action is required. (C 111) SECTION .0300 - PHYSICAL PLANT 100 ANCAC 13F .0302 DESIGN AND CONSTRUCTION(1) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 2. Based on a review of documents, the most recent Fire Safety Inspection was more than a gear ago. Failure to have the building and starty systems inspected and approved as required could result in systems not operating properly in the event of an actual fire. Finding on 8-6-2015: A new Fire Safety Inspection has not yet been completed.	