

PRINTED: 09/27/2017
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078095	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/14/2017
--	--	--	---

NAME OF PROVIDER OR SUPPLIER HOPE SPRINGS	STREET ADDRESS, CITY, STATE, ZIP CODE 104 HOPE LANE RED SPRINGS, NC 28377
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Construction Section Biennial Survey report by Frank Strickland on 09/14/2017:</p> <p>The facility was first licensed on 02/01/1973 with an addition approved on 02/20/1990. This facility is licensed for Sixty-Three (63) residents. Based on this information, we are requiring that this facility to meet the 1971 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm and the 1967 North Carolina State Building Code- Institutional Occupancy; the addition is being required to meet the 1987 Minimum Standards and Regulations for Homes for the Aged and Disabled and the 1978 North Carolina State Building Code; and the entire facility is required to meet the applicable portions of the 2005 Rules for Adult care Home of Seven or More Beds.</p> <p>Deficiencies have been cited and a Plan of Correction is required.</p>	C 000		
C 166	<p>Housekeeping-Maintained Free of Hazards</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS</p> <p>(a) Adult care homes shall:</p> <p>(5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards;</p> <p>(e) This Rule shall apply to new and existing facilities.</p> <p>This Rule is not met as evidenced by: 1-Based on observation, this facility has not maintained free of hazards. This could affect all residents and staff by potentially exposing them to the hazards of a ruptured cylinder.</p>	C 166		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OFFICE

PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE: *Mark Hume* TITLE: *Executive Director* (X6) DATE: *10/5/17*

PRINTED: 09/27/2017
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078095	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/14/2017
NAME OF PROVIDER OR SUPPLIER HOPE SPRINGS		STREET ADDRESS, CITY, STATE, ZIP CODE 104 HOPE LANE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	(D) PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 1 Findings on 09/14/2017: In the 100 HALL/Med Room, there was a 112 ML Helium gas storage cyclinder that was standing upright and unsecured, not in an approved rack or secured to the adjacent wall by a chain. NOTE: Vender arrived on site during the survey and removed. the noted cyclinder.	C 166	Removed by vender onsite.	9-14-17
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observation, this facility has failed to provide fire protection in all HVAC air distribution grilles that penetrate the ceilings that a part of the fire rated roof/ceiling assemblies.	C 189		
C 169	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER Findings on 09/14/2017: The HVAC supply grille that is located in the 200 HALL/RCC Office does not have any fire protection that penetrates the ceiling through a fire-rated roof/ceiling assembly.	C 109	Requesting HVAC Contractor to install Fire Damper	11-30-17

PRINTED: 09/27/2017
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078095	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/14/2017
--	--	--	---

NAME OF PROVIDER OR SUPPLIER HOPE SPRINGS	STREET ADDRESS, CITY, STATE, ZIP CODE 104 HOPE LANE RED SPRINGS, NC 28377
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	<p>Continued From page 2</p> <p>REQUIREMENTS</p> <p>(g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces:</p> <ol style="list-style-type: none"> (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. <p>(k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <p>1-Based on observation, this facility failed to provide an environment in accordance with this Rule by not providing ventilation where odors are generated. This could affect residents and staff by subjecting them to unwanted odors.</p> <p>Findings on 09/14/2017: The mechanical exhaust fan is not exhausting interior air in the Spa Bath that is located in the 100/Women's Hall.</p>	C 199	<p><i>The exhaust fan for Spa Bath located in the 100/Women's Hall has been installed</i></p>	<p><i>9/26/17</i></p>