

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL034104</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>R-C</b> <b>11/21/2017</b>
--	--	--	---

NAME OF PROVIDER OR SUPPLIER  <b>FORSYTH VILLAGE</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>5100 LANSING DRIVE WINSTON SALEM, NC 27105</b>
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments  Report of Complaint Follow Up Construction Survey by Dennis Harrell on 11-21-2017.  A deficiency was cited that will require a new Plan of Correction.	{C 000}		
{C 189}	Building Equipment Maintained Safe, Operating  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.  This Rule is not met as evidenced by: Based on observation, the fire alarm system was not being maintained in a safe and operating condition. Fire alarm systems that do not work properly endanger all residents and staff. Finding on 7-12-2017, 9-12-2017 and 11-21-17: a. The corridor smoke detector near bedroom 30 activated when tested with smoke but failed to sound the fire alarm system. Note; There was a fire alarm technician onsite and this deficiency was corrected before the end of the survey.	{C 189}	Fixed onsite	12/19/17

Division of Health Service Regulation  
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE **Admin**

(X6) DATE  
**12/19/17**