Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONST AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING: 01

(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY
A. BUILDING: 01 (X3) DATE SURVEY

HAL044012

B. WING

11/08/2017

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

PIGEON VALLEY REST HOME

55 LAKE DRIVE CANTON, NC 28716

PIGEON VALLEY REST HOME CANTON,			NC 28716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 000	Initial Comments	C 000			
	Construction Section Biennial Survey report by Frank Strickland on 11/08/2017:				
	This facility was first licensed on 10/01/1962. This facility is currently licensed for 29 BEDS. A plaque on the building shows that the building was constructed as the County Rest Home in 1911. Based on this information, we are requiring the facility to meet the 1971 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm (which all Adult Care Homes must meet regardless of when they were first licensed), the 1967 NC State Building Code for Institutional Occupancies and the applicable portions of the current 2005 Rules for Adult Care Homes.				
	Deficiencies have been cited and a Plan of Correction is required.				
C 152	Entrances-Steps, Porches with Handrails  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (h) The requirements for outside entrances and exits are: (2) All steps, porches, stoops and ramps shall be provided with handrails and guardrails;  This Rule is not met as evidenced by: 1-Based on observation, this facility has failed to provide handrails at all steps.  Findings on 11/08/2017: There is a step at the Main Entry door base and a handrail is not provided	C 152	A grab bar has been added beside the step at the main door. All steps, porches, stoops, and ramps have been inspected to ensure no other entrance or exit lacks a handrail or guardrail or grab bar.	12/11/17	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Administrator

(X6) DATE 12-11-17

STATE FORM

689

en

WQD221

If continuation sheet 1 of 3

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING HAL044012 11/08/2017 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 55 LAKE DRIVE PIGEON VALLEY REST HOME CANTON, NC 28716 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL COMPLETE (EACH CORRECTIVE ACTION SHOULD BE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) C 160 | Continued From page 1 C 160 C 160 Outside Premises-Clean, Safe C 160 The leaves and debris were 11/13/17 immediately removed from the SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL lower wing exterior concrete ENVIRONMENT pathway. All pathways were (m) The requirements for outside premises are: inspected daily to ensure leaves The outside grounds of new and existing facilities shall be maintained in a clean and safe did not re-accumulate. Weekly condition; inspections of all grounds will continue to ensure no other This Rule is not met as evidenced by: debris re-accumulates causing a 1-Based on observation, this facility has failed to trip hazard. keep the grounds clean and in a safe condition. Findings on 11/08/2017: There is an exit that is adjacent to Bedroom L-1 in the LOWER WING that opens up to a exterior concrete pathway that has excessive leaves and debris that presents a trip hazard. 12/19/17 C 162 Outside Premises-Outdoor Lighting C 162 Additional lighting has been SECTION .0300 - PHYSICAL PLANT added to the exit adjacent to 10A NCAC 13F .0305 PHYSICAL bedroom L-1/lower wing and to ENVIRONMENT the exterior ramp located (m) The requirements for outside premises are: (3) Outdoor walkways and drives shall be outside bedroom N-9/North illuminated by no less than five foot-candles of Wing. All exits have been light at ground level. inspected to ensure all exits have adequate lighting in an This Rule is not met as evidenced by: 1-Based on observation, this facility has failed to emergency. Routine monthly provide illumination at outdoor walkways and inspections will be conducted ramps. to ensure adequate lighting is Findings on 11/08/2017: available. The following locations do not have illumination at

Division of Health Service Regulation

HAL044012 B. WING 11/0	11/08/2017					
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE						
PIGEON VALLEY REST HOME 55 LAKE DRIVE						
CANTON, NC 28716						
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION)    X4) ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	COMPLETE DATE					
C 162 Continued From page 2 C 162						
C 162  Continued From page 2 exit access pathways to assist resident and staff in the event of an emergency: (a) The exterior pathway that is located outside the exit adjacent to Bedroom L-1/LOWER WING. (b) The exterior ramp that is located outside Bedroom N-9/NORTH WING.						