Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA

		(X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY	
AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		IDENTIFICATION NUMBER:	A. BUILDING: 01		COMPLETED	
		HAL007015	B. WING		04/26/2018	
NAME OF F	PROVIDER OR SUPPLIER	STREET ADI	DRESS, CITY, S	STATE, ZIP CODE		
PANTEG	O REST HOME	143 SWAN PANTEGO	MP ROAD), NC 27860			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRODEFICIENCY)	.D BE	(X5) COMPLETE DATE
C 000	Initial Comments		C 000			
	Report of a Biennial Construction Survey by Suzanna Fay conducted on April 26, 2018.					
	June 1, 1973. The f 30 Beds. Therefore conformance with the 2005 Rules for Lice Seven or More Bed the 1967 Edition of Code(s), Institutional Rules for Licensing	is facility was first licensed on facility is currently licensed for the facility was surveyed for the applicable portions of the ensing of Adult Care Homes of its and applicable portions of the North Carolina Building al Occupancy and the 1971 of Adult Care Homes of its in effect at the time of initial				
C 101	Existing Licensed F	ac- No less than '71 Rules	C 101			
	PHYSICAL PLANT The physical plant recare home shall be (2) Except where of licensed facilities or facilities shall meet requirements in effecting in service or renovation, or alterathe requirements for addition or renovation than those requirem "Minimum and Des Regulations" for "Hecopies of which are Health Service Regulations"	O1 APPLICATION OF REQUIREMENTS requirements for each adult applied as follows: otherwise specified, existing reportions of existing licensed licensure and code ect at the time of construction, or bed count, addition, ation; however in no case shall or any licensed facility where wation has been made, be less ments found in the 1971 ired Standards and omes for the Aged and Infirm", available at the Division of gulation at no cost;				
	This Rule is not met as evidenced by: 1. Observations revealed that all of the facility's					

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE TITLE

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING:	E CONSTRUCTION 01	(X3) DATE COMP	SURVEY LETED
			71. BOILBING.	•.		
		HAL007015	B. WING		04/2	6/2018
NAME OF F	PROVIDER OR SUPPLIER			STATE, ZIP CODE		
PANTEG	O REST HOME	143 SWAN PANTEGO	, NC 27860			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRODEFICIENCY)	D BE	(X5) COMPLETE DATE
C 101	Continued From pa	ge 1	C 101			
		ne requirements in effect at the n, renovation or alteration.				
	room to the kitchen requirements for a opens onto a concrimmediately to the laround the can was The exit does not a Verify with the local	5, 2018: c - the exit from the dining porch does not meet the path of egress. The door ete path that slopes up kitchen's can wash. The path is only 24 inches wide. ppear to be a required exit. Building and Fire Code it sign can be removed.				
C 132	rooms are: (5) The bathrooms designed to provide rooms with two or n (commodes) shall h curtains for each washower shall have p. This Rule is not me 1. Observations rewas not designed to Findings on April 26 a. Staff bathroom -	PHYSICAL PLANT 05 PHYSICAL Ints for bathrooms and toilet and toilet rooms shall be exprivacy. Bathrooms and toilet more water closets mave privacy partitions or mater closet. Each tub or privacy partitions or curtains; et as evidenced by: wealed that the staff bathroom or provide privacy. 5, 2018: The bathroom has two water mo privacy partitions or	C 132			

Division of Health Service Regulation STATE FORM

TYKU21 If continuation sheet 2 of 7

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED	
	HAL007015		B. WING		04/26/2018	
NAME OF F	PROVIDER OR SUPPLIER	STREET ADI	DRESS, CITY, S	STATE, ZIP CODE	_	
PANTEG	O REST HOME	143 SWAN PANTEGO	MP ROAD), NC 27860			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETE DATE
C 160	Continued From pa	ge 2	C 160			
C 160	Outside Premises-0	Clean, Safe	C 160			
	(1) The outside gro facilities shall be m condition; This Rule is not mo 1. Based on obser	ents for outside premises are: bunds of new and existing aintained in a clean and safe				
	Findings on April 26 a. Right elevation of mildew and dirt state exterior wall. b. The exterior fast mildew stains and to flaking. c. A section of the of the smoking port and has dropped at at the seam. d. A recent storm in sized limbs from the	of bedroom wing - there are ns along the bottom of the cia trim boards have black he paint is cracked and exterior fascia trim to the right ch has separated at the seamed turned inward leaving a gap has broken some substantially e pine trees at the parking lot. as splintered and broken and is				
C 162	Outside Premises-0	Outdoor Lighting	C 162			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING:	E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
	HAL007015		B. WING		04/26/2018	
NAME OF I	PROVIDER OR SUPPLIER	STREET ADI	DRESS, CITY, S	STATE, ZIP CODE		
PANTEG	O REST HOME	143 SWAM	_			
(X4) ID	SUMMARY STA	TEMENT OF DEFICIENCIES	D, NC 27860	PROVIDER'S PLAN OF CORRECTION	ON .	(X5)
PREFIX TAG		MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREFIX TAG	(EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)		COMPLETE DATE
C 162	Continued From pa	ge 3	C 162			
	illuminated by no le light at ground level	ss than five foot-candles of l.				
		et as evidenced by: vealed that the outdoor provided with illumination.				
	Findings on April 26, 2018: a. Rear exit - there were two exterior light fixtures at the back door. One of the fixtures did not have any bulbs and the second light fixture did not illuminate when the switch was flipped.					
C 164	Housekeeping and	Furnishings-Clean, Repaired	C 164			
	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities.					
	This Rule is not me 1. Observations re were not maintaine	vealed that the furnishings				
		5, 2018: or hardware is loose. oor hardware is loose.				
	2. Observations revealed that the walls were not maintained in good repair.					
	Findings on April 26, 2018: a. Women's bath - the wallpaper border over the					

6899

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:					DATE SURVEY COMPLETED	
		HAL007015	B. WING		04/2	26/2018
	NAME OF PROVIDER OR SUPPLIER STREET AD PANTEGO REST HOME 143 SWAI			STATE, ZIP CODE		
		PANTEGO), NC 27860			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETE DATE
C 164	Continued From pa	ge 4	C 164			
	window was torn ar	nd hanging from the wall.				
C 189	Building Equipment	Maintained Safe, Operating	C 189			
	mechanical, and plu care home shall be operating condition (k) This Rule shall facilities with the ex	11 OTHER d all fire safety, electrical, umbing equipment in an adult maintained in a safe and				
	equipment is not ma condition. Failure to equipment in opera	vation the facility's fire safety aintained in operating maintain fire safety ting condition could effect cility if the equipment did not				
	Findings on April 26 a. Kitchen - the hea was not secure to the	at detector in the left pantry				
	maintain the facility safe operating concompartment could doors do not compl	vation there is a failure to 's fire safety equipment in a dition. Occupants in the smoke be exposed to smoke or fire if etely close and latch to help smoke or fire to the area of				
		6, 2018: atch plate was missing from oor did not latch when closed.				

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLI A. BUILDING:	E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED		
HAL007015		B. WING		04/26/2018		
NAME OF I	PROVIDER OR SUPPLIER	STREET ADI	DRESS, CITY, S	TATE, ZIP CODE		
PANTEG	O REST HOME	143 SWAN PANTEGO	MP ROAD), NC 27860			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	.D BE	(X5) COMPLETE DATE
C 189	Continued From pa	ge 5	C 189			
	b. Room 15 - the la door would not clos	the door drags on the frame				
	maintain the buildin safe condition. Hole through fire resistar	vation there is a failure to g's fire safety systems in a es or gaps at penetrations at rated ceilings or walls could e to spread beyond the area				
	metal cover plate to previous door hards cover plate had shif This item was corre b. Room 6 - there i ceiling to the right o c. Laundry room - f	oor to the bedroom had a seal a hole where the ware penetrated the door. The fed leaving a hole in the door. ected at the time of survey. It is a 1" diameter hole in the fithe closet. There is an unsealed edryer unit where a conduit				
		vealed that the mechanical maintained in operating				
	Findings on April 26 a. Laundry room - 1 disconnected at the was corrected at the	the dryer duct was back of the dryer. This item				
	maintain electrical e equipment in safe of effect occupants of	vation the facility did not emergency/safety lighting operating condition. This could the facility if egress paths and inated during a power outage.				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 (X3) DAT CON		(X3) DATE COMI	OATE SURVEY OMPLETED	
		HAL007015	B. WING		04/	26/2018
	PROVIDER OR SUPPLIER	143 SWAI		STATE, ZIP CODE		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THI DEFICIENCY)	N SHOULD BE E APPROPRIATE	(X5) COMPLETE DATE
C 189	Findings on April 26	5, 2018: light outside of Room 1 did	C 189			

6899