Division of Health Service Regulation

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 C B. WING HAL099018 08/14/2023 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **409 HARRISON AVENUE** PATRIOT LIVING OF YADKINVILLE YADKINVILLE, NC 27055 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 Report of a Construction Section Complaint/Fire Investigation by Ed Miller, conducted on August 14, 2023. This facility was licensed on 10/06/1983 for (50) FIFTY BEDS. The facility is required to meet the 1977 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm, the 1978 NC State Building Code and the applicable portions of the current Rules for Adult Care Homes of Seven or More Beds The Complaint alleged that the facility had a fire. The complaint was substantiated. Deficiencies were cited that require a Plan of Correction. C 189 Building Equipment Maintained Safe, Operating C 189 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, and record review, the Fire Alarm system is not maintained in a safe and operating condition. This would affect all by not providing early detection and activation of the fire alarm system.

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Division of Health Service Regulation						
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED	
HAL099018		B. WING		C 08/14/2023		
NAME OF F	PROVIDER OR SUPPLIER	STREET ADI	DRESS, CITY, S	STATE, ZIP CODE		
PATRIOT LIVING OF YADKINVILLE 409 HARRISON AVENUE						
YADKINVILLE, NC 27055						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROINT DEFICIENCY)	JLD BE COMPLÉTE	
C 189	Continued From page 1		C 189			
	Bathroom near Bed was disassembled, in trouble.	it In Attic near Ladies froom 13 - the duct detector and the fire alarm system was eived on August 16, 2023				
C 199	9 Exhaust Ventilation		C 199			
	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation the facility failed to provide mechanical ventilation for required spaces. Findings on August 14, 2023: a. Ladies Bathroom near Bedroom 13 - The exhaust fan had been removed.					

6899

Division of Health Service Regulation STATE FORM