

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL002003</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>11/29/2023</b>
--	--	---	---

NAME OF PROVIDER OR SUPPLIER  <b>TAYLORSVILLE HOUSE</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>350 SCHOOL DRIVE TAYLORSVILLE, NC 28681</b>
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report of a Construction Section Biennial Survey by Tod Hancock, conducted on November 29, 2023.</p> <p>Records indicate this facility was first licensed on 11-26-1997, as a Special Care facility for 60 residents. Based on this information, the facility is required to meet the 1996 Rules for the Licensing of Adult Care Homes, the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds, and the 1996 Edition of the North Carolina State Building Code-Volume I-General Construction Section 409 Institutional Occupancies.</p> <p>Deficiencies were cited that require a Plan of Correction</p>	C 000	Responses to the cited deficiencies do not constitute an admission or agreement by the facility of the truth of facts alleged or conclusions set forth in the statement of deficiencies or corrective action report; the plan of correction is prepared solely as a matter of compliance of state law.	1/3/2024
C 188	<p>Electrical Outlets in Wet Locations</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters.</p> <p>This Rule is not met as evidenced by: 1. Based on observation the facility is not maintaining the electrical components located near a water source in a safe manner. Findings on November 29, 2023:</p> <p>a.200 Hall - Spa- The GFCI receptacle will not re-set after testing. b.200 Hall- Salon/Laundry- The receptacle behind the washing machine did not trip on test indicating the lack of ground fault protection.</p>	C 188	The facility will install new receptacles in both 200 Hall Spa and 200 Hall Salon/Laundry.	

Division of Health Service Regulation  
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

*Heather Lackey, CD*

TITLE

(X6) DATE

1/4/2024

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL002003</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>11/29/2023</b>
--	--	---	---

NAME OF PROVIDER OR SUPPLIER  <b>TAYLORSVILLE HOUSE</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>350 SCHOOL DRIVE TAYLORSVILLE, NC 28681</b>
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 1	C 199	Facility will install an exhaust fan in the 200 Hall Spa.	1/3/2024
C 199	<p>Exhaust Ventilation</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS</p> <p>(g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces:</p> <p>(1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area.</p> <p>(k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.</p> <p>This Rule is not met as evidenced by: 1. Based on observation, the facility is not maintaining its exhaust fan in an operable condition. This could cause unnecessary odors as well as mildew. Findings November 29, 2023: a. 200 Hall- Spa- The exhaust fan is not working.</p>	C 199		