

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL080024	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/27/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER LIBBY FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 4035 WOODLEAF-BARBER ROAD CLEVELAND, NC 27013
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report by Kelly Myers</p> <p>DHSR Construction Section conducted a Biennial Survey on November 27, 2023 from 1:10 PM to 2:05 PM at the above referenced facility. DHSR records indicate the home was first licensed on October 22, 2007 as a Family Care Home for three (3) ambulatory Residents (able to respond and evacuate without any physical or verbal assistance during a fire or other emergency.) Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes and the 2002 North Carolina State Building Code - Residential (One & Two Dwelling) - Section R101.2.</p> <p>NOTES:</p> <p>1.) At the time of our visit, we cited deficiencies that require an acceptable plan of correction. All deficiencies listed were discussed with on-site staff during the exit interview.</p> <p>2.) Take actions to correct all listed deficiencies, once completed provide verification in the form of photos, receipts, invoices, etc. for all work performed.</p> <p>The cited deficiencies are as follows:</p>	C 000		
C 169	<p>Fire Safety-Smoke Detectors</p> <p>SECTION .0300 - THE BUILDING 10A NCAC 13G .0316 FIRE SAFETY AND DISASTER PLAN (b) The building shall be provided with smoke detectors as required by the North Carolina State Building Code and U.L. listed heat detectors</p>	C 169		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL080024	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/27/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER LIBBY FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 4035 WOODLEAF-BARBER ROAD CLEVELAND, NC 27013
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 169	<p>Continued From page 1</p> <p>connected to a dedicated sounding device located in the attic and basement. These detectors shall be interconnected and be provided with battery backup. Note: Smoke detectors are required to be interconnected by this Rule. The application of the Rule permits the heat detectors to be interconnected with smoke detectors, but does not require it.</p> <p>This Rule is not met as evidenced by: 1. At the time of the survey it was observed that access to the attic was very limited to confirm the presence of a heat detector. This is not compliant with the rule. Take the necessary steps to confirm and verify that there is a heat detector in the attic that is hard wired and sounds at the device or is connected to another sounding device. Provide documentation such as pictures or an invoice as proof of the presence of a heat detector and the rating. The heat detector must be of a minimum 194 degrees fixed temperature or 135 degrees rate to rise.</p>	C 169		
C 172	<p>Fire Safety-Four Rehearsals</p> <p>SECTION .0300 - THE BUILDING 10A NCAC 13G .0316 FIRE SAFETY AND DISASTER PLAN (e) There shall be at least four rehearsals of the fire evacuation plan each year. Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, staff members present, and a short description of what the rehearsal involved.</p>	C 172		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL080024	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/27/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER LIBBY FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 4035 WOODLEAF-BARBER ROAD CLEVELAND, NC 27013
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 172	Continued From page 2 This Rule is not met as evidenced by: 1. At the time of the survey a live fire drill was performed. At the time one (1) resident was on-site. The one resident did not respond or evacuated when the alarm was sounded. The resident remained in her bedroom. This is not compliant with the rule. Take the necessary steps to train the residents to respond or evacuate at the sound of the smoke alarms and any resident that requires physical or verbal prompting and or assistance may need to be relocated to another facility to better accommodate their needs. 2. At the time of the survey it was observed that there is a client that requires prompting during fire drill rehearsals. This is not compliant with the rule. Take the necessary steps to train clients to respond to the sound of a smoke detector alarm any time that one is activated. The license for this home is for ambulatory clients which means they should be able to evacuate without verbal or physical assistance in the event of a fire emergency.	C 172		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL080024	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/27/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER LIBBY FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 4035 WOODLEAF-BARBER ROAD CLEVELAND, NC 27013
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	<p>Continued From page 3</p> <p>bedroom #1 doorknob is loose and it doesn't latch. This is not compliant with the rule. Take the necessary steps to secure the doorknob and adjust it so that it will latch and allow for privacy.</p> <p>2. At the time of the survey it was observed that bedroom #2 has a missing electrical cover just inside the door. This is not compliant with the rule. Take the necessary steps to install the electrical cover to prevent the potential for electrical shock.</p> <p>3. At the time of the survey it was observed that there is a broken receptacle cover in the closet under the right side window that has the potential to cause electrical shock. This is not compliant with the rule. Take the necessary steps to replace the broken receptacle cover.</p> <p>4. At the time of the survey it was observed that the light globe is missing at the closet light fixture in bedroom #3. Take the necessary steps to install a light globe.</p> <p>5. At the time of the survey it was observed that there is a triple plug adapter at the kitchen countertop to the right that is not UL rated. This is not compliant with the rule. Take the necessary steps to remove the adapter that is not UL rated.</p> <p>6. At the time of the survey it was observed that the rangehood fan was locked up and not spinning. This is not compliant with the rule. Take the necessary steps repair or replace the rangehood.</p> <p>7. At the time of the survey it was observed that the front bathroom by bedroom #1 is missing the faucet aerator and has a loose doorknob. This is not compliant with the rule. Take the necessary</p>	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL080024	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/27/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER LIBBY FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 4035 WOODLEAF-BARBER ROAD CLEVELAND, NC 27013
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	<p>Continued From page 4</p> <p>steps to repair the faucet and loose doorknob.</p> <p>8. At the time of the survey it was observed that the front bathroom by bedroom #1 has is loose at the base. This is not compliant with the rule. Take the necessary steps to secure the toilet at the base to prevent leaks that could be a slip hazard.</p> <p>9. At the time of the survey is was observed that there are multiple holes in the vinyl siding, corner trim and shutters. This is not compliant with the rule. Take the necessary step to repair or replace the damaged vinyl siding, corner trim and shutters.</p> <p>10. At the time of the survey it was observed that was a eye hook on the front storm door. This is not compliant with the rule. Take the necessary steps to remove the eye hook as it has the potential to impede egress in the event of an emergency.</p> <p>11. At the time of the survey it was observed that there are two window sills and trim on the left side that are rotting. This is not compliant with the rule. Take the necessary steps to repair or replace the rotting windowsill and trim.</p> <p>12. At the time of the survey it was observed that there is unfinished drywall in bedroom #3 in the closet area. This is not compliant with the rule. Take the necessary steps to repair the unfinished drywall.</p> <p>13. At the time of the survey there were several damaged pickets at the back deck/ramp. This is not compliant with the rule. Take the necessary steps to repair or replace the damaged pickets.</p>	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL080024	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/27/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER LIBBY FAMILY CARE HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 4035 WOODLEAF-BARBER ROAD CLEVELAND, NC 27013
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	<p>Continued From page 5</p> <p>14. At the time of the survey it was observed that the electrical wires at the top of the electric water heater are not properly secured. This is not compliant with the rule. Take the necessary steps to properly secure the wires so that there are no exposed wires.</p> <p>15. At the time of the survey it was observed that there was a torn storm door screen at the back door. This is not compliant with the rule. Take the necessary steps to replace or repair the torn screen to prevent pests from entering the home.</p>	C 174		