PRINTED: 10/06/2022 FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED								
			A. BUILDING:			,							
		MHL047-170	B. WING		09/2	9/2022							
NAME OF F	NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE												
SHARON LEAK AFL 255 CASTLE CREEKS DRIVE RAEFORD, NC 28376													
(X4) ID PREFIX TAG	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	(X5) COMPLETE DATE								
V 000	INITIAL COMMENTS		V 000										
		ow-up survey was completed 2022. A deficiency was cited.											
	This facility is licensed for the following service category: 10A NCAC 27G .5600F Supervised Living: Alternative Family Living in a Private Residence.												
		sed for 1 and currently has a urvey sample consisted of 1											
V 752	27G .0304(b)(4) Ho	ot Water Temperatures	V 752										
	EQUIPMENT (b) Safety: Each factoristructed and equensures the physical visitors. (4) In areas of exposed to hot wat	acility shall be designed, juipped in a manner that all safety of clients, staff and of the facility where clients are er, the temperature of the stained between 100-116 t.											
	failed to maintain th	et as evidenced by: ion and interviews the facility ne facility water temperature legrees Fahrenheit. The											
	approximately 10:0 -The kitchen sink w degrees Fahrenhei	vater temperature was 122 t. r temperature was 118											

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE TITLE

PRINTED: 10/06/2022 FORM APPROVED

Division of Health Service Regulation

NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE SHARON LEAK AFL 255 CASTLE CREEKS DRIVE RAEFORD, NC 28376 (X4) ID PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) V 752 Continued From page 1 Interview with the Alternative Family Living Provider on 9/29/22 revealed: -She did not realize the water temperature was over 120 degreesShe recently had the water adjustedShe did not know what the right temperature was to have. She was not aware that the water temperature needed to be under 116 degrees FahrenheitIt took a long time for warm water to reach client #1's bathroom and it would not be very warmClient #1 was able to regulate his own water.	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED							
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 255 CASTLE CREEKS DRIVE RAEFORD, NC 28376 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) V 752 Continued From page 1 Interview with the Alternative Family Living Provider on 9/29/22 revealed: -She did not realize the water temperature was over 120 degreesShe recently had the water adjustedShe did not know what the right temperature was to have. She was not aware that the water temperature needed to be under 116 degrees FahrenheitIt took a long time for warm water to reach client #1's bathroom and it would not be very warmClient #1 was able to regulate his own water.			MIII 047 470			1							
SHARON LEAK AFL 255 CASTLE CREEKS DRIVE RAEFORD, NC 28376 (X4) ID PREFIX TAG SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) V 752 Continued From page 1 Interview with the Alternative Family Living Provider on 9/29/22 revealed: -She did not realize the water temperature was over 120 degreesShe recently had the water adjustedShe did not know what the right temperature was to have. She was not aware that the water temperature needed to be under 116 degrees FahrenheitIt took a long time for warm water to reach client #1's bathroom and it would not be very warmClient #1 was able to regulate his own water.						09/2	9/2022						
CX4) ID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREFIX TAG TAG PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DATE DATE V 752													
PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) V 752 Continued From page 1 Interview with the Alternative Family Living Provider on 9/29/22 revealed: -She did not realize the water temperature was over 120 degreesShe recently had the water adjustedShe did not know what the right temperature was to have. She was not aware that the water temperature needed to be under 116 degrees FahrenheitIt took a long time for warm water to reach client #1's bathroom and it would not be very warmClient #1 was able to regulate his own water.	SHARON LEAK AFI												
Interview with the Alternative Family Living Provider on 9/29/22 revealed: -She did not realize the water temperature was over 120 degreesShe recently had the water adjustedShe did not know what the right temperature was to have. She was not aware that the water temperature needed to be under 116 degrees FahrenheitIt took a long time for warm water to reach client #1's bathroom and it would not be very warmClient #1 was able to regulate his own water.	PRÉFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETE						
-She would have someone come to the house to adjust the hot water to be bellow 116 degrees Fahrenheit. -She confirmed the facility failed to maintain the facility water temperature between 100-116 degrees Fahrenheit.	V 752	Interview with the A Provider on 9/29/22 -She did not realize over 120 degreesShe recently had the She did not know with to have. She was not temperature needer FahrenheitIt took a long time #1's bathroom and -Client #1 was able -She would have so adjust the hot water FahrenheitShe confirmed the facility water tempe	Alternative Family Living 2 revealed: 2 the water temperature was 3 the water adjusted. 3 what the right temperature was 3 to aware that the water 3 to be under 116 degrees 4 for warm water to reach client 5 it would not be very warm. 6 to regulate his own water. 6 period to be bellow 116 degrees 6 facility failed to maintain the 6 trature between 100-116	V 752									

6899

Division of Health Service Regulation STATE FORM

4NRR11 If continuation sheet 2 of 2