

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>MHL0411211</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>02/29/2024</b>
NAME OF PROVIDER OR SUPPLIER  <b>MCCRARY HOME</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>721 PARAMOUNT STREET HIGH POINT, NC 27260</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	INITIAL COMMENTS  An annual survey was completed on 2/29/24. A Deficiency was cited.  This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disability.  This facility is licensed for 4 and currently has a census of 3. The survey sample consisted of audits of 3 current clients.	V 000		
V 736	27G .0303(c) Facility and Grounds Maintenance  10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.  This Rule is not met as evidenced by: Based on observation and interview the facility was not maintained in a clean and attractive manner. The findings are.  Observation of the facility on 2/27/24 at 12:15pm revealed: -One outside lawn chair placed at the kitchen table for clients. -Two broken slats in the mini blinds in Client #1's bedroom window. -Hallway bathroom shower/tub had 1.5 feet of black residue at the bottom and 6 inches of black residue along the side of the tub wall. -Hallway bathroom had two ½ dollar size peeling damage to the popcorn ceiling by the ventilation system. - Client #3's bedroom window had 4 broken slats in the mini blinds.	V 736		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>MHL0411211</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>02/29/2024</b>
NAME OF PROVIDER OR SUPPLIER  <b>MCCRARY HOME</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>721 PARAMOUNT STREET HIGH POINT, NC 27260</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	<p>Continued From page 1</p> <p>-Client #3's bed was not attached to the bed frame on the floor; also another boxspring and mattress were on the floor in the room.</p> <p>-Hallway smoke detector chirped approximately every 30 seconds.</p> <p>Interview on 2/28/24 with client #3 revealed:</p> <p>-Bed had been broken "for a long time."</p> <p>-Did not break the other bed in the room, the other client that left did.</p> <p>Interview on 2/27/24 with staff #1 revealed:</p> <p>-Client #3's bed had been without a frame for at least 3 weeks.</p> <p>-"he (Client #3) is a big guy...he just breaks his beds."</p> <p>Interview on 2/29/24 with the Owner revealed:</p> <p>-"The tub had stains from day one ....the stain will not come out."</p> <p>-The battery needed to be replaced in the smoke detector.</p> <p>-Client #3 "just breaks his beds" .... "he is going to break it every time."</p> <p>-The clients "like to look out the windows and break the mini blinds, they (clients) are destructive."</p> <p>-The "popcorn" ceiling will be getting replaced very soon.</p> <p>-"I will be purchasing kitchen chairs today!"</p>	V 736		