

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL096-088	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 04/25/2024
--	---	---	---

NAME OF PROVIDER OR SUPPLIER TINDERWOOD	STREET ADDRESS, CITY, STATE, ZIP CODE 102 TINDERWOOD DRIVE GOLDSBORO, NC 27534
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual survey was completed on April 25, 2024. A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disabilities.</p> <p>This facility is licensed for 3 and currently has a census of 3. The survey sample consisted of audits of 3 current clients.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT</p> <p>(b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors.</p> <p>(4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interview the facility failed to maintain the water temperature between 100-116 degrees Fahrenheit. The findings are:</p> <p>Observation on 04/24/24 at approximately 11:57am revealed:</p> <ul style="list-style-type: none"> - The hot water temperature in the kitchen sink was 122 degrees Fahrenheit. - The hot water temperature in the client bathroom was 122 degrees Fahrenheit. <p>Interview on 04/24/24 the Residential Supervisor stated:</p>	V 752		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL096-088	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 04/25/2024
--	---	---	---

NAME OF PROVIDER OR SUPPLIER TINDERWOOD	STREET ADDRESS, CITY, STATE, ZIP CODE 102 TINDERWOOD DRIVE GOLDSBORO, NC 27534
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	<p>Continued From page 1</p> <ul style="list-style-type: none"> - Staff check the hot water temperature in the facility. - He understood the hot water temperature was to high. - he would forward the concern to maintenance for follow up. <p>Interview on 04/25/24 the Human Resources Director stated she understood the hot water temperature was required to be between 100 and 116 degrees Fahrenheit.</p>	V 752		