STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER: MHL079-110			(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED	
		B. WING		07	07/03/2024	
NAME OF PF	ROVIDER OR SUPPLIER	STREET A	ADDRESS, CITY, STATE	, ZIP CODE		
BRENTWO	OOD MANOR		ENTWOOD DRIVE ILLE, NC 27320			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIEN	ACTION SHOULD BE COMPL TO THE APPROPRIATE DAT	
V 000	INITIAL COMMENTS		V 000			
	An annual and follow up survey was completed on July 3, 2024. A deficiency was cited.					
	This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disability.					
	•	d for 6 and has a current vey sample consisted of ents.				
V 736	27G .0303(c) Facility	and Grounds Maintenance	V 736			
		EMENTS				
		-				
	1:08 pm revealed: -The doorbell cover a cracked.					
	were missing toilet ta -The wall at the edge	and 2nd client bathrooms nk tops. of the shelves above the 2nd client bathrooms had				
	-Client #2's bedroom unpainted areas on th and purple squares a	ne wall below the red, green,				

Division of Health Service Regu STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CO		(X3) DATE SURVEY COMPLETED	
			A. BUILDING:			
	MHL079-110		B. WING		07	7/03/2024
NAME OF PI	ROVIDER OR SUPPLIER	STREET A	ADDRESS, CITY, STATE,	ZIP CODE		
BRENTWO	DOD MANOR		ENTWOOD DRIVE			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN ((EACH CORRECTIVE A CROSS-REFERENCED TO DEFICIE	ACTION SHOULD BE COMF TO THE APPROPRIATE DA	
V 736	Continued From page	e 1	V 736			
	stored adult incontine approximately 5"x 5" unpainted. -Client #5's window in unfolded paper cardit bottom part of his wir -Client #5 had a plass his wall beside a ham plastered and unpain 8"x 13" in size with a crack in the middle o -A square-shaped pio missing on one of Cli bedroom. -There was a separa frame and the hallwa -The shower floor in which was a standup broken floor pieces a brown and black colo edges of the shower pieces of various size shower floor. -A bottom white right the 2nd client bathroo semi-circular pattern substance in the crace that made streaks do Review on 7/2/24 reve -Client #5 became up him he had one hour went to his room, sta and Client #5 continu window until the wind bleeding of Client #5 to a medical facility for	ence pullups had an area that was plastered and in his bedroom had an board box that covered the hdow. tered and unpainted area on id sanitizer poster. The ited area was approximately in exposed semi-circular if this area. ece of wainscoting was tent #5's walls in his tion between Client #5's door y wall. the 2nd client bathroom, is shower, had at least 3 round the water drain with a ored substance around the floor with at least 75-100 is debris at the front of the corner shelf of the shower in om was cracked in a and had brown and black ck and a brown substance own the shower surround. facility incident reports from				

6899

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: B. WING			(X3) DATE SURVEY COMPLETED	
	MHL079-110				07/03/2024		
NAME OF PI	ROVIDER OR SUPPLIER	STREETA	DDRESS, CITY, STATE,	ZIP CODE			
BRENTWO	DOD MANOR		ILLE, NC 27320				
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN ((EACH CORRECTIVE A CROSS-REFERENCED TO DEFICIE	CTION SHOULD BE D THE APPROPRIATE	(X5) COMPLET DATE	
V 736	Continued From page 2		V 736				
	Response and Improvement System (IRIS).						
	Preventive Maintenan 2024 through July 20 -The reports were co House Manager. -January 2024, "show in shower wall." -May 2024, "shower is hole in wall. Water is in shower. -July 2024, shower w peeling." Interviews on 7/2/24 revealed:	mpleted and signed by the wer floor peeling. Rusty holes in handicap bathroom has staying in hole floor, peeling vall has a hole in it and is with Clients #1, #2 and #3 ble to answer questions					
	Manager revealed: -She was aware that front door remained of -The toilet tank cover clients such as Client tendency to pick up t them and the landlor only to have the tank -The paint was peelir the bathroom shelves and needed repaintin -On 6/3/24, Client #5 by hitting the window parents were getting the window replaced update about 2 days -Client #5 punched h	rs were removed because t #2, #4 and #5 had a he tank covers and shatter d had kept replacing them covers broken again. ng away from the wall above s in both client bathrooms ng. broke his bedroom window with his fist. Client #5's cost quotes to pay and have . The Licensee gave her this					

STATEMENT OF DEFICIENCIES (X AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:			(X3) DATE SURVEY COMPLETED	
		MHL079-110	B. WING		07	7/03/2024	
IAME OF P	ROVIDER OR SUPPLIER	STREET A	ADDRESS, CITY, STATE,	ZIP CODE			
BRENTW	OOD MANOR		ENTWOOD DRIVE ILLE, NC 27320				
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN C (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIEN	ACTION SHOULD BE COM TO THE APPROPRIATE D		
V 736	Continued From page 3		V 736				
	-She had been conce the clients' 2nd bathr -All the clients who liv that 2nd bathroom sh walk-in shower. No c because of the broke existed for harm to or mold buildup around -The inspector for the of the 2nd bathroom (7/2/24) but she did r going to be done to r -She submitted her rr to the Licensee and t made aware of the co Interview on 7/3/24 w revealed: -"We are aware of it (bathroom) and we ar -He did not know a til would be started on t	ved there preferred to use hower because it was a lient had been harmed yet in shower floor but potential ccur to their feet and the the shower's floor areas. e landlord saw the conditions shower on the previous day not know if anything was epair the shower. nonthly maintenance report the landlord, so both were condition of the shower. with the landlord's inspector (the shower in the 2nd client e going to fix it." meframe for when the repair the shower. he shower.					