

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL047-158	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/12/2025
NAME OF PROVIDER OR SUPPLIER CANYON HILLS TREATMENT FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 769 ABERDEEN ROAD RAEFORD, NC 28376		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual and complaint survey was completed on June 12, 2025. The complaint (intake #NC00229869) was unsubstantiated. A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G. 1900. PRTF-Psychiatric Residential Treatment Facility for Children and Adolescents.</p> <p>This facility is licensed for 24 and currently has a census of 24. The survey sample consisted of audits of 3 current clients.</p>	V 000		
V 736	<p>27G .0303(c) Facility and Grounds Maintenance</p> <p>10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.</p> <p>This Rule is not met as evidenced by: Based on observation and interviews, the facility was not maintained in a safe, clean and attractive manner. The findings are:</p> <p>Observation on 6/10/25 at 12:15 p.m. of the facility revealed: Unit A: -Laminate slats about 7x 60 were detached in the hallway. -1st bedroom to the left - slats missing in front of the bedroom door. -2nd bedroom to the left - slats were missing in front of the door into the room. -4th bedroom to the left - slats missing the bedroom door and tile was missing from the front</p>	V 736		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL047-158	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/12/2025
NAME OF PROVIDER OR SUPPLIER CANYON HILLS TREATMENT FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 769 ABERDEEN ROAD RAEFORD, NC 28376		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	<p>Continued From page 1</p> <p>of the door into the room.</p> <p>-Common area: laminate slats about 7x60 were detached from the floor throughout the room.</p> <p>Unit B:</p> <p>-1st bedroom to the left - laminate slats were detached running from the hallway to the bedroom.</p> <p>-1st bedroom to the right - bedroom door wood was peeling.</p> <p>-2nd bedroom door to the left was missing the doorknob.</p> <p>-Common area: laminate slats about 7x60 detached from the floor - two on the right side and two on the left side of the room.</p> <p>Interview on 6/12/25 with the Program Director revealed:</p> <p>-She would speak with the Chief Executive Officer to inform him of the findings.</p> <p>-She would meet with maintenance staff to have the floor replaced.</p> <p>-There were plans to move within 30 days to a new location.</p>	V 736		