

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL029-006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 03/25/2026
--	---	---	---


NAME OF PROVIDER OR SUPPLIER PATH OF HOPE	STREET ADDRESS, CITY, STATE, ZIP CODE 1675 EAST CENTER STREET EXTENSION LEXINGTON, NC 27292
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

V 000	<p>INITIAL COMMENTS</p> <p>An annual and follow up survey was completed on 3/25/26. A deficiency was cited.</p> <p>This facility is licensed for the following service categories: 10A NCAC 27G .3400 Residential Treatment for Substance Abuse Adults; 10A NCAC 27G.3700 Day Treatment for Individuals for Substance Abuse Individuals; 10A NCAC 27G .4400 Substance Abuse Intensive Outpatient Program, and 10A NCAC 27G .4500 Substance Abuse Comprehensive Outpatient Treatment Program.</p> <p>This facility is licensed for 12 and has a current census of 10. The 10A NCAC 27G .3400 Residential Treatment/Rehabilitation for Individuals with Substance Abuse Disorders has a current census of 10, the 10A NCAC 27G .3700 Day Treatment Facilities for Individuals with Substance Abuse Disorders has a current census of 0, the 10A NCAC 27G .4400 Substance Abuse Intensive Outpatient Program (SAIOP) has a current census of 0, and the 10A NCAC 27G .4500 Substance Abuse Comprehensive Outpatient Treatment Program (SACOT) has a current census of 0.</p> <p>The survey sample consisted of audits of 3 current clients in the 10A NCAC 27G .3400 Residential Treatment/Rehabilitation for Individuals with Substance Abuse Disorders.</p>	V 000	<p>We have implemented a new position, Director of Residential Operations, [REDACTED] She will be responsible for performing monthly safety inspections of all residential houses, to ensure that they meet required guidelines.</p>	
V 736	<p>27G .0303(c) Facility and Grounds Maintenance</p> <p>10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive</p>	V 736		

RECEIVED
APR 15 2026
DHSR-MH Licensure Sect

RECEIVED
APR 15 2026
DHSR-MH Licensure Sect

Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE 	TITLE Director of Operations	(X6) DATE 4/9/2026
---	---------------------------------	-----------------------

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL029-006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED R 03/25/2026
NAME OF PROVIDER OR SUPPLIER PATH OF HOPE			STREET ADDRESS, CITY, STATE, ZIP CODE 1675 EAST CENTER STREET EXTENSION LEXINGTON, NC 27292		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
V 736	Continued From page 1 odor. This Rule is not met as evidenced by: Based on observation and interview, the facility was not maintained in a safe, clean, attractive and orderly manner. The findings are: Observation on 3/25/26 at 10:43 am of the facility revealed: - In the second living room, the seat on the end of a plaid fabric sofa was broken. The end table beside the damaged portion of the sofa was unstable. - In the dining room, all twelve chairs used for seating were in disrepair. The padded stackable chairs had cuts in the vinyl covering, exposing the padding. The plastic chairs were missing fasteners required to secure the seat to the metal frame. A rolling office chair was also observed to be unstable. TV's bottom base was broken that sat on a dresser. - In the main floor bathroom, the toilet was not secured (bolted) to the floor. The walls surrounding the shower had flaking plaster consistent with damage from a previously installed shower door frame. - At the top of the stairs, the door leading into the bedroom areas was propped open with two books. - In Bedroom #1, the walls had large gashes in the plaster. Capped electrical wires were observed protruding from the wall. - In the upstairs bathroom, one of the two toilets was continuously running. The smaller shower stall contained a loose section of an old shower door panel. The ceiling vent was covered in orange residue and had peeling paint. The exhaust vent contained a buildup of thick dust. - In Bedroom #3, the vent register was covered in orange residue and the paint was flaking. Two	V 736	The sofa has been discarded. Table repaired. The padded chairs have been replaced. Bolts have been added to secure seating area on plastic chairs. Office chair has been discarded. TV has been replaced. ACME Plumbing replaced flange and bolts to secure toilet. Plaster will be redone and painted. Books were removed and sign placed on door to remain closed. Plaster will be redone and painted. Wall plate was installed to cover wires. ACME Plumbing replaced fill valve and handle, toilet is no longer running. Loose section removed from shower.	4/8/26 4/8/26 4/9/26 4/9/26 4/8/26 4/9/2026 4/8/26	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL029-006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 03/25/2026
NAME OF PROVIDER OR SUPPLIER PATH OF HOPE		STREET ADDRESS, CITY, STATE, ZIP CODE 1675 EAST CENTER STREET EXTENSION LEXINGTON, NC 27292		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	Continued From page 2 of the screen outside of the window were broken at the top and base of the screens. - In the upstairs hallway, the HVAC return vent on the ceiling had a visible accumulation of thick dust on the grates. - In Bedroom #5, a dresser was missing a drawer, which was observed lying on the floor. This deficiency constitutes a re-cited deficiency and must be corrected within 30 days.	V 736	Ceiling vent in bathroom replaced. Exhaust fan vent cleaned, Bedroom 3 vent replaced. Screens removed and discarded. HVAC return vent cleaned. Drawer will be repaired or dresser replaced if unable to repair.	4/9/26 4/9/26 4/9/26 4/8/26 4/8/26 within 30 days