Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	MHL064-145	A. BUILDING: _____ B. WING _____	R 02/07/2019

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
BETTER DAYS AHEAD GROUP HOME #6	501 CASCADE AVENUE ROCKY MOUNT, NC 27803

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	INITIAL COMMENTS An annual and follow up survey was completed on 2/7/19. A deficiency was cited. The facility is licensed for the following service category 10A NCAC .27G 5600C Supervised Living for Developmentally Disabled Adult.	V 000		
V 736	27G .0303(c) Facility and Grounds Maintenance 10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor. This Rule is not met as evidenced by: Based on observation and interviews the facility failed to ensure the home was maintained in a safe, attractive manner. The findings are: Observation on 2/7/19 at 12:30 PM revealed the following: -Kitchen floor appeared to be sinking in front of the sink. -Bathroom floor tile was broken and coming apart around vent in the floor. -Client bedrooms throughout dresser drawers were broken and off tracks. During interview on the Qualified Professional (QP) stated: -Had not been in the home in a while to check on things. -"Its my fault, I take full responsibility for not checking in to make sure repairs are completed."	V 736		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	MHL064-145	A. BUILDING: _____ B. WING _____	R 02/07/2019

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
BETTER DAYS AHEAD GROUP HOME #6	501 CASCADE AVENUE ROCKY MOUNT, NC 27803

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	Continued From page 1 During interview on 2/7/19 the Licensee stated: -Had a repair guy to come out to the homes to repair things. -Had not followed up to make sure he completed requested repairs. -Need to make sure all repairs are completed as requested before payment rendered.	V 736		