Division of Health Service Regulation						
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA			(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:	A. BUILDING: <b>01</b>		COMPLETED	
					R	
HAL045092		B. WING		05/14/2015		
NAME OF PROVIDER OR SUPPLIER STREET ADDR				STATE ZID CODE		
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE  1825 PISGAH DRIVE						
SPRING ARBOR WEST  HENDERSONVILLE, NC 28791						
·						
(X4) ID PREFIX	FIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL		(X5) COMPLETE
TAG			TAG	CROSS-REFERENCED TO THE APPROPRIATE		DATE
				DEFICIENCY)		
ነር በበበነ	0) Initial Comments		{C 000}			
(000 0)	of initial comments		[0 000]			
	Report of Follow-up Survey by Dennis Harrell on 5-14-2015.					
	Some deficiencies were not corrected. Further action is required.					
{C 189}	C 189 Building Equipment Maintained Safe, Operating		{C 189}			
	OFOTION COOK BUNGLON BUNKT					
	SECTION .0300 - PHYSICAL PLANT					
	10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical,					
	mechanical, and plumbing equipment in an adult					
	care home shall be maintained in a safe and					
	operating condition.					
	(k) This Rule shall apply to new and existing					
	facilities with the exception of Paragraph (e)					
	which shall not apply to existing facilities.					
	This Duly is not not so widened by					
	This Rule is not met as evidenced by:					
	1. Based on observation the required one-hour fire rated walls and/or ceilings were compromised in several locations. Holes, sleeves and penetrations that are not sealed with materials approved for use in one-hour fire rated construction present the possibility that a fire that begins in one space can quickly spread to other areas of the facility.  Findings include:  c. Hole in the attic smoke barrier wall above 200 Hall,  e. The sprinkler escutcheons were missing or not tightly fitted to the ceiling complete the one-hour protection in the following locations;					
	i. Sunroom,	lowing locations,				
	i. Guilloull,					

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE TITLE