

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL021009</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>05/04/2017</b>
NAME OF PROVIDER OR SUPPLIER  <b>EDENTON HOUSE</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>323 MEDICAL ARTS DRIVE EDENTON, NC 27932</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments  Construction Section Biennial Survey report by Frank Strickland on 05/04/2017:  This facility was licensed on 06/28/2007 as a Home for the Aged (HA) housing sixty beds. Therefore, this facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds, applicable portions of the 2002 Edition of the North Carolina Building Code(s), Section 407-Group I-2.  Deficiencies have been cited and a Plan of Correction is required.	C 000		
C 164	Housekeeping and Furnishings-Clean, Repaired  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1-Based on observations, this facility has failed to maintain the interior finishes.  Findings on 05/04/2017: The following interior doors have scratches and veneer damage due to wheelchair interaction: (a) Room 113 (b) Room 114 (c) Room 115 (d) Room 206	C 164		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL021009</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>05/04/2017</b>
NAME OF PROVIDER OR SUPPLIER  <b>EDENTON HOUSE</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>323 MEDICAL ARTS DRIVE EDENTON, NC 27932</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 1  (e) Room 208 (f) Room 210  2-Based on observations, this facility has not maintained in a safe the securement of the corridor handrails. This could affect residents by disrupting grasping support for stability of a resident.  Findings on 05/04/2017: The corridor handrail is not secured to the wall accross the hall from the 300 Hall Nurse's Station.  3-Based on observations, this facility has failed to keep clean HVAC distribution grilles free of dust and other particulates.  Findings on 05/04/2017: The Staff Bathroom in the 300 Hall has a return air grille that is clogged with dust and particulates.	C 164		
C 166	Housekeeping-Maintained Free of Hazards  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1-Based on observation, the facility has not maintained in a safe manner by improper storage of oxygen cyclinders. This could affect all residents and staff by potentially exposing them	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL021009</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>05/04/2017</b>
NAME OF PROVIDER OR SUPPLIER  <b>EDENTON HOUSE</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>323 MEDICAL ARTS DRIVE EDENTON, NC 27932</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 2  to hazards for a ruptured ruptured cyclinder.  Findings on 05/03/2017: There are oxygen bottles not stored in approved racks in the 300 Hall Med Room.	C 166		
C 189	Building Equipment Maintained Safe, Operating  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.  This Rule is not met as evidenced by: 1-Based on observations, the facility fire protection equipment has not been maintained in a safe manner.  Findings on 05/04/2017: The sprinkler head escutcheon is not in place that is located in the closet at Room 206.	C 189		