

1/18/2024

To: Jod Hancock

From: Heritage Care of Rocky Mount

pages: 4 includes this page

PRINTED: 01/11/2024
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL033005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/13/2023
--------------------------------------------------	----------------------------------------------------------------------------	---------------------------------------------------------------------------	-----------------------------------------------------

NAME OF PROVIDER OR SUPPLIER
HERITAGE CARE OF ROCKY MOUNT

STREET ADDRESS, CITY, STATE, ZIP CODE
**1650 COKEY ROAD
ROCKY MOUNT, NC 27801**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report of a Construction Section Biennial Survey conducted by Tod Hancock on December 13, 2023.</p> <p>Records indicate this facility was first licensed or submitted on August 1, 1981, as a Home for the Aged. The facility is currently licensed for 126 Beds. Therefore, this facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds, the 1977 Minimum Standards and Regulations for Homes for the Aged in effect at time of initial licensure and the 1978 (Revision 3) Edition of the North Carolina State Building Code, I-2 Institutional Occupancy.</p> <p>Deficiencies were cited and a Plan of Correction is required.</p>	C 000		
C 188	<p>Electrical Outlets in Wet Locations</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters.</p> <p>This Rule is not met as evidenced by: 1. Based on observation the facility is not maintaining the electrical components located near a water source in a safe manner. Findings on December 13, 2023:</p> <p>a. A Hall-Community Bath- The receptacle adjacent to the lavatory did not trip on test indicating the lack of ground fault protection. b. Middle Hall-Men's and Women's Bath- The receptacle adjacent to the lavatory did not trip on</p>	C 188	<p><i>Repaired/replaced</i></p> <p><i>Repaired/replaced</i></p>	<p><i>1/15/2024</i></p> <p><i>1/15/2024</i></p>

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Bobbie Williams

TITLE

Administrator

(X6) DATE

1/18/2024

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL033005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 12/13/2023
--------------------------------------------------	----------------------------------------------------------------------------	----------------------------------------------------------------------------	-----------------------------------------------------

NAME OF PROVIDER OR SUPPLIER HERITAGE CARE OF ROCKY MOUNT	STREET ADDRESS, CITY, STATE, ZIP CODE 1650 COKEY ROAD ROCKY MOUNT, NC 27801
-------------------------------------------------------------------------	-------------------------------------------------------------------------------------------

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	------------------------------------------------------------------------------------------------------------------------	---------------	-----------------------------------------------------------------------------------------------------------------	--------------------

C 199	<p>Continued From page 2</p> <p>two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces:</p> <ul style="list-style-type: none"> (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. <p>(k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <p>1. Based on observation, the facility is not maintaining its exhaust fan in an operable condition. This could cause unnecessary odors as well as mildew.</p> <p>Findings December 13, 2023:</p> <p>a. C- Hall- Community Shower- The exhaust fan is not working.</p>	C 199	<p>Repaired</p> <p>For all the above the areas will be checked monthly to ensure in proper working order</p>	1/19/2024
-------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------	--------------------------------------------------------------------------------------------------------------	-----------