Division of Health Service Regulation

| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 | | (X3) DATE SURVEY COMPLETED | |
|--|--|--|--|---|-------------------------------|--------------------------|
| | | | A. BOILDING. | | F | , |
| HAL068025 | | B. WING | | 02/28/2024 | | |
| NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE | | | | | | |
| THE STRATFORD 405 SMITH LEVEL ROAD CHAPEL HILL, NC 27516 | | | | | | |
| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | | (X5) COMPLETE DATE |
| {C 000} | Initial Comments | | {C 000} | | | |
| | Report of a Biennial Follow Up Construction Survey by Ryan Meyer, conducted on February 28, 2024. | | | | | |
| | All deficiencies hav action required. | e been corrected. No further | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE