

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL0601402	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 11/07/2019
--	---	---	---

NAME OF PROVIDER OR SUPPLIER LEWIS HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 7621 KUCK ROAD MINT HILL, NC 28227
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual survey was completed on 11/7/19. A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .5600F Alternative Family Living.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT</p> <p>(b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors.</p> <p>(4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observations and interviews, the facility failed to ensure in areas of the facility where clients were exposed to hot water, the temperature of the water was maintained between 100-116 degrees Fahrenheit. The findings are:</p> <p>Observation on 11/7/19 at 3:50pm revealed the following: -hot water temperature in the kitchen sink was 121 degrees Fahrenheit; -hot water temperature in the bathroom sink was 127 degrees Fahrenheit.</p> <p>Interview on 11/7/19 with the Qualified Professional revealed:</p>	V 752		

Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
--	-------	-----------

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL0601402	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 11/07/2019
--	---	---	---

NAME OF PROVIDER OR SUPPLIER LEWIS HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 7621 KUCK ROAD MINT HILL, NC 28227
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	<p>Continued From page 1</p> <ul style="list-style-type: none"> - no incident reports on client #1 or client #2; -no emergency room visits or injuries to client #1 and client #2. <p>Interview on 11/7/19 with staff #1 revealed:</p> <ul style="list-style-type: none"> -had tried to adjust hot water temperature to meet the requirements; -not sure why it was too hot; -last time was checked it was within the required range; -will adjust hot water tank temperature to meet the required range immediately. . 	V 752		