

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL081-109	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED C 10/16/2020
--	---	---	---

NAME OF PROVIDER OR SUPPLIER PEACE IN THE CITY	STREET ADDRESS, CITY, STATE, ZIP CODE 724 THOMPSON ROAD RUTHERFORDTON, NC 28139
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>A complaint survey was completed on 10/16/20. The complaint was unsubstantiated. (Intake ID# NC168917) A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .1700 Residential Treatment Staff Secure for Children or Adolescents.</p>	V 000		
V 736	<p>27G .0303(c) Facility and Grounds Maintenance</p> <p>10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.</p> <p>This Rule is not met as evidenced by: Based on observation, record review and interviews the facility failed to be maintained in a safe, clean, attractive, orderly manner. The findings are:</p> <p>Observation on 10/15/20 at approximately 10:30am of the facility interior revealed: -2 large (2 foot by 3 foot) dry wall patches in the common area on the wall behind the TV and 1 large dry wall patch on the left inside wall. -Down the hall, to the right was another bedroom with 1 twin bed. 8 smaller (1 foot by 1 foot) dry wall patches covered all 4 walls. -The shared bathroom off of the kitchen had multiple switches on the wall but did not turn any light or fan on. 1 switch had a broken face plate.</p>	V 736		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL081-109	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED C 10/16/2020
--	---	---	---

NAME OF PROVIDER OR SUPPLIER PEACE IN THE CITY	STREET ADDRESS, CITY, STATE, ZIP CODE 724 THOMPSON ROAD RUTHERFORDTON, NC 28139
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	<p>Continued From page 1</p> <p>-The 3rd bedroom off the kitchen also had 1 twin bed. The door to this room was broken and cracked in the center of the door about 12 inches long and 12 inches wide.</p> <p>Interview on 10/15/20 with the Director revealed: -had a maintenance person who would immediately take care of painting and electrical in the house. -had multiple issues with that rental house and were looking at the options to move to another house.</p>	V 736		