PRINTED: 04/28/2022 FORM APPROVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL054-176			(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED		
		B. WING		04	04/18/2022		
iame of Pf	ROVIDER OR SUPPLIER	STREET	DDRESS, CITY, STATE, ZIP CODE				
ARNES	GROUP HOMES LLC		LEY ROAD N, NC 28504				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO DEFICIENC	TION SHOULD BE THE APPROPRIATE		
∨ 000	INITIAL COMMENTS		V 000				
	An annual survey was completed on April 18, 2022. A deficiency was cited.						
	This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disabilities.						
		d for 6 and currently has a vey sample consisted of ents.					
V 752	27G .0304(b)(4) Hot	Water Temperatures	V 752				
	 10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT (b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors. (4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit. 						
	water temperatures v 100-116 degrees Fat	as evidenced by: n and interview, the facility vere not maintained between nrenheit in areas where to hot water. The findings					
	Observation on 4/18/ 10:00am revealed: -The hot water tempe was 123 degrees Fal	erature at the kitchen sink					
	-	the Qualified Professional					

PRINTED: 04/28/2022 FORM APPROVED

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING:		(X3) DATE SURVEY COMPLETED	
		MHL054-176	B. WING		04/18/2022	
AME OF PI	ROVIDER OR SUPPLIER	STREET	ADDRESS, CITY, STATE	, ZIP CODE		
ARNES	GROUP HOMES LLC		LEY ROAD N, NC 28504			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIEN	CTION SHOULD BE COMPLET D THE APPROPRIATE DATE	
V 752	Continued From page 1		V 752			
	- He would follow up of water temperature	to ensure the proper range was maintained.				