Division of Health Service Regulation

(X1) PROVIDER/SUPPLIER/CLIA

STATEMENT OF DEFICIENCIES

STATEMENT OF DEFICIENCIES (X AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING:			(X3) DATE SURVEY COMPLETED						
			A. BUILDING	o:								
		mhl010-057	B. WING		R <b>02/16/2024</b>							
NAME OF I	PROVIDER OR SUPPLIER	STREET AL	DRESS, CITY,	STATE, ZIP CODE								
THE TRINITY HOME 1117 OLD FAYETTEVILLE ROAD LELAND, NC 28451												
(VA) ID	CLIMMADV CTA			DROVIDERIO DI ANI GE CORRECTIO	\h.i	<del></del>						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE						
V 000 INITIAL COMMENTS		V 000										
		w up survey was completed 24. A deficiency was cited.										
	This facility is licensed for the following ser category: 10A NCAC 27G .5600C Supervisions for Adults with Developmental Disab											
		ed for 4 and currently has a urvey sample consisted of lients.										
V 736	736 27G .0303(c) Facility and Grounds Maintenance		V 736									
10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive												
	odor.			RECEIVED								
	This Rule is not met as evidenced by: Based on observation and interview, the facility was not maintained in a safe, clean, attractive and orderly manner, free from offensive odor. The findings are:			APR 2 9 2024								
				DHSR-MH Licensure Se	ect							
	1:30 pm revealed:	5/24 between 1:00pm and		-The siding over front stoop has b	een	4/1/24						
	detached, exposing	openings above both sides of		secured.	een	4/1/24						
	the front entry door Dust was visible, adhered to the textured ceiling above the dining table ceiling fan.			-Dust was removed from the ceilin the dining table ceiling fan.		9 4/1/24						
		ucet was loose from the		-Kitchen sink faucet has been sect the countertop.	ured to							
	- Stains and buildup microwave over the	were visible on the top of the		-The microwave has been remove	d.	4/1/24						
	- The kitchen cabine	ts extending over the stove separating from the ceiling.		-The kitchen cabinets extending ov stove have been secured to the ce		4/1/24						

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE Operations Manager (X6) DATE

4/22/24

PRINTED: 02/22/2024 FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING:			(X3) DATE SURVEY COMPLETED	
		mhl010-057	B. WING		R <b>02/16/2024</b>		
THE TRIN	ITY HOME	1117 OLD LELAND,	FAYETTEV NC 28451	, STATE, ZIP CODE /ILLE ROAD			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIVE (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRODEFICIENCY)	N SHOULD BE C E APPROPRIATE		
- - - - -	entry into the rooms - The wall paper in baround the door and Interview on 2/16/24 stated: - She would ensure	ngent odor was present upon of client #1 and client #3. pathroom #2 was peeling window.  the Qualified Professional repairs were completed.	V 736	-The odor upon entry to client #1 client #3 rooms has been addrest is no longer presentWall paper in bathroom #2 has removed and wall has been pain.  All deficiencies in this report will listed as items on the quarterly hand Safety Home checklist to enthey remain in compliance and soff on by the Qualified Profession.	be health isure	4/1/24	

Division of Health Service Regulation