## Received and approved POC./TO 10/19/2021

PRINTED: 09/17/2021 FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING:		(X3) DATE SURVEY COMPLETED	
			B WING			
AB0028		5. 11110			08/26/2021	
NAME OF PR	OVIDER OR SUPPLIER	STREET ADI	DRESS, CITY,	STATE, ZIP CODE		
		3305 DRA	KE CIRCLI	=		
A WOMA	N'S CHOICE OF RAL		NO 07007			
						(X5)
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROF DEFICIENCY)	ION SHOULD BE HE APPROPRIATE	
	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		E 165	E 165 AWCR Staff member failed to folk AWCR Scrub Room Protocol.  8/28/2021 AWCR Clinic Manager the staff member on AWCR Scrub Protocol.  The Director of Nursing will observation staff member once a week for a mensure the staff member is following AWCR Scrub Room Protocol. The manager and/or Director of nursin report any findings to the Quality Committee.	ction should be of the appropriate act)  ailed to follow otocol.  c Manager retrained WCR Scrub Room  will observe the eek for a month to be is following otocol. The clinic or of nursing will	
IVISION HE	ealth Service Regulation	Spenu C	linic	manager 8/291	2021	E
TATE FOR	VI		899	GG5T11	If continuat	ion sheet 1 of 2

Division of Health Service Regulation

DIVISION	of Health Service The				TOWN DATE (	SUDVEY							
STATEMENT OF DEFICIENCIES AND (X1) PROVIDER PLAN OF CORRECTION IDENTIFICATION NUMB			(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY COMPLETED								
		IDENTIFICATION NUMBER:	A. BUILDING: _										
			D MANAG										
		4 D0000	B. WING		08/2	6/2021							
		AB0028											
NAME OF PR	NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE												
	3305 DRAKE CIRCLE												
A WOMAN'S CHOICE OF RALEIGH, INC RALEIGH, NC 27607													
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIES		ID	PROVIDER'S PLAN OF CORRECT! (EACH CORRECTIVE ACTION SHOULD									
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX	CROSS-REFERENCED TO THE APPRO									
TAG	REGULATORTORE	SO IDENTIFY THE IN STATE CO.		DEFICIENCY)	1								
		4	E 165										
E 165	Continued From pa	Continued From page 1 vaginal speculum.  Observation revealed CNA #2 rinsed the vaginal											
	Observation reveal	ed UNA #2 mised the vaginal	1										
	speculum and place	ed it in a container filled with											
	enzyme soap clear	ner and water to soak for 2											
		on revealed the vaginal	1		i								
	speculum was placed in a pill pack with indicators, sealed, and placed in the autoclave.												
	Observation reveal	and placed in the dutodays.											
	Observation revealed CNA #2 did not take the vaginal speculum apart allowing all surface areas to be cleaned. Observation revealed CNA #2				,								
		I probes in her left hand and	in the second										
	scrubbed them tog	ether with the brush.											
Observation revealed all surfaces of the va		led all surfaces of the vaginal			į								
	probes were not cleaned due to not separating the probes from each other during the cleaning				İ								
	process.												
	Interview on 08/26/	/2021 at 1155 with CNA #2											
	confirmed she had completed the cleaning of the												
	instruments.												
	Interview on 08/26/	/2021 at 1155 with RMA	5										
Interview on 08/26/2021 at 1155 with RMA (Registered Medical Assistant) #3 revealed the													
	vaginal speculum should have been taken apart												
	to clean.		100										
			The state of the s										
		/2021 at 1200 with Clinic											
	Manager #4 reveal	led she had trained CNA #2.				annia prop							
	Interview revealed	the policy and protocol was not				manus a company of the company of th							
	followed. Interview	revealed the speculum should	i i i i i i i i i i i i i i i i i i i										
have been taken apart to clean and the vaginal													
	probes should eac	h be cleaned individually.											
	į.					To a second							
						O House							
1													

6899

Division of Health Service Regulation STATE FORM