Division of Health Service Regulation

| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | (X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING | | (X3) DATE SURVEY COMPLETED |
|---|--|--|-------------------------------|
| HAL045115 | | | R 07/08/2025 |
| NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE | | | |
| CHERRY SPRINGS VILLAGE 358 CLEAR CREEK ROAD HENDERSONVILLE, NC 28792 | | | |
| (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY) | D BE COMPLETE |
| {C 000} Initial Comments | {C 000} | | |
| Report of a Construction Section Biennial Follow Up Survey by Tod Hancock conducted on July 8, 2025. Deficiencies have been corrected. No further action is necessary. | | | |

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE