

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL094-007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R-C 01/24/2020
--------------------------------------------------	-----------------------------------------------------------------------------	-----------------------------------------------------------------------	-------------------------------------------------------------

NAME OF PROVIDER OR SUPPLIER A PLUS RESULTS INDEPENDENT LIVING INC	STREET ADDRESS, CITY, STATE, ZIP CODE 102 WEST WATER STREET PLYMOUTH, NC 27962
----------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>A complaint and follow up survey was completed on 1/24/2020. The complaint was substantiated (intake #NC00158927). A deficiency was cited.</p> <p>This facility is licensed for the following service categories: 10A NCAC 27G .4400 Substance Abuse Intensive Outpatient Program and 10A NCAC 27G .4500 Substance Abuse Comprehensive Outpatient Treatment</p>	V 000		
V 736	<p>27G .0303(c) Facility and Grounds Maintenance</p> <p>10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS</p> <p>(c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.</p> <p>This Rule is not met as evidenced by: Based on record review and interview the Licensee failed to ensure the facility was maintained in a safe, attractive manner. The findings are:</p> <p>Observation on 1/21/2020 at 11:00 AM revealed:</p> <ul style="list-style-type: none"> -Missing tiles in hallway ceiling. -Tile floor in men's bathroom ripped. -Chirping smoke detectors throughout the building. -Multiple fly strips hanging down with dead flies on them. -Water ceiling stains throughout building. -Outdoor path to smoking area had metal pieces and wires hanging from the ceiling. 	V 736		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL094-007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R-C 01/24/2020
--------------------------------------------------	-----------------------------------------------------------------------------	-----------------------------------------------------------------------	-------------------------------------------------------------

NAME OF PROVIDER OR SUPPLIER A PLUS RESULTS INDEPENDENT LIVING INC	STREET ADDRESS, CITY, STATE, ZIP CODE 102 WEST WATER STREET PLYMOUTH, NC 27962
----------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	Continued From page 1 During interview on 1/21/20 The Program Director stated: <ul style="list-style-type: none"> -The building is very old and the landlord is not good about fixing repairs. -The fly strips were up because they had flies so bad and this was an attempt to reduce that. -There had been some leaks, but the roof was repaired. -The outdoor area is not an area they rent, it the landlord's area and that can touch that. -Have been looking to relocate to a different location but having difficulty doing so. 	V 736		