Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>		(X3) DATE SURVEY COMPLETED		
			A. BOILDING. VI		R		
		HAL045115	B. WING	<del> </del>		3/2016	
				DRESS, CITY, STATE, ZIP CODE			
CHERRY SPRINGS VILLAGE 358 CLEAR CREEK ROAD HENDERSONVILLE, NC 28792							
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROFIDEFICIENCY)	ILD BE COMPLETE		
{C 000}	Initial Comments		{C 000}				
	Report of Follow-up Survey by Dennis Harrell on 12-13-2016.  Not all deficiencies were corrected. Further action is required.						
{C 189}	Building Equipment Maintained Safe, Operating  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.		{C 189}				
	are prevented from are not fitting prope and smoke. Corrid- completely and late fire that begins in or to the corridor and t Findings still include b. Corridor door the	vation, many corridor doors closing quickly and latching or rly to resist the passage of fire or doors that do not close h present the possibility that a ne space can quickly spread the remainder of the facility.					

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE