

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092180	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/28/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER MAGNOLIA GLEN	STREET ADDRESS, CITY, STATE, ZIP CODE 3215 CREEDMOOR ROAD RALEIGH, NC 27612
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

C 000	<p>Initial Comments</p> <p>Report of a Construction Section Biennial Survey by Suzanna Fay conducted on June 28, 2023.</p> <p>Records indicate that this Facility was licensed on October 11, 2002. The facility is currently licensed for 66 Beds. Therefore, the facility was surveyed for conformance with the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and applicable portions of the 2002 Edition of the North Carolina Building Code(s), Institutional Occupancy, and the 1996 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure.</p> <p>Deficiencies were cited that require a Plan of Correction.</p>	C 000	<p>Reports could not be printed the day of the visit due to a system wide network outage. Reports are attached to this document/email for further review.</p>	7/13/2023
C 111	<p>Must Have Current San. & Fire Safety Reports</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION{</p> <p>f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review.</p> <p>This Rule is not met as evidenced by:</p> <p>1. Review of records revealed that the current fire and building safety inspection reports were not available for review due to an issue with the company's computer system.</p> <p>Findings on June 28, 2023:</p> <p>a. A copy of the most recent Fire Official's inspection report was not available for review.</p> <p>b. A copy of the most recent Fire Alarm System inspection report was not available for review.</p> <p>c. A copy of the most recent Fire Sprinkler</p>	C 111		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092180	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/28/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER MAGNOLIA GLEN	STREET ADDRESS, CITY, STATE, ZIP CODE 3215 CREEDMOOR ROAD RALEIGH, NC 27612
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 111	Continued From page 1 System inspection report was not available for review.	C 111		
C 155	Floors-Non-skid, in Good Repair SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (i) The requirements for floors are: (1) All floors shall be of smooth, non-skid material and so constructed as to be easily cleanable; (2) Scatter or throw rugs shall not be used; and (3) All floors shall be kept in good repair. This Rule is not met as evidenced by: 1. Observations revealed that the facility had scatter or throw rugs in use. Findings on June 28, 2023: a. Room A217 - there is a small rug in the corridor at the room entrance.	C 155	Mat was removed and resident was informed that they can no longer have a mat placed in their doorway/entryway.	7/13/2023
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the ceilings and	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092180	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/28/2023
--	--	--	---

NAME OF PROVIDER OR SUPPLIER MAGNOLIA GLEN	STREET ADDRESS, CITY, STATE, ZIP CODE 3215 CREEDMOOR ROAD RALEIGH, NC 27612
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

C 164	<p>Continued From page 2</p> <p>walls were not kept clean and in good repair.</p> <p>Findings on June 28, 2023:</p> <p>a. There is a ceiling tile out outside of A319. The tile was removed to repair a condensation problem in the space above.</p> <p>b. Third Floor - there is a damaged ceiling tile outside of Laundry.</p> <p>c. Third Floor Roof Access off of the Living Room - there is a 10" x 10" patch to the right of the door that has not been finished.</p> <p>d. Second Floor Laundry - there is one tile out in the back corner.</p> <p>e. First Floor Caregivers' Office - there are three ceiling tiles with water stains.</p>	C 164	<p>New ceiling tiles that will match each area have been ordered and were replaced on 7/21/2023. This includes completing the 10x10 patch.</p>	7/21/2023
C 185	<p>Fire Safety-Rehearsals on Each Shift</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION</p> <p>(b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official.</p> <p>(c) Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short description of what the rehearsal involved.</p> <p>(f) This Rule shall apply to new and existing facilities.</p> <p>This Rule is not met as evidenced by:</p> <p>1. Review of records revealed that the facility was not conducting the fire rehearsals quarterly on each shift.</p>	C 185		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092180	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/28/2023
NAME OF PROVIDER OR SUPPLIER MAGNOLIA GLEN		STREET ADDRESS, CITY, STATE, ZIP CODE 3215 CREEDMOOR ROAD RALEIGH, NC 27612		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 185	Continued From page 3 Findings on June 28, 2023: a. There was not a record of a fire rehearsal conducted on the third shift of the third quarter of 2022. b. There was not a record of a fire rehearsal conducted on the third shift of the fourth quarter of 2022. c. There was not a record of a fire rehearsal conducted on the third shift of the first quarter of 2023.	C 185	3rd shift fire drills have been added to the maintenance schedule. This schedule will ensure that we are including 3rd shift in the drill rotation for training compliance. A 3rd shift drill was completed on 7/13/2023.	7/13/2023
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation and testing there is failure to maintain the facility's emergency fire alarm system devices and equipment in a safe operating condition. All the occupants of the facility could be effected if the equipment failed to alert the occupants in case of a fire. Findings on June 28, 2023: a. The FACP stated that there was a battery charger failure. Interview with staff revealed that the parts have been ordered. The system appeared to function normally when tested.	C 189	The battery charger was ordered by our 3rd party vendor, Siemens, for the fire alarm and sprinkler. The part was replaced on 7/11/2023 and the receipt is attached to this report.	7/11/2023

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092180	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/28/2023	
NAME OF PROVIDER OR SUPPLIER MAGNOLIA GLEN		STREET ADDRESS, CITY, STATE, ZIP CODE 3215 CREEDMOOR ROAD RALEIGH, NC 27612		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 4</p> <p>2. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin.</p> <p>Findings on June 28, 2023: a. Room A317 - the escutcheon ring on the sprinkler head in the closet is missing leaving a hole in the fire resistant rated ceiling.</p> <p>3. Based on observation there is a failure to maintain the buildings's fire safety components in a safe operating condition. Any unapproved device used to keep a door open is an impediment to quickly closing the door. The occupants in the facility could be effected if doors cannot be closed as required so as to limit the spread of smoke and/or fire to the area of origin.</p> <p>Findings on June 28, 2023: a. Second Floor Wellness Room - the magnet for the hold open device is broken and a wedge was under the door to hold it open. The wedge was removed at the time of survey.</p> <p>4. Based on observation, the electrical equipment is not being maintained in a safe operating condition. Missing or broken cover plates on electrical devices may cause injury to the occupants of the facility if wiring is exposed.</p> <p>Findings on June 28, 2023: a. Third Floor Roof Access off of the Living Room - there is an open junction box above the door.</p> <p>5. Based on observation there is a failure to maintain the building's fire safety systems in a</p>	C 189	<p>The gaps were filled with fire resistant foam on 7/21/2023.</p> <p>The e-ring was replaced on 7/21/2023.</p> <p>Parts have been ordered for this repair and they will be installed when they arrive. Staff have been trained/informed that door stops cannot be used on corridor doors.</p> <p>A blank plate was installed on this junction box.</p>	<p>7/21/2023</p> <p>7/21/2023</p> <p>7/21/2023</p>

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092180	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/28/2023
--	--	---	---

NAME OF PROVIDER OR SUPPLIER MAGNOLIA GLEN	STREET ADDRESS, CITY, STATE, ZIP CODE 3215 CREEDMOOR ROAD RALEIGH, NC 27612
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 safe condition. Use of materials that are not fire resistant rated could allow fire and smoke to spread beyond the area of origin. Findings on June 28, 2023: a. First Floor Electrical Room - gaps around the conduit that penetrate the fire resistant ceiling are sealed with an expandable foam type of insulation material that is not fire resistant rated.	C 189	These gaps were sealed with a fire resistant material which was determined to be the best product for this space.	7/21/2023
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility did not maintain exhaust ventilation in specified spaces. Lack of ventilation allows for the build up humidity that can cause mildew and slick areas and prevents the dissipation of odors. Findings on June 28, 2023: a. Third Floor - the exhaust fans in the resident	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092180	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/28/2023
NAME OF PROVIDER OR SUPPLIER MAGNOLIA GLEN		STREET ADDRESS, CITY, STATE, ZIP CODE 3215 CREEDMOOR ROAD RALEIGH, NC 27612		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 6 bathroom on the right side of the smoke barrier doors did not appear to be working. b. Third Floor - the exhaust fan in the Janitor's Closet was not working. c. Room A110 - the exhaust fan in the bathroom was not working.	C 199	These exhaust vents are suctioned by a large exhaust fan on the roof and ducted to each area. These registers/grills were cleaned and are now drawing exhaust.	7/13/2023

SIEMENS

Invoice FIRE

Cust PO No
Carl Benson

Cust PO Date

Quotation No

Invoice No
5330979406

Date
07/11/2023

Sales Order No
3802401063

Sales Ord Date
07/11/2023

Lock Box No

Customer No
30569848

Page 1 of 2

Bill To:	Sold To:	Ship To:
KSL MG ST LLC SUITE 300 5790 FLEET ST CARLSBAD CA 92008-4703	MAGNOLIA GLEN COMMUNITY ASSOCIATION INC C/O KISCO SENIOR LIVING LLC SUITE 300 5790 FLEET ST CARLSBAD CA 92008	MAGNOLIA GLEN COMMUNITY ASSOCIATION INC 5301 CREEDMOOR RD RALEIGH NC 27612

Remit Incoming ACH's To:(Preferred)	Remit Incoming Wires To:	Remit check payments to:
Citibank New York 111 Wall St. New York, NY 10043 USA ABA# 021000089 Account# 30824211 Credit Siemens Industry Inc - BT / 4433 Payment for Invoice # 5330979406 Email Detailed Remittance advice to bfgarwires.us.sbt@siemens.com	Citibank New York 111 Wall St. New York, NY 10043 USA ABA# 021000089 SWIFT Code: CITIUS33 Account# 30824211 Credit Siemens Industry Inc - BT / 4433 Payment for Invoice # 5330979406 Email Detailed Remittance advice to bfgarwires.us.sbt@siemens.com	SIEMENS INDUSTRY, INC. C/O Citibank (Bldg Tech) PO Box 2134 Carol Stream IL 60132-2134

Delivery#:	Ship Date:
INCO Terms: Prepaid & Allow	Carrier/Route: Best Way

This invoice is subject to the Siemens Industry, Inc., Smart Infrastructure terms and conditions applicable to the products and services sold pursuant to this invoice, which shall govern in the event of any conflict with any other terms or conditions, specifications, proposal, purchase order, acknowledgment or other document. These terms can be viewed at the following site: <https://www.siemens.com/download?A6V11694115>. BY ACCEPTING THIS INVOICE, YOU AFFIRM THAT YOU HAVE READ, UNDERSTOOD AND AGREE TO BE BOUND BY ITS TERMS AND CONDITIONS INCLUDING ANY AND ALL REFERENCED AND INCORPORATED DOCUMENTS THEREIN.

Line Item	Material Number/Description	U/M	Invoice Qty	Unit Price	Total Price
100	Service Order Number: 5004653442 Building Name: Magnolia Glen Community A7F55000007 Specialist - work normal time ECCN: EAR99 Customer PO item #: 000100 Service Rendered: until	H	4	231.00	924.00
200	S54430-C26-A1 / S54430-C26-A1 PSC-12M 12A at 24VDC Pwr Supp w Charger HTS: 8504409530 ECCN: EAR99 Country Of Origin: MY Customer PO item #: 000200 Service Rendered: until	PC	1	3,350.65	3,350.65
300	A7F55000061 Trip Charge ECCN: EAR99 Customer PO item #: 000300 Service Rendered: until	PC	1	125.00	125.00
400	A7F55000080 On-Site Support ECCN: EAR99 Customer PO item #: 000400	PC	1	40.00	40.00

SIEMENS

Invoice FIRE

Cust PO No
Carl Benson

Cust PO Date

Quotation No

Invoice No
5330979406

Date
07/11/2023

Sales Order No
3802401063

Sales Ord Date
07/11/2023

Lock Box No

Customer No
30569848

Page 2 of 2

Line Item	Material Number/Description	U/M	Invoice Qty	Unit Price	Total Price
	<p>Notes: Issue: FIS TO REPLACE PSC-12 External comment: External Description TO REPLACE PSC-12 Resolution: Delivery Mode:ONSITE</p> <p>CUSTOMER ISSUE: FAULTY POWER SUPPLY ## Previous Tech determined the power supply was faulty - not charging batteries and hot to the touch ## Panel had a "MAIN PANEL PSC" "BATTERY CHARGER FAILURE" trouble on arrival</p> <p>RESOLUTION: ## Replaced PSC-12 with PSC-12M and verified system returned to normal condition PSC-12M obtained from office (solutions)</p> <p>Contact: Customer Service</p> <p>Siemens Industry, Inc. Raleigh-Durham Sales Office 215 Southport Drive Suite 900 Morrisville NC 27560 Phone: (919)469-5095 Fax: (919)469-9846</p>				
	State Taxes				0.00
	State Taxes				203.05
	County Taxes				85.49
	District Taxes				21.37

Total Wt.: 0 KG Currency: USD Invoice Total: 4,749.56

Our preferred payment method is ACH/EFT funds transfer. Our Dunn and Bradstreet # is 01-094-4650

Payment Terms: Net Due 30 Days

*These items are controlled by the U.S. Government (when labeled with "ECCN" unequal "N") and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. Government or as otherwise authorized by U.S. law and regulations. Items labeled with "AL" unequal "N" are subject to European / national export authorization. Items without label, with label "AL N", "ECCN N" or label "AL 9X9999", "ECCN 9X9999" may require authorization from responsible authorities depending on the final end-use or the destination.

*We hereby certify that these goods were produced in compliance with all the applicable requirements of Section 8, 7, and 12 of the Fair Labor Standards Act, as amended, and regulations and orders of the United States Department of Labor issued under Section 14, thereof.
For shipment to California, "Displays exceeding 4" include the e-Waste recycle fee up to \$10 per item.

Sprinkler Inspection Certificate

For

Magnolia Glen
5301 Creedmoor
Raleigh, NC 27612

Tested to NFPA 25 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

*Annual Inspection
Inspection Date
Apr 7, 2023*

Building: Magnolia Glen
Contact: Carl Benson
Title: PM

Company: Summit Fire & Security - Raleigh
Contact: TJ Bogue
Title: Lead Inspector

Executive Summary

Generated by: BuildingReports.com


Building Information			
Building: Magnolia Glen			Contact: Carl Benson
Address: 5301 Creedmoor			Phone: 919-841-4747
Address:			Fax:
City/State/ZIP Code: Raleigh, NC 27612			Mobile:
Country: United States of America			Email: carl.benson@kiscosl.com
Inspection Performed By			
Company: Summit Fire & Security – Raleigh			Inspector: TJ Bogue
Address: 1731 Round Rock Dr			Phone: 9194275978
Address:			Fax:
City/State/ZIP Code: Raleigh, North Carolina 27615			Mobile:
Country: United States of America			Email: TGBogue@summitfiresecurity.com
System Control Unit			
System Type	System Location	Protected Area	Devices
Service Main	5205-5209 Creedmoor Road	5205-5209 Creedmoor Road	1
Service Main	5301 Creedmoor Road	5301 Creedmoor Road	3
Standpipe	5301 Creedmoor Road	5301 Creedmoor Road	31
Standpipe	5301 Creedmoor Road	Area-	1
Wet Pipe	5301 Creedmoor Road	5301 Creedmoor Road	65
Central Station Signal Verification			
Type:	Mfg:	Model #:	
Test Time/Date:	Restore Time:	Note:	
Type of Signal	Signal Confirmation	Notes	
Type: Trouble	Confirmed Time: 4:20	Note:	

Inspection Summary

Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Alarm	24	23.76%	24	100.00%	24	100.00%	0	0.00%
Device	14	13.86%	14	100.00%	4	28.57%	10	71.43%
Hose	28	27.72%	28	100.00%	28	100.00%	0	0.00%
Sprinkler	15	14.85%	15	100.00%	15	100.00%	0	0.00%
Valve	20	19.80%	20	100.00%	20	100.00%	0	0.00%
Totals	101	100%	101	100.00%	91	90.10%	10	9.90%


Certification

Company: Summit Fire & Security – Raleigh
 Inspector: TJ Bogue



Signed: Apr 7, 2023

Building: Magnolia Glen
 Contact: Carl Benson



Signed: Apr 7, 2023

Discrepancy Report

Generated by: BuildingReports.com

Building: Magnolia Glen			
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.</i></p>			
Device Type	Manufacturer	ModelNumber	Date
<i>Items listed for Recall or Replacement/Upgrade</i>			
No items found during this inspection.			
🔍 ScanID	📍 Location	🚩 Problem	📖 Reference
<i>5301 Creedmoor Road Standpipe, 5301 Creedmoor Road</i>			
Gauge			
37502061	3rd Str6 East	Date Expired	NFPA25 13.2.7.2
37502049	5th Str1 North	Date Expired	NFPA25 13.2.7.2
37502056	5th Str3 south	Date Expired	NFPA25 13.2.7.2
<i>5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road</i>			
Gauge			
37502071	1st Boiler Rm/riser rm	Date Expired	NFPA25 13.2.7.2
37502070	1st Boiler Rm/riser rm Noncritical	Date Expired	NFPA25 13.2.7.2
15896245	1st Boiler Rm/riser rm Isolation	Date Expired	NFPA25 13.2.7.2
37502062	2nd Str4 south Mech Rm	Date Expired	NFPA25 13.2.7.2
15245925	3rd Str4 south Mech Rm	Date Expired	NFPA25 13.2.7.2
15245923	4th Str4 south Mech Rm	Date Expired	NFPA25 13.2.7.2
54162887	5th Str4 south Mech Rm	Date Expired	NFPA25 13.2.7.2
<i>Code References</i>			
NFPA25 13.2.7.2	Gauges shall be replaced every 5 years or tested every 5 years by comparison with a calibrated gauge.		

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Magnolia Glen

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix
<i>5301 Creedmoor Road Standpipe, 5301 Creedmoor Road</i>					
Gauge					
37502061	3rd Str6 East	5 Year Service	N/A	T/M	<input type="checkbox"/>
37502049	5th Str1 North	5 Year Service	N/A	T/M	<input type="checkbox"/>
37502056	5th Str3 south	5 Year Service	N/A	T/M	<input type="checkbox"/>
<i>5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road</i>					
Gauge					
37502071	1st Boiler Rm/riser rm	5 Year Service	N/A	T/M	<input type="checkbox"/>
37502070	1st Boiler Rm/riser rm Noncritical	5 Year Service	N/A	T/M	<input type="checkbox"/>
15896245	1st Boiler Rm/riser rm Isolation	5 Year Service	N/A	T/M	<input type="checkbox"/>
37502062	2nd Str4 south Mech Rm	5 Year Service	N/A	T/M	<input type="checkbox"/>
15245925	3rd Str4 south Mech Rm	5 Year Service	N/A	T/M	<input type="checkbox"/>
15245923	4th Str4 south Mech Rm	5 Year Service	N/A	T/M	<input type="checkbox"/>
54162887	5th Str4 south Mech Rm	5 Year Service	N/A	T/M	<input type="checkbox"/>
				PO #: (none)	T/M

Inspection & Testing

Generated by: BuildingReports.com

Building: Magnolia Glen

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
Passed				
5205-5209 Creedmoor Road Service Main, 5205-5209 Creedmoor Road				
Fire Hydrant	Fire Hydrant Between BLDG 5209 And 5205	Tested	11:05:45 AM	03/02/2023
5301 Creedmoor Road Service Main, 5301 Creedmoor Road				
Fire Hydrant	Fire Hydrant Right Side Of Main BLDG 5301	Tested	10:50:33 AM	03/02/2023
Fire Hydrant	Fire Hydrant Front Of BLDG 5215 And BLDG 5301	Tested	10:57:23 AM	03/02/2023
Fire Hydrant	Fire Hydrant Rear BLDG Of 5215 Near Loading Dock	Tested	11:19:32 AM	03/02/2023
5301 Creedmoor Road Standpipe, 5301 Creedmoor Road				
Monitoring	3rd FACP/Electrical Room	Tested	4:09:35 PM	04/06/2023
Tamper Switch	1st Str4 south Corridor	Tested	12:57:17 PM	03/27/2023
Tamper Switch	1st Work Shop Corridor	Tested	1:06:36 PM	03/27/2023
Tamper Switch	1st Rm113 Corridor	Tested	1:09:11 PM	03/27/2023
Tamper Switch	1st Str1 North	Tested	1:13:47 PM	03/27/2023
Hose Connection	1st Str1 North Raleigh Threads	Tested	11:30:39 AM	03/28/2023
Hose Connection	1st Rm 113 Corridor Raleigh Threads	Tested	12:00:38 PM	03/28/2023
Hose Connection	1st Str3 south Raleigh Threads	Tested	11:10:09 AM	04/07/2023
Hose Connection	2nd Str1 North Raleigh Threads	Tested	11:29:24 AM	03/28/2023
Hose Connection	2nd Rm 213 Corridor	Tested	11:57:26 AM	03/28/2023
Hose Connection	2nd Str6 East Raleigh Threads	Tested	12:13:04 PM	03/28/2023
Hose Connection	2nd Str3 south Raleigh Threads	Tested	12:18:49 PM	03/28/2023
Hose Connection	3rd Str1 North Raleigh Threads	Tested	11:28:31 AM	03/28/2023
Hose Connection	3rd Rm 313 Corridor Raleigh Threads	Tested	11:53:22 AM	03/28/2023
Hose Connection	3rd Str6 East Raleigh Threads	Tested	12:11:15 PM	03/28/2023
Hose Connection	3rd Str3 south Raleigh Threads	Tested	12:18:31 PM	03/28/2023
Hose Connection	4th Str4 south	Tested	2:31:20 PM	03/27/2023
Hose Connection	4th Rm 4th Corridor Raleigh Threads	Tested	11:48:15 AM	03/28/2023
Hose Connection	4th Str3 south Raleigh Threads	Tested	12:18:14 PM	03/28/2023
Hose Connection	4th Str1 North Raleigh Threads	Inspected	4:07:53 PM	04/06/2023
Hose Connection	5th Str1 North Raleigh Threads	Tested	11:22:27 AM	03/28/2023
Hose Connection	5th Rm 513 Corridor	Tested	11:45:13 AM	03/28/2023
Hose Connection	5th Str3 south Raleigh Threads	Tested	12:17:58 PM	03/28/2023
Control Valve	1st Work Shop Corridor	Inspected	1:06:41 PM	03/27/2023
Control Valve	1st Rm113 Corridor	Inspected	1:09:16 PM	03/27/2023
Control Valve	1st Str1 North Corridor 6' Ladder	Inspected	1:13:48 PM	03/27/2023
Control Valve	2nd Str4 south Mech Rm Str4 Isolation	Inspected	11:42:48 AM	03/27/2023
Control Valve	2nd Str4 south Mech Rm	Inspected	11:43:26 AM	03/27/2023
5301 Creedmoor Road Standpipe, Area-				

Device Type	Location	Service	Time	Date
Hose Connection	1st Str6 East Raleigh Threads	Tested	12:13:40 PM	03/28/2023
5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road				
Tamper Switch	1st Boiler Rm/riser rm	Tested	10:21:08 AM	03/27/2023
Tamper Switch	1st Boiler Rm/riser rm	Tested	10:27:54 AM	03/27/2023
Tamper Switch	1st Str3 South Corridor	Tested	1:02:40 PM	03/27/2023
Tamper Switch	1st Str5 East Closet	Tested	4:03:16 PM	04/06/2023
Tamper Switch	2nd Str4 south Mech Rm	Tested	11:31:37 AM	03/27/2023
Tamper Switch	2nd Str4 south Mech Rm Str4 Isolation	Tested	11:42:50 AM	03/27/2023
Tamper Switch	2nd Str4 south Mech Rm	Tested	11:43:21 AM	03/27/2023
Tamper Switch	2nd Main Lobby AFL Door At Executive Director Office	Tested	4:06:40 PM	04/06/2023
Tamper Switch	3rd Str4 south Mech Rm	Tested	11:52:30 AM	03/27/2023
Tamper Switch	4th Str4 south Mech Rm	Tested	11:21:35 AM	03/27/2023
Tamper Switch	5th Str4 south Mech Rm	Tested	11:15:40 AM	03/27/2023
Tamper Switch	Loading Dock Hotbox	Tested	1:37:42 PM	03/27/2023
Tamper Switch	Loading Dock Hotbox	Tested	1:37:53 PM	03/27/2023
Waterflow Switch	1st Boiler Rm/riser rm Isolation	Tested	10:31:11 AM	03/27/2023
Waterflow Switch	1st Boiler Rm/riser rm Main	Tested	10:31:15 AM	03/27/2023
Waterflow Switch	2nd Str4 south Mech Rm	Tested	11:34:35 AM	03/27/2023
Waterflow Switch	3rd Str4 south Mech Rm	Tested	11:52:18 AM	03/27/2023
Waterflow Switch	4th Str4 south Mech Rm	Tested	11:22:17 AM	03/27/2023
Waterflow Switch	5th Str4 south Mech Rm	Tested	11:24:59 AM	03/27/2023
Antifreeze System	1st Str5 East Closet Critical	Tested	4:03:10 PM	04/06/2023
Antifreeze System	2nd Main Lobby Door At Executive Director Office	Tested	4:06:41 PM	04/06/2023
Drain	1st Boiler/Riser Room Main	Tested	10:31:37 AM	03/27/2023
Heating System	Loading Dock Hotbox	Inspected	1:38:24 PM	03/27/2023
Fire Dep't Connection	Loading Dock By Fence	Inspected	1:44:16 PM	03/27/2023
Hose Connection	1st Str4 south	Tested	2:43:43 PM	03/27/2023
Hose Connection	2nd Str4 south Raleigh Threads	Tested	2:40:48 PM	03/27/2023
Hose Connection	3rd Str4 south Raleigh Threads	Tested	2:38:00 PM	03/27/2023
Hose Connection	5th Str4 south	Tested	2:28:31 PM	03/27/2023
Dry Sprinkler	Entire Building Visual Inspection	Inspected	4:04:34 PM	04/06/2023
Fast Response	Entire Building Visual Inspection	Inspected	4:04:32 PM	04/06/2023
Fast Response	Entire Building Antifreeze Visual Inspection	Inspected	4:04:41 PM	04/06/2023
Fast Response	Entire Building Visual Inspection Discontinued	Inspected	4:04:42 PM	04/06/2023
Fast Response	Entire Building Visual Inspection	Inspected	4:04:42 PM	04/06/2023
Fast Response	Entire Building Visual Inspection	Inspected	4:04:44 PM	04/06/2023
Piping	Entire Building Visual Inspection	Inspected	4:04:34 PM	04/06/2023
Sprinkler Box	1st Boiler Rm/riser rm	Inspected	10:33:04 AM	03/27/2023
Sprinkler Box Spares	1st Boiler Rm/riser rm	Inspected	10:33:08 AM	03/27/2023
Sprinkler Box Spares	1st Boiler Rm/riser rm	Inspected	10:33:11 AM	03/27/2023
Sprinkler Box Spares	1st Boiler Rm/riser rm	Inspected	10:33:15 AM	03/27/2023
Sprinkler Box Spares	1st Boiler Rm/riser rm	Inspected	10:33:19 AM	03/27/2023
Sprinkler Box Spares	1st Boiler Rm/riser rm	Inspected	10:33:23 AM	03/27/2023
Sprinkler Box Spares	1st Boiler Rm/riser rm	Inspected	10:33:25 AM	03/27/2023
Sprinkler Box Spares	1st Boiler Rm/riser rm	Inspected	10:33:28 AM	03/27/2023
Check Valve	1st Boiler Rm/riser rm 5 Year Performed 2019	Inspected	10:23:49 AM	03/27/2023
Check Valve	1st Str5 East Closet 5 Year Performed 2019	Inspected	4:03:13 PM	04/06/2023
Check Valve	2nd Main Lobby AFL	Inspected	4:06:40 PM	04/06/2023
Control Valve	1st Boiler Rm/riser rm	Inspected	10:21:23 AM	03/27/2023

Device Type	Location	Service	Time	Date
Control Valve	1st Boiler Rm/riser rm	Inspected	10:28:03 AM	03/27/2023
Control Valve	1st Str4 south Corridor	Inspected	12:57:15 PM	03/27/2023
Control Valve	1st At Str3 South In Hallway	Inspected	1:02:38 PM	03/27/2023
Control Valve	1st Str5 East Closet Different Master Key AL Wing	Inspected	4:03:14 PM	04/06/2023
Control Valve	2nd Str4 south Mech Rm Sprinkler Feed 2&1st	Inspected	11:42:42 AM	03/27/2023
Control Valve	2nd Main Lobby AFL Candy Closet	Inspected	4:06:39 PM	04/06/2023
Control Valve	3rd Str4 south Mech Rm	Inspected	11:52:32 AM	03/27/2023
Control Valve	4th Str4 south Mech Rm	Inspected	11:21:40 AM	03/27/2023
Control Valve	5th Str4 south Mech Rm	Inspected	11:15:39 AM	03/27/2023
Control Valve	Loading Dock Hotbox	Inspected	1:37:45 PM	03/27/2023
Control Valve	Loading Dock Hotbox	Inspected	1:37:55 PM	03/27/2023
<i>Failed/Other</i>				
5301 Creedmoor Road Standpipe, 5301 Creedmoor Road				
Gauge	3rd Str6 East	Inspected	12:12:46 PM	03/28/2023
Gauge	5th Str1 North	Inspected	11:22:23 AM	03/28/2023
Gauge	5th Str3 south	Inspected	12:17:55 PM	03/28/2023
5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road				
Gauge	1st Boiler Rm/riser rm	Inspected	10:26:52 AM	03/27/2023
Gauge	1st Boiler Rm/riser rm Noncritical	Inspected	10:27:10 AM	03/27/2023
Gauge	1st Boiler Rm/riser rm Isolation	Inspected	10:31:02 AM	03/27/2023
Gauge	2nd Str4 south Mech Rm	Inspected	11:34:31 AM	03/27/2023
Gauge	3rd Str4 south Mech Rm	Inspected	11:52:14 AM	03/27/2023
Gauge	4th Str4 south Mech Rm	Inspected	11:22:08 AM	03/27/2023
Gauge	5th Str4 south Mech Rm	Inspected	11:25:40 AM	03/27/2023

Wet Pipe Fire Sprinkler Systems

Generated by: BuildingReports.com

Building: Magnolia Glen	5301 Creedmoor Road, 5301 Creedmoor Road
--------------------------------	---

This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.

Alarms

Tamper Switch

Type	Description	Location	Number of Turns	Zone/Address	OK	ScanID
Control Valve	Supervisory	1st Boiler Rm/riser rm		1-2-58	<input checked="" type="checkbox"/>	37502072
Control Valve	Supervisory	1st Boiler Rm/riser rm		1-5-24	<input checked="" type="checkbox"/>	14242580
Control Valve	Supervisory	1st Str3 South Corridor		1-6-50	<input checked="" type="checkbox"/>	15896243
Control Valve	Supervisory	1st Str5 East Closet		1-1-58	<input checked="" type="checkbox"/>	15896226
Control Valve	Supervisory	2nd Str4 south Mech Rm		1-2-30	<input checked="" type="checkbox"/>	14242585
Control Valve	Supervisory	2nd Str4 south Mech Rm Str4 Isolation		1-2-29	<input checked="" type="checkbox"/>	14242584
Control Valve	Supervisory	2nd Str4 south Mech Rm		1-2-26	<input checked="" type="checkbox"/>	14242583
Control Valve	Supervisory	2nd Main Lobby AFL Door At Executive Director Office		1-7-59	<input checked="" type="checkbox"/>	15896209
Control Valve	Supervisory	3rd Str4 south Mech Rm		1-14-005	<input checked="" type="checkbox"/>	14242587
Control Valve	Supervisory	4th Str4 south Mech Rm		1-3-002	<input checked="" type="checkbox"/>	14242589
Control Valve	Supervisory	5th Str4 south Mech Rm		1-14-006	<input checked="" type="checkbox"/>	15896238
Bf In	Supervisory	Loading Dock Hotbox		1-5-25	<input checked="" type="checkbox"/>	61055894
Bf Out	Supervisory	Loading Dock Hotbox		1-5-25	<input checked="" type="checkbox"/>	15896252

Waterflow Switch

Type	Manufacturer	Model #	Sec	Size	Zone/Address	OK	ScanID
Vane	Potter Electric	VSR	55	4"	1-2-22	<input checked="" type="checkbox"/>	14242581
Vane	Potter Electric	VSC	54	6"	1-2-57	<input checked="" type="checkbox"/>	61052776
Vane	Potter Electric	VSC	45	4"	1-2-25	<input checked="" type="checkbox"/>	15245927
Vane	Potter Electric	VSC	45	4"	1-2 M27	<input checked="" type="checkbox"/>	14242588
Vane	Potter Electric	VSC	40	4"	1-14-006	<input checked="" type="checkbox"/>	14242590
Vane	Potter Electric	VSC	44	4"	1-14-006	<input checked="" type="checkbox"/>	15245922

Components

Check Valve

Type	Location	Internal Date	Size	OK	ScanID
Grooved	1st Boiler Rm/riser rm 5 Year Performed 2019	03/13/2019	6"	<input checked="" type="checkbox"/>	14242578
Grooved	1st Str5 East Closet 5 Year	03/14/2019	3"	<input checked="" type="checkbox"/>	15896228

	Performed 2019							
Grooved	2nd Main Lobby AFL		03/13/2019	4"	<input checked="" type="checkbox"/>	15896208		
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	BFV	1st Boiler Rm/riser rm	6"	Open	Supervised	<input checked="" type="checkbox"/>	15896247
Description								
Main Control								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	BFV	1st Boiler Rm/riser rm	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896246
Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	BFV	1st Str4 south Corridor	2.5"	Open	Supervised	<input checked="" type="checkbox"/>	14975510
Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524 - W 2	1st At Str3 South In Hallway	2.5"	Open	Supervised	<input checked="" type="checkbox"/>	14975508
Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524 - W 2	1st Str5 East Closet Different Master Key AL Wing	3"	Open	Supervised	<input checked="" type="checkbox"/>	15896227
Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524 - W 2	2nd Str4 south Mech Rm Sprinkler Feed 2&1st	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896230
Description								
Isolation								

Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	2nd Main Lobby AFL Candy Closet	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896210
Description Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	3rd Str4 south Mech Rm	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896234
Description Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	4th Str4 south Mech Rm	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896236
Description Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	BFV	5th Str4 south Mech Rm	4"	Open	Supervised	<input checked="" type="checkbox"/>	14242591
Description Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
OS&Y	Kennedy	OSY	Loading Dock Hotbox	6"	Open	Supervised	<input checked="" type="checkbox"/>	61055895
Description BF Inlet								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
OS&Y	Kennedy	OSY	Loading Dock Hotbox	6"	Open	Supervised	<input checked="" type="checkbox"/>	15896251
Description BF Outlet								
<i>Devices</i>								
Antifreeze System								
Type	Temperature			Capacity		OK	ScanID	
Glycerine						<input checked="" type="checkbox"/>	15896202	
Proper Signage	Specific Gravity			Min. SG	Last Test			
Yes					01/06/2022			

Antifreeze System								
Type	Temperature		Capacity		OK	ScanID		
Glycerine			N/A		<input checked="" type="checkbox"/>	15896207		
Proper Signage	Specific Gravity		Min. SG	Last Test				
Yes	N/A			01/12/2022				
Drain								
Current Inspection								
Type	Location	Size	Supply psi	Restored psi	Residual psi	Sec	OK	ScanID
Main	1st Boiler/Riser Room Main	2"	95	90	80	02	<input checked="" type="checkbox"/>	77634043
Previous Inspections								
October 24, 2022								
Type	Location	Size	Supply psi	Static psi	Residual psi	Sec	OK	ScanID
Main	1st Boiler/Riser Room Main	2"	100	90	85	02	<input checked="" type="checkbox"/>	77634043
Dry Sprinkler								
Qty	Type	Size	KFactor	Finish	Temperature	OK	ScanID	
42	Recessed Horizontal	1"	5.6	Chrome	155	<input checked="" type="checkbox"/>	50967985	
Location				Description				
Entire Building Visual Inspection								
Fast Response								
Qty	Type	Size	KFactor	Finish	Temperature	OK	ScanID	
	Recessed Pendant	.5"	5.6	Chrome	155	<input checked="" type="checkbox"/>	50967990	
Location				Description				
Entire Building Visual Inspection								
Qty	Type	Size	KFactor	Finish	Temperature	OK	ScanID	
	Recessed Pendant	.5		White	155	<input checked="" type="checkbox"/>	50967989	
Location				Description				
Entire Building Antifreeze Visual Inspection				Quick Response				
Qty	Type	Size	KFactor	Finish	Temperature	OK	ScanID	
	Horizontal Sidewall	.5"	5.5	White	155	<input checked="" type="checkbox"/>	50967986	
Location				Description				
Entire Building Visual Inspection Discontinued Sprinkler Head								
Qty	Type	Size	KFactor	Finish	Temperature	OK	ScanID	
	Upright	.5"	5.6	Brass	155	<input checked="" type="checkbox"/>	50967987	
Location				Description				
Entire Building Visual Inspection								
Qty	Type	Size	KFactor	Finish	Temperature	OK	ScanID	
	Concealed Pendant	.5"	5.6	White	155	<input checked="" type="checkbox"/>	50967988	
Location				Description				
Entire Building Visual Inspection								
Fire Dep't Connection								
Location		Type	BallDrip	Rotating Swivels	Size	OK	ScanID	

Loading Dock By Fence	Freestanding	Ground ?	Yes	2.5"X 2	<input checked="" type="checkbox"/>	37502073	
Gauge							
Location			Service Date				
1st Boiler Rm/riser rm			04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID
Supply Pressure	Wika	N/A	95	N/A	1/4	<input type="checkbox"/>	37502071
Gauge							
Location			Service Date				
1st Boiler Rm/riser rm Noncritical			04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID
System Pressure	Wika	N/A	105	N/A	1/4	<input type="checkbox"/>	37502070
Gauge							
Location			Service Date				
1st Boiler Rm/riser rm Isolation			04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID
System Pressure	Wika	N/A	110	N/A	1/4	<input type="checkbox"/>	15896245
Gauge							
Location			Service Date				
2nd Str4 south Mech Rm			04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID
System Pressure	Wika	N/A	105	N/A	1/4	<input type="checkbox"/>	37502062
Gauge							
Location			Service Date				
3rd Str4 south Mech Rm			04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID
System Pressure	Wika	N/A	90	N/A	1/4	<input type="checkbox"/>	15245925
Gauge							
Location			Service Date				
4th Str4 south Mech Rm			04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID
System Pressure	Wika	N/A	95	N/A	1/4	<input type="checkbox"/>	15245923
Gauge							
Location			Service Date				
5th Str4 south Mech Rm			04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID
System Pressure	Wika	N/A	80	N/A	1/4	<input type="checkbox"/>	54162887
Heating System							
Location		Manufacturer	Model Number	Deg	OK	ScanID	
Loading Dock Hotbox					<input checked="" type="checkbox"/>	77634044	
Hose Connection							

Location	Size	OK	ScanID				
1st Str4 south	Class I - 2.5"	<input checked="" type="checkbox"/>	37502068				
2nd Str4 south Raleigh Threads	Class I - 2.5"	<input checked="" type="checkbox"/>	37502063				
3rd Str4 south Raleigh Threads	Class I - 2.5"	<input checked="" type="checkbox"/>	37502064				
5th Str4 south	Class I - 2.5"	<input checked="" type="checkbox"/>	37502066				
Piping							
Location	Type	Size	Internal Date				
Entire Building Visual Inspection	Lightweight Steel	Various	10/17/2019				
Hangers	Braces	Fittings	Identified	Antifreeze	ScanID		
Normal	Normal	Cast Iron	Tagged	Propylene Glycol	50967984		
Sprinkler Box							
Qty	Tool Available?	SIN List?	Size	Manufacturer	Location	OK	ScanID
1	Yes		12 unit		1st Boiler Rm /riser rm	<input checked="" type="checkbox"/>	15896262
Sprinkler Box Spares							
Qty	Type	Manufacturer	Location	OK	ScanID		
4	Pendant	Viking	1st Boiler Rm /riser rm	<input checked="" type="checkbox"/>	15896263		
Temperature	KFactor	Size	Finish	Response Time			
155	5.6		White	Fast Response			
Sprinkler Box Spares							
Qty	Type	Manufacturer	Location	OK	ScanID		
3	Pendant	Central	1st Boiler Rm /riser rm	<input checked="" type="checkbox"/>	15896264		
Temperature	KFactor	Size	Finish	Response Time			
155	5.6	.5"	White	Fast Response			
Sprinkler Box Spares							
Qty	Type	Manufacturer	Location	OK	ScanID		
5	Pendant	Viking	1st Boiler Rm /riser rm	<input checked="" type="checkbox"/>	15896265		
Temperature	KFactor	Size	Finish	Response Time			
155	5.6		Chrome	Fast Response			
Sprinkler Box Spares							
Qty	Type	Manufacturer	Location	OK	ScanID		
3	Upright	Viking	1st Boiler Rm /riser rm	<input checked="" type="checkbox"/>	15896266		
Temperature	KFactor	Size	Finish	Response Time			
155	5.6		Brass	Fast Response			
Sprinkler Box Spares							
Qty	Type	Manufacturer	Location	OK	ScanID		
1	Upright	Central	1st Boiler Rm /riser rm	<input checked="" type="checkbox"/>	15896267		
Temperature	KFactor	Size	Finish	Response Time			
200	5.6		Brass	Fast Response			
Sprinkler Box Spares							

Qty	Type	Manufacturer	Location		OK	ScanID
1	Horizontal Sidewall	Viking	1st Boiler Rm/riser rm		<input checked="" type="checkbox"/>	15896268
Temperature		KFactor	Size	Finish	Response Time	
155		5.5		White	Fast Response	
Sprinkler Box Spares						
Qty	Type	Manufacturer	Location		OK	ScanID
2	Concealed Pendant	Viking	1st Boiler Rm/riser rm		<input checked="" type="checkbox"/>	15896269
Temperature		KFactor	Size	Finish	Response Time	
155		5.5		Brass	Fast Response	

Standpipe Systems

Generated by: BuildingReports.com

Building: Magnolia Glen				5301 Creedmoor Road, 5301 Creedmoor Road				
<p><i>This section lists out all the devices and components that have been associated with a Standpipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.</i></p>								
Alarms								
Tamper Switch								
Type	Description	Location	Number of Turns	Zone/Address	OK	ScanID		
Control Valve	Supervisory	1st Str4 south Corridor		1-5-12	<input checked="" type="checkbox"/>	15896244		
Control Valve	Supervisory	1st Work Shop Corridor		1-6-046	<input checked="" type="checkbox"/>	15896242		
Control Valve	Supervisory	1st Rm113 Corridor		1-6-48	<input checked="" type="checkbox"/>	14975511		
Control Valve	Supervisory	1st Str1 North		1-6-45	<input checked="" type="checkbox"/>	15896240		
Components								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	1st Work Shop Corridor	4"	Open	Supervised	<input checked="" type="checkbox"/>	14975509
Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	1st Rm113 Corridor	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896241
Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	1st Str1 North Corridor 6' Ladder	4"	Open	Supervised	<input checked="" type="checkbox"/>	14975512
Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	2nd Str4 south Mech Rm Str4 Isolation	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896231

Description								
Isolation								
Control Valve								
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID
Butterfly	Victaulic	V0403524-W 2	2nd Str4 south Mech Rm	4"	Open	Supervised	<input checked="" type="checkbox"/>	15896232
Description								
Isolation								
<i>Devices</i>								
Gauge								
Location				Service Date				
3rd Str6 East				04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID	
System Pressure	Wika	N/A	80	.N/A	1/4	<input type="checkbox"/>	37502061	
Gauge								
Location				Service Date				
5th Str1 North				04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID	
System Pressure	Wika	N/A	85	N/A	1/4	<input type="checkbox"/>	37502049	
Gauge								
Location				Service Date				
5th Str3 south				04/22/2018				
Type	Manufacturer	Model #	Static psi	Fill Type	Size	OK	ScanID	
System Pressure	Wika	N/A	85	.N/A	1/4	<input type="checkbox"/>	37502056	
Hose Connection								
Location			Size	OK	ScanID			
1st Str1 North Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502043			
1st Rm 113 Corridor Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502042			
1st Str3 south Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502052			
2nd Str1 North Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502044			
2nd Rm 213 Corridor			Class I - 2.5"	<input checked="" type="checkbox"/>	37502098			
2nd Str6 East Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502059			
2nd Str3 south Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502053			
3rd Str1 North Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502045			
3rd Rm 313 Corridor Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502079			
3rd Str6 East Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502060			
3rd Str3 south Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502054			
4th Str4 south			Class I - 2.5"	<input checked="" type="checkbox"/>	37502065			
4th Rm 4th Corridor Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502097			
4th Str3 south Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502055			
4th Str1 North Raleigh Threads			Class I - 2.5"	<input checked="" type="checkbox"/>	37502046			

5th Str1 North Raleigh Threads	Class I - 2.5"	<input checked="" type="checkbox"/>	37502050
5th Rm 513 Corridor	Class I - 2.5"	<input checked="" type="checkbox"/>	37502051
5th Str3 south Raleigh Threads	Class I - 2.5"	<input checked="" type="checkbox"/>	37502057

Building: Magnolia Glen

5301 Creedmoor Road, Area-

This section lists out all the devices and components that have been associated with a Standpipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.

Hose Connection

Location	Size	OK	ScanID
1st Str6 East Raleigh Threads	Class I - 2.5"	<input checked="" type="checkbox"/>	37502058

Private Fire Service Mains

Generated by: BuildingReports.com

Building: Magnolia Glen					5205-5209 Creedmoor Road, 5205-5209 Creedmoor Road		
<p><i>This section lists out all the devices and components that have been associated with a Private Fire Service Main and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.</i></p>							
Devices							
Fire Hydrant							
Location	Mfr	Model	Type	Position	Size	OK	ScanID
Fire Hydrant Between BLDG 5209 And 5205	Clow		Dry Barrel/Ground		4.5"	<input checked="" type="checkbox"/>	74727775
Description	Orifice	Flow Rate	Static	Residual	Valve Type	Flush Test Date	
1000 gpm/3786 lpm	2@2-1/2" and 1@4"	N/A	N/A	N/A	Closed against pressure	01/11/2022	

Building: Magnolia Glen

5301 Creedmoor Road, 5301
Creedmoor Road

This section lists out all the devices and components that have been associated with a Private Fire Service Main and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.

Fire Hydrant

Location	Mfr	Model	Type	Position	Size	OK	ScanID
Fire Hydrant Right Side Of Main BLDG 5301	Clow		Wet Barrel/Ground	Closed	4.5"	<input checked="" type="checkbox"/>	74727785
Description	Orifice	Flow Rate	Static	Residual	Valve Type	Flush Test Date	
1000 gpm/3786 lpm	2@2-1/2" and 1@4"	N/A	N/A	N/A	Closed against pressure	03/02/2023	

Fire Hydrant

Location	Mfr	Model	Type	Position	Size	OK	ScanID
Fire Hydrant Front Of BLDG 5215 And BLDG 5301	Mueller	BSR	Dry Barrel/Ground	Closed	4.5"	<input checked="" type="checkbox"/>	74727774
Description	Orifice	Flow Rate	Static	Residual	Valve Type	Flush Test Date	
1000 gpm/3786 lpm	2@2-1/2" and 1@4.5"	N/A	N/A	N/A	Closed against pressure	03/02/2023	

Fire Hydrant

Location	Mfr	Model	Type	Position	Size	OK	ScanID
Fire Hydrant Rear BLDG Of 5215 Near Loading Dock	Clow		Wet Barrel/Ground	Closed	4.5"	<input checked="" type="checkbox"/>	74727780
Description	Orifice	Flow Rate	Static	Residual	Valve Type	Flush Test Date	
1000 gpm/3786 lpm	2@2-1/2" and 1@4"	N/A	N/A	N/A	Closed against pressure	03/02/2023	

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Magnolia Glen

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Antifreeze System	Device	1.98%	2
Check Valve	Valve	2.97%	3
Control Valve	Valve	16.83%	17
Drain	Device	0.99%	1
Dry Sprinkler	Sprinkler	0.99%	1
Fast Response	Sprinkler	4.95%	5
Fire Dep't Connection	Hose	0.99%	1
Fire Hydrant	Hose	3.96%	4
Gauge	Device	9.90%	10
Heating System	Device	0.99%	1
Hose Connection	Hose	22.77%	23
Monitoring	Alarm	0.99%	1
Piping	Sprinkler	0.99%	1
Sprinkler Box	Sprinkler	0.99%	1
Sprinkler Box Spares	Sprinkler	6.93%	7
Tamper Switch	Alarm	16.83%	17
Waterflow Switch	Alarm	5.94%	6

Device Type	Qty	Model #	Type	Description	Install Date
<i>In Service - 3 Years to 5 Years</i>					
5301 Creedmoor Road Standpipe, 5301 Creedmoor Road					
Monitoring	1	XLS-MME3-ADPT	Trouble		01/01/2019
5301 Creedmoor Road Service Main, 5301 Creedmoor Road					
Fire Hydrant	1	BSR	Dry Barrel/Ground	1000 gpm/3786 lpm	11/01/2018
<i>In Service - 5 Years to 10 Years</i>					
5301 Creedmoor Road Standpipe, 5301 Creedmoor Road					
Gauge	3	N/A	System Pressure		04/22/2018
5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road					
Gauge	1	N/A	Supply Pressure		04/22/2018
Gauge	6	N/A	System Pressure		04/22/2018
<i>In Service - 10 Years to 15 Years</i>					
5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road					
Dry Sprinkler	1	M/ VK176	Recessed Horizontal		04/22/2013
Waterflow Switch	1	VSC	Vane	Alarm	04/22/2010
<i>In Service - 15 Years to 25 Years</i>					

5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road

Piping	1		Lightweight Steel		04/22/2008
--------	---	--	-------------------	--	------------

5301 Creedmoor Road Standpipe, 5301 Creedmoor Road

Hose Connection	10	Raleigh			04/22/2002
Hose Connection	8	Raleigh			04/22/2002
Control Valve	5	V0403524-W2	Butterfly	Isolation	04/22/2002
Tamper Switch	1	BFV	Control Valve	Supervisory	04/22/2002
Tamper Switch	3	V0403524-W2	Control Valve	Supervisory	04/22/2002

5301 Creedmoor Road Standpipe, Area-

Hose Connection	1	Raleigh			04/22/2002
-----------------	---	---------	--	--	------------

5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road

Antifreeze System	1		Glycerine		04/22/2002
Sprinkler Box	1				04/22/2002
Antifreeze System	1	V0403524-W2	Glycerine		04/22/2002
Check Valve	2		Grooved		04/22/2002
Check Valve	1	V0403524-W2	Grooved		04/22/2002
Drain	1	Ball	Main		04/22/2002
Sprinkler Box Spares	1	C3101	Upright		04/22/2002
Sprinkler Box Spares	1	C3201	Pendant		04/22/2002
Hose Connection	2	NA			04/22/2002
Hose Connection	2	Raleigh			04/22/2002
Waterflow Switch	4	VSC	Vane	Alarm	04/22/2002
Waterflow Switch	1	VSR	Vane	Alarm	04/22/2002
Control Valve	3	BFV	Butterfly	Isolation	04/22/2002
Control Valve	1	BFV	Butterfly	Main Control	04/22/2002
Control Valve	6	V0403524-W2	Butterfly	Isolation	04/22/2002
Tamper Switch	4	BFV	Control Valve	Supervisory	04/22/2002
Tamper Switch	7	V0403524-W2	Control Valve	Supervisory	04/22/2002
Fast Response	1	B2/ VK404	Concealed Pendant		04/22/2002
Fast Response	1	M/ VK300	Upright		04/22/2002
Fast Response	1	M/ VK302	Recessed Pendant		04/22/2002
Fast Response	1	M/ VK302	Recessed Pendant	Quick Response	04/22/2002
Fast Response	1	M/ VK442	Horizontal Sidewall		04/22/2002
Sprinkler Box Spares	1	VK300	Upright		04/22/2002
Sprinkler Box Spares	2	VK302	Pendant		04/22/2002
Sprinkler Box Spares	1	VK404	Concealed Pendant		04/22/2002
Sprinkler Box Spares	1	VK442	Horizontal Sidewall		04/22/2002

5205-5209 Creedmoor Road Service Main, 5205-5209 Creedmoor Road

Fire Hydrant	1		Dry Barrel/Ground	1000 gpm/3786 lpm	06/15/2001
--------------	---	--	-------------------	-------------------	------------

5301 Creedmoor Road Service Main, 5301 Creedmoor Road

Fire Hydrant	2		Wet Barrel/Ground	1000 gpm/3786 lpm	06/15/2001
--------------	---	--	-------------------	-------------------	------------

In Service - 25 Years or Older**5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road**

Heating System	1				04/22/1998
Fire Dep't Connection	1	A106	Freestanding		04/22/1998
Control Valve	1	OSY	OS&Y	BF Inlet	04/22/1998

Control Valve	1	OSY	OS&Y	BF Outlet	04/22/1998
Tamper Switch	1	OSY	Bf In	Supervisory	04/22/1998
Tamper Switch	1	OSY	Bf Out	Supervisory	04/22/1998

Zone Address Report

Generated by: BuildingReports.com

Building: Magnolia Glen

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location and description are included for your reference. For more information on the device, use the link provided under ScanID.

Address	Device Type	Location	Type	ScanID
Control Panel 1				
Zone/Address: 2				
M27	Waterflow Switch	3rd Str4 south Mech Rm	Vane	14242588
1-58	Tamper Switch	1st Str5 East Closet	Control Valve	15896226
2	Control Valve	4th Str4 south Mech Rm	Butterfly	15896236
2-22	Waterflow Switch	1st Boiler Rm/riser rm Isolation	Vane	14242581
2-25	Waterflow Switch	2nd Str4 south Mech Rm	Vane	15245927
2-26	Tamper Switch	2nd Str4 south Mech Rm	Control Valve	14242583
2-29	Tamper Switch	2nd Str4 south Mech Rm Str4 Isolation	Control Valve	14242584
2-30	Tamper Switch	2nd Str4 south Mech Rm	Control Valve	14242585
2-57	Waterflow Switch	1st Boiler Rm/riser rm Main	Vane	61052776
2-58	Tamper Switch	1st Boiler Rm/riser rm	Control Valve	37502072
3-002	Tamper Switch	4th Str4 south Mech Rm	Control Valve	14242589
5-12	Tamper Switch	1st Str4 south Corridor	Control Valve	15896244
5-24	Tamper Switch	1st Boiler Rm/riser rm	Control Valve	14242580
5-25	Tamper Switch	Loading Dock Hotbox	Bf Out	15896252
5-25	Tamper Switch	Loading Dock Hotbox	Bf In	61055894
06	Control Valve	5th Str4 south Mech Rm	Butterfly	14242591
6-45	Tamper Switch	1st Str1 North	Control Valve	15896240
6-046	Tamper Switch	1st Work Shop Corridor	Control Valve	15896242
6-48	Tamper Switch	1st Rm113 Corridor	Control Valve	14975511
6-50	Tamper Switch	1st Str3 South Corridor	Control Valve	15896243
7-59	Tamper Switch	2nd Main Lobby AFL Door At Executive Director Office	Control Valve	15896209
12	Control Valve	1st Str4 south Corridor	Butterfly	14975510
14-005	Tamper Switch	3rd Str4 south Mech Rm	Control Valve	14242587
14-006	Waterflow Switch	4th Str4 south Mech Rm	Vane	14242590
14-006	Tamper Switch	5th Str4 south Mech Rm	Control Valve	15896238
14-006	Waterflow Switch	5th Str4 south Mech Rm	Vane	15245922
25	Control Valve	Loading Dock Hotbox	OS&Y	61055895
28	Control Valve	2nd Str4 south Mech Rm	Butterfly	15896232
28	Control Valve	3rd Str4 south Mech Rm	Butterfly	15896234
29	Control Valve	2nd Str4 south Mech Rm Str4 Isolation	Butterfly	15896231
30	Control Valve	2nd Str4 south Mech Rm Sprinkler Feed 2&1st	Butterfly	15896230
45	Control Valve	1st Str1 North Corridor 6' Ladder	Butterfly	14975512
48	Control Valve	1st Rm113 Corridor	Butterfly	15896241
50	Control Valve	1st At Str3 South In Hallway	Butterfly	14975508
57	Control Valve	1st Boiler Rm/riser rm	Butterfly	15896247
58	Control Valve	1st Str5 East Closet Different Master Key AL Wing	Butterfly	15896227

Notes & Recommendations

Generated by: BuildingReports.com

Building: Magnolia Glen				
<i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by SystemID.</i>				
Note	Device Type	Location	Comment	ScanID
<i>5301 Creedmoor Road Standpipe, 5301 Creedmoor Road</i>				
1	Gauge Noncritical Deficiency	3rd Str6 East	Date Expired	37502061
2	Gauge Noncritical Deficiency	5th Str1 North	Date Expired	37502049
3	Gauge Noncritical Deficiency	5th Str3 south	Date Expired	37502056
<i>5301 Creedmoor Road Wet Pipe, 5301 Creedmoor Road</i>				
4	Gauge Noncritical Deficiency	1st Boiler Rm/riser rm Noncritical	Date Expired	37502070
5	Gauge Noncritical Deficiency	1st Boiler Rm/riser rm	Date Expired	37502071
6	Gauge Noncritical Deficiency	1st Boiler Rm/riser rm Isolation	Date Expired	15896245
7	Gauge Noncritical Deficiency	2nd Str4 south Mech Rm	Date Expired	37502062
8	Gauge Noncritical Deficiency	3rd Str4 south Mech Rm	Date Expired	15245925
9	Gauge Noncritical Deficiency	4th Str4 south Mech Rm	Date Expired	15245923
10	Gauge Noncritical Deficiency	5th Str4 south Mech Rm	Date Expired	54162887

FIRE SAFETY INSPECTION REPORT

City of Raleigh Fire Department

Office of the Fire Marshal P.O. Box 590 Raleigh, NC 27622 (919) 996-6392 Fax (919) 831-6180

Property Address 5301 CREEDMOOR RD RALEIGH, NC 27612		Inspection Date: <u>06/27/2023</u>
Business Name <u>MAGNOLIA GLEN SENIOR LIVING</u>		Completed By: <u>Olive, Jr., John E.</u>
Building Class R2 -Apartment, Boarding, Dormitories, Covents	Stories 4	Phone <u>OFFC 919-841-4747</u> <u>FAX 919-787-5474</u>
Construction Type 3 Protected	Max Occupancy 200	
Square Foot 152000		
Property Use 459 -Residential board and care		
Violations Are Indicated Below By Code Reference		

901.6 Inspection testing and maintenance

Remarks: "Fire detection, alarm, and extinguishing systems, mechanical smoke exhaust systems, and smoke and heat vents shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Nonrequired fire protection systems and equipment shall be inspected, tested and maintained or the exposed components of such systems shall be removed."

FIRE SPRINKLER GAUGES DUE FOR SERVICE OR REPLACEMENT

901.6 Inspection testing and maintenance

Remarks: "Fire detection, alarm, and extinguishing systems, mechanical smoke exhaust systems, and smoke and heat vents shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Nonrequired fire protection systems and equipment shall be inspected, tested and maintained or the exposed components of such systems shall be removed."

FIRE STANDPIPE GAUGES DUE FOR SERVICE OR REPLACEMENT

901.6 Inspection testing and maintenance

Remarks: "Fire detection, alarm, and extinguishing systems, mechanical smoke exhaust systems, and smoke and heat vents shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Nonrequired fire protection systems and equipment shall be inspected, tested and maintained or the exposed components of such systems shall be removed."

TROUBLE ON THE FIRE ALARM PANEL

TROUBLE SIGNAL WAS NOTED ON THE FIRE INSPECTION IT SAYS BATTERY CHARGER ERROR PARTS HAVE BEEN ORDERED BUT NOT RECEIVED YET FOR THE REPAIRS

THE FOLLOWING ITEMS WERE NOTED ON YOUR FIRE ALARM SYSTEM INSPECTION REPORT

FIRE ALARM BATTERIES DUE FOR REPLACEMENT

901.6 Inspection testing and maintenance

Remarks: "Fire detection, alarm, and extinguishing systems, mechanical smoke exhaust systems, and smoke and heat vents shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Nonrequired fire protection systems and equipment shall be inspected, tested and maintained or the exposed components of such systems shall be removed."

Failure to correct any and all violations identified in this fire inspection report within 30 days will result in a re-inspection fee. This includes faxing all required documentation within 30 days of the original inspection date.

THE FOLLOWING ITEMS WERE NOTED ON YOUR FIRE ALARM INSPECTION REPORT AND NEED CLARIFICATION.

Horn/Strobe

68319040 2nd Total (42) Failed Test

68319041 3rd Total (28) Failed Test/See note

68319042 4th Total (10) Failed Test/ See note

I CANT TELL IF THESE ARE DEVICE NUMBERS OR IF YOU HAVE 80 FAILED HORN STROBES . PLEASE VERIFY THIS WITH YOUR CONTRACTOR

IF YOU HAVE A 80 FAILED STROBES THE BUILDING MUST BE PLACED ON FIRE WATCH

904.12.6.2 Extinguishing system service

Remarks: "Automatic fire-extinguishing systems shall be serviced at least every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion."

WE DO NOT HAVE A CURRENT KITCHEN HOOD FIRE SUPPRESSION SYSTEM IN THE ASSISTED LIVING KITCHEN . IT WAS LAST INSPECTED MAY 2022

THE KITCHEN HOOD IN THE INDEPENDENT LIVING SECTION DOES NOT HAVE AN INSPECTION TAG

Failure to correct any and all violations identified in this fire inspection report within 30 days will result in a re-inspection fee. This includes faxing all required documentation within 30 days of the original inspection date.

Fire Code Permit

City of Raleigh Fire Department

Office of the Fire Marshal P.O. Box 590 Raleigh, NC 27622 (919) 996-6392 Fax (919) 831-6180

Property Address

5301 CREEDMOOR RD
RALEIGH, NC 27612

Permit Issued By

Olive, Jr., John E.

Phone

OFFC 919-841-4747

Business Name

MAGNOLIA GLEN SENIOR LIVING

Inspection District

B4

Stories

4

Date Issued: 06/27/2023

Date Expires: 06/27/2024

Construction Type

3 Protected

Max Occupancy

200

Square Foot

152000

Permit is hereby granted to: MAGNOLIA GLEN SENIOR LIVING

For the following activities:

105.6.36 Places of Assembly

Issued: 06/27/2023

Comments [Location:](#)

Pursuant to the provision of the North Carolina Fire Prevention Code and Raleigh City Ordinance, any violation of these regulations may be grounds for revocation of the permit.

This permit does not take the place of any license required by law and is not transferable. Any change in the use, occupancy, location of premises shall require a new permit.

Approved by: **Olive, Jr., John E.**

Title: **Deputy Fire Marshal**

THIS PERMIT MUST BE POSTED AT ALL TIMES ON THE PREMISES MENTIONED ABOVE

Fire Safety Inspection Invoice

City of Raleigh Fire Department

Office of the Fire Marshal P.O. Box 590 Raleigh, NC 27602 (919) 996-6392 Fax (919) 831-6180

Invoice Number : **_6NE0YED4R**

Inspection Performed at:
MAGNOLIA GLEN SENIOR LIVING
5301 CREEDMOOR RD
RALEIGH, NC 27612

Phone OFFC 919-841-4747
FAX 919-787-5474

Responsible Party:
MAGNOLIA GLEN SENIOR LIVING
CREGG BARBOUR
7900 CREEDMOOR RD
Apt/Room
RALEIGH, NC 27613

Inspection Type
1YR Inspection - Yearly

Inspection Date
06/27/2023

Inspection Completed By
Olive, Jr., John E.

Inspection Fees

PERM 105.6.36 Places of Assembly		92.00
	Inspection Fee Total:	\$618.00
	Citation Fee:	\$0.00
	Permit Fee Total:	\$92.00
	Grand Total:	\$710.00

Please detach the bottom of the invoice and return it with your payment of \$ 710.00 by Thursday July 27, 2023 Failure to comply with this requirement will constitute a misdemeanor charge under the North Carolina Fire Prevention of Raleigh Ordinance.

Make Checks Payable to: City of Raleigh

Include Business Name and Invoice Number on check.

Mail Payment and Application to: City of Raleigh
Revenue Services - AR
P.O. Box 590
Raleigh, NC 27602-0590

Inspection Performed at:
MAGNOLIA GLEN SENIOR LIVING
5301 CREEDMOOR RD
RALEIGH, NC 27612

Responsible Party:
MAGNOLIA GLEN SENIOR LIVING
CREGG BARBOUR
7900 CREEDMOOR RD
RALEIGH, NC 27613

Invoice Number: _6NE0YED4R

Total: \$710.00

Enclosed: _____

To Pay by Credit Card:
Call (919)996 -3200 and Select Option #4

RevenueServices@raleighnc.gov

Payment Location:
222 W Hargett Street
Raleigh Services Lobby

Fire Alarm and Life Safety System Inspection Certificate

For

Magnolia Glen
5301 Creedmoor
Raleigh, NC 27612

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

*Annual Inspection
Inspection Date
Apr 12, 2023*

Building: Magnolia Glen
Contact: Carl Benson
Title: PM

Company: Summit Fire & Security - Raleigh
Contact: James Cogan
Title: Inspector

Executive Summary

Generated by: *BuildingReports.com*

Building Information		
Building: Magnolia Glen	Contact: Carl Benson	
Address: 5301 Creedmoor	Phone: 919-841-4747	
Address:	Fax:	
City/State/ZIP Code: Raleigh, NC 27612	Mobile:	
Country: United States of America	Email: carl.benson@kiscosl.com	
Inspection Performed By		
Company: Summit Fire & Security – Raleigh	Inspector: James Cogan	
Address: 1731 Round Rock Dr	Phone: 9197229521	
Address:	Fax:	
City/State/ZIP Code: Raleigh, North Carolina 27615	Mobile:	
Country: United States of America	Email: JCogan@summitfiresecurity.com	
System Control Unit		
Manufacturer: Siemens	Inspection Date: 03/30/2023	IDC Style:
Model Number: XLS-MME-ADPT	Install Date: 10/24/2016	SLC Style:
Software Version:	Version Date: 12/23/2016	NAC Style:
Location: 3rd Telephone/FACP	Current Protection: Breaker	
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Silent Knight	Model #: SK-5208
Test Time/Date: 4/12/23 11:28:22 AM	Restore Time:	Note:


Inspection Summary

Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	22	3.42%	22	100.00%	20	90.91%	2	9.09%
Indicating	5	0.78%	5	100.00%	2	40.00%	3	60.00%
Initiating	617	95.81%	617	100.00%	617	100.00%	0	0.00%
Totals	644	100%	644	100.00%	639	99.22%	5	0.78%

Certification

Company: Summit Fire & Security - Raleigh

Inspector: James Cogan



Signed: Apr 12, 2023

Building: Magnolia Glen

Contact: Carl Benson



Signed: Apr 12, 2023

Discrepancy Report

Generated by: BuildingReports.com

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
Items listed for Recall or Replacement/Upgrade				
No items found during this inspection.				
🔍 ScanID	📍 Location	🔧 Problem	Address	📖 Reference
Control				
Battery				
52545307	3rd Telephone/FACP	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)
Communicator				
14244542	2nd IL side Telephone Room by room 226	Trouble On Panel	1	
Indicating				
Horn/Strobe				
68319040	2nd Total (42)	Failed Test	1	NFPA 72 Table 10.4.2.2.14(a)
68319041	3rd Total (28)	Failed Test/ See note	1-3 05	
68319042	4th Total (10)	Failed Test/ See note	1-3 05	
Code References				
NFPA 72 Table 10.4.2.2.5(a-e)	<p>(a) Batteries shall be inspected for corrosion or leakage. Tightness of connections shall be checked and ensured. If necessary, battery terminals or connections shall be cleaned and coated. Electrolyte level in lead-acid batteries shall be visibly inspected. (b) Batteries shall be replaced in accordance with the recommendations of the alarm equipment manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations. (c) Operation of battery charger shall be checked in accordance with charger test for the specific type of battery. (d) Discharge Test: With the battery charger disconnected, the batteries shall be load tested following the manufacturer's recommendations. The voltage level shall not fall below the levels specified. Exception: An artificial load equal to the full fire alarm load connected to the battery shall be permitted to be used in conducting this test. (e) With the battery charger disconnected, the terminal voltage shall be measured while supplying the maximum load required by its application. The voltage level shall not fall below the levels specified for the specific type of battery. If the voltage falls below the level specified, corrective action shall be taken and the batteries shall be retested. Exception: An artificial load equal to the full fire alarm load connected to the battery shall be permitted to be used in conducting this test.</p>			
NFPA 72 Table 10.4.2.2.14(a)	<p>Sound pressure level shall be measured with sound level meter meeting ANSI S1.4a, Specifications for sound Level Meters, Type 2 requirements. Levels throughout protected area shall be measured and</p>			

recorded. The sound level meter shall be set in accordance with ANSI S3.41, American National Standard Audible Evacuation signal, using the time-weighted characteristic F (FAST). Record the maximum output when the audible emergency evacuation signal is on.

Proposed Solutions Report

Generated by: *BuildingReports.com*

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT			
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
<i>Control</i>					
Battery					
52545307	3rd Telephone/FACP	Replace	PS12350-NB	T/M	<input type="checkbox"/>
Communicator					
14244542	2nd IL side Telephone Room by room 226	Investigate/Correct	SK-5208	T/M	<input type="checkbox"/>
<i>Indicating</i>					
Horn/Strobe					
68319040	2nd Total (42)	Replace		T/M	<input type="checkbox"/>
68319041	3rd Total (28)	Replace	NS4-24110W	T/M	<input type="checkbox"/>
68319042	4th Total (10)	Replace	NS4-24110W	T/M	<input type="checkbox"/>
				PO #: (none)	T/M

Notes & Recommendations

Generated by: BuildingReports.com

ScanID	Note	Device Type	Location	Comment
Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT		
<i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i>				
<i>Control</i>				
74727778	1	Power Supply	4th IL side Telephone Room by room 432	Passed
Barcode on device				
<i>Indicating</i>				
68319040	2	Horn/Strobe	2nd Total (42)	Failed Test
Unit IL 330				
68319041	3	Horn/Strobe	3rd Total (28)	Failed Test/ See note
Unit IL 215				
68319042	4	Horn/Strobe	4th Total (10)	Failed Test/ See note
Unit 426. 428. 430				
<i>Initiating</i>				
14244621	5	Smoke Detector	1st IL side Room 105 Living Room	Passed
Under construction				
14244042	6	Smoke Detector	5th IL side Electrical Room by room 521	Passed
Barcode on device				
14243950	7	Smoke Detector	5th IL side Mechanical Room by room 533	Passed
Barcode on Device				

Inspection & Testing

Generated by: BuildingReports.com

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT		
<p><i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i></p>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	2nd Main entrance by reception desk	Tested	12:40:59 PM	03/30/2023
Annunciator	2nd AL side Front entrance in lobby	Tested	1:40:23 PM	03/30/2023
Battery	2nd IL side Telephone Room by room 226	Tested	2:32:49 PM	03/29/2023
Battery	2nd IL side Telephone Room by room 226	Tested	2:34:41 PM	03/29/2023
Battery	2nd IL side Telephone Room by room 226	Tested	2:36:26 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332	Tested	2:17:56 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332 Bottom	Tested	2:16:01 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332 Too right	Tested	2:12:51 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332 Top left	Tested	2:06:51 PM	03/29/2023
Battery	4th IL side Telephone Room by room 432	Tested	2:54:37 PM	03/29/2023
Battery	5th IL side Mechanical Room by room 532	Tested	1:52:38 PM	03/29/2023
Control Panel	3rd Telephone/FACP	Tested	12:37:27 PM	03/30/2023
Power Supply	2nd IL side Telephone Room by room 226	Tested	2:31:48 PM	03/29/2023
Power Supply	2nd IL side Telephone Room by room 226	Tested	2:38:05 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:06:39 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:11:46 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:15:49 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:17:49 PM	03/29/2023
Power Supply	4th IL side Telephone Room by room 432	Tested	2:54:17 PM	03/29/2023
Power Supply	5th IL side Mechanical Room by room 532	Tested	1:52:26 PM	03/29/2023
Indicating				
Horn/Strobe	1st Total (49)	Tested	3:14:48 PM	03/30/2023
Horn/Strobe	5th Total (11)	Tested	9:30:47 PM	03/30/2023
Initiating				
Duct Detector	3rd by room A303	Tested	1:12:16 PM	03/30/2023
Duct Detector	3rd by room A311	Tested	1:09:13 PM	03/30/2023
Duct Detector	5th by room 503	Tested	12:50:08 PM	03/30/2023
Duct Detector	5th by room 518	Tested	12:45:34 PM	03/30/2023
Heat Detector	1st AL side Laundry	Tested	11:13:59 AM	04/12/2023
Heat Detector	1st Elevator Equipment B	Tested	4:15:16 PM	04/06/2023
Heat Detector	1st Elevator Equipment Room A	Tested	4:15:19 PM	04/06/2023
Heat Detector	1st Elevator Equipment Room D	Tested	3:52:19 PM	04/06/2023
Heat Detector	1st Elevator Equipment w C	Tested	4:15:09 PM	04/06/2023
Heat Detector	1st IL side Laundry	Tested	10:27:31 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:10:19 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:10:56 AM	04/12/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	1st bistro kitchen	Tested	10:11:02 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:11:34 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:11:43 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:11:53 AM	04/12/2023
Heat Detector	1st main mechanical/ electrical room	Tested	10:59:11 AM	04/12/2023
Heat Detector	1st main mechanical/ electrical room	Tested	10:59:57 AM	04/12/2023
Heat Detector	1st main mechanical/ electrical room	Tested	11:00:25 AM	04/12/2023
Heat Detector	1st mech room in corridor by fitness	Tested	10:42:39 AM	04/12/2023
Heat Detector	1st workshop maintenance office	Tested	10:46:28 AM	04/12/2023
Heat Detector	1st workshop hallway kitchen mech room beside office	Tested	10:54:41 AM	04/12/2023
Heat Detector	1st workshop hallway mech room beside maintenance office	Tested	10:50:02 AM	04/12/2023
Heat Detector	2nd 1st Floor AL Kitchen	Tested	11:10:35 AM	04/12/2023
Heat Detector	2nd 1st Floor AL Kitchen	Tested	11:11:17 AM	04/12/2023
Heat Detector	2nd 1st Floor AL Kitchen	Tested	11:11:43 AM	04/12/2023
Heat Detector	2nd 1st Floor AL side soiled utility	Tested	11:17:56 AM	04/12/2023
Heat Detector	2nd AL side Laundry	Tested	3:29:53 PM	04/06/2023
Heat Detector	2nd IL side electrical/Mech room by Salon & Spa	Tested	9:39:55 AM	04/12/2023
Heat Detector	2nd IL side laundry	Inspected	11:10:52 AM	03/29/2023
Heat Detector	2nd conference room mechanical closet near Executive Director room	Tested	9:51:28 AM	04/12/2023
Heat Detector	3rd AL side Laundry	Tested	3:23:22 PM	04/06/2023
Heat Detector	3rd IL side Laundry	Tested	12:58:30 PM	03/30/2023
Heat Detector	4th IL side Laundry	Inspected	12:53:56 PM	03/30/2023
Heat Detector	5th IL side Laundry	Inspected	12:47:33 PM	03/30/2023
Pull Station	1st Cafeteria dining room by exit	Tested	10:15:39 AM	04/12/2023
Pull Station	1st Cafeteria dining room by exit	Tested	10:15:56 AM	04/12/2023
Pull Station	1st Chapel	Tested	10:26:21 AM	04/12/2023
Pull Station	1st Corridor by Fitness Center	Tested	10:25:28 AM	04/12/2023
Pull Station	1st Dining Room by exit	Tested	10:17:52 AM	04/12/2023
Pull Station	1st IL side by room 102	Tested	10:32:51 AM	04/12/2023
Pull Station	1st Main Mechanical/Electrical Room	Tested	11:02:11 AM	04/12/2023
Pull Station	1st Pool area	Tested	10:37:21 AM	04/12/2023
Pull Station	1st The Bistro by exit	Tested	10:18:18 AM	04/12/2023
Pull Station	1st Workshop hallway by Staff Lounge	Tested	10:10:03 AM	04/12/2023
Pull Station	2nd AL side Front entrance	Tested	1:32:49 PM	03/30/2023
Pull Station	2nd AL side near stairwell 6	Tested	1:45:52 PM	03/30/2023
Pull Station	2nd By freight elevator near AL Kitchen	Tested	1:44:14 PM	03/30/2023
Pull Station	2nd Corridor near stairwell 4 by Receiving	Tested	1:30:06 PM	03/30/2023
Pull Station	2nd Front Lobby	Tested	1:27:38 PM	03/30/2023
Pull Station	2nd Front Lobby near stairwell 3	Tested	1:21:05 PM	03/30/2023
Pull Station	2nd Hallway by stairwell 1 IL Side	Tested	1:25:59 PM	03/30/2023
Pull Station	2nd Hallway by stairwell 5 AL side	Tested	1:16:37 PM	03/30/2023
Pull Station	2nd Hallway by stairwell 6 AL side	Tested	1:17:30 PM	03/30/2023
Pull Station	2nd Legacy Health Services	Tested	1:30:59 PM	03/30/2023
Pull Station	3rd Hallway by stairwell 1 IL side	Tested	10:07:52 AM	03/24/2023
Pull Station	3rd Hallway by stairwell 3 IL side	Tested	10:11:23 AM	03/24/2023
Pull Station	3rd Hallway by stairwell 4 IL side	Tested	1:15:59 PM	03/30/2023
Pull Station	3rd Hallway by stairwell 5 AL side	Tested	1:57:04 PM	03/24/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	3rd Hallway by stairwell 6 AL side	Tested	1:59:14 PM	03/24/2023
Pull Station	4th Hallway by stairwell 1 IL Side	Tested	2:18:37 PM	03/24/2023
Pull Station	4th Hallway by stairwell 3 IL Side	Tested	2:09:08 PM	03/24/2023
Pull Station	4th Hallway by stairwell 4 IL Side	Tested	2:02:41 PM	03/24/2023
Pull Station	5th Hallway by stairwell 1 IL side	Tested	11:12:01 AM	03/24/2023
Pull Station	5th Hallway by stairwell 3 IL side	Tested	10:59:04 AM	03/24/2023
Pull Station	5th Hallway by stairwell 4 IL side	Tested	11:27:59 AM	03/24/2023
Smoke Detector	1st hallway by Fitness Center	Tested/Cleaned	10:22:19 AM	04/12/2023
Smoke Detector	1st AL side Electrical Room by A106	Tested/Cleaned	11:18:41 AM	04/12/2023
Smoke Detector	1st AL side Front Lobby	Tested/Cleaned	9:25:18 AM	04/12/2023
Smoke Detector	1st AL side Living/Lounge Area	Tested/Cleaned	3:43:38 PM	04/06/2023
Smoke Detector	1st AL side Living/Lounge Area	Tested/Cleaned	9:26:24 AM	04/12/2023
Smoke Detector	1st AL side Room A101 Living Room	Tested/Cleaned	1:00:45 PM	03/29/2023
Smoke Detector	1st AL side Room A101 Living Room	Tested/Cleaned	1:01:02 PM	03/29/2023
Smoke Detector	1st AL side Room A102 Bedroom	Tested/Cleaned	1:01:46 PM	03/29/2023
Smoke Detector	1st AL side Room A102 Living Room	Tested/Cleaned	1:01:38 PM	03/29/2023
Smoke Detector	1st AL side Room A103 Living Room	Tested/Cleaned	1:02:06 PM	03/29/2023
Smoke Detector	1st AL side Room A105 Bedroom	Tested/Cleaned	1:04:07 PM	03/29/2023
Smoke Detector	1st AL side Room A105 Living Room	Tested/Cleaned	1:03:59 PM	03/29/2023
Smoke Detector	1st AL side Room A106 Bed room	Tested/Cleaned	1:04:32 PM	03/29/2023
Smoke Detector	1st AL side Room A106 Bedroom	Tested/Cleaned	1:04:25 PM	03/29/2023
Smoke Detector	1st AL side Room A107 Living Room	Tested/Cleaned	12:59:27 PM	03/29/2023
Smoke Detector	1st AL side Room A108 Living Room	Tested/Cleaned	12:59:12 PM	03/29/2023
Smoke Detector	1st AL side Room A109 Bedroom	Tested/Cleaned	12:54:07 PM	03/29/2023
Smoke Detector	1st AL side Room A110 Bedroom	Tested/Cleaned	1:06:01 PM	03/29/2023
Smoke Detector	1st AL side Room A110 Living Room	Tested/Cleaned	1:05:54 PM	03/29/2023
Smoke Detector	1st AL side Trash Room	Tested/Cleaned	3:41:36 PM	04/06/2023
Smoke Detector	1st Corridor by Fitness Center	Tested/Cleaned	10:25:16 AM	04/12/2023
Smoke Detector	1st Corridor by Fitness Center	Tested/Cleaned	10:25:23 AM	04/12/2023
Smoke Detector	1st Elevator Equipment Room A	Tested/Cleaned	4:15:57 PM	04/06/2023
Smoke Detector	1st Elevator Equipment Room B	Tested/Cleaned	4:15:53 PM	04/06/2023
Smoke Detector	1st Elevator Equipment Room C	Tested/Cleaned	4:16:01 PM	04/06/2023
Smoke Detector	1st Elevator Equipment Room D	Tested/Cleaned	3:52:22 PM	04/06/2023
Smoke Detector	1st Elevator Lobby A	Tested/Cleaned	2:28:33 PM	04/06/2023
Smoke Detector	1st Elevator Lobby B	Tested/Cleaned	10:21:02 AM	04/12/2023
Smoke Detector	1st Elevator Lobby C	Tested/Cleaned	2:49:49 PM	04/06/2023
Smoke Detector	1st Hallway by Fitness Center	Tested/Cleaned	10:21:27 AM	04/12/2023
Smoke Detector	1st IL side Electrical Room by room 105	Tested/Cleaned	10:30:55 AM	04/12/2023
Smoke Detector	1st IL side Room 101 Living Room	Tested/Cleaned	1:31:34 PM	03/29/2023
Smoke Detector	1st IL side Room 102 Bedroom	Tested/Cleaned	1:33:18 PM	03/29/2023
Smoke Detector	1st IL side Room 102 Bedroom	Tested/Cleaned	1:33:52 PM	03/29/2023
Smoke Detector	1st IL side Room 102 Living Room	Tested/Cleaned	1:32:54 PM	03/29/2023
Smoke Detector	1st IL side Room 103 Bedroom	Tested/Cleaned	1:30:18 PM	03/29/2023
Smoke Detector	1st IL side Room 103 Living Room	Tested/Cleaned	1:30:06 PM	03/29/2023
Smoke Detector	1st IL side Room 104 Bedroom	Tested/Cleaned	1:28:03 PM	03/29/2023
Smoke Detector	1st IL side Room 104 Living Room	Tested/Cleaned	1:26:49 PM	03/29/2023
Smoke Detector	1st IL side Room 105 Bedroom	Inspected	1:25:29 PM	03/29/2023
Smoke Detector	1st IL side Room 105 Living Room	Inspected	1:25:46 PM	03/29/2023
Smoke Detector	1st IL side Room 106 Living Room	Tested/Cleaned	1:23:55 PM	03/29/2023
Smoke Detector	1st IL side Room 107 Bedroom	Tested/Cleaned	1:19:58 PM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st IL side Room 107 Bedroom	Tested/Cleaned	1:20:15 PM	03/29/2023
Smoke Detector	1st IL side Room 107 Living Room	Tested/Cleaned	1:21:10 PM	03/29/2023
Smoke Detector	1st IL side Room 108 Bedroom	Tested/Cleaned	1:22:01 PM	03/29/2023
Smoke Detector	1st IL side Room 108 Living Room	Tested/Cleaned	1:22:32 PM	03/29/2023
Smoke Detector	1st IL side Room 109 Bedroom	Tested/Cleaned	1:16:55 PM	03/29/2023
Smoke Detector	1st IL side Room 109 Living Room	Tested/Cleaned	1:17:06 PM	03/29/2023
Smoke Detector	1st IL side Room 110 Bedroom	Tested/Cleaned	1:18:07 PM	03/29/2023
Smoke Detector	1st IL side Room 110 Living Room	Tested/Cleaned	1:18:49 PM	03/29/2023
Smoke Detector	1st IL side Room 111 Bedroom	Tested/Cleaned	1:13:24 PM	03/29/2023
Smoke Detector	1st IL side Room 111 Living Room	Tested/Cleaned	1:13:48 PM	03/29/2023
Smoke Detector	1st IL side Room 112 Bedroom	Tested/Cleaned	1:14:55 PM	03/29/2023
Smoke Detector	1st IL side Room 112 Living Room	Tested/Cleaned	1:15:15 PM	03/29/2023
Smoke Detector	1st IL side Room 113 Bedroom	Tested/Cleaned	1:12:05 PM	03/29/2023
Smoke Detector	1st IL side Room 113 Living Room	Tested/Cleaned	1:12:23 PM	03/29/2023
Smoke Detector	1st IL side Trash room by 113	Tested/Cleaned	10:34:45 AM	04/12/2023
Smoke Detector	1st IL side fire doors by room by 113	Tested/Cleaned	10:28:35 AM	04/12/2023
Smoke Detector	1st IL side fire doors by room by 113	Tested/Cleaned	10:29:10 AM	04/12/2023
Smoke Detector	1st IL side hallway by pool	Tested/Cleaned	10:27:09 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 102	Tested/Cleaned	10:32:38 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 104	Tested/Cleaned	1:03:30 PM	03/29/2023
Smoke Detector	1st IL side hallway by room 104	Tested/Cleaned	10:32:28 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 105	Tested/Cleaned	10:30:41 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 107	Tested/Cleaned	10:30:27 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 109	Tested/Cleaned	1:07:14 PM	03/29/2023
Smoke Detector	1st IL side hallway by room 109	Tested/Cleaned	10:30:14 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 111	Tested/Cleaned	10:29:59 AM	04/12/2023
Smoke Detector	1st In Room IL/CR Across From Fitness Center In Left Closet	Tested/Cleaned	10:22:42 AM	04/12/2023
Smoke Detector	1st Kitchen by office	Tested/Cleaned	10:12:39 AM	04/12/2023
Smoke Detector	1st Main Mechanical/Electrical Room	Tested/Cleaned	11:00:35 AM	04/12/2023
Smoke Detector	1st Main Mechanical/Electrical Room	Tested/Cleaned	11:03:59 AM	04/12/2023
Smoke Detector	1st Media Worship Center across from pool	Tested/Cleaned	10:40:50 AM	04/12/2023
Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Tested/Cleaned	10:04:38 AM	04/12/2023
Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Tested/Cleaned	10:05:22 AM	04/12/2023
Smoke Detector	1st Workshop	Tested/Cleaned	10:46:22 AM	04/12/2023
Smoke Detector	1st Workshop Electrical Room	Tested/Cleaned	11:06:39 AM	04/12/2023
Smoke Detector	1st Workshop Mechanical Room	Tested/Cleaned	10:48:38 AM	04/12/2023
Smoke Detector	1st Workshop Hallway	Tested/Cleaned	10:45:42 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:51:23 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:52:19 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:53:06 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:57:27 AM	04/12/2023
Smoke Detector	1st Workshop hallway Mech room beside Dining Services Office	Tested/Cleaned	10:54:11 AM	04/12/2023
Smoke Detector	1st Workshop hallway by Clean Linen	Tested/Cleaned	10:07:43 AM	04/12/2023
Smoke Detector	1st Workshop hallway by Staff Lounge	Tested/Cleaned	10:09:09 AM	04/12/2023
Smoke Detector	1st Workshop hallway by kitchen	Tested/Cleaned	10:08:29 AM	04/12/2023
Smoke Detector	1st elevator lobby D	Tested/Cleaned	10:06:46 AM	04/12/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st mech room in Corridor by Fitness Center	Tested/Cleaned	10:42:07 AM	04/12/2023
Smoke Detector	1st pool mechanical rm in pool area	Tested/Cleaned	10:39:26 AM	04/12/2023
Smoke Detector	2nd 1st Floor AL side Soiled Linen By A101	Tested/Cleaned	11:17:21 AM	04/12/2023
Smoke Detector	2nd AL side At room A201	Tested/Cleaned	10:23:20 AM	03/24/2023
Smoke Detector	2nd AL side At room A204	Tested/Cleaned	10:22:07 AM	03/24/2023
Smoke Detector	2nd AL side At room A208	Tested/Cleaned	10:21:18 AM	03/24/2023
Smoke Detector	2nd AL side At room A209	Tested/Cleaned	10:20:10 AM	03/24/2023
Smoke Detector	2nd AL side At room A211	Tested/Cleaned	10:18:14 AM	03/24/2023
Smoke Detector	2nd AL side At room A213	Tested/Cleaned	10:30:53 AM	03/24/2023
Smoke Detector	2nd AL side At room A214	Tested/Cleaned	10:31:13 AM	03/24/2023
Smoke Detector	2nd AL side At room A216	Tested/Cleaned	10:31:24 AM	03/24/2023
Smoke Detector	2nd AL side At room A218	Tested/Cleaned	10:31:34 AM	03/24/2023
Smoke Detector	2nd AL side At stairwell 5	Tested/Cleaned	10:19:09 AM	03/24/2023
Smoke Detector	2nd AL side At stairwell 5	Tested/Cleaned	3:31:06 PM	04/06/2023
Smoke Detector	2nd AL side By Legacy Health Services	Tested/Cleaned	9:26:48 AM	04/12/2023
Smoke Detector	2nd AL side By Room A102	Tested/Cleaned	3:39:59 PM	04/06/2023
Smoke Detector	2nd AL side By Room A104	Tested/Cleaned	9:58:25 AM	04/12/2023
Smoke Detector	2nd AL side By Room A105	Tested/Cleaned	3:40:43 PM	04/06/2023
Smoke Detector	2nd AL side By Room A110	Tested/Cleaned	9:57:57 AM	04/12/2023
Smoke Detector	2nd AL side By Staff Lounge near Receiving	Tested/Cleaned	9:27:37 AM	04/12/2023
Smoke Detector	2nd AL side By Trash Room	Tested/Cleaned	9:58:10 AM	04/12/2023
Smoke Detector	2nd AL side By stairwell 4 near Receiving	Tested/Cleaned	9:27:47 AM	04/12/2023
Smoke Detector	2nd AL side By stairwell 4 near Receiving	Tested/Cleaned	9:27:55 AM	04/12/2023
Smoke Detector	2nd AL side In Dining At Kitchen Door	Tested/Cleaned	9:59:49 AM	04/12/2023
Smoke Detector	2nd AL side Room A201 Bedroom	Tested/Cleaned	2:41:34 PM	03/28/2023
Smoke Detector	2nd AL side Room A201 Living Room	Tested/Cleaned	2:41:28 PM	03/28/2023
Smoke Detector	2nd AL side Room A202 Bedroom	Tested/Cleaned	2:40:05 PM	03/28/2023
Smoke Detector	2nd AL side Room A202 Living Room	Tested/Cleaned	2:39:53 PM	03/28/2023
Smoke Detector	2nd AL side Room A203 Living Room	Tested/Cleaned	2:38:49 PM	03/28/2023
Smoke Detector	2nd AL side Room A204 Living Room	Tested/Cleaned	2:37:23 PM	03/28/2023
Smoke Detector	2nd AL side Room A206 Bedroom	Tested/Cleaned	2:34:28 PM	03/28/2023
Smoke Detector	2nd AL side Room A206 Living Room	Tested/Cleaned	2:33:43 PM	03/28/2023
Smoke Detector	2nd AL side Room A207 Living Room	Tested/Cleaned	2:42:34 PM	03/28/2023
Smoke Detector	2nd AL side Room A208 Living Room	Tested/Cleaned	2:42:11 PM	03/28/2023
Smoke Detector	2nd AL side Room A209 Bedroom	Tested/Cleaned	2:44:20 PM	03/28/2023
Smoke Detector	2nd AL side Room A209 Living Room	Tested/Cleaned	2:44:05 PM	03/28/2023
Smoke Detector	2nd AL side Room A210 Bedroom	Tested/Cleaned	2:45:09 PM	03/28/2023
Smoke Detector	2nd AL side Room A210 Living Room	Tested/Cleaned	2:45:19 PM	03/28/2023
Smoke Detector	2nd AL side Room A211 Bedroom	Tested/Cleaned	9:34:06 AM	03/29/2023
Smoke Detector	2nd AL side Room A212 Bedroom	Tested/Cleaned	9:31:18 AM	03/29/2023
Smoke Detector	2nd AL side Room A212 Living Room	Tested/Cleaned	9:30:09 AM	03/29/2023
Smoke Detector	2nd AL side Room A213 Bedroom	Tested/Cleaned	9:30:33 AM	03/29/2023
Smoke Detector	2nd AL side Room A213 Living room	Tested/Cleaned	9:30:17 AM	03/29/2023
Smoke Detector	2nd AL side Room A215 Living Room	Tested/Cleaned	9:32:31 AM	03/29/2023
Smoke Detector	2nd AL side Room A216 Living Room	Tested/Cleaned	9:35:14 AM	03/29/2023
Smoke Detector	2nd AL side Room A217 Living Room	Tested/Cleaned	9:33:06 AM	03/29/2023
Smoke Detector	2nd AL side Room A218 Bedroom	Tested/Cleaned	9:37:47 AM	03/29/2023
Smoke Detector	2nd AL side Room A218 Living Room	Tested/Cleaned	9:36:35 AM	03/29/2023
Smoke Detector	2nd AL side Room A219 Bedroom	Tested/Cleaned	9:35:56 AM	03/29/2023
Smoke Detector	2nd AL side Room A219 Living Room	Tested/Cleaned	9:35:33 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd AL side Soiled Utility Room by room A201	Tested/Cleaned	3:25:55 PM	04/06/2023
Smoke Detector	2nd AL side Trash room	Tested/Cleaned	10:28:12 AM	03/24/2023
Smoke Detector	2nd AL side near cafe	Tested/Cleaned	9:25:47 AM	04/12/2023
Smoke Detector	2nd AL side near front lobby By Room A109 At Fire Doors	Tested/Cleaned	9:58:49 AM	04/12/2023
Smoke Detector	2nd AL side near front lobby By Room A110	Tested/Cleaned	9:57:19 AM	04/12/2023
Smoke Detector	2nd AL side stairwell 6	Tested/Cleaned	10:23:48 AM	03/24/2023
Smoke Detector	2nd Elevator Lobby A	Tested/Cleaned	2:19:03 PM	04/06/2023
Smoke Detector	2nd Elevator Lobby B	Tested/Cleaned	9:33:12 AM	04/12/2023
Smoke Detector	2nd Elevator Lobby C	Tested/Cleaned	2:44:09 PM	04/06/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	1:32:55 PM	03/24/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	1:37:23 PM	03/24/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	9:34:37 AM	04/12/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	9:36:08 AM	04/12/2023
Smoke Detector	2nd Front Lobby Above Light	Tested/Cleaned	9:34:46 AM	04/12/2023
Smoke Detector	2nd Front Lobby At Main Desk	Tested/Cleaned	9:35:23 AM	04/12/2023
Smoke Detector	2nd Front Lobby hallway near Conference Room	Tested/Cleaned	1:34:33 PM	03/24/2023
Smoke Detector	2nd Front Lobby hallway near Human Resources	Tested/Cleaned	1:38:18 PM	03/24/2023
Smoke Detector	2nd Front Lobby hallway near Sales	Tested/Cleaned	1:39:23 PM	03/24/2023
Smoke Detector	2nd Front Lobby near Copy Room	Tested/Cleaned	1:33:56 PM	03/24/2023
Smoke Detector	2nd Front Lobby near mailboxes	Tested/Cleaned	9:33:27 AM	04/12/2023
Smoke Detector	2nd IL side At Room 205	Tested/Cleaned	1:44:41 PM	03/24/2023
Smoke Detector	2nd IL side At Room 206	Tested/Cleaned	1:48:31 PM	03/24/2023
Smoke Detector	2nd IL side At Room 210	Tested/Cleaned	1:42:47 PM	03/24/2023
Smoke Detector	2nd IL side At Room 212	Tested/Cleaned	1:42:32 PM	03/24/2023
Smoke Detector	2nd IL side At Room 213	Tested/Cleaned	9:36:56 AM	04/12/2023
Smoke Detector	2nd IL side At Room IL/CA Near front lobby	Tested/Cleaned	9:36:39 AM	04/12/2023
Smoke Detector	2nd IL side By Room 201	Tested/Cleaned	1:47:01 PM	03/24/2023
Smoke Detector	2nd IL side By Room 214	Tested/Cleaned	1:29:29 PM	03/24/2023
Smoke Detector	2nd IL side By Room 218	Tested/Cleaned	9:32:48 AM	04/12/2023
Smoke Detector	2nd IL side By Room 220	Tested/Cleaned	9:32:36 AM	04/12/2023
Smoke Detector	2nd IL side By Room 222	Tested/Cleaned	9:32:25 AM	04/12/2023
Smoke Detector	2nd IL side By Room 223	Tested/Cleaned	9:32:13 AM	04/12/2023
Smoke Detector	2nd IL side By Room 225	Tested/Cleaned	9:32:02 AM	04/12/2023
Smoke Detector	2nd IL side Electrical Room In card table room	Tested/Cleaned	9:43:17 AM	04/12/2023
Smoke Detector	2nd IL side Electrical Room by room 226	Tested/Cleaned	9:28:25 AM	04/12/2023
Smoke Detector	2nd IL side Electrical/Mechanical Room by Salon	Tested/Cleaned	9:40:01 AM	04/12/2023
Smoke Detector	2nd IL side Mechanical Room In Library	Tested/Cleaned	9:46:13 AM	04/12/2023
Smoke Detector	2nd IL side Mechanical Room In card table room	Tested/Cleaned	9:38:17 AM	04/12/2023
Smoke Detector	2nd IL side Room 201 Bedroom	Tested/Cleaned	10:52:26 AM	03/29/2023
Smoke Detector	2nd IL side Room 201 Bedroom	Tested/Cleaned	10:53:11 AM	03/29/2023
Smoke Detector	2nd IL side Room 201 Living Room	Tested/Cleaned	10:52:41 AM	03/29/2023
Smoke Detector	2nd IL side Room 202 Living Room	Tested/Cleaned	10:58:01 AM	03/29/2023
Smoke Detector	2nd IL side Room 203 Bedroom	Tested/Cleaned	10:57:17 AM	03/29/2023
Smoke Detector	2nd IL side Room 203 Living Room	Tested/Cleaned	10:57:08 AM	03/29/2023
Smoke Detector	2nd IL side Room 204 Bedroom	Tested/Cleaned	11:00:20 AM	03/29/2023
Smoke Detector	2nd IL side Room 204 Bedroom	Tested/Cleaned	11:00:32 AM	03/29/2023
Smoke Detector	2nd IL side Room 206 Living Room	Tested/Cleaned	11:01:12 AM	03/29/2023
Smoke Detector	2nd IL side Room 207 Bedroom	Tested/Cleaned	11:07:29 AM	03/29/2023
Smoke Detector	2nd IL side Room 208 Bedroom	Tested/Cleaned	11:02:54 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd IL side Room 208 Living Room	Tested/Cleaned	11:03:23 AM	03/29/2023
Smoke Detector	2nd IL side Room 210 Bedroom	Tested/Cleaned	11:05:38 AM	03/29/2023
Smoke Detector	2nd IL side Room 210 Living Room	Tested/Cleaned	11:05:31 AM	03/29/2023
Smoke Detector	2nd IL side Room 212 Bedroom	Tested/Cleaned	11:08:29 AM	03/29/2023
Smoke Detector	2nd IL side Room 212 Living Room	Tested/Cleaned	11:08:21 AM	03/29/2023
Smoke Detector	2nd IL side Room 214 Bedroom	Tested/Cleaned	12:08:29 PM	03/29/2023
Smoke Detector	2nd IL side Room 214 Living Room	Tested/Cleaned	12:08:07 PM	03/29/2023
Smoke Detector	2nd IL side Room 215 Bedroom	Tested/Cleaned	12:10:50 PM	03/29/2023
Smoke Detector	2nd IL side Room 215 Bedroom	Tested/Cleaned	12:11:58 PM	03/29/2023
Smoke Detector	2nd IL side Room 216 Bed Room	Tested/Cleaned	12:14:51 PM	03/29/2023
Smoke Detector	2nd IL side Room 216 Living Room	Tested/Cleaned	12:14:14 PM	03/29/2023
Smoke Detector	2nd IL side Room 217 Bed Room	Tested/Cleaned	12:19:25 PM	03/29/2023
Smoke Detector	2nd IL side Room 217 Living Room	Tested/Cleaned	12:16:54 PM	03/29/2023
Smoke Detector	2nd IL side Room 218 Bedroom	Tested/Cleaned	12:22:43 PM	03/29/2023
Smoke Detector	2nd IL side Room 218 Bedroom	Tested/Cleaned	12:22:56 PM	03/29/2023
Smoke Detector	2nd IL side Room 219 Bedroom	Tested/Cleaned	12:25:44 PM	03/29/2023
Smoke Detector	2nd IL side Room 219 Living Room	Tested/Cleaned	12:25:31 PM	03/29/2023
Smoke Detector	2nd IL side Room 220 Bed Room	Tested/Cleaned	12:29:23 PM	03/29/2023
Smoke Detector	2nd IL side Room 220 Living Room	Tested/Cleaned	12:29:03 PM	03/29/2023
Smoke Detector	2nd IL side Room 221 Bed Room	Tested/Cleaned	12:42:37 PM	03/29/2023
Smoke Detector	2nd IL side Room 221 Bedroom	Tested/Cleaned	12:39:07 PM	03/29/2023
Smoke Detector	2nd IL side Room 222 Bedroom	Tested/Cleaned	12:32:13 PM	03/29/2023
Smoke Detector	2nd IL side Room 222 Living Room	Tested/Cleaned	12:32:06 PM	03/29/2023
Smoke Detector	2nd IL side Room 224 Bedroom	Tested/Cleaned	12:44:00 PM	03/29/2023
Smoke Detector	2nd IL side Room 224 Living Room	Tested/Cleaned	12:43:50 PM	03/29/2023
Smoke Detector	2nd IL side Room 225 Bedroom	Tested/Cleaned	12:44:05 PM	03/29/2023
Smoke Detector	2nd IL side Room 225 Bedroom	Tested/Cleaned	12:44:18 PM	03/29/2023
Smoke Detector	2nd IL side Room 226 Living Room	Tested/Cleaned	12:45:55 PM	03/29/2023
Smoke Detector	2nd IL side Telephone Room	Tested/Cleaned	9:30:26 AM	04/12/2023
Smoke Detector	2nd IL side Trash Room	Tested/Cleaned	1:48:00 PM	03/24/2023
Smoke Detector	2nd IL side Trash Room by room 214	Tested/Cleaned	1:30:41 PM	03/24/2023
Smoke Detector	2nd conference room mech closet behind front desk	Tested/Cleaned	9:51:23 AM	04/12/2023
Smoke Detector	2nd elevator lobby D	Tested/Cleaned	1:25:45 PM	04/06/2023
Smoke Detector	3rd AL side At Room A302	Tested/Cleaned	2:31:04 PM	03/30/2023
Smoke Detector	3rd AL side At Room A303	Tested/Cleaned	1:58:24 PM	03/24/2023
Smoke Detector	3rd AL side At Room A305	Tested/Cleaned	1:59:30 PM	03/24/2023
Smoke Detector	3rd AL side At Room A307	Tested/Cleaned	2:21:55 PM	03/30/2023
Smoke Detector	3rd AL side At Room A309	Tested/Cleaned	2:22:10 PM	03/30/2023
Smoke Detector	3rd AL side At Room A311	Tested/Cleaned	1:55:43 PM	03/24/2023
Smoke Detector	3rd AL side At Room A315	Tested/Cleaned	1:55:14 PM	03/24/2023
Smoke Detector	3rd AL side At Room A317	Tested/Cleaned	1:54:19 PM	03/24/2023
Smoke Detector	3rd AL side At Room A319	Tested/Cleaned	1:53:57 PM	03/24/2023
Smoke Detector	3rd AL side Room 303 Bedroom	Tested/Cleaned	10:33:54 AM	03/29/2023
Smoke Detector	3rd AL side Room 303 Living Room	Tested/Cleaned	10:34:03 AM	03/29/2023
Smoke Detector	3rd AL side Room A301 Bedroom	Tested/Cleaned	2:26:11 PM	03/28/2023
Smoke Detector	3rd AL side Room A301 Living room	Tested/Cleaned	2:27:11 PM	03/28/2023
Smoke Detector	3rd AL side Room A302 Bedroom	Tested/Cleaned	2:26:58 PM	03/28/2023
Smoke Detector	3rd AL side Room A303 Living room	Tested/Cleaned	2:29:09 PM	03/28/2023
Smoke Detector	3rd AL side Room A304 Living room	Tested/Cleaned	2:29:53 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd AL side Room A305 Bedroom	Tested/Cleaned	2:32:07 PM	03/28/2023
Smoke Detector	3rd AL side Room A305 Living room	Tested/Cleaned	2:31:21 PM	03/28/2023
Smoke Detector	3rd AL side Room A306 Bedroom	Tested/Cleaned	2:30:51 PM	03/28/2023
Smoke Detector	3rd AL side Room A306 Living Room	Tested/Cleaned	2:32:00 PM	03/28/2023
Smoke Detector	3rd AL side Room A307 Living Room	Tested/Cleaned	2:23:54 PM	03/28/2023
Smoke Detector	3rd AL side Room A308 Living Room	Tested/Cleaned	2:24:53 PM	03/28/2023
Smoke Detector	3rd AL side Room A309 Bedroom	Tested/Cleaned	2:22:47 PM	03/28/2023
Smoke Detector	3rd AL side Room A310 Bedroom	Tested/Cleaned	2:21:41 PM	03/28/2023
Smoke Detector	3rd AL side Room A310 Living Room	Tested/Cleaned	2:24:18 PM	03/28/2023
Smoke Detector	3rd AL side Room A313 Bedroom	Tested/Cleaned	2:18:03 PM	03/28/2023
Smoke Detector	3rd AL side Room A313 Living Room	Tested/Cleaned	2:19:18 PM	03/28/2023
Smoke Detector	3rd AL side Room A314 Living Room	Tested/Cleaned	2:16:41 PM	03/28/2023
Smoke Detector	3rd AL side Room A315 Living Room	Tested/Cleaned	2:15:55 PM	03/28/2023
Smoke Detector	3rd AL side Room A316 Living Room	Tested/Cleaned	2:12:19 PM	03/28/2023
Smoke Detector	3rd AL side Room A317 Living Room	Tested/Cleaned	2:14:05 PM	03/28/2023
Smoke Detector	3rd AL side Room A318 Bedroom	Tested/Cleaned	2:11:06 PM	03/28/2023
Smoke Detector	3rd AL side Room A318 Living Room	Tested/Cleaned	2:10:24 PM	03/28/2023
Smoke Detector	3rd AL side Room A319 Bedroom	Tested/Cleaned	2:12:30 PM	03/28/2023
Smoke Detector	3rd AL side Room A319 Living Room	Tested/Cleaned	2:11:39 PM	03/28/2023
Smoke Detector	3rd AL side Soiled Utility Room by A302	Tested/Cleaned	3:24:21 PM	04/06/2023
Smoke Detector	3rd AL side Stairwell 5	Tested/Cleaned	2:27:55 PM	03/30/2023
Smoke Detector	3rd AL side Stairwell 6	Tested/Cleaned	2:26:17 PM	03/30/2023
Smoke Detector	3rd AL side Trash room near room A303	Tested/Cleaned	2:01:23 PM	03/24/2023
Smoke Detector	3rd AL side by stairwell 5 At Room A309	Tested/Cleaned	2:22:45 PM	03/30/2023
Smoke Detector	3rd Electrical Room	Tested/Cleaned	10:33:42 AM	03/24/2023
Smoke Detector	3rd Elevator Lobby A	Tested/Cleaned	2:16:03 PM	04/06/2023
Smoke Detector	3rd Elevator Lobby B	Tested/Cleaned	1:45:59 PM	04/06/2023
Smoke Detector	3rd Elevator Lobby C	Tested/Cleaned	2:39:43 PM	04/06/2023
Smoke Detector	3rd FACP/Telephone Room	Tested/Cleaned	9:43:55 AM	03/24/2023
Smoke Detector	3rd IL Side Electrical Toom At Room 433	Tested/Cleaned	2:18:24 PM	03/30/2023
Smoke Detector	3rd IL Side Telephone Room At Room 433	Tested/Cleaned	2:17:00 PM	03/30/2023
Smoke Detector	3rd IL side At FACP room	Tested/Cleaned	9:49:33 AM	03/24/2023
Smoke Detector	3rd IL side At Room 301	Tested/Cleaned	10:07:30 AM	03/24/2023
Smoke Detector	3rd IL side At Room 305	Tested/Cleaned	10:06:31 AM	03/24/2023
Smoke Detector	3rd IL side At Room 307	Tested/Cleaned	10:04:27 AM	03/24/2023
Smoke Detector	3rd IL side At Room 309	Tested/Cleaned	10:04:16 AM	03/24/2023
Smoke Detector	3rd IL side At Room 311	Tested/Cleaned	10:04:03 AM	03/24/2023
Smoke Detector	3rd IL side At Room 313	Tested/Cleaned	10:02:33 AM	03/24/2023
Smoke Detector	3rd IL side At Room 316	Tested/Cleaned	9:57:17 AM	03/24/2023
Smoke Detector	3rd IL side At Room 317	Tested/Cleaned	9:55:47 AM	03/24/2023
Smoke Detector	3rd IL side At Room 320	Tested/Cleaned	9:55:23 AM	03/24/2023
Smoke Detector	3rd IL side At room 323	Tested/Cleaned	9:52:58 AM	03/24/2023
Smoke Detector	3rd IL side At room 324	Tested/Cleaned	9:52:06 AM	03/24/2023
Smoke Detector	3rd IL side At room 326	Tested/Cleaned	9:51:26 AM	03/24/2023
Smoke Detector	3rd IL side At room 329	Tested/Cleaned	9:50:35 AM	03/24/2023
Smoke Detector	3rd IL side At room 331	Tested/Cleaned	9:50:18 AM	03/24/2023
Smoke Detector	3rd IL side At stairwell 4	Tested/Cleaned	3:32:52 PM	04/06/2023
Smoke Detector	3rd IL side Electrical Room by room 304	Tested/Cleaned	1:02:54 PM	03/30/2023
Smoke Detector	3rd IL side Room 301 Bedroom	Tested/Cleaned	10:25:09 AM	03/29/2023
Smoke Detector	3rd IL side Room 301 Bedroom	Tested/Cleaned	10:25:19 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd IL side Room 301 Living Room	Tested/Cleaned	10:25:01 AM	03/29/2023
Smoke Detector	3rd IL side Room 302 Bedroom	Tested/Cleaned	10:29:00 AM	03/29/2023
Smoke Detector	3rd IL side Room 302 Bedroom	Tested/Cleaned	10:29:10 AM	03/29/2023
Smoke Detector	3rd IL side Room 302 Living Room	Tested/Cleaned	10:28:43 AM	03/29/2023
Smoke Detector	3rd IL side Room 304 Bedroom	Tested/Cleaned	10:20:57 AM	03/29/2023
Smoke Detector	3rd IL side Room 304 Bedroom	Tested/Cleaned	10:21:14 AM	03/29/2023
Smoke Detector	3rd IL side Room 304 Living Room	Tested/Cleaned	10:20:36 AM	03/29/2023
Smoke Detector	3rd IL side Room 305 Bedroom	Tested/Cleaned	10:35:15 AM	03/29/2023
Smoke Detector	3rd IL side Room 305 Living Room	Tested/Cleaned	10:35:04 AM	03/29/2023
Smoke Detector	3rd IL side Room 306 Living Room	Tested/Cleaned	10:18:53 AM	03/29/2023
Smoke Detector	3rd IL side Room 307 Bedroom	Tested/Cleaned	10:30:16 AM	03/29/2023
Smoke Detector	3rd IL side Room 307 Bedroom	Tested/Cleaned	10:34:26 AM	03/29/2023
Smoke Detector	3rd IL side Room 307 Living Room	Tested/Cleaned	10:30:07 AM	03/29/2023
Smoke Detector	3rd IL side Room 308 Bedroom	Tested/Cleaned	10:16:25 AM	03/29/2023
Smoke Detector	3rd IL side Room 308 Living Room	Tested/Cleaned	10:16:20 AM	03/29/2023
Smoke Detector	3rd IL side Room 309 Bedroom	Tested/Cleaned	10:28:29 AM	03/29/2023
Smoke Detector	3rd IL side Room 309 Living Room	Tested/Cleaned	10:27:51 AM	03/29/2023
Smoke Detector	3rd IL side Room 310 Bedroom	Tested/Cleaned	10:13:36 AM	03/29/2023
Smoke Detector	3rd IL side Room 310 Living Room	Tested/Cleaned	10:13:27 AM	03/29/2023
Smoke Detector	3rd IL side Room 311 Bedroom	Tested/Cleaned	10:25:55 AM	03/29/2023
Smoke Detector	3rd IL side Room 311 Living Room	Tested/Cleaned	10:25:49 AM	03/29/2023
Smoke Detector	3rd IL side Room 312 Bedroom	Tested/Cleaned	10:10:55 AM	03/29/2023
Smoke Detector	3rd IL side Room 312 Living Room	Tested/Cleaned	10:10:50 AM	03/29/2023
Smoke Detector	3rd IL side Room 320 Bedroom	Tested/Cleaned	9:57:45 AM	03/29/2023
Smoke Detector	3rd IL side Room 320 Bedroom	Tested/Cleaned	9:59:48 AM	03/29/2023
Smoke Detector	3rd IL side Room 320 Living Room	Tested/Cleaned	9:57:36 AM	03/29/2023
Smoke Detector	3rd IL side Room 326 Living Room	Tested/Cleaned	9:48:19 AM	03/29/2023
Smoke Detector	3rd IL side Room A313 Bedroom	Tested/Cleaned	10:23:53 AM	03/29/2023
Smoke Detector	3rd IL side Room A313 Living Room	Tested/Cleaned	10:23:16 AM	03/29/2023
Smoke Detector	3rd IL side Room A314 Bedroom	Tested/Cleaned	10:07:13 AM	03/29/2023
Smoke Detector	3rd IL side Room A314 Bedroom	Tested/Cleaned	10:07:25 AM	03/29/2023
Smoke Detector	3rd IL side Room A314 Living Room	Tested/Cleaned	10:07:01 AM	03/29/2023
Smoke Detector	3rd IL side Room A315 Bedroom	Tested/Cleaned	10:07:31 AM	03/29/2023
Smoke Detector	3rd IL side Room A315 Bedroom	Tested/Cleaned	10:07:43 AM	03/29/2023
Smoke Detector	3rd IL side Room A315 Living Room	Tested/Cleaned	10:08:30 AM	03/29/2023
Smoke Detector	3rd IL side Room A316 Bedroom	Tested/Cleaned	10:05:04 AM	03/29/2023
Smoke Detector	3rd IL side Room A316 Living Room	Tested/Cleaned	10:06:20 AM	03/29/2023
Smoke Detector	3rd IL side Room A317 Bedroom	Tested/Cleaned	10:02:50 AM	03/29/2023
Smoke Detector	3rd IL side Room A317 Living Room	Tested/Cleaned	10:02:40 AM	03/29/2023
Smoke Detector	3rd IL side Room A318 Bedroom	Tested/Cleaned	10:01:18 AM	03/29/2023
Smoke Detector	3rd IL side Room A318 Living Room	Tested/Cleaned	10:01:05 AM	03/29/2023
Smoke Detector	3rd IL side Room A319 Bedroom	Tested/Cleaned	10:04:50 AM	03/29/2023
Smoke Detector	3rd IL side Room A319 Bedroom	Tested/Cleaned	10:05:09 AM	03/29/2023
Smoke Detector	3rd IL side Room A319 Living Room	Tested/Cleaned	10:05:00 AM	03/29/2023
Smoke Detector	3rd IL side Room A321 Bedroom	Tested/Cleaned	9:59:14 AM	03/29/2023
Smoke Detector	3rd IL side Room A321 Living Room	Tested/Cleaned	9:59:54 AM	03/29/2023
Smoke Detector	3rd IL side Room A322 Bedroom	Tested/Cleaned	9:54:11 AM	03/29/2023
Smoke Detector	3rd IL side Room A322 Living Room	Tested/Cleaned	9:54:05 AM	03/29/2023
Smoke Detector	3rd IL side Room A323 Bedroom	Tested/Cleaned	9:57:00 AM	03/29/2023
Smoke Detector	3rd IL side Room A323 Living Room	Tested/Cleaned	9:57:33 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd IL side Room A324 Bedroom	Tested/Cleaned	9:51:50 AM	03/29/2023
Smoke Detector	3rd IL side Room A324 Living Room	Tested/Cleaned	9:51:44 AM	03/29/2023
Smoke Detector	3rd IL side Room A325 Bedroom	Tested/Cleaned	9:54:28 AM	03/29/2023
Smoke Detector	3rd IL side Room A325 Living Room	Tested/Cleaned	9:54:36 AM	03/29/2023
Smoke Detector	3rd IL side Room A326 Bedroom	Tested/Cleaned	9:48:26 AM	03/29/2023
Smoke Detector	3rd IL side Room A327 Bedroom	Tested/Cleaned	9:51:16 AM	03/29/2023
Smoke Detector	3rd IL side Room A327 Living Room	Tested/Cleaned	9:51:08 AM	03/29/2023
Smoke Detector	3rd IL side Room A328 Bedroom	Tested/Cleaned	9:47:46 AM	03/29/2023
Smoke Detector	3rd IL side Room A328 Living Room	Tested/Cleaned	9:47:29 AM	03/29/2023
Smoke Detector	3rd IL side Room A329 Bedroom	Tested/Cleaned	9:47:39 AM	03/29/2023
Smoke Detector	3rd IL side Room A329 Bedroom	Tested/Cleaned	9:47:53 AM	03/29/2023
Smoke Detector	3rd IL side Room A330 Living Room	Tested/Cleaned	9:43:37 AM	03/29/2023
Smoke Detector	3rd IL side Room A331 Bedroom	Tested/Cleaned	9:44:35 AM	03/29/2023
Smoke Detector	3rd IL side Room A331 Living Room	Tested/Cleaned	9:44:29 AM	03/29/2023
Smoke Detector	3rd IL side Room A332 Bedroom	Tested/Cleaned	9:39:25 AM	03/29/2023
Smoke Detector	3rd IL side Room A332 Bedroom	Tested/Cleaned	9:40:20 AM	03/29/2023
Smoke Detector	3rd IL side Room A332 Living Room	Tested/Cleaned	9:40:01 AM	03/29/2023
Smoke Detector	3rd IL side Trash Room At room 313	Tested/Cleaned	10:03:10 AM	03/24/2023
Smoke Detector	3rd IL side Trash Room At room 321	Tested/Cleaned	3:20:50 PM	04/06/2023
Smoke Detector	3rd elevator lobby D	Tested/Cleaned	1:22:45 PM	04/06/2023
Smoke Detector	4th Elevator Lobby A	Tested/Cleaned	2:13:55 PM	04/06/2023
Smoke Detector	4th Elevator Lobby B	Tested/Cleaned	1:41:34 PM	04/06/2023
Smoke Detector	4th IL Side At Stairwell 4	Tested/Cleaned	1:52:42 PM	03/24/2023
Smoke Detector	4th IL side By Room 401	Tested/Cleaned	2:17:45 PM	03/24/2023
Smoke Detector	4th IL side By Room 405	Tested/Cleaned	2:16:32 PM	03/24/2023
Smoke Detector	4th IL side By Room 406	Tested/Cleaned	2:15:25 PM	03/24/2023
Smoke Detector	4th IL side By Room 409	Tested/Cleaned	2:15:05 PM	03/24/2023
Smoke Detector	4th IL side By Room 411	Tested/Cleaned	2:13:16 PM	03/24/2023
Smoke Detector	4th IL side By Room 413	Tested/Cleaned	2:12:44 PM	03/24/2023
Smoke Detector	4th IL side By Room 415	Tested/Cleaned	2:12:24 PM	03/24/2023
Smoke Detector	4th IL side By Room 417	Tested/Cleaned	2:10:30 PM	03/24/2023
Smoke Detector	4th IL side By Room 420	Tested/Cleaned	2:09:23 PM	03/24/2023
Smoke Detector	4th IL side By Room 421	Tested/Cleaned	2:12:52 PM	03/30/2023
Smoke Detector	4th IL side By Room 424	Tested/Cleaned	2:06:44 PM	03/24/2023
Smoke Detector	4th IL side By Room 426	Tested/Cleaned	2:05:27 PM	03/24/2023
Smoke Detector	4th IL side By Room 428	Tested/Cleaned	2:04:19 PM	03/24/2023
Smoke Detector	4th IL side By Room 431	Tested/Cleaned	2:03:21 PM	03/24/2023
Smoke Detector	4th IL side By Room 432	Tested/Cleaned	2:03:11 PM	03/24/2023
Smoke Detector	4th IL side Electrical Room by room 421	Tested/Cleaned	2:08:06 PM	03/24/2023
Smoke Detector	4th IL side Electrical room by room 404	Tested/Cleaned	2:06:00 PM	03/30/2023
Smoke Detector	4th IL side Room 414 Bedroom	Tested/Cleaned	1:35:46 PM	03/28/2023
Smoke Detector	4th IL side Room 414 Bedroom	Tested/Cleaned	1:36:00 PM	03/28/2023
Smoke Detector	4th IL side Room 414 Living Room	Tested/Cleaned	1:35:36 PM	03/28/2023
Smoke Detector	4th IL side Room 415 Bedroom	Tested/Cleaned	1:37:33 PM	03/28/2023
Smoke Detector	4th IL side Room 415 Bedroom	Tested/Cleaned	1:39:15 PM	03/28/2023
Smoke Detector	4th IL side Room 415 Living Room	Tested/Cleaned	1:38:27 PM	03/28/2023
Smoke Detector	4th IL side Room 416 Bedroom	Tested/Cleaned	1:37:00 PM	03/28/2023
Smoke Detector	4th IL side Room 416 Living Room	Tested/Cleaned	1:37:47 PM	03/28/2023
Smoke Detector	4th IL side Room 417 Bedroom	Tested/Cleaned	1:42:29 PM	03/28/2023
Smoke Detector	4th IL side Room 417 Living Room	Tested/Cleaned	1:40:34 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	4th IL side Room 418 Bedroom	Tested/Cleaned	1:45:16 PM	03/28/2023
Smoke Detector	4th IL side Room 418 Living Room	Tested/Cleaned	1:45:57 PM	03/28/2023
Smoke Detector	4th IL side Room 419 Bedroom	Tested/Cleaned	1:40:46 PM	03/28/2023
Smoke Detector	4th IL side Room 419 Bedroom	Tested/Cleaned	1:41:33 PM	03/28/2023
Smoke Detector	4th IL side Room 419 Living Room	Tested/Cleaned	1:39:59 PM	03/28/2023
Smoke Detector	4th IL side Room 420 Bedroom	Tested/Cleaned	1:44:20 PM	03/28/2023
Smoke Detector	4th IL side Room 420 Bedroom	Tested/Cleaned	1:44:35 PM	03/28/2023
Smoke Detector	4th IL side Room 420 Living Room	Tested/Cleaned	1:44:04 PM	03/28/2023
Smoke Detector	4th IL side Room 421 Bedroom	Tested/Cleaned	1:49:00 PM	03/28/2023
Smoke Detector	4th IL side Room 421 Living Room	Tested/Cleaned	1:50:51 PM	03/28/2023
Smoke Detector	4th IL side Room 422 Bedroom	Tested/Cleaned	1:49:40 PM	03/28/2023
Smoke Detector	4th IL side Room 422 Living Room	Tested/Cleaned	1:48:54 PM	03/28/2023
Smoke Detector	4th IL side Room 423 Bedroom	Tested/Cleaned	1:51:36 PM	03/28/2023
Smoke Detector	4th IL side Room 423 Living Room	Tested/Cleaned	1:50:57 PM	03/28/2023
Smoke Detector	4th IL side Room 424 Bedroom	Tested/Cleaned	1:51:54 PM	03/28/2023
Smoke Detector	4th IL side Room 424 Living Room	Tested/Cleaned	1:52:08 PM	03/28/2023
Smoke Detector	4th IL side Room 425 Bedroom	Tested/Cleaned	1:53:55 PM	03/28/2023
Smoke Detector	4th IL side Room 425 Living Room	Tested/Cleaned	1:53:17 PM	03/28/2023
Smoke Detector	4th IL side Room 426 Bedroom	Tested/Cleaned	1:55:51 PM	03/28/2023
Smoke Detector	4th IL side Room 426 Living room	Tested/Cleaned	1:55:03 PM	03/28/2023
Smoke Detector	4th IL side Room 427 Bedroom	Tested/Cleaned	1:54:09 PM	03/28/2023
Smoke Detector	4th IL side Room 427 Living Room	Tested/Cleaned	1:54:51 PM	03/28/2023
Smoke Detector	4th IL side Room 428 Bedroom	Tested/Cleaned	1:59:24 PM	03/28/2023
Smoke Detector	4th IL side Room 428 Living Room	Tested/Cleaned	1:58:39 PM	03/28/2023
Smoke Detector	4th IL side Room 429 Bedroom	Tested/Cleaned	1:56:13 PM	03/28/2023
Smoke Detector	4th IL side Room 429 Bedroom	Tested/Cleaned	1:57:11 PM	03/28/2023
Smoke Detector	4th IL side Room 429 Living Room	Tested/Cleaned	1:56:02 PM	03/28/2023
Smoke Detector	4th IL side Room 430 Living Room	Tested/Cleaned	2:01:35 PM	03/28/2023
Smoke Detector	4th IL side Room 432 Bedroom	Tested/Cleaned	2:04:12 PM	03/28/2023
Smoke Detector	4th IL side Room 432 Bedroom	Tested/Cleaned	2:05:16 PM	03/28/2023
Smoke Detector	4th IL side Room 432 Living Room	Tested/Cleaned	2:04:55 PM	03/28/2023
Smoke Detector	4th IL side Room 433 Bedroom	Tested/Cleaned	2:08:43 PM	03/28/2023
Smoke Detector	4th IL side Room 433 Living Room	Tested/Cleaned	2:07:23 PM	03/28/2023
Smoke Detector	4th IL side Trash Room by room 413	Tested/Cleaned	2:10:35 PM	03/30/2023
Smoke Detector	4th IL side room 401 Bedroom	Tested/Cleaned	1:18:52 PM	03/28/2023
Smoke Detector	4th IL side room 401 Bedroom	Tested/Cleaned	1:19:39 PM	03/28/2023
Smoke Detector	4th IL side room 401 Living room	Tested/Cleaned	1:17:56 PM	03/28/2023
Smoke Detector	4th IL side room 402 Bedroom	Tested/Cleaned	1:21:09 PM	03/28/2023
Smoke Detector	4th IL side room 402 Bedroom	Tested/Cleaned	1:21:30 PM	03/28/2023
Smoke Detector	4th IL side room 402 Living room	Tested/Cleaned	1:19:42 PM	03/28/2023
Smoke Detector	4th IL side room 403 Bedroom	Tested/Cleaned	1:20:42 PM	03/28/2023
Smoke Detector	4th IL side room 403 Living room	Tested/Cleaned	1:20:27 PM	03/28/2023
Smoke Detector	4th IL side room 404 Bedroom	Tested/Cleaned	1:23:28 PM	03/28/2023
Smoke Detector	4th IL side room 404 Bedroom	Tested/Cleaned	1:23:38 PM	03/28/2023
Smoke Detector	4th IL side room 404 Living room	Tested/Cleaned	1:23:11 PM	03/28/2023
Smoke Detector	4th IL side room 405 Bedroom	Tested/Cleaned	1:23:33 PM	03/28/2023
Smoke Detector	4th IL side room 405 Living room	Tested/Cleaned	1:23:12 PM	03/28/2023
Smoke Detector	4th IL side room 406 Living room	Tested/Cleaned	1:27:00 PM	03/28/2023
Smoke Detector	4th IL side room 407 Bedroom	Tested/Cleaned	1:26:20 PM	03/28/2023
Smoke Detector	4th IL side room 407 Bedroom	Tested/Cleaned	1:27:07 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	4th IL side room 407 Living room	Tested/Cleaned	1:26:29 PM	03/28/2023
Smoke Detector	4th IL side room 408 Bedroom	Tested/Cleaned	1:27:40 PM	03/28/2023
Smoke Detector	4th IL side room 408 Living room	Tested/Cleaned	1:31:00 PM	03/28/2023
Smoke Detector	4th IL side room 409 Bedroom	Tested/Cleaned	1:29:27 PM	03/28/2023
Smoke Detector	4th IL side room 409 Living room	Tested/Cleaned	1:28:41 PM	03/28/2023
Smoke Detector	4th IL side room 410 Bedroom	Tested/Cleaned	1:30:06 PM	03/28/2023
Smoke Detector	4th IL side room 410 Living room	Tested/Cleaned	1:29:30 PM	03/28/2023
Smoke Detector	4th IL side room 411 Bedroom	Tested/Cleaned	1:34:25 PM	03/28/2023
Smoke Detector	4th IL side room 411 Living room	Tested/Cleaned	1:32:34 PM	03/28/2023
Smoke Detector	4th IL side room 412 Bedroom	Tested/Cleaned	1:32:40 PM	03/28/2023
Smoke Detector	4th IL side room 412 Living room	Tested/Cleaned	1:33:15 PM	03/28/2023
Smoke Detector	4th IL side room 413 Bedroom	Tested/Cleaned	1:36:00 PM	03/28/2023
Smoke Detector	4th IL side room 413 Living room	Tested/Cleaned	1:35:25 PM	03/28/2023
Smoke Detector	4th elevator lobby D	Tested/Cleaned	1:17:36 PM	04/06/2023
Smoke Detector	5th	Tested/Cleaned	11:33:25 AM	03/24/2023
Smoke Detector	5th Elevator Lobby A	Tested/Cleaned	2:07:40 PM	04/06/2023
Smoke Detector	5th Elevator Lobby B	Tested/Cleaned	1:37:24 PM	04/06/2023
Smoke Detector	5th IL side Electrical Room by room 513	Tested/Cleaned	11:07:07 AM	03/24/2023
Smoke Detector	5th IL side Electrical Room by room 521	Tested/Cleaned	11:17:13 AM	03/24/2023
Smoke Detector	5th IL side Mechanical Room by room 504	Tested/Cleaned	3:15:48 PM	04/06/2023
Smoke Detector	5th IL side Mechanical Room by room 533	Tested/Cleaned	11:25:40 AM	03/24/2023
Smoke Detector	5th IL side Room 501 Bedroom	Tested/Cleaned	1:12:46 PM	03/28/2023
Smoke Detector	5th IL side Room 501 Bedroom	Tested/Cleaned	1:14:08 PM	03/28/2023
Smoke Detector	5th IL side Room 501 Living Room	Tested/Cleaned	1:12:35 PM	03/28/2023
Smoke Detector	5th IL side Room 502 Bedroom	Tested/Cleaned	1:15:25 PM	03/28/2023
Smoke Detector	5th IL side Room 502 Living Room	Tested/Cleaned	1:13:40 PM	03/28/2023
Smoke Detector	5th IL side Room 503 Bedroom	Tested/Cleaned	1:11:14 PM	03/28/2023
Smoke Detector	5th IL side Room 503 Living Room	Tested/Cleaned	1:12:31 PM	03/28/2023
Smoke Detector	5th IL side Room 504 Bedroom	Tested/Cleaned	1:11:24 PM	03/28/2023
Smoke Detector	5th IL side Room 504 Bedroom	Tested/Cleaned	1:11:39 PM	03/28/2023
Smoke Detector	5th IL side Room 504 Living Room	Tested/Cleaned	1:11:53 PM	03/28/2023
Smoke Detector	5th IL side Room 505 Bedroom	Tested/Cleaned	1:09:49 PM	03/28/2023
Smoke Detector	5th IL side Room 505 Living Room	Tested/Cleaned	1:09:42 PM	03/28/2023
Smoke Detector	5th IL side Room 506 Living Room	Tested/Cleaned	1:07:50 PM	03/28/2023
Smoke Detector	5th IL side Room 507 Bedroom	Tested/Cleaned	1:08:09 PM	03/28/2023
Smoke Detector	5th IL side Room 507 Bedroom	Tested/Cleaned	1:09:57 PM	03/28/2023
Smoke Detector	5th IL side Room 507 Living Room	Tested/Cleaned	1:08:47 PM	03/28/2023
Smoke Detector	5th IL side Room 508 Bedroom	Tested/Cleaned	1:07:02 PM	03/28/2023
Smoke Detector	5th IL side Room 508 Living Room	Tested/Cleaned	1:06:27 PM	03/28/2023
Smoke Detector	5th IL side Room 509 Bedroom	Tested/Cleaned	1:04:34 PM	03/28/2023
Smoke Detector	5th IL side Room 509 Living Room	Tested/Cleaned	1:05:19 PM	03/28/2023
Smoke Detector	5th IL side Room 510 Bedroom	Tested/Cleaned	1:03:03 PM	03/28/2023
Smoke Detector	5th IL side Room 510 Living Room	Tested/Cleaned	1:03:31 PM	03/28/2023
Smoke Detector	5th IL side Room 511 Bedroom	Tested/Cleaned	1:03:12 PM	03/28/2023
Smoke Detector	5th IL side Room 511 Living Room	Tested/Cleaned	1:02:29 PM	03/28/2023
Smoke Detector	5th IL side Room 512 Bedroom	Tested/Cleaned	1:02:20 PM	03/28/2023
Smoke Detector	5th IL side Room 512 Living Room	Tested/Cleaned	1:02:11 PM	03/28/2023
Smoke Detector	5th IL side Room 513 Bedroom	Tested/Cleaned	1:00:51 PM	03/28/2023
Smoke Detector	5th IL side Room 513 Living Room	Tested/Cleaned	12:59:52 PM	03/28/2023
Smoke Detector	5th IL side Room 514 Bedroom	Tested/Cleaned	12:59:11 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	5th IL side Room 514 Bedroom	Tested/Cleaned	12:59:45 PM	03/28/2023
Smoke Detector	5th IL side Room 514 Living Room	Tested/Cleaned	12:58:34 PM	03/28/2023
Smoke Detector	5th IL side Room 515 Bedroom	Tested/Cleaned	12:56:58 PM	03/28/2023
Smoke Detector	5th IL side Room 515 Bedroom	Tested/Cleaned	12:57:18 PM	03/28/2023
Smoke Detector	5th IL side Room 515 Living Room	Tested/Cleaned	12:56:40 PM	03/28/2023
Smoke Detector	5th IL side Room 516 Bedroom	Tested/Cleaned	12:58:58 PM	03/28/2023
Smoke Detector	5th IL side Room 516 Living Room	Tested/Cleaned	12:58:20 PM	03/28/2023
Smoke Detector	5th IL side Room 517 Bedroom	Tested/Cleaned	12:53:57 PM	03/28/2023
Smoke Detector	5th IL side Room 517 Living Room	Tested/Cleaned	12:52:58 PM	03/28/2023
Smoke Detector	5th IL side Room 518 Bedroom	Tested/Cleaned	12:57:00 PM	03/28/2023
Smoke Detector	5th IL side Room 518 Living Room	Tested/Cleaned	12:55:52 PM	03/28/2023
Smoke Detector	5th IL side Room 519 Bedroom	Tested/Cleaned	12:54:02 PM	03/28/2023
Smoke Detector	5th IL side Room 519 Bedroom	Tested/Cleaned	12:54:15 PM	03/28/2023
Smoke Detector	5th IL side Room 519 Living Room	Tested/Cleaned	12:55:26 PM	03/28/2023
Smoke Detector	5th IL side Room 520 Bedroom	Tested/Cleaned	12:52:18 PM	03/28/2023
Smoke Detector	5th IL side Room 520 Bedroom	Tested/Cleaned	12:52:44 PM	03/28/2023
Smoke Detector	5th IL side Room 520 Living Room	Tested/Cleaned	12:51:38 PM	03/28/2023
Smoke Detector	5th IL side Room 521 Bedroom	Tested/Cleaned	12:49:32 PM	03/28/2023
Smoke Detector	5th IL side Room 521 Living Room	Tested/Cleaned	12:49:22 PM	03/28/2023
Smoke Detector	5th IL side Room 522 Bedroom	Tested/Cleaned	12:49:34 PM	03/28/2023
Smoke Detector	5th IL side Room 522 Living Room	Tested/Cleaned	12:49:17 PM	03/28/2023
Smoke Detector	5th IL side Room 523 Bedroom	Tested/Cleaned	12:46:34 PM	03/28/2023
Smoke Detector	5th IL side Room 523 Living Room	Tested/Cleaned	12:46:26 PM	03/28/2023
Smoke Detector	5th IL side Room 524 Bedroom	Tested/Cleaned	12:45:57 PM	03/28/2023
Smoke Detector	5th IL side Room 524 Living Room	Tested/Cleaned	12:45:50 PM	03/28/2023
Smoke Detector	5th IL side Room 525 Bedroom	Tested/Cleaned	12:46:15 PM	03/28/2023
Smoke Detector	5th IL side Room 525 Living Room	Tested/Cleaned	12:46:50 PM	03/28/2023
Smoke Detector	5th IL side Room 526 Bedroom	Tested/Cleaned	12:43:13 PM	03/28/2023
Smoke Detector	5th IL side Room 526 Living Room	Tested/Cleaned	12:42:55 PM	03/28/2023
Smoke Detector	5th IL side Room 527 Bedroom	Tested/Cleaned	12:45:01 PM	03/28/2023
Smoke Detector	5th IL side Room 527 Living Room	Tested/Cleaned	12:44:53 PM	03/28/2023
Smoke Detector	5th IL side Room 528 Bedroom	Tested/Cleaned	12:40:59 PM	03/28/2023
Smoke Detector	5th IL side Room 528 Living Room	Tested/Cleaned	12:40:21 PM	03/28/2023
Smoke Detector	5th IL side Room 529 Bedroom	Tested/Cleaned	12:42:38 PM	03/28/2023
Smoke Detector	5th IL side Room 529 Bedroom	Tested/Cleaned	12:43:08 PM	03/28/2023
Smoke Detector	5th IL side Room 529 Living Room	Tested/Cleaned	12:42:29 PM	03/28/2023
Smoke Detector	5th IL side Room 530 Living Room	Tested/Cleaned	12:38:31 PM	03/28/2023
Smoke Detector	5th IL side Room 531 Bedroom	Tested/Cleaned	12:43:56 PM	03/28/2023
Smoke Detector	5th IL side Room 531 Living Room	Tested/Cleaned	12:43:49 PM	03/28/2023
Smoke Detector	5th IL side Room 532 Bedroom	Tested/Cleaned	12:37:00 PM	03/28/2023
Smoke Detector	5th IL side Room 532 Living Room	Tested/Cleaned	12:38:04 PM	03/28/2023
Smoke Detector	5th IL side Room 533 Bedroom	Tested/Cleaned	12:36:22 PM	03/28/2023
Smoke Detector	5th IL side Room 533 Living Room	Tested/Cleaned	12:35:30 PM	03/28/2023
Smoke Detector	5th IL side Room 535 Bedroom	Tested/Cleaned	12:33:45 PM	03/28/2023
Smoke Detector	5th IL side Room 535 Living Room	Tested/Cleaned	12:33:34 PM	03/28/2023
Smoke Detector	5th IL side hallway by room 501	Tested/Cleaned	11:11:09 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 504	Tested/Cleaned	11:13:03 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 505	Tested/Cleaned	11:13:08 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 508	Tested/Cleaned	11:13:19 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 510	Tested/Cleaned	11:13:44 AM	03/24/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	5th IL side hallway by room 513	Tested/Cleaned	11:13:55 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 516	Tested/Cleaned	11:14:17 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 517	Tested/Cleaned	11:14:33 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 520	Tested/Cleaned	11:14:44 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 521	Tested/Cleaned	11:14:56 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 524	Tested/Cleaned	11:19:20 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 526	Tested/Cleaned	11:19:41 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 528	Tested/Cleaned	11:21:54 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 530	Tested/Cleaned	11:22:45 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 533	Tested/Cleaned	11:24:40 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 534	Tested/Cleaned	11:27:33 AM	03/24/2023
Smoke Detector	5th Top of stairwell 3 IL side	Tested/Cleaned	11:31:05 AM	03/24/2023
Smoke Detector	5th Top of stairwell 4 IL side	Tested/Cleaned	11:29:52 AM	03/24/2023
Smoke Detector	5th elevator lobby D	Tested/Cleaned	12:47:28 PM	04/06/2023
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	3rd Telephone/FACP	Tested	11:37:27 AM	04/12/2023
Communicator	2nd IL side Telephone Room by room 226	Tested	11:28:22 AM	04/12/2023
Indicating				
Horn/Strobe	2nd Total (42)	Tested	9:31:08 PM	03/30/2023
Horn/Strobe	3rd Total (28)	Tested	9:30:03 PM	03/30/2023
Horn/Strobe	4th Total (10)	Tested	3:18:57 PM	03/30/2023

Service Summary

Generated by: BuildingReports.com

Building: Magnolia Glen

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Communicator	Tested	1
Horn/Strobe	Tested	3
Total		5
<i>Passed</i>		
Annunciator	Tested	2
Battery	Tested	9
Control Panel	Tested	1
Duct Detector	Tested	4
Heat Detector	Inspected	3
Heat Detector	Tested	28
Horn/Strobe	Tested	2
Power Supply	Tested	8
Pull Station	Tested	31
Smoke Detector	Inspected	2
Smoke Detector	Tested/Cleaned	549
Total		639
Grand Total		644

Auxiliary Functions Testing

Generated by: BuildingReports.com

Type	Location	Comment	ScanID	Simulated
Building: Magnolia Glen				
Control Panel: 1 - Siemens				
XLS-MME-ADPT				
<p><i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i></p>				
Passed				
Duct Detector				
Air Duct	3rd by room A303	Passed	22983382	
Air Duct	3rd by room A311	Passed	22983381	
Air Duct	5th by room 503	Passed	14244049	
Air Duct	5th by room 518	Passed	22983380	
Smoke Detector				
Elevator Recall	1st Elevator Equipment Room C	Passed	14244563	
Elevator Recall	1st Elevator Equipment Room D	Passed	14244580	
Elevator Recall	1st Elevator Lobby C	Passed	14244565	
Elevator Recall	1st elevator lobby D	Passed	14244394	
Elevator Recall	2nd Elevator Lobby C	Passed	14244442	
Elevator Recall	2nd elevator lobby D	Passed	14244545	
Elevator Recall	3rd Elevator Lobby C	Passed	14244088	
Elevator Recall	3rd elevator lobby D	Passed	14244449	
Elevator Recall	4th elevator lobby D	Passed	14244080	
Elevator Recall	5th elevator lobby D	Passed	14242703	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Magnolia Glen				Control Panel: 1 - Siemens XLS-MME-ADPT			
<p>The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</p>							
Battery							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Passed</i>							
Sealed Lead Acid	2nd IL side Telephone Room by room 226	7	12				
Sealed Lead Acid	2nd IL side Telephone Room by room 226	7	12				
Sealed Lead Acid	2nd IL side Telephone Room by room 226	7	12				
Sealed Lead Acid	3rd IL side FACP Room by room 332	7	12				7.0
Sealed Lead Acid	3rd IL side FACP Room by room 332 Bottom	7	12				7.9
Sealed Lead Acid	3rd IL side FACP Room by room 332 Too right	7	12				
Sealed Lead Acid	3rd IL side FACP Room by room 332 Top left	7	12				
Sealed Lead Acid	4th IL side Telephone Room by room 432	7	12				7.6
Sealed Lead Acid	5th IL side Mechanical Room by room 532	7	12				7.9
<i>Failed/Other</i>							
Sealed Lead Acid	3rd Telephone/FACP	35 bolt	12				
Power Supply							
Protection Type	Location	Rated Ah	Rated Volts	Charging Voltage			
<i>Passed</i>							
Breaker	2nd IL side Telephone Room by room 226	1	120				
Breaker	2nd IL side Telephone Room by room 226	1	120				
Breaker	3rd IL side FACP Room by room 332	3	120				
Breaker	3rd IL side FACP Room by room 332	3	120				
Breaker	3rd IL side FACP Room by room 332	3	120				
Breaker	3rd IL side FACP Room by room 332	3	120				

	332		
Breaker	4th IL side Telephone Room by room 432	1	120
Breaker	5th IL side Mechanical Room by room 532	1	120

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Magnolia Glen	Control Panel: 1 - Siemens XLS-MME-ADPT
--------------------------------	--

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Annunciator	Control	0.31%	2
Battery	Control	1.55%	10
Communicator	Control	0.16%	1
Control Panel	Control	0.16%	1
Duct Detector	Initiating	0.62%	4
Heat Detector	Initiating	4.81%	31
Horn/Strobe	Indicating	0.78%	5
Power Supply	Control	1.24%	8
Pull Station	Initiating	4.81%	31
Smoke Detector	Initiating	85.56%	551

Type	Qty	Model #	Description	Install Date
------	-----	---------	-------------	--------------

In Service - 3 Years to 5 Years

DURACELL

Battery	1	DURA12-7F	Sealed Lead Acid	04/01/2020
---------	---	-----------	------------------	------------

DURACELL ULTRA

Battery	1	DURA12-7	Sealed Lead Acid	04/01/2020
---------	---	----------	------------------	------------

Battery	5	DURA12-7F	Sealed Lead Acid	04/01/2020
---------	---	-----------	------------------	------------

Battery	2	WKA12-7F	Sealed Lead Acid	04/01/2020
---------	---	----------	------------------	------------

Power Sonic

Battery	1	PS12350-NB	Sealed Lead Acid	10/01/2018
---------	---	------------	------------------	------------

In Service - 5 Years to 10 Years

Siemens

Annunciator	2	RCC-1	LCD Display	10/24/2016
-------------	---	-------	-------------	------------

Control Panel	1	XLS-MME-ADPT	Addressable	10/24/2016
---------------	---	--------------	-------------	------------

Heat Detector	28	FPT-11	Fixed Temperature	10/24/2016
---------------	----	--------	-------------------	------------

Heat Detector	3	FPT-11	Fixed Temperature	10/24/2016
---------------	---	--------	-------------------	------------

Horn/Strobe	1			10/24/2016
-------------	---	--	--	------------

Pull Station	31	MSI-10B	Single Action	10/24/2016
--------------	----	---------	---------------	------------

Smoke Detector	551	FP-11	Photoelectric	10/24/2016
----------------	-----	-------	---------------	------------

Wheelock

Horn/Strobe	4	NS4-241 10W		10/24/2016
-------------	---	-------------	--	------------

System Sensor

Duct Detector	3	DH100ACDCLP	Ionization	12/02/2015
---------------	---	-------------	------------	------------

Duct Detector	1	DH100ACDCLP	Photoelectric	12/02/2015
---------------	---	-------------	---------------	------------

In Service - 15 Years to 25 Years

Siemens				
Power Supply	1	PAD-3		12/02/2000
Fire-Lite				
Power Supply	5	FCPS-24F		10/24/2000
Siemens				
Power Supply	2	PAD-3		10/24/2000
Silent Knight				
Communicator	1	SK-5208	Digital Communicator	10/24/2000

Zone Address Report

Generated by: BuildingReports.com

Building: Magnolia Glen	Control Panel: 1 - Siemens XLS-MME-ADPT
--------------------------------	--

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 1				
01	Smoke Detector	1st AL side Room A106 Bed room	Photoelectric	14244793
02	Smoke Detector	1st AL side Room A106 Bedroom	Photoelectric	14244792
03	Smoke Detector	1st AL side Room A105 Living Room	Photoelectric	14244794
04	Smoke Detector	1st AL side Room A105 Bedroom	Photoelectric	14244795
06	Smoke Detector	1st AL side Room A103 Living Room	Photoelectric	14244797
07	Smoke Detector	1st AL side Room A102 Bedroom	Photoelectric	14244799
09	Smoke Detector	1st AL side Room A101 Living Room	Photoelectric	14244800
09	Smoke Detector	1st AL side Room A102 Living Room	Photoelectric	14244798
10	Smoke Detector	1st AL side Room A101 Living Room	Photoelectric	14244801
11	Smoke Detector	1st AL side Room A108 Living Room	Photoelectric	14244790
12	Smoke Detector	1st AL side Room A110 Living Room	Photoelectric	14244786
13	Smoke Detector	1st AL side Room A110 Bedroom	Photoelectric	14244787
15	Smoke Detector	1st AL side Room A109 Bedroom	Photoelectric	14244788
16	Smoke Detector	1st AL side Room A107 Living Room	Photoelectric	14244791
17	Smoke Detector	2nd AL side By Room A105	Photoelectric	14244576
18	Smoke Detector	2nd AL side By Room A104	Photoelectric	14244571
19	Smoke Detector	2nd AL side By Room A102	Photoelectric	14244573
20	Smoke Detector	2nd 1st Floor AL side Soiled Linen By A101	Photoelectric	72108677
21	Heat Detector	2nd 1st Floor AL side soiled utility		14244574
22	Heat Detector	1st AL side Laundry		14244572
23	Smoke Detector	1st AL side Electrical Room by A106	Photoelectric	37498866
24	Smoke Detector	2nd AL side By Trash Room	Photoelectric	14244569
25	Smoke Detector	2nd AL side By Room A110	Photoelectric	14244568
26	Smoke Detector	2nd AL side near front lobby By Room A110	Photoelectric	14244567
27	Smoke Detector	2nd AL side near front lobby By Room A109 At Fire Doors	Photoelectric	14244566
30	Smoke Detector	1st Elevator Equipment Room C	Photoelectric	14244563
31	Heat Detector	1st Elevator Equipment w C		14244564
32	Smoke Detector	1st AL side Front Lobby	Photoelectric	14244560
33	Smoke Detector	2nd AL side near cafe	Photoelectric	14244556
34	Smoke Detector	2nd AL side By Legacy Health Services	Photoelectric	14244555
35	Smoke Detector	2nd AL side By Staff Lounge near Receiving	Photoelectric	14244551
36	Smoke Detector	2nd AL side By stairwell 4 near Receiving	Photoelectric	14244549
37	Smoke Detector	2nd AL side By stairwell 4 near Receiving	Photoelectric	14244548
40	Pull Station	2nd AL side near stairwell 6	Single Action	14244577
41	Pull Station	2nd AL side Front entrance	Single Action	14244559

46	Smoke Detector	1st AL side Living/Lounge Area	Photoelectric	14244562
47	Pull Station	2nd Legacy Health Services	Single Action	29189783
59	Smoke Detector	1st Elevator Lobby C	Photoelectric	14244565
60	Smoke Detector	1st AL side Living/Lounge Area	Photoelectric	14244561

Zone/Circuit: 2

01	Heat Detector	2nd 1st Floor AL Kitchen	Fixed Temperature	14244552
02	Heat Detector	2nd 1st Floor AL Kitchen	Fixed Temperature	14244553
08	Smoke Detector	2nd AL side At room A204	Photoelectric	14244432
09	Smoke Detector	2nd AL side Room A209 Bedroom	Photoelectric	14244877
10	Smoke Detector	2nd AL side Room A209 Living Room	Photoelectric	14244876
11	Smoke Detector	2nd AL side Room A207 Living Room	Photoelectric	14244812
12	Smoke Detector	2nd AL side Room A206 Bedroom	Photoelectric	14244811
13	Smoke Detector	2nd AL side Room A206 Living Room	Photoelectric	14244810
16	Smoke Detector	2nd AL side Room A204 Living Room	Photoelectric	14244807
17	Smoke Detector	2nd AL side Room A203 Living Room	Photoelectric	14244806
18	Smoke Detector	2nd AL side Room A202 Bedroom	Photoelectric	14244805
19	Smoke Detector	2nd AL side Room A202 Living Room	Photoelectric	14244804
20	Smoke Detector	2nd AL side Room A201 Living Room	Photoelectric	14244802
21	Smoke Detector	2nd AL side Room A201 Bedroom	Photoelectric	14244803
22	Smoke Detector	2nd AL side Room A208 Living Room	Photoelectric	14244878
23	Smoke Detector	2nd AL side Room A210 Living Room	Photoelectric	14244874
24	Smoke Detector	2nd AL side Room A210 Bedroom	Photoelectric	14244875
31	Smoke Detector	2nd AL side stairwell 6	Photoelectric	14244430
32	Smoke Detector	2nd AL side At room A201	Photoelectric	14244434
33	Smoke Detector	2nd AL side Soiled Utility Room by room A201	Photoelectric	14244435
34	Heat Detector	2nd AL side Laundry		14244433
35	Smoke Detector	2nd AL side At room A208	Photoelectric	14244437
36	Smoke Detector	2nd AL side At room A209	Photoelectric	14244438
37	Smoke Detector	2nd AL side At stairwell 5	Photoelectric	14244439
38	Smoke Detector	2nd AL side At stairwell 5	Photoelectric	14244440
39	Smoke Detector	2nd Elevator Lobby C	Photoelectric	14244442
40	Smoke Detector	1st AL side Trash Room	Photoelectric	14244570
41	Smoke Detector	2nd AL side Trash room	Photoelectric	14244436
42	Heat Detector	2nd 1st Floor AL Kitchen	Fixed Temperature	29189785
43	Smoke Detector	2nd AL side In Dining At Kitchen Door	Photoelectric	29189784
44	Pull Station	2nd Hallway by stairwell 6 AL side	Single Action	14244431
45	Pull Station	2nd Hallway by stairwell 5 AL side	Single Action	14244441

Zone/Circuit: 3

05	Horn/Strobe	1st Total (49)		52545308
05	Smoke Detector	3rd FACP/Telephone Room	Photoelectric	14244453
05	Horn/Strobe	3rd Total (28)		68319041
05	Horn/Strobe	4th Total (10)		68319042
05	Horn/Strobe	5th Total (11)		68319043
06	Smoke Detector	3rd Electrical Room	Photoelectric	14244451
07	Smoke Detector	2nd IL side Telephone Room	Photoelectric	37498861
07	Battery	2nd IL side Telephone Room by room 226	Sealed Lead Acid	14244537
09	Smoke Detector	3rd AL side Room A309 Bedroom	Photoelectric	14244657
11	Smoke Detector	3rd AL side Room A307 Living Room	Photoelectric	14244669
12	Smoke Detector	3rd AL side Room A306 Bedroom	Photoelectric	14244660
13	Smoke Detector	3rd AL side Room A306 Living Room	Photoelectric	14244659

14	Smoke Detector	3rd AL side Room A305 Living room	Photoelectric	14244662
15	Smoke Detector	3rd AL side Room A305 Bedroom	Photoelectric	14244661
16	Smoke Detector	3rd AL side Room A304 Living room	Photoelectric	14244663
17	Smoke Detector	3rd AL side Room A303 Living room	Photoelectric	14244664
18	Smoke Detector	3rd AL side Room A302 Bedroom	Photoelectric	14244666
20	Smoke Detector	3rd AL side Room A301 Living room	Photoelectric	14244667
21	Smoke Detector	3rd AL side Room A301 Bedroom	Photoelectric	14244668
22	Smoke Detector	3rd AL side Room A308 Living Room	Photoelectric	14244658
23	Smoke Detector	3rd AL side Room A310 Living Room	Photoelectric	14244654
24	Smoke Detector	3rd AL side Room A310 Bedroom	Photoelectric	14244655
30	Smoke Detector	3rd AL side Stairwell 6	Photoelectric	14244429
31	Smoke Detector	3rd AL side At Room A305	Photoelectric	14244428
32	Smoke Detector	3rd AL side At Room A302	Photoelectric	14244096
33	Smoke Detector	3rd AL side Soiled Utility Room by A302	Photoelectric	14244426
34	Heat Detector	3rd AL side Laundry		14244095
35	Smoke Detector	3rd AL side At Room A303	Photoelectric	14244093
36	Smoke Detector	3rd AL side At Room A307	Photoelectric	14244091
37	Smoke Detector	3rd AL side At Room A309	Photoelectric	14244090
38	Smoke Detector	3rd AL side by stairwell 5 At Room A309	Photoelectric	14244089
39	Smoke Detector	3rd Elevator Lobby C	Photoelectric	14244088
40	Smoke Detector	3rd AL side Trash room near room A303	Photoelectric	14244092
43	Smoke Detector	3rd AL side Stairwell 5	Photoelectric	14244086
44	Pull Station	3rd Hallway by stairwell 6 AL side	Single Action	14244427
45	Pull Station	3rd Hallway by stairwell 5 AL side	Single Action	14244087

Zone/Circuit: 4

01	Smoke Detector	2nd AL side Room A219 Living Room	Photoelectric	14244860
02	Smoke Detector	2nd AL side Room A219 Bedroom	Photoelectric	14244861
03	Smoke Detector	2nd AL side Room A217 Living Room	Photoelectric	14244864
04	Smoke Detector	2nd AL side Room A215 Living Room	Photoelectric	14244866
05	Smoke Detector	2nd AL side Room A213 BedRoom	Photoelectric	14244869
06	Smoke Detector	2nd AL side Room A213 Living room	Photoelectric	14244868
07	Smoke Detector	2nd AL side Room A211 Bedroom	Photoelectric	14244873
09	Smoke Detector	2nd AL side Room A212 Living Room	Photoelectric	14244870
10	Smoke Detector	2nd AL side Room A212 Bedroom	Photoelectric	14244871
12	Smoke Detector	2nd AL side Room A216 Living Room	Photoelectric	14244865
13	Smoke Detector	2nd AL side Room A218 Bedroom	Photoelectric	14244863
14	Smoke Detector	2nd AL side Room A218 Living Room	Photoelectric	14244862
24	Smoke Detector	3rd AL side Room A319 Living Room	Photoelectric	14244226
25	Smoke Detector	3rd AL side Room A319 Bedroom	Photoelectric	14244225
26	Smoke Detector	3rd AL side Room A317 Living Room	Photoelectric	14244223
27	Smoke Detector	3rd AL side Room A315 Living Room	Photoelectric	14244221
28	Smoke Detector	3rd AL side Room A313 Bedroom	Photoelectric	14244219
29	Smoke Detector	3rd AL side Room A313 Living Room	Photoelectric	14244220
34	Smoke Detector	3rd AL side Room A314 Living Room	Photoelectric	14244222
35	Smoke Detector	3rd AL side Room A316 Living Room	Photoelectric	14244224
36	Smoke Detector	3rd AL side Room A318 Bedroom	Photoelectric	14244227
37	Smoke Detector	3rd AL side Room A318 Living Room	Photoelectric	14244228
47	Smoke Detector	2nd AL side At room A218	Photoelectric	14244447
48	Smoke Detector	2nd AL side At room A216	Photoelectric	14244446
49	Smoke Detector	2nd AL side At room A213	Photoelectric	14244444
50	Smoke Detector	2nd AL side At room A211	Photoelectric	14244443
51	Smoke Detector	3rd AL side At Room A311	Photoelectric	14244084
52	Smoke Detector	3rd AL side At Room A315	Photoelectric	14244083

53	Smoke Detector	3rd AL side At Room A317	Photoelectric	14244082
54	Smoke Detector	3rd AL side At Room A319	Photoelectric	14244081
55	Smoke Detector	2nd AL side At room A214	Photoelectric	14244445

Zone/Circuit: 5

1	Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Photoelectric	37498874
2	Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Photoelectric	37498873
03	Smoke Detector	1st Elevator Equipment Room D	Photoelectric	14244580
11	Smoke Detector	1st elevator lobby D	Photoelectric	14244394
13	Smoke Detector	1st Main Mechanical/Electrical Room	Photoelectric	66860927
13	Heat Detector	1st main mechanical/ electrical room		14244582
14	Smoke Detector	1st Main Mechanical/Electrical Room	Photoelectric	68318900
15	Heat Detector	1st main mechanical/ electrical room		14244584
16	Heat Detector	1st main mechanical/ electrical room		14244587
17	Heat Detector	1st mech room in corridor by fitness		14244605
18	Pull Station	1st Main Mechanical/Electrical Room	Single Action	14244589
26	Smoke Detector	1st Workshop hallway by Clean Linen	Photoelectric	14244395
27	Smoke Detector	1st Workshop hallway by kitchen	Photoelectric	14244396
28	Smoke Detector	1st Workshop hallway by Staff Lounge	Photoelectric	14244397
29	Pull Station	1st Workshop hallway by Staff Lounge	Single Action	14244398
30	Smoke Detector	1st Workshop hallway	Photoelectric	14244407
31	Heat Detector	1st bistro kitchen		14244403
32	Heat Detector	1st bistro kitchen		14244404
33	Heat Detector	1st bistro kitchen		14244399
34	Heat Detector	1st bistro kitchen		14244400
35	Heat Detector	1st bistro kitchen		14244401
36	Heat Detector	1st bistro kitchen		14244402
38	Smoke Detector	1st Kitchen by office	Photoelectric	14244406
39	Smoke Detector	1st Workshop hallway Mech room beside Dining Services Office	Photoelectric	37498868
40	Heat Detector	1st workshop hallway kitchen mech room beside office		14244592
41	Smoke Detector	1st Workshop hallway	Photoelectric	14244409
42	Smoke Detector	1st Workshop hallway	Photoelectric	14244410
43	Pull Station	1st Cafeteria dining room by exit	Single Action	14244417
44	Pull Station	1st Cafeteria dining room by exit	Single Action	14244416
45	Pull Station	1st Dining Room by exit	Single Action	14244415
46	Pull Station	1st The Bistro by exit	Single Action	14244414
47	Smoke Detector	1st Workshop Hallway	Photoelectric	14244411
48	Smoke Detector	1st Workshop Electrical Room	Photoelectric	37498884
49	Heat Detector	1st workshop maintenance office		14244599
50	Smoke Detector	1st Workshop	Photoelectric	14244412
51	Smoke Detector	1st Workshop Mechanical Room	Photoelectric	37498867
52	Heat Detector	1st workshop hallway mech room beside maintenance office		14244594
54	Smoke Detector	1st Workshop hallway	Photoelectric	14244408
57	Heat Detector	1st Elevator Equipment Room D		14244581

Zone/Circuit: 6

1	Smoke Detector	1st Elevator Lobby B	Photoelectric	14244413
2	Smoke Detector	1st Elevator Equipment Room B	Photoelectric	16486159
03	Heat Detector	1st Elevator Equipment B		16486158

09	Smoke Detector	1st IL side Trash room by 113	Photoelectric	14244295
10	Smoke Detector	1st Hallway by Fitness Center	Photoelectric	14244418
11	Smoke Detector	1st hallway by Fitness Center	Photoelectric	14244419
12	Smoke Detector	1st Corridor by Fitness Center	Photoelectric	14244420
13	Smoke Detector	1st Corridor by Fitness Center	Photoelectric	14244421
13	Smoke Detector	1st mech room in Corridor by Fitness Center	Photoelectric	37498885
14	Pull Station	1st Corridor by Fitness Center	Single Action	14244422
19	Smoke Detector	1st IL side hallway by pool	Photoelectric	14244425
20	Smoke Detector	1st Media Worship Center across from pool	Photoelectric	14244424
21	Pull Station	1st Chapel	Single Action	14244423
22	Smoke Detector	1st pool mechanical rm in pool area	Photoelectric	14244606
24	Heat Detector	1st IL side Laundry		14244297
25	Pull Station	1st Pool area	Single Action	66860928
26	Smoke Detector	1st Elevator Lobby A	Photoelectric	14244299
27	Smoke Detector	1st IL side fire doors by room by 113	Photoelectric	14244298
28	Smoke Detector	1st IL side fire doors by room by 113	Photoelectric	14244296
29	Smoke Detector	1st Elevator Equipment Room A	Photoelectric	14244608
30	Heat Detector	1st Elevator Equipment Room A		14244609
37	Smoke Detector	1st IL side hallway by room 111	Photoelectric	14244294
38	Smoke Detector	1st IL side hallway by room 109	Photoelectric	14244293
38	Smoke Detector	1st IL side hallway by room 109	Photoelectric	14244789
39	Smoke Detector	1st IL side hallway by room 107	Photoelectric	14244292
40	Smoke Detector	1st IL side hallway by room 105	Photoelectric	14244291
41	Smoke Detector	1st IL side Electrical Room by room 105	Photoelectric	37498888
42	Smoke Detector	1st IL side hallway by room 104	Photoelectric	14244290
42	Smoke Detector	1st IL side hallway by room 104	Photoelectric	14244796
43	Smoke Detector	1st IL side hallway by room 102	Photoelectric	14244289
44	Pull Station	1st IL side by room 102	Single Action	14244288
47	Smoke Detector	1st In Room IL/CR Across From Fitness Center In Left Closet	Photoelectric	14244601

Zone/Circuit: 7

1	Smoke Detector	1st IL side Room 113 Bedroom	Photoelectric	14244638
2	Smoke Detector	1st IL side Room 113 Living Room	Photoelectric	14244637
3	Smoke Detector	1st IL side Room 111 Living Room	Photoelectric	14244633
4	Smoke Detector	1st IL side Room 111 Bedroom	Photoelectric	14244634
5	Smoke Detector	1st IL side Room 109 Bedroom	Photoelectric	14244630
6	Smoke Detector	1st IL side Room 109 Living Room	Photoelectric	14244629
07	Smoke Detector	1st IL side Room 107 Bedroom	Photoelectric	14244626
08	Smoke Detector	1st IL side Room 107 Living Room	Photoelectric	14244624
09	Smoke Detector	1st IL side Room 107 Bedroom	Photoelectric	14244625
10	Smoke Detector	1st IL side Room 105 Bedroom	Photoelectric	14244622
11	Smoke Detector	1st IL side Room 105 Living Room	Photoelectric	14244621
12	Smoke Detector	1st IL side Room 104 Bedroom	Photoelectric	14244620
14	Smoke Detector	1st IL side Room 104 Living Room	Photoelectric	14244618
15	Smoke Detector	1st IL side Room 103 Bedroom	Photoelectric	14244617
16	Smoke Detector	1st IL side Room 103 Living Room	Photoelectric	14244616
17	Smoke Detector	1st IL side Room 102 Living Room	Photoelectric	14244613
18	Smoke Detector	1st IL side Room 102 Bedroom	Photoelectric	14244614
19	Smoke Detector	1st IL side Room 102 Bedroom	Photoelectric	14244615
20	Smoke Detector	1st IL side Room 101 Living Room	Photoelectric	14244611
22	Pull Station	2nd Front Lobby near stairwell 3	Single Action	14244526

23	Smoke Detector	1st IL side Room 106 Living Room	Photoelectric	14244623
24	Smoke Detector	1st IL side Room 108 Bedroom	Photoelectric	14244628
25	Smoke Detector	1st IL side Room 108 Living Room	Photoelectric	14244627
26	Smoke Detector	1st IL side Room 110 Living Room	Photoelectric	14244631
27	Smoke Detector	1st IL side Room 110 Bedroom	Photoelectric	14244632
28	Smoke Detector	1st IL side Room 112 Bedroom	Photoelectric	14244636
29	Smoke Detector	1st IL side Room 112 Living Room	Photoelectric	14244635
30	Pull Station	2nd Corridor near stairwell 4 by Receiving	Single Action	14244547
31	Smoke Detector	2nd elevator lobby D	Photoelectric	14244545
36	Smoke Detector	2nd IL side By Room 225	Photoelectric	14244533
37	Smoke Detector	2nd IL side By Room 223	Photoelectric	14244532
38	Smoke Detector	2nd IL side By Room 222	Photoelectric	14244531
39	Smoke Detector	2nd IL side By Room 220	Photoelectric	14244530
40	Smoke Detector	2nd IL side By Room 218	Photoelectric	14244529
41	Smoke Detector	2nd IL side By Room 214	Photoelectric	14244527
42	Smoke Detector	2nd Elevator Lobby B	Photoelectric	14244525
43	Smoke Detector	2nd Front Lobby near mailboxes	Photoelectric	14244524
44	Smoke Detector	2nd IL side Mechanical Room In Library	Photoelectric	37498894
45	Smoke Detector	2nd Front Lobby	Photoelectric	14244523
46	Smoke Detector	2nd Front Lobby At Main Desk	Photoelectric	14244510
47	Smoke Detector	2nd Front Lobby	Photoelectric	14244514
48	Smoke Detector	2nd Front Lobby near Copy Room	Photoelectric	14244517
49	Smoke Detector	2nd Front Lobby hallway near Conference Room	Photoelectric	14244519
50	Smoke Detector	2nd conference room mech closet behind front desk	Photoelectric	37499627
52	Smoke Detector	2nd Front Lobby	Photoelectric	14244287
53	Smoke Detector	2nd Front Lobby hallway near Human Resources	Photoelectric	14244511
55	Pull Station	2nd Front Lobby	Single Action	14244513
55	Smoke Detector	2nd Front Lobby hallway near Sales	Photoelectric	14244512
58	Pull Station	2nd By freight elevator near AL Kitchen	Single Action	14244546
60	Smoke Detector	2nd IL side Trash Room by room 214	Photoelectric	14244528

Zone/Circuit: 8

1	Smoke Detector	2nd IL side At Room IL/CA Near front lobby	Photoelectric	14244508
2	Smoke Detector	2nd IL side Mechanical Room In card table room	Photoelectric	37498893
3	Smoke Detector	2nd IL side Electrical Room In card table room	Photoelectric	37498892
04	Smoke Detector	2nd Elevator Lobby A	Photoelectric	14244500
6	Smoke Detector	2nd IL side Electrical/Mechanical Room by Salon	Photoelectric	37498891
7	Smoke Detector	2nd IL side At Room 213	Photoelectric	14244499
8	Smoke Detector	2nd IL side At Room 212	Photoelectric	14244497
9	Smoke Detector	2nd IL side At Room 210	Photoelectric	14244496
10	Smoke Detector	2nd IL side At Room 206	Photoelectric	14244495
11	Smoke Detector	2nd IL side Trash Room	Photoelectric	14244493
12	Smoke Detector	2nd IL side At Room 205	Photoelectric	14244494
13	Smoke Detector	2nd IL side By Room 201	Photoelectric	14244491
14	Pull Station	2nd Hallway by stairwell 1 IL Side	Single Action	14244492
21	Smoke Detector	2nd IL side Room 207 Bedroom	Photoelectric	14244748

26	Smoke Detector	2nd IL side Room 204 Bedroom	Photoelectric	14244649
27	Smoke Detector	2nd IL side Room 204 Bedroom	Photoelectric	14244648
29	Smoke Detector	2nd IL side Room 203 Bedroom	Photoelectric	14244646
30	Smoke Detector	2nd IL side Room 203 Living Room	Photoelectric	14244645
31	Smoke Detector	2nd IL side Room 202 Living Room	Photoelectric	14244642
33	Smoke Detector	3rd IL Side Telephone Room At Room 433	Photoelectric	14244073
34	Smoke Detector	2nd IL side Room 201 Living Room	Photoelectric	14244641
34	Smoke Detector	3rd IL Side Electrical Toom At Room 433	Photoelectric	14244077
35	Smoke Detector	2nd IL side Room 201 Bedroom	Photoelectric	14244640
36	Smoke Detector	2nd IL side Room 201 Bedroom	Photoelectric	14244639
37	Smoke Detector	2nd IL side Room 206 Living Room	Photoelectric	14244746
38	Smoke Detector	2nd IL side Room 208 Bedroom	Photoelectric	14244751
39	Smoke Detector	2nd IL side Room 208 Living Room	Photoelectric	14244750
40	Smoke Detector	2nd IL side Room 210 Living Room	Photoelectric	14244754
41	Smoke Detector	2nd IL side Room 210 Bedroom	Photoelectric	14244755
42	Smoke Detector	2nd IL side Room 212 Bedroom	Photoelectric	14244759
43	Smoke Detector	2nd IL side Room 212 Living Room	Photoelectric	14244758
53	Heat Detector	2nd IL side electrical/Mech room by Salon & Spa		54160088
53	Heat Detector	2nd IL side laundry		14244498
55	Smoke Detector	2nd Front Lobby	Photoelectric	29189782
55	Smoke Detector	2nd Front Lobby Above Light	Photoelectric	20163933

Zone/Circuit: 9

1	Smoke Detector	2nd IL side Room 226 Living Room	Photoelectric	14244785
2	Smoke Detector	2nd IL side Room 225 Bedroom	Photoelectric	14244784
4	Smoke Detector	2nd IL side Room 225 Bedroom	Photoelectric	29189788
5	Smoke Detector	2nd IL side Room 224 Living Room	Photoelectric	14244780
6	Smoke Detector	2nd IL side Room 224 Bedroom	Photoelectric	14244781
7	Smoke Detector	2nd IL side Room 221 Bedroom	Photoelectric	14244776
9	Smoke Detector	2nd IL side Room 221 Bed Room	Photoelectric	14244777
10	Smoke Detector	2nd IL side Room 219 Bedroom	Photoelectric	14244773
11	Smoke Detector	2nd IL side Room 219 Living Room	Photoelectric	14244772
12	Smoke Detector	2nd IL side Room 217 Living Room	Photoelectric	14244768
13	Smoke Detector	2nd IL side Room 217 Bed Room	Photoelectric	14244769
14	Smoke Detector	2nd IL side Room 215 Bedroom	Photoelectric	14244765
15	Smoke Detector	2nd IL side Room 215 Bedroom	Photoelectric	14244764
16	Smoke Detector	2nd IL side Room 214 Living Room	Photoelectric	14244762
17	Smoke Detector	2nd IL side Room 214 Bedroom	Photoelectric	14244763
18	Smoke Detector	2nd IL side Room 222 Bedroom	Photoelectric	14244814
19	Smoke Detector	2nd IL side Room 222 Living Room	Photoelectric	14244813
21	Smoke Detector	2nd IL side Room 220 Bed Room	Photoelectric	14244775
22	Smoke Detector	2nd IL side Room 220 Living Room	Photoelectric	14244774
23	Smoke Detector	2nd IL side Room 218 Bedroom	Photoelectric	14244770
24	Smoke Detector	2nd IL side Room 218 Bedroom	Photoelectric	14244771
25	Smoke Detector	2nd IL side Room 216 Bed Room	Photoelectric	14244767
26	Smoke Detector	2nd IL side Room 216 Living Room	Photoelectric	14244766
27	Pull Station	3rd Hallway by stairwell 4 IL side	Single Action	14244450
28	Smoke Detector	3rd IL side At stairwell 4	Photoelectric	14244448
29	Smoke Detector	3rd elevator lobby D	Photoelectric	14244449
34	Smoke Detector	3rd IL side At FACP room	Photoelectric	14244452
35	Smoke Detector	3rd IL side At room 331	Photoelectric	14244469
36	Smoke Detector	3rd IL side At room 329	Photoelectric	14244470

37	Smoke Detector	3rd IL side At room 326	Photoelectric	14244471
38	Smoke Detector	3rd IL side At room 324	Photoelectric	14244472
39	Smoke Detector	3rd IL side At room 323	Photoelectric	14244473
40	Smoke Detector	3rd IL side Trash Room At room 313	Photoelectric	14244483
40	Smoke Detector	3rd IL side Trash Room At room 321	Photoelectric	14244474
41	Smoke Detector	3rd Elevator Lobby B	Photoelectric	14244476
42	Pull Station	3rd Hallway by stairwell 3 IL side	Single Action	14244475
43	Smoke Detector	3rd IL side At Room 320	Photoelectric	14244477
44	Smoke Detector	3rd IL side At Room 317	Photoelectric	14244478
45	Smoke Detector	3rd IL side At Room 316	Photoelectric	14244479
46	Smoke Detector	3rd Elevator Lobby A	Photoelectric	14244481
47	Heat Detector	3rd IL side Laundry		14244480
48	Smoke Detector	3rd IL side At Room 313	Photoelectric	14244482
49	Smoke Detector	3rd IL side At Room 311	Photoelectric	14244484
50	Smoke Detector	3rd IL side At Room 309	Photoelectric	14244485
51	Smoke Detector	3rd IL side At Room 307	Photoelectric	14244486
52	Smoke Detector	3rd IL side At Room 305	Photoelectric	14244487
53	Smoke Detector	3rd IL side Electrical Room by room 304	Photoelectric	14244488
54	Pull Station	3rd Hallway by stairwell 1 IL side	Single Action	14244489
55	Smoke Detector	3rd IL side At Room 301	Photoelectric	14244490

Zone/Circuit: 10

3	Smoke Detector	3rd IL side Room A332 Bedroom	Photoelectric	14244855
4	Smoke Detector	3rd IL side Room A332 Living Room	Photoelectric	14244856
5	Smoke Detector	3rd IL side Room A332 Bedroom	Photoelectric	14244857
6	Smoke Detector	3rd IL side Room A331 Living Room	Photoelectric	14244853
7	Smoke Detector	3rd IL side Room A331 Bedroom	Photoelectric	14244854
8	Smoke Detector	3rd IL side Room A329 Bedroom	Photoelectric	14244735
10	Smoke Detector	3rd IL side Room A329 Bedroom	Photoelectric	29189787
11	Smoke Detector	3rd IL side Room A327 Bedroom	Photoelectric	14244732
12	Smoke Detector	3rd IL side Room A327 Living Room	Photoelectric	14244731
13	Smoke Detector	3rd IL side Room A325 Living Room	Photoelectric	14244727
14	Smoke Detector	3rd IL side Room A325 Bedroom	Photoelectric	14244728
15	Smoke Detector	3rd IL side Room A323 Bedroom	Photoelectric	14244724
16	Smoke Detector	3rd IL side Room A323 Living Room	Photoelectric	14244723
17	Smoke Detector	3rd IL side Room A321 Living Room	Photoelectric	14244719
18	Smoke Detector	3rd IL side Room A321 Bedroom	Photoelectric	14244720
19	Smoke Detector	3rd IL side Room A319 Bedroom	Photoelectric	14244713
20	Smoke Detector	3rd IL side Room A319 Living Room	Photoelectric	14244711
21	Smoke Detector	3rd IL side Room A319 Bedroom	Photoelectric	14244712
22	Smoke Detector	3rd IL side Room A315 Bedroom	Photoelectric	14244707
23	Smoke Detector	3rd IL side Room A315 Living Room	Photoelectric	14244706
24	Smoke Detector	3rd IL side Room A315 Bedroom	Photoelectric	14244708
25	Smoke Detector	3rd IL side Room A314 Bedroom	Photoelectric	14244703
26	Smoke Detector	3rd IL side Room A314 Bedroom	Photoelectric	14244702
27	Smoke Detector	3rd IL side Room A314 Living Room	Photoelectric	14244701
28	Smoke Detector	3rd IL side Room A316 Living Room	Photoelectric	14244705
29	Smoke Detector	3rd IL side Room A316 Bedroom	Photoelectric	14244704
30	Smoke Detector	3rd IL side Room A317 Living Room	Photoelectric	14244709
31	Smoke Detector	3rd IL side Room A317 Bedroom	Photoelectric	14244710
32	Smoke Detector	3rd IL side Room A318 Bedroom	Photoelectric	14244715
33	Smoke Detector	3rd IL side Room A318 Living Room	Photoelectric	14244714
37	Smoke Detector	3rd IL side Room A322 Living Room	Photoelectric	14244721
38	Smoke Detector	3rd IL side Room A322 Bedroom	Photoelectric	14244722

39	Smoke Detector	3rd IL side Room A324 Bedroom	Photoelectric	14244726
40	Smoke Detector	3rd IL side Room A324 Living Room	Photoelectric	14244725
41	Smoke Detector	3rd IL side Room 326 Living Room	Photoelectric	14244729
42	Smoke Detector	3rd IL side Room A326 Bedroom	Photoelectric	14244730
43	Smoke Detector	3rd IL side Room A328 Bedroom	Photoelectric	14244734
44	Smoke Detector	3rd IL side Room A328 Living Room	Photoelectric	14244733
45	Smoke Detector	3rd IL side Room A330 Living Room	Photoelectric	14244852

Zone/Circuit: 11

1	Pull Station	4th Hallway by stairwell 4 IL Side	Single Action	14244078
2	Smoke Detector	4th IL Side At Stairwell 4	Photoelectric	14244079
3	Smoke Detector	4th elevator lobby D	Photoelectric	14244080
04	Smoke Detector	4th IL side Trash Room by room 413	Photoelectric	14244057
8	Smoke Detector	4th IL side By Room 432	Photoelectric	14244072
9	Smoke Detector	4th IL side By Room 431	Photoelectric	14244071
10	Smoke Detector	4th IL side By Room 428	Photoelectric	14244070
11	Smoke Detector	4th IL side By Room 426	Photoelectric	14244069
12	Smoke Detector	4th IL side By Room 424	Photoelectric	14244068
13	Smoke Detector	4th IL side By Room 421	Photoelectric	14244066
15	Smoke Detector	4th Elevator Lobby B	Photoelectric	14244064
16	Pull Station	4th Hallway by stairwell 3 IL Side	Single Action	14244065
17	Smoke Detector	4th IL side By Room 420	Photoelectric	14244063
18	Smoke Detector	4th IL side By Room 417	Photoelectric	14244062
19	Smoke Detector	4th IL side By Room 415	Photoelectric	14244061
20	Smoke Detector	4th Elevator Lobby A	Photoelectric	14244059
21	Heat Detector	4th IL side Laundry		14244060
22	Smoke Detector	4th IL side By Room 413	Photoelectric	14244058
23	Smoke Detector	4th IL side By Room 411	Photoelectric	14244056
24	Smoke Detector	4th IL side By Room 409	Photoelectric	14244055
25	Smoke Detector	4th IL side By Room 406	Photoelectric	14244054
26	Smoke Detector	4th IL side By Room 405	Photoelectric	14244053
27	Smoke Detector	4th IL side Electrical room by room 404	Photoelectric	14244052
28	Pull Station	4th Hallway by stairwell 1 IL Side	Single Action	14244050
29	Smoke Detector	4th IL side By Room 401	Photoelectric	14244051
30	Smoke Detector	3rd IL side Room A313 Bedroom	Photoelectric	14244700
31	Smoke Detector	3rd IL side Room A313 Living Room	Photoelectric	14244699
32	Smoke Detector	3rd IL side Room 311 Living Room	Photoelectric	14244695
33	Smoke Detector	3rd IL side Room 311 Bedroom	Photoelectric	14244696
34	Smoke Detector	2nd IL side Electrical Room by room 226	Photoelectric	37498862
34	Smoke Detector	3rd IL side Room 309 Bedroom	Photoelectric	14244692
34	Smoke Detector	3rd IL side Room 320 Living Room	Photoelectric	14244716
35	Smoke Detector	3rd IL side Room 309 Living Room	Photoelectric	14244691
35	Smoke Detector	3rd IL side Room 320 Bedroom	Photoelectric	14244717
36	Smoke Detector	3rd IL side Room 307 Bedroom	Photoelectric	14244688
36	Smoke Detector	3rd IL side Room 320 Bedroom	Photoelectric	14244718
37	Smoke Detector	3rd IL side Room 307 Living Room	Photoelectric	14244686
38	Smoke Detector	3rd IL side Room 307 Bedroom	Photoelectric	14244687
39	Smoke Detector	3rd IL side Room 305 Bedroom	Photoelectric	14244684
40	Smoke Detector	3rd IL side Room 305 Living Room	Photoelectric	14244683
41	Smoke Detector	3rd IL side Room 304 Bedroom	Photoelectric	14244682
42	Smoke Detector	3rd IL side Room 304 Bedroom	Photoelectric	14244681
43	Smoke Detector	3rd IL side Room 304 Living Room	Photoelectric	14244680
44	Smoke Detector	3rd AL side Room 303 Bedroom	Photoelectric	14244679
45	Smoke Detector	3rd AL side Room 303 Living Room	Photoelectric	14244678

46	Smoke Detector	3rd IL side Room 302 Living Room	Photoelectric	14244677
47	Smoke Detector	3rd IL side Room 302 Bedroom	Photoelectric	14244675
48	Smoke Detector	3rd IL side Room 302 Bedroom	Photoelectric	14244676
49	Smoke Detector	3rd IL side Room 301 Living Room	Photoelectric	14244672
50	Smoke Detector	3rd IL side Room 301 Bedroom	Photoelectric	14244673
51	Smoke Detector	3rd IL side Room 301 Bedroom	Photoelectric	14244674
52	Smoke Detector	3rd IL side Room 306 Living Room	Photoelectric	14244685
53	Smoke Detector	3rd IL side Room 308 Bedroom	Photoelectric	14244690
54	Smoke Detector	3rd IL side Room 308 Living Room	Photoelectric	14244689
55	Smoke Detector	3rd IL side Room 310 Living Room	Photoelectric	14244693
56	Smoke Detector	3rd IL side Room 310 Bedroom	Photoelectric	14244694
57	Smoke Detector	3rd IL side Room 312 Bedroom	Photoelectric	14244698
58	Smoke Detector	3rd IL side Room 312 Living Room	Photoelectric	14244697

Zone/Circuit: 12

1	Smoke Detector	4th IL side Room 433 Living Room	Photoelectric	14244230
2	Smoke Detector	4th IL side Room 433 Bedroom	Photoelectric	14244229
3	Smoke Detector	4th IL side Room 432 Bedroom	Photoelectric	14244233
4	Smoke Detector	4th IL side Room 432 Living Room	Photoelectric	14244232
5	Smoke Detector	4th IL side Room 432 Bedroom	Photoelectric	14244231
8	Smoke Detector	4th IL side Room 429 Bedroom	Photoelectric	14244237
9	Smoke Detector	4th IL side Room 429 Living Room	Photoelectric	14244239
10	Smoke Detector	4th IL side Room 429 Bedroom	Photoelectric	14244238
11	Smoke Detector	4th IL side Room 427 Bedroom	Photoelectric	14244242
12	Smoke Detector	4th IL side Room 427 Living Room	Photoelectric	14244243
13	Smoke Detector	4th IL side Room 425 Bedroom	Photoelectric	14244244
14	Smoke Detector	4th IL side Electrical Room by room 421	Photoelectric	14244067
14	Smoke Detector	4th IL side Room 425 Living Room	Photoelectric	14244245
15	Smoke Detector	4th IL side Room 423 Bedroom	Photoelectric	14244248
16	Smoke Detector	4th IL side Room 423 Living Room	Photoelectric	14244249
17	Smoke Detector	4th IL side Room 421 Living Room	Photoelectric	14244253
18	Smoke Detector	4th IL side Room 421 Bedroom	Photoelectric	14244252
19	Smoke Detector	4th IL side Room 419 Bedroom	Photoelectric	14244260
20	Smoke Detector	4th IL side Room 419 Living Room	Photoelectric	14244261
21	Smoke Detector	4th IL side Room 419 Bedroom	Photoelectric	14244259
22	Smoke Detector	4th IL side Room 415 Bedroom	Photoelectric	14244264
23	Smoke Detector	4th IL side Room 415 Living Room	Photoelectric	14244266
24	Smoke Detector	4th IL side Room 415 Bedroom	Photoelectric	14244265
25	Smoke Detector	4th IL side Room 414 Bedroom	Photoelectric	14244270
26	Smoke Detector	4th IL side Room 414 Bedroom	Photoelectric	14244269
27	Smoke Detector	4th IL side Room 414 Living Room	Photoelectric	14244271
28	Smoke Detector	4th IL side Room 416 Living Room	Photoelectric	14244268
29	Smoke Detector	4th IL side Room 416 Bedroom	Photoelectric	14244267
30	Smoke Detector	4th IL side Room 417 Living Room	Photoelectric	14244263
31	Smoke Detector	4th IL side Room 417 Bedroom	Photoelectric	14244262
32	Smoke Detector	4th IL side Room 418 Bedroom	Photoelectric	14244257
33	Smoke Detector	4th IL side Room 418 Living Room	Photoelectric	14244258
34	Smoke Detector	4th IL side Room 420 Living Room	Photoelectric	14244256
35	Smoke Detector	4th IL side Room 420 Bedroom	Photoelectric	14244254
36	Smoke Detector	4th IL side Room 420 Bedroom	Photoelectric	14244255
37	Smoke Detector	4th IL side Room 422 Living Room	Photoelectric	14244251
38	Smoke Detector	4th IL side Room 422 Bedroom	Photoelectric	14244250
39	Smoke Detector	4th IL side Room 424 Bedroom	Photoelectric	14244246
40	Smoke Detector	4th IL side Room 424 Living Room	Photoelectric	14244247

41	Smoke Detector	4th IL side Room 426 Living room	Photoelectric	14244670
42	Smoke Detector	4th IL side Room 426 Bedroom	Photoelectric	14244671
43	Smoke Detector	4th IL side Room 428 Bedroom	Photoelectric	14244240
44	Smoke Detector	4th IL side Room 428 Living Room	Photoelectric	14244241
45	Smoke Detector	4th IL side Room 430 Living Room	Photoelectric	14244236
57	Smoke Detector	5th IL side Room 513 Living Room	Photoelectric	14244327
58	Smoke Detector	5th IL side Electrical Room by room 513	Photoelectric	68318899
58	Smoke Detector	5th IL side Room 513 Bedroom	Photoelectric	14244328

Zone/Circuit: 13

1	Smoke Detector	4th IL side room 413 Bedroom	Photoelectric	14244272
2	Smoke Detector	4th IL side room 413 Living room	Photoelectric	14244273
3	Smoke Detector	4th IL side room 411 Living room	Photoelectric	14244277
4	Smoke Detector	4th IL side room 411 Bedroom	Photoelectric	14244276
5	Smoke Detector	4th IL side room 409 Bedroom	Photoelectric	14244280
6	Smoke Detector	4th IL side room 409 Living room	Photoelectric	14244281
7	Smoke Detector	4th IL side room 407 Bedroom	Photoelectric	14244284
8	Smoke Detector	4th IL side room 407 Living room	Photoelectric	14244286
9	Smoke Detector	4th IL side room 407 Bedroom	Photoelectric	14244285
10	Smoke Detector	4th IL side room 405 Bedroom	Photoelectric	14244392
11	Smoke Detector	4th IL side room 405 Living room	Photoelectric	14244391
12	Smoke Detector	4th IL side room 404 Bedroom	Photoelectric	14244390
13	Smoke Detector	4th IL side room 404 Bedroom	Photoelectric	14244389
14	Smoke Detector	4th IL side room 404 Living room	Photoelectric	14244388
15	Smoke Detector	4th IL side room 403 Bedroom	Photoelectric	14244387
16	Smoke Detector	4th IL side room 403 Living room	Photoelectric	14244386
17	Smoke Detector	4th IL side room 402 Living room	Photoelectric	14244383
18	Smoke Detector	4th IL side room 402 Bedroom	Photoelectric	14244384
19	Smoke Detector	4th IL side room 402 Bedroom	Photoelectric	14244385
20	Smoke Detector	4th IL side room 401 Living room	Photoelectric	14244381
21	Smoke Detector	4th IL side room 401 Bedroom	Photoelectric	14244382
22	Smoke Detector	4th IL side room 401 Bedroom	Photoelectric	14244380
23	Smoke Detector	4th IL side room 406 Living room	Photoelectric	14244393
24	Smoke Detector	4th IL side room 408 Bedroom	Photoelectric	14244282
25	Smoke Detector	4th IL side room 408 Living room	Photoelectric	14244283
26	Smoke Detector	4th IL side room 410 Living room	Photoelectric	14244279
27	Smoke Detector	4th IL side room 410 Bedroom	Photoelectric	14244278
28	Smoke Detector	4th IL side room 412 Bedroom	Photoelectric	14244274
29	Smoke Detector	4th IL side room 412 Living room	Photoelectric	14244275
30	Smoke Detector	5th IL side Room 511 Living Room	Photoelectric	14244323
31	Smoke Detector	5th IL side Room 511 Bedroom	Photoelectric	14244324
33	Smoke Detector	5th IL side Room 507 Bedroom	Photoelectric	14244315
33	Smoke Detector	5th IL side Room 509 Living Room	Photoelectric	14244321
34	Smoke Detector	5th IL side Room 509 Bedroom	Photoelectric	14244322
35	Smoke Detector	5th IL side Room 507 Living Room	Photoelectric	14244314
36	Smoke Detector	5th IL side Room 506 Living Room	Photoelectric	14244313
36	Smoke Detector	5th IL side Room 507 Bedroom	Photoelectric	14244316
37	Smoke Detector	5th IL side Room 505 Bedroom	Photoelectric	14244312
38	Smoke Detector	5th IL side Room 505 Living Room	Photoelectric	14244311
39	Smoke Detector	5th IL side Room 504 Bedroom	Photoelectric	14244319
40	Smoke Detector	5th IL side Room 504 Bedroom	Photoelectric	14244320
41	Smoke Detector	5th IL side Room 504 Living Room	Photoelectric	14244310
42	Smoke Detector	5th IL side Room 503 Bedroom	Photoelectric	14244309
43	Smoke Detector	5th IL side Room 503 Living Room	Photoelectric	14244308

44	Smoke Detector	5th IL side Room 502 Living Room	Photoelectric	14244305
45	Smoke Detector	5th IL side Room 502 Bedroom	Photoelectric	14244306
47	Smoke Detector	5th IL side Room 501 Living Room	Photoelectric	14244303
48	Smoke Detector	5th IL side Room 501 Bedroom	Photoelectric	14244304
49	Smoke Detector	5th IL side Room 501 Bedroom	Photoelectric	20163939
51	Smoke Detector	5th IL side Room 508 Bedroom	Photoelectric	14244318
52	Smoke Detector	5th IL side Room 508 Living Room	Photoelectric	14244317
53	Smoke Detector	5th IL side Room 510 Living Room	Photoelectric	14244379
54	Smoke Detector	5th IL side Room 510 Bedroom	Photoelectric	14244378
55	Smoke Detector	5th IL side Room 512 Bedroom	Photoelectric	14244326
56	Smoke Detector	5th IL side Room 512 Living Room	Photoelectric	14244325

Zone/Circuit: 14

1	Smoke Detector	5th Top of stairwell 4 IL side	Photoelectric	14242706
2	Pull Station	5th Hallway by stairwell 4 IL side	Single Action	14242704
3	Smoke Detector	5th IL side hallway by room 534	Photoelectric	14242707
4	Smoke Detector	5th elevator lobby D	Photoelectric	14242703
7	Smoke Detector	5th IL side Mechanical Room by room 533	Photoelectric	14243950
11	Smoke Detector	5th IL side hallway by room 533	Photoelectric	14242708
12	Smoke Detector	5th IL side hallway by room 530	Photoelectric	14242709
13	Smoke Detector	5th IL side hallway by room 528	Photoelectric	14242710
14	Smoke Detector	5th IL side hallway by room 526	Photoelectric	14242711
15	Smoke Detector	5th IL side hallway by room 524	Photoelectric	14242712
16	Smoke Detector	5th IL side hallway by room 521	Photoelectric	14242713
17	Smoke Detector	5th IL side Electrical Room by room 521	Photoelectric	14244042
20	Smoke Detector	5th Elevator Lobby B	Photoelectric	14242714
21	Pull Station	5th Hallway by stairwell 3 IL side	Single Action	14242715
22	Smoke Detector	5th IL side hallway by room 520	Photoelectric	14242717
23	Smoke Detector	5th IL side hallway by room 517	Photoelectric	14242718
24	Smoke Detector	5th IL side hallway by room 516	Photoelectric	14242719
25	Smoke Detector	5th Elevator Lobby A	Photoelectric	14242720
26	Heat Detector	5th IL side Laundry		14242705
28	Smoke Detector	5th IL side hallway by room 513	Photoelectric	14242721
29	Smoke Detector	5th IL side hallway by room 510	Photoelectric	14242722
30	Smoke Detector	5th IL side hallway by room 508	Photoelectric	14242723
31	Smoke Detector	5th IL side hallway by room 505	Photoelectric	14242724
32	Smoke Detector	5th IL side Mechanical Room by room 504	Photoelectric	37498863
33	Smoke Detector	5th IL side hallway by room 504	Photoelectric	14242725
34	Smoke Detector	5th	Photoelectric	14244302
35	Pull Station	5th Hallway by stairwell 1 IL side	Single Action	14244300
36	Smoke Detector	5th IL side hallway by room 501	Photoelectric	14244301
37	Smoke Detector	5th IL side Room 530 Living Room	Photoelectric	14244364
38	Smoke Detector	5th IL side Room 528 Living Room	Photoelectric	14244362
39	Smoke Detector	5th IL side Room 528 Bedroom	Photoelectric	14244363
40	Smoke Detector	5th IL side Room 526 Bedroom	Photoelectric	14244356
41	Smoke Detector	5th IL side Room 526 Living Room	Photoelectric	14244355
42	Smoke Detector	5th IL side Room 524 Living Room	Photoelectric	14244353
43	Smoke Detector	5th IL side Room 524 Bedroom	Photoelectric	14244354
44	Smoke Detector	5th IL side Room 522 Bedroom	Photoelectric	14244352
45	Smoke Detector	5th IL side Room 522 Living Room	Photoelectric	14244351
46	Smoke Detector	5th IL side Room 520 Bedroom	Photoelectric	14244345
47	Smoke Detector	5th IL side Room 520 Bedroom	Photoelectric	14244346

48	Smoke Detector	5th IL side Room 520 Living Room	Photoelectric	14244344
49	Smoke Detector	5th IL side Room 518 Living Room	Photoelectric	14244342
50	Smoke Detector	5th IL side Room 518 Bedroom	Photoelectric	14244343
51	Smoke Detector	5th IL side Room 517 Bedroom	Photoelectric	14244338
52	Smoke Detector	5th IL side Room 517 Living Room	Photoelectric	14244337
53	Smoke Detector	5th IL side Room 516 Bedroom	Photoelectric	14244332
54	Smoke Detector	5th IL side Room 516 Living Room	Photoelectric	14244333
55	Smoke Detector	5th IL side Room 514 Living Room	Photoelectric	14244329
56	Smoke Detector	5th IL side Room 514 Bedroom	Photoelectric	14244330
57	Smoke Detector	5th IL side Room 514 Bedroom	Photoelectric	14244331
59	Smoke Detector	5th Top of stairwell 3 IL side	Photoelectric	14242716

Zone/Circuit: 15

3	Smoke Detector	5th IL side Room 535 Bedroom	Photoelectric	14244375
4	Smoke Detector	5th IL side Room 535 Living Room	Photoelectric	14244374
5	Smoke Detector	5th IL side Room 533 Living Room	Photoelectric	14244370
6	Smoke Detector	5th IL side Room 533 Bedroom	Photoelectric	14244371
7	Smoke Detector	5th IL side Room 532 Bedroom	Photoelectric	14244367
9	Smoke Detector	5th IL side Room 532 Living Room	Photoelectric	14244368
10	Smoke Detector	5th IL side Room 531 Living Room	Photoelectric	14244365
11	Smoke Detector	5th IL side Room 531 Bedroom	Photoelectric	14244366
12	Smoke Detector	5th IL side Room 529 Bedroom	Photoelectric	14244360
13	Smoke Detector	5th IL side Room 529 Living Room	Photoelectric	14244359
14	Smoke Detector	5th IL side Room 529 Bedroom	Photoelectric	14244361
15	Smoke Detector	5th IL side Room 527 Bedroom	Photoelectric	14244358
16	Smoke Detector	5th IL side Room 527 Living Room	Photoelectric	14244357
17	Smoke Detector	5th IL side Room 525 Living Room	Photoelectric	14244376
18	Smoke Detector	5th IL side Room 525 Bedroom	Photoelectric	14244377
19	Smoke Detector	5th IL side Room 523 Bedroom	Photoelectric	14244350
20	Smoke Detector	5th IL side Room 523 Living Room	Photoelectric	14244349
21	Smoke Detector	5th IL side Room 521 Living Room	Photoelectric	14244347
22	Smoke Detector	5th IL side Room 521 Bedroom	Photoelectric	14244348
23	Smoke Detector	5th IL side Room 519 Bedroom	Photoelectric	14244341
24	Smoke Detector	5th IL side Room 519 Living Room	Photoelectric	14244340
25	Smoke Detector	5th IL side Room 519 Bedroom	Photoelectric	14244339
26	Smoke Detector	5th IL side Room 515 Bedroom	Photoelectric	14244336
27	Smoke Detector	5th IL side Room 515 Living Room	Photoelectric	14244334
28	Smoke Detector	5th IL side Room 515 Bedroom	Photoelectric	14244335
28	Duct Detector	3rd by room A311	Ionization	22983381
29	Duct Detector	3rd by room A303	Ionization	22983382
30	Duct Detector	5th by room 518	Photoelectric	22983380
33	Duct Detector	5th by room 503	Ionization	14244049

Fire Alarm and Life Safety System Inspection Certificate

For

Magnolia Glen
5301 Creedmoor
Raleigh, NC 27612

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

*Annual Inspection
Inspection Date
Apr 12, 2023*

Building: Magnolia Glen
Contact: Carl Benson
Title: PM

Company: Summit Fire & Security - Raleigh
Contact: James Cogan
Title: Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Magnolia Glen	Contact: Carl Benson	
Address: 5301 Creedmoor	Phone: 919-841-4747	
Address:	Fax:	
City/State/ZIP Code: Raleigh, NC 27612	Mobile:	
Country: United States of America	Email: carl.benson@kiscosl.com	
Inspection Performed By		
Company: Summit Fire & Security - Raleigh	Inspector: James Cogan	
Address: 1731 Round Rock Dr	Phone: 9197229521	
Address:	Fax:	
City/State/ZIP Code: Raleigh, North Carolina 27615	Mobile:	
Country: United States of America	Email: JCogan@summitfiresecurity.com	
System Control Unit		
Manufacturer: Siemens	Inspection Date: 03/30/2023	IDC Style:
Model Number: XLS-MME-ADPT	Install Date: 10/24/2016	SLC Style:
Software Version:	Version Date: 12/23/2016	NAC Style:
Location: 3rd Telephone/FACP	Current Protection: Breaker	
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Silent Knight	Model #: SK-5208
Test Time/Date: 4/12/23 11:28:22 AM	Restore Time:	Note:

Inspection Summary

Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	22	3.42%	22	100.00%	20	90.91%	2	9.09%
Indicating	5	0.78%	5	100.00%	2	40.00%	3	60.00%
Initiating	617	95.81%	617	100.00%	617	100.00%	0	0.00%
Totals	644	100%	644	100.00%	639	99.22%	5	0.78%

Certification

Company: Summit Fire & Security - Raleigh

Inspector: James Cogan



Signed: Apr 12, 2023

Building: Magnolia Glen

Contact: Carl Benson



Signed: Apr 12, 2023

Discrepancy Report

Generated by: BuildingReports.com

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
Items listed for Recall or Replacement/Upgrade				
No items found during this inspection.				
🔍 ScanID	📍 Location	🔍 Problem	📍 Address	📖 Reference
Control				
Battery				
52545307	3rd Telephone /FACP	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)
Communicator				
14244542	2nd IL side Telephone Room by room 226	Trouble On Panel	1	
Indicating				
Horn/Strobe				
68319040	2nd Total (42)	Failed Test	1	NFPA 72 Table 10.4.2.2.14(a)
68319041	3rd Total (28)	Failed Test / See note	1-3 05	
68319042	4th Total (10)	Failed Test / See note	1-3 05	
Code References				
NFPA 72 Table 10.4.2.2.5(a-e)	<p>(a) Batteries shall be inspected for corrosion or leakage. Tightness of connections shall be checked and ensured. If necessary, battery terminals or connections shall be cleaned and coated. Electrolyte level in lead-acid batteries shall be visibly inspected. (b) Batteries shall be replaced in accordance with the recommendations of the alarm equipment manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations. (c) Operation of battery charger shall be checked in accordance with charger test for the specific type of battery. (d) Discharge Test: With the battery charger disconnected, the batteries shall be load tested following the manufacturer's recommendations. The voltage level shall not fall below the levels specified. Exception: An artificial load equal to the full fire alarm load connected to the battery shall be permitted to be used in conducting this test. (e) With the battery charger disconnected, the terminal voltage shall be measured while supplying the maximum load required by its application. The voltage level shall not fall below the levels specified for the specific type of battery. If the voltage falls below the level specified, corrective action shall be taken and the batteries shall be retested. Exception: An artificial load equal to the full fire alarm load connected to the battery shall be permitted to be used in conducting this test.</p>			
NFPA 72 Table 10.4.2.2.14(a)	<p>Sound pressure level shall be measured with sound level meter meeting ANSI S1.4a, Specifications for sound Level Meters, Type 2 requirements. Levels throughout protected area shall be measured and</p>			

recorded. The sound level meter shall be set in accordance with ANSI S3.41, American National Standard Audible Evacuation signal, using the time-weighted characteristic F (FAST). Record the maximum output when the audible emergency evacuation signal is on.

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT			
<p><i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i></p>					
ScanID	Location	Solution	Model #	Cost	Fix
<i>Control</i>					
Battery					
52545307	3rd Telephone/FACP	Replace	PS12350-NB	T/M	<input type="checkbox"/>
Communicator					
14244542	2nd IL side Telephone Room by room 226	Investigate/Correct	SK-5208	T/M	<input type="checkbox"/>
<i>Indicating</i>					
Horn/Strobe					
68319040	2nd Total (42)	Replace		T/M	<input type="checkbox"/>
68319041	3rd Total (28)	Replace	NS4-24110W	T/M	<input type="checkbox"/>
68319042	4th Total (10)	Replace	NS4-24110W	T/M	<input type="checkbox"/>
				PO #: (none)	T/M

Notes & Recommendations

Generated by: BuildingReports.com

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT		
<p><i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i></p>				
ScanID	Note	Device Type	Location	Comment
Control				
74727778	1	Power Supply	4th IL side Telephone Room by room 432	Passed
	Barcode on device			
Indicating				
68319040	2	Horn/Strobe	2nd Total (42)	Failed Test
	Unit IL 330			
68319041	3	Horn/Strobe	3rd Total (28)	Failed Test/See note
	Unit IL 215			
68319042	4	Horn/Strobe	4th Total (10)	Failed Test/ See note
	Unit 426. 428. 430			
Initiating				
14244621	5	Smoke Detector	1st IL side Room 105 Living Room	Passed
	Under construction			
14244042	6	Smoke Detector	5th IL side Electrical Room by room 521	Passed
	Barcode on device			
14243950	7	Smoke Detector	5th IL side Mechanical Room by room 533	Passed
	Barcode on Device			

Inspection & Testing

Generated by: BuildingReports.com

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT		
<p><i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i></p>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	2nd Main entrance by reception desk	Tested	12:40:59 PM	03/30/2023
Annunciator	2nd AL side Front entrance in lobby	Tested	1:40:23 PM	03/30/2023
Battery	2nd IL side Telephone Room by room 226	Tested	2:32:49 PM	03/29/2023
Battery	2nd IL side Telephone Room by room 226	Tested	2:34:41 PM	03/29/2023
Battery	2nd IL side Telephone Room by room 226	Tested	2:36:26 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332	Tested	2:17:56 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332 Bottom	Tested	2:16:01 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332 Too right	Tested	2:12:51 PM	03/29/2023
Battery	3rd IL side FACP Room by room 332 Top left	Tested	2:06:51 PM	03/29/2023
Battery	4th IL side Telephone Room by room 432	Tested	2:54:37 PM	03/29/2023
Battery	5th IL side Mechanical Room by room 532	Tested	1:52:38 PM	03/29/2023
Control Panel	3rd Telephone/FACP	Tested	12:37:27 PM	03/30/2023
Power Supply	2nd IL side Telephone Room by room 226	Tested	2:31:48 PM	03/29/2023
Power Supply	2nd IL side Telephone Room by room 226	Tested	2:38:05 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:06:39 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:11:46 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:15:49 PM	03/29/2023
Power Supply	3rd IL side FACP Room by room 332	Tested	2:17:49 PM	03/29/2023
Power Supply	4th IL side Telephone Room by room 432	Tested	2:54:17 PM	03/29/2023
Power Supply	5th IL side Mechanical Room by room 532	Tested	1:52:26 PM	03/29/2023
Indicating				
Horn/Strobe	1st Total (49)	Tested	3:14:48 PM	03/30/2023
Horn/Strobe	5th Total (11)	Tested	9:30:47 PM	03/30/2023
Initiating				
Duct Detector	3rd by room A303	Tested	1:12:16 PM	03/30/2023
Duct Detector	3rd by room A311	Tested	1:09:13 PM	03/30/2023
Duct Detector	5th by room 503	Tested	12:50:08 PM	03/30/2023
Duct Detector	5th by room 518	Tested	12:45:34 PM	03/30/2023
Heat Detector	1st AL side Laundry	Tested	11:13:59 AM	04/12/2023
Heat Detector	1st Elevator Equipment B	Tested	4:15:16 PM	04/06/2023
Heat Detector	1st Elevator Equipment Room A	Tested	4:15:19 PM	04/06/2023
Heat Detector	1st Elevator Equipment Room D	Tested	3:52:19 PM	04/06/2023
Heat Detector	1st Elevator Equipment w C	Tested	4:15:09 PM	04/06/2023
Heat Detector	1st IL side Laundry	Tested	10:27:31 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:10:19 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:10:56 AM	04/12/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	1st bistro kitchen	Tested	10:11:02 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:11:34 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:11:43 AM	04/12/2023
Heat Detector	1st bistro kitchen	Tested	10:11:53 AM	04/12/2023
Heat Detector	1st main mechanical/ electrical room	Tested	10:59:11 AM	04/12/2023
Heat Detector	1st main mechanical/ electrical room	Tested	10:59:57 AM	04/12/2023
Heat Detector	1st main mechanical/ electrical room	Tested	11:00:25 AM	04/12/2023
Heat Detector	1st mech room in corridor by fitness	Tested	10:42:39 AM	04/12/2023
Heat Detector	1st workshop maintenance office	Tested	10:46:28 AM	04/12/2023
Heat Detector	1st workshop hallway kitchen mech room beside office	Tested	10:54:41 AM	04/12/2023
Heat Detector	1st workshop hallway mech room beside maintenance office	Tested	10:50:02 AM	04/12/2023
Heat Detector	2nd 1st Floor AL Kitchen	Tested	11:10:35 AM	04/12/2023
Heat Detector	2nd 1st Floor AL Kitchen	Tested	11:11:17 AM	04/12/2023
Heat Detector	2nd 1st Floor AL Kitchen	Tested	11:11:43 AM	04/12/2023
Heat Detector	2nd 1st Floor AL side soiled utility	Tested	11:17:56 AM	04/12/2023
Heat Detector	2nd AL side Laundry	Tested	3:29:53 PM	04/06/2023
Heat Detector	2nd IL side electrical/Mech room by Salon & Spa	Tested	9:39:55 AM	04/12/2023
Heat Detector	2nd IL side laundry	Inspected	11:10:52 AM	03/29/2023
Heat Detector	2nd conference room mechanical closet near Executive Director room	Tested	9:51:28 AM	04/12/2023
Heat Detector	3rd AL side Laundry	Tested	3:23:22 PM	04/06/2023
Heat Detector	3rd IL side Laundry	Tested	12:58:30 PM	03/30/2023
Heat Detector	4th IL side Laundry	Inspected	12:53:56 PM	03/30/2023
Heat Detector	5th IL side Laundry	Inspected	12:47:33 PM	03/30/2023
Pull Station	1st Cafeteria dining room by exit	Tested	10:15:39 AM	04/12/2023
Pull Station	1st Cafeteria dining room by exit	Tested	10:15:56 AM	04/12/2023
Pull Station	1st Chapel	Tested	10:26:21 AM	04/12/2023
Pull Station	1st Corridor by Fitness Center	Tested	10:25:28 AM	04/12/2023
Pull Station	1st Dining Room by exit	Tested	10:17:52 AM	04/12/2023
Pull Station	1st IL side by room 102	Tested	10:32:51 AM	04/12/2023
Pull Station	1st Main Mechanical/Electrical Room	Tested	11:02:11 AM	04/12/2023
Pull Station	1st Pool area	Tested	10:37:21 AM	04/12/2023
Pull Station	1st The Bistro by exit	Tested	10:18:18 AM	04/12/2023
Pull Station	1st Workshop hallway by Staff Lounge	Tested	10:10:03 AM	04/12/2023
Pull Station	2nd AL side Front entrance	Tested	1:32:49 PM	03/30/2023
Pull Station	2nd AL side near stairwell 6	Tested	1:45:52 PM	03/30/2023
Pull Station	2nd By freight elevator near AL Kitchen	Tested	1:44:14 PM	03/30/2023
Pull Station	2nd Corridor near stairwell 4 by Receiving	Tested	1:30:06 PM	03/30/2023
Pull Station	2nd Front Lobby	Tested	1:27:38 PM	03/30/2023
Pull Station	2nd Front Lobby near stairwell 3	Tested	1:21:05 PM	03/30/2023
Pull Station	2nd Hallway by stairwell 1 IL Side	Tested	1:25:59 PM	03/30/2023
Pull Station	2nd Hallway by stairwell 5 AL side	Tested	1:16:37 PM	03/30/2023
Pull Station	2nd Hallway by stairwell 6 AL side	Tested	1:17:30 PM	03/30/2023
Pull Station	2nd Legacy Health Services	Tested	1:30:59 PM	03/30/2023
Pull Station	3rd Hallway by stairwell 1 IL side	Tested	10:07:52 AM	03/24/2023
Pull Station	3rd Hallway by stairwell 3 IL side	Tested	10:11:23 AM	03/24/2023
Pull Station	3rd Hallway by stairwell 4 IL side	Tested	1:15:59 PM	03/30/2023
Pull Station	3rd Hallway by stairwell 5 AL side	Tested	1:57:04 PM	03/24/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	3rd Hallway by stairwell 6 AL side	Tested	1:59:14 PM	03/24/2023
Pull Station	4th Hallway by stairwell 1 IL Side	Tested	2:18:37 PM	03/24/2023
Pull Station	4th Hallway by stairwell 3 IL Side	Tested	2:09:08 PM	03/24/2023
Pull Station	4th Hallway by stairwell 4 IL Side	Tested	2:02:41 PM	03/24/2023
Pull Station	5th Hallway by stairwell 1 IL side	Tested	11:12:01 AM	03/24/2023
Pull Station	5th Hallway by stairwell 3 IL side	Tested	10:59:04 AM	03/24/2023
Pull Station	5th Hallway by stairwell 4 IL side	Tested	11:27:59 AM	03/24/2023
Smoke Detector	1st hallway by Fitness Center	Tested/Cleaned	10:22:19 AM	04/12/2023
Smoke Detector	1st AL side Electrical Room by A106	Tested/Cleaned	11:18:41 AM	04/12/2023
Smoke Detector	1st AL side Front Lobby	Tested/Cleaned	9:25:18 AM	04/12/2023
Smoke Detector	1st AL side Living/Lounge Area	Tested/Cleaned	3:43:38 PM	04/06/2023
Smoke Detector	1st AL side Living/Lounge Area	Tested/Cleaned	9:26:24 AM	04/12/2023
Smoke Detector	1st AL side Room A101 Living Room	Tested/Cleaned	1:00:45 PM	03/29/2023
Smoke Detector	1st AL side Room A101 Living Room	Tested/Cleaned	1:01:02 PM	03/29/2023
Smoke Detector	1st AL side Room A102 Bedroom	Tested/Cleaned	1:01:46 PM	03/29/2023
Smoke Detector	1st AL side Room A102 Living Room	Tested/Cleaned	1:01:38 PM	03/29/2023
Smoke Detector	1st AL side Room A103 Living Room	Tested/Cleaned	1:02:06 PM	03/29/2023
Smoke Detector	1st AL side Room A105 Bedroom	Tested/Cleaned	1:04:07 PM	03/29/2023
Smoke Detector	1st AL side Room A105 Living Room	Tested/Cleaned	1:03:59 PM	03/29/2023
Smoke Detector	1st AL side Room A106 Bed room	Tested/Cleaned	1:04:32 PM	03/29/2023
Smoke Detector	1st AL side Room A106 Bedroom	Tested/Cleaned	1:04:25 PM	03/29/2023
Smoke Detector	1st AL side Room A107 Living Room	Tested/Cleaned	12:59:27 PM	03/29/2023
Smoke Detector	1st AL side Room A108 Living Room	Tested/Cleaned	12:59:12 PM	03/29/2023
Smoke Detector	1st AL side Room A109 Bedroom	Tested/Cleaned	12:54:07 PM	03/29/2023
Smoke Detector	1st AL side Room A110 Bedroom	Tested/Cleaned	1:06:01 PM	03/29/2023
Smoke Detector	1st AL side Room A110 Living Room	Tested/Cleaned	1:05:54 PM	03/29/2023
Smoke Detector	1st AL side Trash Room	Tested/Cleaned	3:41:36 PM	04/06/2023
Smoke Detector	1st Corridor by Fitness Center	Tested/Cleaned	10:25:16 AM	04/12/2023
Smoke Detector	1st Corridor by Fitness Center	Tested/Cleaned	10:25:23 AM	04/12/2023
Smoke Detector	1st Elevator Equipment Room A	Tested/Cleaned	4:15:57 PM	04/06/2023
Smoke Detector	1st Elevator Equipment Room B	Tested/Cleaned	4:15:53 PM	04/06/2023
Smoke Detector	1st Elevator Equipment Room C	Tested/Cleaned	4:16:01 PM	04/06/2023
Smoke Detector	1st Elevator Equipment Room D	Tested/Cleaned	3:52:22 PM	04/06/2023
Smoke Detector	1st Elevator Lobby A	Tested/Cleaned	2:28:33 PM	04/06/2023
Smoke Detector	1st Elevator Lobby B	Tested/Cleaned	10:21:02 AM	04/12/2023
Smoke Detector	1st Elevator Lobby C	Tested/Cleaned	2:49:49 PM	04/06/2023
Smoke Detector	1st Hallway by Fitness Center	Tested/Cleaned	10:21:27 AM	04/12/2023
Smoke Detector	1st IL side Electrical Room by room 105	Tested/Cleaned	10:30:55 AM	04/12/2023
Smoke Detector	1st IL side Room 101 Living Room	Tested/Cleaned	1:31:34 PM	03/29/2023
Smoke Detector	1st IL side Room 102 Bedroom	Tested/Cleaned	1:33:18 PM	03/29/2023
Smoke Detector	1st IL side Room 102 Bedroom	Tested/Cleaned	1:33:52 PM	03/29/2023
Smoke Detector	1st IL side Room 102 Living Room	Tested/Cleaned	1:32:54 PM	03/29/2023
Smoke Detector	1st IL side Room 103 Bedroom	Tested/Cleaned	1:30:18 PM	03/29/2023
Smoke Detector	1st IL side Room 103 Living Room	Tested/Cleaned	1:30:06 PM	03/29/2023
Smoke Detector	1st IL side Room 104 Bedroom	Tested/Cleaned	1:28:03 PM	03/29/2023
Smoke Detector	1st IL side Room 104 Living Room	Tested/Cleaned	1:26:49 PM	03/29/2023
Smoke Detector	1st IL side Room 105 Bedroom	Inspected	1:25:29 PM	03/29/2023
Smoke Detector	1st IL side Room 105 Living Room	Inspected	1:25:46 PM	03/29/2023
Smoke Detector	1st IL side Room 106 Living Room	Tested/Cleaned	1:23:55 PM	03/29/2023
Smoke Detector	1st IL side Room 107 Bedroom	Tested/Cleaned	1:19:58 PM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st IL side Room 107 Bedroom	Tested/Cleaned	1:20:15 PM	03/29/2023
Smoke Detector	1st IL side Room 107 Living Room	Tested/Cleaned	1:21:10 PM	03/29/2023
Smoke Detector	1st IL side Room 108 Bedroom	Tested/Cleaned	1:22:01 PM	03/29/2023
Smoke Detector	1st IL side Room 108 Living Room	Tested/Cleaned	1:22:32 PM	03/29/2023
Smoke Detector	1st IL side Room 109 Bedroom	Tested/Cleaned	1:16:55 PM	03/29/2023
Smoke Detector	1st IL side Room 109 Living Room	Tested/Cleaned	1:17:06 PM	03/29/2023
Smoke Detector	1st IL side Room 110 Bedroom	Tested/Cleaned	1:18:07 PM	03/29/2023
Smoke Detector	1st IL side Room 110 Living Room	Tested/Cleaned	1:18:49 PM	03/29/2023
Smoke Detector	1st IL side Room 111 Bedroom	Tested/Cleaned	1:13:24 PM	03/29/2023
Smoke Detector	1st IL side Room 111 Living Room	Tested/Cleaned	1:13:48 PM	03/29/2023
Smoke Detector	1st IL side Room 112 Bedroom	Tested/Cleaned	1:14:55 PM	03/29/2023
Smoke Detector	1st IL side Room 112 Living Room	Tested/Cleaned	1:15:15 PM	03/29/2023
Smoke Detector	1st IL side Room 113 Bedroom	Tested/Cleaned	1:12:05 PM	03/29/2023
Smoke Detector	1st IL side Room 113 Living Room	Tested/Cleaned	1:12:23 PM	03/29/2023
Smoke Detector	1st IL side Trash room by 113	Tested/Cleaned	10:34:45 AM	04/12/2023
Smoke Detector	1st IL side fire doors by room by 113	Tested/Cleaned	10:28:35 AM	04/12/2023
Smoke Detector	1st IL side fire doors by room by 113	Tested/Cleaned	10:29:10 AM	04/12/2023
Smoke Detector	1st IL side hallway by pool	Tested/Cleaned	10:27:09 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 102	Tested/Cleaned	10:32:38 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 104	Tested/Cleaned	1:03:30 PM	03/29/2023
Smoke Detector	1st IL side hallway by room 104	Tested/Cleaned	10:32:28 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 105	Tested/Cleaned	10:30:41 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 107	Tested/Cleaned	10:30:27 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 109	Tested/Cleaned	1:07:14 PM	03/29/2023
Smoke Detector	1st IL side hallway by room 109	Tested/Cleaned	10:30:14 AM	04/12/2023
Smoke Detector	1st IL side hallway by room 111	Tested/Cleaned	10:29:59 AM	04/12/2023
Smoke Detector	1st In Room IL/CR Across From Fitness Center In Left Closet	Tested/Cleaned	10:22:42 AM	04/12/2023
Smoke Detector	1st Kitchen by office	Tested/Cleaned	10:12:39 AM	04/12/2023
Smoke Detector	1st Main Mechanical/Electrical Room	Tested/Cleaned	11:00:35 AM	04/12/2023
Smoke Detector	1st Main Mechanical/Electrical Room	Tested/Cleaned	11:03:59 AM	04/12/2023
Smoke Detector	1st Media Worship Center across from pool	Tested/Cleaned	10:40:50 AM	04/12/2023
Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Tested/Cleaned	10:04:38 AM	04/12/2023
Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Tested/Cleaned	10:05:22 AM	04/12/2023
Smoke Detector	1st Workshop	Tested/Cleaned	10:46:22 AM	04/12/2023
Smoke Detector	1st Workshop Electrical Room	Tested/Cleaned	11:06:39 AM	04/12/2023
Smoke Detector	1st Workshop Mechanical Room	Tested/Cleaned	10:48:38 AM	04/12/2023
Smoke Detector	1st Workshop Hallway	Tested/Cleaned	10:45:42 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:51:23 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:52:19 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:53:06 AM	04/12/2023
Smoke Detector	1st Workshop hallway	Tested/Cleaned	10:57:27 AM	04/12/2023
Smoke Detector	1st Workshop hallway Mech room beside Dining Services Office	Tested/Cleaned	10:54:11 AM	04/12/2023
Smoke Detector	1st Workshop hallway by Clean Linen	Tested/Cleaned	10:07:43 AM	04/12/2023
Smoke Detector	1st Workshop hallway by Staff Lounge	Tested/Cleaned	10:09:09 AM	04/12/2023
Smoke Detector	1st Workshop hallway by kitchen	Tested/Cleaned	10:08:29 AM	04/12/2023
Smoke Detector	1st elevator lobby D	Tested/Cleaned	10:06:46 AM	04/12/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st mech room in Corridor by Fitness Center	Tested/Cleaned	10:42:07 AM	04/12/2023
Smoke Detector	1st pool mechanical rm in pool area	Tested/Cleaned	10:39:26 AM	04/12/2023
Smoke Detector	2nd 1st Floor AL side Soiled Linen By A101	Tested/Cleaned	11:17:21 AM	04/12/2023
Smoke Detector	2nd AL side At room A201	Tested/Cleaned	10:23:20 AM	03/24/2023
Smoke Detector	2nd AL side At room A204	Tested/Cleaned	10:22:07 AM	03/24/2023
Smoke Detector	2nd AL side At room A208	Tested/Cleaned	10:21:18 AM	03/24/2023
Smoke Detector	2nd AL side At room A209	Tested/Cleaned	10:20:10 AM	03/24/2023
Smoke Detector	2nd AL side At room A211	Tested/Cleaned	10:18:14 AM	03/24/2023
Smoke Detector	2nd AL side At room A213	Tested/Cleaned	10:30:53 AM	03/24/2023
Smoke Detector	2nd AL side At room A214	Tested/Cleaned	10:31:13 AM	03/24/2023
Smoke Detector	2nd AL side At room A216	Tested/Cleaned	10:31:24 AM	03/24/2023
Smoke Detector	2nd AL side At room A218	Tested/Cleaned	10:31:34 AM	03/24/2023
Smoke Detector	2nd AL side At stairwell 5	Tested/Cleaned	10:19:09 AM	03/24/2023
Smoke Detector	2nd AL side At stairwell 5	Tested/Cleaned	3:31:06 PM	04/06/2023
Smoke Detector	2nd AL side By Legacy Health Services	Tested/Cleaned	9:26:48 AM	04/12/2023
Smoke Detector	2nd AL side By Room A102	Tested/Cleaned	3:39:59 PM	04/06/2023
Smoke Detector	2nd AL side By Room A104	Tested/Cleaned	9:58:25 AM	04/12/2023
Smoke Detector	2nd AL side By Room A105	Tested/Cleaned	3:40:43 PM	04/06/2023
Smoke Detector	2nd AL side By Room A110	Tested/Cleaned	9:57:57 AM	04/12/2023
Smoke Detector	2nd AL side By Staff Lounge near Receiving	Tested/Cleaned	9:27:37 AM	04/12/2023
Smoke Detector	2nd AL side By Trash Room	Tested/Cleaned	9:58:10 AM	04/12/2023
Smoke Detector	2nd AL side By stairwell 4 near Receiving	Tested/Cleaned	9:27:47 AM	04/12/2023
Smoke Detector	2nd AL side By stairwell 4 near Receiving	Tested/Cleaned	9:27:55 AM	04/12/2023
Smoke Detector	2nd AL side In Dining At Kitchen Door	Tested/Cleaned	9:59:49 AM	04/12/2023
Smoke Detector	2nd AL side Room A201 Bedroom	Tested/Cleaned	2:41:34 PM	03/28/2023
Smoke Detector	2nd AL side Room A201 Living Room	Tested/Cleaned	2:41:28 PM	03/28/2023
Smoke Detector	2nd AL side Room A202 Bedroom	Tested/Cleaned	2:40:05 PM	03/28/2023
Smoke Detector	2nd AL side Room A202 Living Room	Tested/Cleaned	2:39:53 PM	03/28/2023
Smoke Detector	2nd AL side Room A203 Living Room	Tested/Cleaned	2:38:49 PM	03/28/2023
Smoke Detector	2nd AL side Room A204 Living Room	Tested/Cleaned	2:37:23 PM	03/28/2023
Smoke Detector	2nd AL side Room A206 Bedroom	Tested/Cleaned	2:34:28 PM	03/28/2023
Smoke Detector	2nd AL side Room A206 Living Room	Tested/Cleaned	2:33:43 PM	03/28/2023
Smoke Detector	2nd AL side Room A207 Living Room	Tested/Cleaned	2:42:34 PM	03/28/2023
Smoke Detector	2nd AL side Room A208 Living Room	Tested/Cleaned	2:42:11 PM	03/28/2023
Smoke Detector	2nd AL side Room A209 Bedroom	Tested/Cleaned	2:44:20 PM	03/28/2023
Smoke Detector	2nd AL side Room A209 Living Room	Tested/Cleaned	2:44:05 PM	03/28/2023
Smoke Detector	2nd AL side Room A210 Bedroom	Tested/Cleaned	2:45:09 PM	03/28/2023
Smoke Detector	2nd AL side Room A210 Living Room	Tested/Cleaned	2:45:19 PM	03/28/2023
Smoke Detector	2nd AL side Room A211 Bedroom	Tested/Cleaned	9:34:06 AM	03/29/2023
Smoke Detector	2nd AL side Room A212 Bedroom	Tested/Cleaned	9:31:18 AM	03/29/2023
Smoke Detector	2nd AL side Room A212 Living Room	Tested/Cleaned	9:30:09 AM	03/29/2023
Smoke Detector	2nd AL side Room A213 Bedroom	Tested/Cleaned	9:30:33 AM	03/29/2023
Smoke Detector	2nd AL side Room A213 Living room	Tested/Cleaned	9:30:17 AM	03/29/2023
Smoke Detector	2nd AL side Room A215 Living Room	Tested/Cleaned	9:32:31 AM	03/29/2023
Smoke Detector	2nd AL side Room A216 Living Room	Tested/Cleaned	9:35:14 AM	03/29/2023
Smoke Detector	2nd AL side Room A217 Living Room	Tested/Cleaned	9:33:06 AM	03/29/2023
Smoke Detector	2nd AL side Room A218 Bedroom	Tested/Cleaned	9:37:47 AM	03/29/2023
Smoke Detector	2nd AL side Room A218 Living Room	Tested/Cleaned	9:36:35 AM	03/29/2023
Smoke Detector	2nd AL side Room A219 Bedroom	Tested/Cleaned	9:35:56 AM	03/29/2023
Smoke Detector	2nd AL side Room A219 Living Room	Tested/Cleaned	9:35:33 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd AL side Soiled Utility Room by room A201	Tested/Cleaned	3:25:55 PM	04/06/2023
Smoke Detector	2nd AL side Trash room	Tested/Cleaned	10:28:12 AM	03/24/2023
Smoke Detector	2nd AL side near cafe	Tested/Cleaned	9:25:47 AM	04/12/2023
Smoke Detector	2nd AL side near front lobby By Room A109 At Fire Doors	Tested/Cleaned	9:58:49 AM	04/12/2023
Smoke Detector	2nd AL side near front lobby By Room A110	Tested/Cleaned	9:57:19 AM	04/12/2023
Smoke Detector	2nd AL side stairwell 6	Tested/Cleaned	10:23:48 AM	03/24/2023
Smoke Detector	2nd Elevator Lobby A	Tested/Cleaned	2:19:03 PM	04/06/2023
Smoke Detector	2nd Elevator Lobby B	Tested/Cleaned	9:33:12 AM	04/12/2023
Smoke Detector	2nd Elevator Lobby C	Tested/Cleaned	2:44:09 PM	04/06/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	1:32:55 PM	03/24/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	1:37:23 PM	03/24/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	9:34:37 AM	04/12/2023
Smoke Detector	2nd Front Lobby	Tested/Cleaned	9:36:08 AM	04/12/2023
Smoke Detector	2nd Front Lobby Above Light	Tested/Cleaned	9:34:46 AM	04/12/2023
Smoke Detector	2nd Front Lobby At Main Desk	Tested/Cleaned	9:35:23 AM	04/12/2023
Smoke Detector	2nd Front Lobby hallway near Conference Room	Tested/Cleaned	1:34:33 PM	03/24/2023
Smoke Detector	2nd Front Lobby hallway near Human Resources	Tested/Cleaned	1:38:18 PM	03/24/2023
Smoke Detector	2nd Front Lobby hallway near Sales	Tested/Cleaned	1:39:23 PM	03/24/2023
Smoke Detector	2nd Front Lobby near Copy Room	Tested/Cleaned	1:33:56 PM	03/24/2023
Smoke Detector	2nd Front Lobby near mailboxes	Tested/Cleaned	9:33:27 AM	04/12/2023
Smoke Detector	2nd IL side At Room 205	Tested/Cleaned	1:44:41 PM	03/24/2023
Smoke Detector	2nd IL side At Room 206	Tested/Cleaned	1:48:31 PM	03/24/2023
Smoke Detector	2nd IL side At Room 210	Tested/Cleaned	1:42:47 PM	03/24/2023
Smoke Detector	2nd IL side At Room 212	Tested/Cleaned	1:42:32 PM	03/24/2023
Smoke Detector	2nd IL side At Room 213	Tested/Cleaned	9:36:56 AM	04/12/2023
Smoke Detector	2nd IL side At Room IL/CA Near front lobby	Tested/Cleaned	9:36:39 AM	04/12/2023
Smoke Detector	2nd IL side By Room 201	Tested/Cleaned	1:47:01 PM	03/24/2023
Smoke Detector	2nd IL side By Room 214	Tested/Cleaned	1:29:29 PM	03/24/2023
Smoke Detector	2nd IL side By Room 218	Tested/Cleaned	9:32:48 AM	04/12/2023
Smoke Detector	2nd IL side By Room 220	Tested/Cleaned	9:32:36 AM	04/12/2023
Smoke Detector	2nd IL side By Room 222	Tested/Cleaned	9:32:25 AM	04/12/2023
Smoke Detector	2nd IL side By Room 223	Tested/Cleaned	9:32:13 AM	04/12/2023
Smoke Detector	2nd IL side By Room 225	Tested/Cleaned	9:32:02 AM	04/12/2023
Smoke Detector	2nd IL side Electrical Room In card table room	Tested/Cleaned	9:43:17 AM	04/12/2023
Smoke Detector	2nd IL side Electrical Room by room 226	Tested/Cleaned	9:28:25 AM	04/12/2023
Smoke Detector	2nd IL side Electrical/Mechanical Room by Salon	Tested/Cleaned	9:40:01 AM	04/12/2023
Smoke Detector	2nd IL side Mechanical Room In Library	Tested/Cleaned	9:46:13 AM	04/12/2023
Smoke Detector	2nd IL side Mechanical Room In card table room	Tested/Cleaned	9:38:17 AM	04/12/2023
Smoke Detector	2nd IL side Room 201 Bedroom	Tested/Cleaned	10:52:26 AM	03/29/2023
Smoke Detector	2nd IL side Room 201 Bedroom	Tested/Cleaned	10:53:11 AM	03/29/2023
Smoke Detector	2nd IL side Room 201 Living Room	Tested/Cleaned	10:52:41 AM	03/29/2023
Smoke Detector	2nd IL side Room 202 Living Room	Tested/Cleaned	10:58:01 AM	03/29/2023
Smoke Detector	2nd IL side Room 203 Bedroom	Tested/Cleaned	10:57:17 AM	03/29/2023
Smoke Detector	2nd IL side Room 203 Living Room	Tested/Cleaned	10:57:08 AM	03/29/2023
Smoke Detector	2nd IL side Room 204 Bedroom	Tested/Cleaned	11:00:20 AM	03/29/2023
Smoke Detector	2nd IL side Room 204 Bedroom	Tested/Cleaned	11:00:32 AM	03/29/2023
Smoke Detector	2nd IL side Room 206 Living Room	Tested/Cleaned	11:01:12 AM	03/29/2023
Smoke Detector	2nd IL side Room 207 Bedroom	Tested/Cleaned	11:07:29 AM	03/29/2023
Smoke Detector	2nd IL side Room 208 Bedroom	Tested/Cleaned	11:02:54 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd IL side Room 208 Living Room	Tested/Cleaned	11:03:23 AM	03/29/2023
Smoke Detector	2nd IL side Room 210 Bedroom	Tested/Cleaned	11:05:38 AM	03/29/2023
Smoke Detector	2nd IL side Room 210 Living Room	Tested/Cleaned	11:05:31 AM	03/29/2023
Smoke Detector	2nd IL side Room 212 Bedroom	Tested/Cleaned	11:08:29 AM	03/29/2023
Smoke Detector	2nd IL side Room 212 Living Room	Tested/Cleaned	11:08:21 AM	03/29/2023
Smoke Detector	2nd IL side Room 214 Bedroom	Tested/Cleaned	12:08:29 PM	03/29/2023
Smoke Detector	2nd IL side Room 214 Living Room	Tested/Cleaned	12:08:07 PM	03/29/2023
Smoke Detector	2nd IL side Room 215 Bedroom	Tested/Cleaned	12:10:50 PM	03/29/2023
Smoke Detector	2nd IL side Room 215 Bedroom	Tested/Cleaned	12:11:58 PM	03/29/2023
Smoke Detector	2nd IL side Room 216 Bed Room	Tested/Cleaned	12:14:51 PM	03/29/2023
Smoke Detector	2nd IL side Room 216 Living Room	Tested/Cleaned	12:14:14 PM	03/29/2023
Smoke Detector	2nd IL side Room 217 Bed Room	Tested/Cleaned	12:19:25 PM	03/29/2023
Smoke Detector	2nd IL side Room 217 Living Room	Tested/Cleaned	12:16:54 PM	03/29/2023
Smoke Detector	2nd IL side Room 218 Bedroom	Tested/Cleaned	12:22:43 PM	03/29/2023
Smoke Detector	2nd IL side Room 218 Bedroom	Tested/Cleaned	12:22:56 PM	03/29/2023
Smoke Detector	2nd IL side Room 219 Bedroom	Tested/Cleaned	12:25:44 PM	03/29/2023
Smoke Detector	2nd IL side Room 219 Living Room	Tested/Cleaned	12:25:31 PM	03/29/2023
Smoke Detector	2nd IL side Room 220 Bed Room	Tested/Cleaned	12:29:23 PM	03/29/2023
Smoke Detector	2nd IL side Room 220 Living Room	Tested/Cleaned	12:29:03 PM	03/29/2023
Smoke Detector	2nd IL side Room 221 Bed Room	Tested/Cleaned	12:42:37 PM	03/29/2023
Smoke Detector	2nd IL side Room 221 Bedroom	Tested/Cleaned	12:39:07 PM	03/29/2023
Smoke Detector	2nd IL side Room 222 Bedroom	Tested/Cleaned	12:32:13 PM	03/29/2023
Smoke Detector	2nd IL side Room 222 Living Room	Tested/Cleaned	12:32:06 PM	03/29/2023
Smoke Detector	2nd IL side Room 224 Bedroom	Tested/Cleaned	12:44:00 PM	03/29/2023
Smoke Detector	2nd IL side Room 224 Living Room	Tested/Cleaned	12:43:50 PM	03/29/2023
Smoke Detector	2nd IL side Room 225 Bedroom	Tested/Cleaned	12:44:05 PM	03/29/2023
Smoke Detector	2nd IL side Room 225 Bedroom	Tested/Cleaned	12:44:18 PM	03/29/2023
Smoke Detector	2nd IL side Room 226 Living Room	Tested/Cleaned	12:45:55 PM	03/29/2023
Smoke Detector	2nd IL side Telephone Room	Tested/Cleaned	9:30:26 AM	04/12/2023
Smoke Detector	2nd IL side Trash Room	Tested/Cleaned	1:48:00 PM	03/24/2023
Smoke Detector	2nd IL side Trash Room by room 214	Tested/Cleaned	1:30:41 PM	03/24/2023
Smoke Detector	2nd conference room mech closet behind front desk	Tested/Cleaned	9:51:23 AM	04/12/2023
Smoke Detector	2nd elevator lobby D	Tested/Cleaned	1:25:45 PM	04/06/2023
Smoke Detector	3rd AL side At Room A302	Tested/Cleaned	2:31:04 PM	03/30/2023
Smoke Detector	3rd AL side At Room A303	Tested/Cleaned	1:58:24 PM	03/24/2023
Smoke Detector	3rd AL side At Room A305	Tested/Cleaned	1:59:30 PM	03/24/2023
Smoke Detector	3rd AL side At Room A307	Tested/Cleaned	2:21:55 PM	03/30/2023
Smoke Detector	3rd AL side At Room A309	Tested/Cleaned	2:22:10 PM	03/30/2023
Smoke Detector	3rd AL side At Room A311	Tested/Cleaned	1:55:43 PM	03/24/2023
Smoke Detector	3rd AL side At Room A315	Tested/Cleaned	1:55:14 PM	03/24/2023
Smoke Detector	3rd AL side At Room A317	Tested/Cleaned	1:54:19 PM	03/24/2023
Smoke Detector	3rd AL side At Room A319	Tested/Cleaned	1:53:57 PM	03/24/2023
Smoke Detector	3rd AL side Room 303 Bedroom	Tested/Cleaned	10:33:54 AM	03/29/2023
Smoke Detector	3rd AL side Room 303 Living Room	Tested/Cleaned	10:34:03 AM	03/29/2023
Smoke Detector	3rd AL side Room A301 Bedroom	Tested/Cleaned	2:26:11 PM	03/28/2023
Smoke Detector	3rd AL side Room A301 Living room	Tested/Cleaned	2:27:11 PM	03/28/2023
Smoke Detector	3rd AL side Room A302 Bedroom	Tested/Cleaned	2:26:58 PM	03/28/2023
Smoke Detector	3rd AL side Room A303 Living room	Tested/Cleaned	2:29:09 PM	03/28/2023
Smoke Detector	3rd AL side Room A304 Living room	Tested/Cleaned	2:29:53 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd AL side Room A305 Bedroom	Tested/Cleaned	2:32:07 PM	03/28/2023
Smoke Detector	3rd AL side Room A305 Living room	Tested/Cleaned	2:31:21 PM	03/28/2023
Smoke Detector	3rd AL side Room A306 Bedroom	Tested/Cleaned	2:30:51 PM	03/28/2023
Smoke Detector	3rd AL side Room A306 Living Room	Tested/Cleaned	2:32:00 PM	03/28/2023
Smoke Detector	3rd AL side Room A307 Living Room	Tested/Cleaned	2:23:54 PM	03/28/2023
Smoke Detector	3rd AL side Room A308 Living Room	Tested/Cleaned	2:24:53 PM	03/28/2023
Smoke Detector	3rd AL side Room A309 Bedroom	Tested/Cleaned	2:22:47 PM	03/28/2023
Smoke Detector	3rd AL side Room A310 Bedroom	Tested/Cleaned	2:21:41 PM	03/28/2023
Smoke Detector	3rd AL side Room A310 Living Room	Tested/Cleaned	2:24:18 PM	03/28/2023
Smoke Detector	3rd AL side Room A313 Bedroom	Tested/Cleaned	2:18:03 PM	03/28/2023
Smoke Detector	3rd AL side Room A313 Living Room	Tested/Cleaned	2:19:18 PM	03/28/2023
Smoke Detector	3rd AL side Room A314 Living Room	Tested/Cleaned	2:16:41 PM	03/28/2023
Smoke Detector	3rd AL side Room A315 Living Room	Tested/Cleaned	2:15:55 PM	03/28/2023
Smoke Detector	3rd AL side Room A316 Living Room	Tested/Cleaned	2:12:19 PM	03/28/2023
Smoke Detector	3rd AL side Room A317 Living Room	Tested/Cleaned	2:14:05 PM	03/28/2023
Smoke Detector	3rd AL side Room A318 Bedroom	Tested/Cleaned	2:11:06 PM	03/28/2023
Smoke Detector	3rd AL side Room A318 Living Room	Tested/Cleaned	2:10:24 PM	03/28/2023
Smoke Detector	3rd AL side Room A319 Bedroom	Tested/Cleaned	2:12:30 PM	03/28/2023
Smoke Detector	3rd AL side Room A319 Living Room	Tested/Cleaned	2:11:39 PM	03/28/2023
Smoke Detector	3rd AL side Soiled Utility Room by A302	Tested/Cleaned	3:24:21 PM	04/06/2023
Smoke Detector	3rd AL side Stairwell 5	Tested/Cleaned	2:27:55 PM	03/30/2023
Smoke Detector	3rd AL side Stairwell 6	Tested/Cleaned	2:26:17 PM	03/30/2023
Smoke Detector	3rd AL side Trash room near room A303	Tested/Cleaned	2:01:23 PM	03/24/2023
Smoke Detector	3rd AL side by stairwell 5 At Room A309	Tested/Cleaned	2:22:45 PM	03/30/2023
Smoke Detector	3rd Electrical Room	Tested/Cleaned	10:33:42 AM	03/24/2023
Smoke Detector	3rd Elevator Lobby A	Tested/Cleaned	2:16:03 PM	04/06/2023
Smoke Detector	3rd Elevator Lobby B	Tested/Cleaned	1:45:59 PM	04/06/2023
Smoke Detector	3rd Elevator Lobby C	Tested/Cleaned	2:39:43 PM	04/06/2023
Smoke Detector	3rd FACP/Telephone Room	Tested/Cleaned	9:43:55 AM	03/24/2023
Smoke Detector	3rd IL Side Electrical Toom At Room 433	Tested/Cleaned	2:18:24 PM	03/30/2023
Smoke Detector	3rd IL Side Telephone Room At Room 433	Tested/Cleaned	2:17:00 PM	03/30/2023
Smoke Detector	3rd IL side At FACP room	Tested/Cleaned	9:49:33 AM	03/24/2023
Smoke Detector	3rd IL side At Room 301	Tested/Cleaned	10:07:30 AM	03/24/2023
Smoke Detector	3rd IL side At Room 305	Tested/Cleaned	10:06:31 AM	03/24/2023
Smoke Detector	3rd IL side At Room 307	Tested/Cleaned	10:04:27 AM	03/24/2023
Smoke Detector	3rd IL side At Room 309	Tested/Cleaned	10:04:16 AM	03/24/2023
Smoke Detector	3rd IL side At Room 311	Tested/Cleaned	10:04:03 AM	03/24/2023
Smoke Detector	3rd IL side At Room 313	Tested/Cleaned	10:02:33 AM	03/24/2023
Smoke Detector	3rd IL side At Room 316	Tested/Cleaned	9:57:17 AM	03/24/2023
Smoke Detector	3rd IL side At Room 317	Tested/Cleaned	9:55:47 AM	03/24/2023
Smoke Detector	3rd IL side At Room 320	Tested/Cleaned	9:55:23 AM	03/24/2023
Smoke Detector	3rd IL side At room 323	Tested/Cleaned	9:52:58 AM	03/24/2023
Smoke Detector	3rd IL side At room 324	Tested/Cleaned	9:52:06 AM	03/24/2023
Smoke Detector	3rd IL side At room 326	Tested/Cleaned	9:51:26 AM	03/24/2023
Smoke Detector	3rd IL side At room 329	Tested/Cleaned	9:50:35 AM	03/24/2023
Smoke Detector	3rd IL side At room 331	Tested/Cleaned	9:50:18 AM	03/24/2023
Smoke Detector	3rd IL side At stairwell 4	Tested/Cleaned	3:32:52 PM	04/06/2023
Smoke Detector	3rd IL side Electrical Room by room 304	Tested/Cleaned	1:02:54 PM	03/30/2023
Smoke Detector	3rd IL side Room 301 Bedroom	Tested/Cleaned	10:25:09 AM	03/29/2023
Smoke Detector	3rd IL side Room 301 Bedroom	Tested/Cleaned	10:25:19 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd IL side Room 301 Living Room	Tested/Cleaned	10:25:01 AM	03/29/2023
Smoke Detector	3rd IL side Room 302 Bedroom	Tested/Cleaned	10:29:00 AM	03/29/2023
Smoke Detector	3rd IL side Room 302 Bedroom	Tested/Cleaned	10:29:10 AM	03/29/2023
Smoke Detector	3rd IL side Room 302 Living Room	Tested/Cleaned	10:28:43 AM	03/29/2023
Smoke Detector	3rd IL side Room 304 Bedroom	Tested/Cleaned	10:20:57 AM	03/29/2023
Smoke Detector	3rd IL side Room 304 Bedroom	Tested/Cleaned	10:21:14 AM	03/29/2023
Smoke Detector	3rd IL side Room 304 Living Room	Tested/Cleaned	10:20:36 AM	03/29/2023
Smoke Detector	3rd IL side Room 305 Bedroom	Tested/Cleaned	10:35:15 AM	03/29/2023
Smoke Detector	3rd IL side Room 305 Living Room	Tested/Cleaned	10:35:04 AM	03/29/2023
Smoke Detector	3rd IL side Room 306 Living Room	Tested/Cleaned	10:18:53 AM	03/29/2023
Smoke Detector	3rd IL side Room 307 Bedroom	Tested/Cleaned	10:30:16 AM	03/29/2023
Smoke Detector	3rd IL side Room 307 Bedroom	Tested/Cleaned	10:34:26 AM	03/29/2023
Smoke Detector	3rd IL side Room 307 Living Room	Tested/Cleaned	10:30:07 AM	03/29/2023
Smoke Detector	3rd IL side Room 308 Bedroom	Tested/Cleaned	10:16:25 AM	03/29/2023
Smoke Detector	3rd IL side Room 308 Living Room	Tested/Cleaned	10:16:20 AM	03/29/2023
Smoke Detector	3rd IL side Room 309 Bedroom	Tested/Cleaned	10:28:29 AM	03/29/2023
Smoke Detector	3rd IL side Room 309 Living Room	Tested/Cleaned	10:27:51 AM	03/29/2023
Smoke Detector	3rd IL side Room 310 Bedroom	Tested/Cleaned	10:13:36 AM	03/29/2023
Smoke Detector	3rd IL side Room 310 Living Room	Tested/Cleaned	10:13:27 AM	03/29/2023
Smoke Detector	3rd IL side Room 311 Bedroom	Tested/Cleaned	10:25:55 AM	03/29/2023
Smoke Detector	3rd IL side Room 311 Living Room	Tested/Cleaned	10:25:49 AM	03/29/2023
Smoke Detector	3rd IL side Room 312 Bedroom	Tested/Cleaned	10:10:55 AM	03/29/2023
Smoke Detector	3rd IL side Room 312 Living Room	Tested/Cleaned	10:10:50 AM	03/29/2023
Smoke Detector	3rd IL side Room 320 Bedroom	Tested/Cleaned	9:57:45 AM	03/29/2023
Smoke Detector	3rd IL side Room 320 Bedroom	Tested/Cleaned	9:59:48 AM	03/29/2023
Smoke Detector	3rd IL side Room 320 Living Room	Tested/Cleaned	9:57:36 AM	03/29/2023
Smoke Detector	3rd IL side Room 326 Living Room	Tested/Cleaned	9:48:19 AM	03/29/2023
Smoke Detector	3rd IL side Room A313 Bedroom	Tested/Cleaned	10:23:53 AM	03/29/2023
Smoke Detector	3rd IL side Room A313 Living Room	Tested/Cleaned	10:23:16 AM	03/29/2023
Smoke Detector	3rd IL side Room A314 Bedroom	Tested/Cleaned	10:07:13 AM	03/29/2023
Smoke Detector	3rd IL side Room A314 Bedroom	Tested/Cleaned	10:07:25 AM	03/29/2023
Smoke Detector	3rd IL side Room A314 Living Room	Tested/Cleaned	10:07:01 AM	03/29/2023
Smoke Detector	3rd IL side Room A315 Bedroom	Tested/Cleaned	10:07:31 AM	03/29/2023
Smoke Detector	3rd IL side Room A315 Bedroom	Tested/Cleaned	10:07:43 AM	03/29/2023
Smoke Detector	3rd IL side Room A315 Living Room	Tested/Cleaned	10:08:30 AM	03/29/2023
Smoke Detector	3rd IL side Room A316 Bedroom	Tested/Cleaned	10:05:04 AM	03/29/2023
Smoke Detector	3rd IL side Room A316 Living Room	Tested/Cleaned	10:06:20 AM	03/29/2023
Smoke Detector	3rd IL side Room A317 Bedroom	Tested/Cleaned	10:02:50 AM	03/29/2023
Smoke Detector	3rd IL side Room A317 Living Room	Tested/Cleaned	10:02:40 AM	03/29/2023
Smoke Detector	3rd IL side Room A318 Bedroom	Tested/Cleaned	10:01:18 AM	03/29/2023
Smoke Detector	3rd IL side Room A318 Living Room	Tested/Cleaned	10:01:05 AM	03/29/2023
Smoke Detector	3rd IL side Room A319 Bedroom	Tested/Cleaned	10:04:50 AM	03/29/2023
Smoke Detector	3rd IL side Room A319 Bedroom	Tested/Cleaned	10:05:09 AM	03/29/2023
Smoke Detector	3rd IL side Room A319 Living Room	Tested/Cleaned	10:05:00 AM	03/29/2023
Smoke Detector	3rd IL side Room A321 Bedroom	Tested/Cleaned	9:59:14 AM	03/29/2023
Smoke Detector	3rd IL side Room A321 Living Room	Tested/Cleaned	9:59:54 AM	03/29/2023
Smoke Detector	3rd IL side Room A322 Bedroom	Tested/Cleaned	9:54:11 AM	03/29/2023
Smoke Detector	3rd IL side Room A322 Living Room	Tested/Cleaned	9:54:05 AM	03/29/2023
Smoke Detector	3rd IL side Room A323 Bedroom	Tested/Cleaned	9:57:00 AM	03/29/2023
Smoke Detector	3rd IL side Room A323 Living Room	Tested/Cleaned	9:57:33 AM	03/29/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd IL side Room A324 Bedroom	Tested/Cleaned	9:51:50 AM	03/29/2023
Smoke Detector	3rd IL side Room A324 Living Room	Tested/Cleaned	9:51:44 AM	03/29/2023
Smoke Detector	3rd IL side Room A325 Bedroom	Tested/Cleaned	9:54:28 AM	03/29/2023
Smoke Detector	3rd IL side Room A325 Living Room	Tested/Cleaned	9:54:36 AM	03/29/2023
Smoke Detector	3rd IL side Room A326 Bedroom	Tested/Cleaned	9:48:26 AM	03/29/2023
Smoke Detector	3rd IL side Room A327 Bedroom	Tested/Cleaned	9:51:16 AM	03/29/2023
Smoke Detector	3rd IL side Room A327 Living Room	Tested/Cleaned	9:51:08 AM	03/29/2023
Smoke Detector	3rd IL side Room A328 Bedroom	Tested/Cleaned	9:47:46 AM	03/29/2023
Smoke Detector	3rd IL side Room A328 Living Room	Tested/Cleaned	9:47:29 AM	03/29/2023
Smoke Detector	3rd IL side Room A329 Bedroom	Tested/Cleaned	9:47:39 AM	03/29/2023
Smoke Detector	3rd IL side Room A329 Bedroom	Tested/Cleaned	9:47:53 AM	03/29/2023
Smoke Detector	3rd IL side Room A330 Living Room	Tested/Cleaned	9:43:37 AM	03/29/2023
Smoke Detector	3rd IL side Room A331 Bedroom	Tested/Cleaned	9:44:35 AM	03/29/2023
Smoke Detector	3rd IL side Room A331 Living Room	Tested/Cleaned	9:44:29 AM	03/29/2023
Smoke Detector	3rd IL side Room A332 Bedroom	Tested/Cleaned	9:39:25 AM	03/29/2023
Smoke Detector	3rd IL side Room A332 Bedroom	Tested/Cleaned	9:40:20 AM	03/29/2023
Smoke Detector	3rd IL side Room A332 Living Room	Tested/Cleaned	9:40:01 AM	03/29/2023
Smoke Detector	3rd IL side Trash Room At room 313	Tested/Cleaned	10:03:10 AM	03/24/2023
Smoke Detector	3rd IL side Trash Room At room 321	Tested/Cleaned	3:20:50 PM	04/06/2023
Smoke Detector	3rd elevator lobby D	Tested/Cleaned	1:22:45 PM	04/06/2023
Smoke Detector	4th Elevator Lobby A	Tested/Cleaned	2:13:55 PM	04/06/2023
Smoke Detector	4th Elevator Lobby B	Tested/Cleaned	1:41:34 PM	04/06/2023
Smoke Detector	4th IL Side At Stairwell 4	Tested/Cleaned	1:52:42 PM	03/24/2023
Smoke Detector	4th IL side By Room 401	Tested/Cleaned	2:17:45 PM	03/24/2023
Smoke Detector	4th IL side By Room 405	Tested/Cleaned	2:16:32 PM	03/24/2023
Smoke Detector	4th IL side By Room 406	Tested/Cleaned	2:15:25 PM	03/24/2023
Smoke Detector	4th IL side By Room 409	Tested/Cleaned	2:15:05 PM	03/24/2023
Smoke Detector	4th IL side By Room 411	Tested/Cleaned	2:13:16 PM	03/24/2023
Smoke Detector	4th IL side By Room 413	Tested/Cleaned	2:12:44 PM	03/24/2023
Smoke Detector	4th IL side By Room 415	Tested/Cleaned	2:12:24 PM	03/24/2023
Smoke Detector	4th IL side By Room 417	Tested/Cleaned	2:10:30 PM	03/24/2023
Smoke Detector	4th IL side By Room 420	Tested/Cleaned	2:09:23 PM	03/24/2023
Smoke Detector	4th IL side By Room 421	Tested/Cleaned	2:12:52 PM	03/30/2023
Smoke Detector	4th IL side By Room 424	Tested/Cleaned	2:06:44 PM	03/24/2023
Smoke Detector	4th IL side By Room 426	Tested/Cleaned	2:05:27 PM	03/24/2023
Smoke Detector	4th IL side By Room 428	Tested/Cleaned	2:04:19 PM	03/24/2023
Smoke Detector	4th IL side By Room 431	Tested/Cleaned	2:03:21 PM	03/24/2023
Smoke Detector	4th IL side By Room 432	Tested/Cleaned	2:03:11 PM	03/24/2023
Smoke Detector	4th IL side Electrical Room by room 421	Tested/Cleaned	2:08:06 PM	03/24/2023
Smoke Detector	4th IL side Electrical room by room 404	Tested/Cleaned	2:06:00 PM	03/30/2023
Smoke Detector	4th IL side Room 414 Bedroom	Tested/Cleaned	1:35:46 PM	03/28/2023
Smoke Detector	4th IL side Room 414 Bedroom	Tested/Cleaned	1:36:00 PM	03/28/2023
Smoke Detector	4th IL side Room 414 Living Room	Tested/Cleaned	1:35:36 PM	03/28/2023
Smoke Detector	4th IL side Room 415 Bedroom	Tested/Cleaned	1:37:33 PM	03/28/2023
Smoke Detector	4th IL side Room 415 Bedroom	Tested/Cleaned	1:39:15 PM	03/28/2023
Smoke Detector	4th IL side Room 415 Living Room	Tested/Cleaned	1:38:27 PM	03/28/2023
Smoke Detector	4th IL side Room 416 Bedroom	Tested/Cleaned	1:37:00 PM	03/28/2023
Smoke Detector	4th IL side Room 416 Living Room	Tested/Cleaned	1:37:47 PM	03/28/2023
Smoke Detector	4th IL side Room 417 Bedroom	Tested/Cleaned	1:42:29 PM	03/28/2023
Smoke Detector	4th IL side Room 417 Living Room	Tested/Cleaned	1:40:34 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	4th IL side Room 418 Bedroom	Tested/Cleaned	1:45:16 PM	03/28/2023
Smoke Detector	4th IL side Room 418 Living Room	Tested/Cleaned	1:45:57 PM	03/28/2023
Smoke Detector	4th IL side Room 419 Bedroom	Tested/Cleaned	1:40:46 PM	03/28/2023
Smoke Detector	4th IL side Room 419 Bedroom	Tested/Cleaned	1:41:33 PM	03/28/2023
Smoke Detector	4th IL side Room 419 Living Room	Tested/Cleaned	1:39:59 PM	03/28/2023
Smoke Detector	4th IL side Room 420 Bedroom	Tested/Cleaned	1:44:20 PM	03/28/2023
Smoke Detector	4th IL side Room 420 Bedroom	Tested/Cleaned	1:44:35 PM	03/28/2023
Smoke Detector	4th IL side Room 420 Living Room	Tested/Cleaned	1:44:04 PM	03/28/2023
Smoke Detector	4th IL side Room 421 Bedroom	Tested/Cleaned	1:49:00 PM	03/28/2023
Smoke Detector	4th IL side Room 421 Living Room	Tested/Cleaned	1:50:51 PM	03/28/2023
Smoke Detector	4th IL side Room 422 Bedroom	Tested/Cleaned	1:49:40 PM	03/28/2023
Smoke Detector	4th IL side Room 422 Living Room	Tested/Cleaned	1:48:54 PM	03/28/2023
Smoke Detector	4th IL side Room 423 Bedroom	Tested/Cleaned	1:51:36 PM	03/28/2023
Smoke Detector	4th IL side Room 423 Living Room	Tested/Cleaned	1:50:57 PM	03/28/2023
Smoke Detector	4th IL side Room 424 Bedroom	Tested/Cleaned	1:51:54 PM	03/28/2023
Smoke Detector	4th IL side Room 424 Living Room	Tested/Cleaned	1:52:08 PM	03/28/2023
Smoke Detector	4th IL side Room 425 Bedroom	Tested/Cleaned	1:53:55 PM	03/28/2023
Smoke Detector	4th IL side Room 425 Living Room	Tested/Cleaned	1:53:17 PM	03/28/2023
Smoke Detector	4th IL side Room 426 Bedroom	Tested/Cleaned	1:55:51 PM	03/28/2023
Smoke Detector	4th IL side Room 426 Living room	Tested/Cleaned	1:55:03 PM	03/28/2023
Smoke Detector	4th IL side Room 427 Bedroom	Tested/Cleaned	1:54:09 PM	03/28/2023
Smoke Detector	4th IL side Room 427 Living Room	Tested/Cleaned	1:54:51 PM	03/28/2023
Smoke Detector	4th IL side Room 428 Bedroom	Tested/Cleaned	1:59:24 PM	03/28/2023
Smoke Detector	4th IL side Room 428 Living Room	Tested/Cleaned	1:58:39 PM	03/28/2023
Smoke Detector	4th IL side Room 429 Bedroom	Tested/Cleaned	1:56:13 PM	03/28/2023
Smoke Detector	4th IL side Room 429 Bedroom	Tested/Cleaned	1:57:11 PM	03/28/2023
Smoke Detector	4th IL side Room 429 Living Room	Tested/Cleaned	1:56:02 PM	03/28/2023
Smoke Detector	4th IL side Room 430 Living Room	Tested/Cleaned	2:01:35 PM	03/28/2023
Smoke Detector	4th IL side Room 432 Bedroom	Tested/Cleaned	2:04:12 PM	03/28/2023
Smoke Detector	4th IL side Room 432 Bedroom	Tested/Cleaned	2:05:16 PM	03/28/2023
Smoke Detector	4th IL side Room 432 Living Room	Tested/Cleaned	2:04:55 PM	03/28/2023
Smoke Detector	4th IL side Room 433 Bedroom	Tested/Cleaned	2:08:43 PM	03/28/2023
Smoke Detector	4th IL side Room 433 Living Room	Tested/Cleaned	2:07:23 PM	03/28/2023
Smoke Detector	4th IL side Trash Room by room 413	Tested/Cleaned	2:10:35 PM	03/30/2023
Smoke Detector	4th IL side room 401 Bedroom	Tested/Cleaned	1:18:52 PM	03/28/2023
Smoke Detector	4th IL side room 401 Bedroom	Tested/Cleaned	1:19:39 PM	03/28/2023
Smoke Detector	4th IL side room 401 Living room	Tested/Cleaned	1:17:56 PM	03/28/2023
Smoke Detector	4th IL side room 402 Bedroom	Tested/Cleaned	1:21:09 PM	03/28/2023
Smoke Detector	4th IL side room 402 Bedroom	Tested/Cleaned	1:21:30 PM	03/28/2023
Smoke Detector	4th IL side room 402 Living room	Tested/Cleaned	1:19:42 PM	03/28/2023
Smoke Detector	4th IL side room 403 Bedroom	Tested/Cleaned	1:20:42 PM	03/28/2023
Smoke Detector	4th IL side room 403 Living room	Tested/Cleaned	1:20:27 PM	03/28/2023
Smoke Detector	4th IL side room 404 Bedroom	Tested/Cleaned	1:23:28 PM	03/28/2023
Smoke Detector	4th IL side room 404 Bedroom	Tested/Cleaned	1:23:38 PM	03/28/2023
Smoke Detector	4th IL side room 404 Living room	Tested/Cleaned	1:23:11 PM	03/28/2023
Smoke Detector	4th IL side room 405 Bedroom	Tested/Cleaned	1:23:33 PM	03/28/2023
Smoke Detector	4th IL side room 405 Living room	Tested/Cleaned	1:23:12 PM	03/28/2023
Smoke Detector	4th IL side room 406 Living room	Tested/Cleaned	1:27:00 PM	03/28/2023
Smoke Detector	4th IL side room 407 Bedroom	Tested/Cleaned	1:26:20 PM	03/28/2023
Smoke Detector	4th IL side room 407 Bedroom	Tested/Cleaned	1:27:07 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	4th IL side room 407 Living room	Tested/Cleaned	1:26:29 PM	03/28/2023
Smoke Detector	4th IL side room 408 Bedroom	Tested/Cleaned	1:27:40 PM	03/28/2023
Smoke Detector	4th IL side room 408 Living room	Tested/Cleaned	1:31:00 PM	03/28/2023
Smoke Detector	4th IL side room 409 Bedroom	Tested/Cleaned	1:29:27 PM	03/28/2023
Smoke Detector	4th IL side room 409 Living room	Tested/Cleaned	1:28:41 PM	03/28/2023
Smoke Detector	4th IL side room 410 Bedroom	Tested/Cleaned	1:30:06 PM	03/28/2023
Smoke Detector	4th IL side room 410 Living room	Tested/Cleaned	1:29:30 PM	03/28/2023
Smoke Detector	4th IL side room 411 Bedroom	Tested/Cleaned	1:34:25 PM	03/28/2023
Smoke Detector	4th IL side room 411 Living room	Tested/Cleaned	1:32:34 PM	03/28/2023
Smoke Detector	4th IL side room 412 Bedroom	Tested/Cleaned	1:32:40 PM	03/28/2023
Smoke Detector	4th IL side room 412 Living room	Tested/Cleaned	1:33:15 PM	03/28/2023
Smoke Detector	4th IL side room 413 Bedroom	Tested/Cleaned	1:36:00 PM	03/28/2023
Smoke Detector	4th IL side room 413 Living room	Tested/Cleaned	1:35:25 PM	03/28/2023
Smoke Detector	4th elevator lobby D	Tested/Cleaned	1:17:36 PM	04/06/2023
Smoke Detector	5th	Tested/Cleaned	11:33:25 AM	03/24/2023
Smoke Detector	5th Elevator Lobby A	Tested/Cleaned	2:07:40 PM	04/06/2023
Smoke Detector	5th Elevator Lobby B	Tested/Cleaned	1:37:24 PM	04/06/2023
Smoke Detector	5th IL side Electrical Room by room 513	Tested/Cleaned	11:07:07 AM	03/24/2023
Smoke Detector	5th IL side Electrical Room by room 521	Tested/Cleaned	11:17:13 AM	03/24/2023
Smoke Detector	5th IL side Mechanical Room by room 504	Tested/Cleaned	3:15:48 PM	04/06/2023
Smoke Detector	5th IL side Mechanical Room by room 533	Tested/Cleaned	11:25:40 AM	03/24/2023
Smoke Detector	5th IL side Room 501 Bedroom	Tested/Cleaned	1:12:46 PM	03/28/2023
Smoke Detector	5th IL side Room 501 Bedroom	Tested/Cleaned	1:14:08 PM	03/28/2023
Smoke Detector	5th IL side Room 501 Living Room	Tested/Cleaned	1:12:35 PM	03/28/2023
Smoke Detector	5th IL side Room 502 Bedroom	Tested/Cleaned	1:15:25 PM	03/28/2023
Smoke Detector	5th IL side Room 502 Living Room	Tested/Cleaned	1:13:40 PM	03/28/2023
Smoke Detector	5th IL side Room 503 Bedroom	Tested/Cleaned	1:11:14 PM	03/28/2023
Smoke Detector	5th IL side Room 503 Living Room	Tested/Cleaned	1:12:31 PM	03/28/2023
Smoke Detector	5th IL side Room 504 Bedroom	Tested/Cleaned	1:11:24 PM	03/28/2023
Smoke Detector	5th IL side Room 504 Bedroom	Tested/Cleaned	1:11:39 PM	03/28/2023
Smoke Detector	5th IL side Room 504 Living Room	Tested/Cleaned	1:11:53 PM	03/28/2023
Smoke Detector	5th IL side Room 505 Bedroom	Tested/Cleaned	1:09:49 PM	03/28/2023
Smoke Detector	5th IL side Room 505 Living Room	Tested/Cleaned	1:09:42 PM	03/28/2023
Smoke Detector	5th IL side Room 506 Living Room	Tested/Cleaned	1:07:50 PM	03/28/2023
Smoke Detector	5th IL side Room 507 Bedroom	Tested/Cleaned	1:08:09 PM	03/28/2023
Smoke Detector	5th IL side Room 507 Bedroom	Tested/Cleaned	1:09:57 PM	03/28/2023
Smoke Detector	5th IL side Room 507 Living Room	Tested/Cleaned	1:08:47 PM	03/28/2023
Smoke Detector	5th IL side Room 508 Bedroom	Tested/Cleaned	1:07:02 PM	03/28/2023
Smoke Detector	5th IL side Room 508 Living Room	Tested/Cleaned	1:06:27 PM	03/28/2023
Smoke Detector	5th IL side Room 509 Bedroom	Tested/Cleaned	1:04:34 PM	03/28/2023
Smoke Detector	5th IL side Room 509 Living Room	Tested/Cleaned	1:05:19 PM	03/28/2023
Smoke Detector	5th IL side Room 510 Bedroom	Tested/Cleaned	1:03:03 PM	03/28/2023
Smoke Detector	5th IL side Room 510 Living Room	Tested/Cleaned	1:03:31 PM	03/28/2023
Smoke Detector	5th IL side Room 511 Bedroom	Tested/Cleaned	1:03:12 PM	03/28/2023
Smoke Detector	5th IL side Room 511 Living Room	Tested/Cleaned	1:02:29 PM	03/28/2023
Smoke Detector	5th IL side Room 512 Bedroom	Tested/Cleaned	1:02:20 PM	03/28/2023
Smoke Detector	5th IL side Room 512 Living Room	Tested/Cleaned	1:02:11 PM	03/28/2023
Smoke Detector	5th IL side Room 513 Bedroom	Tested/Cleaned	1:00:51 PM	03/28/2023
Smoke Detector	5th IL side Room 513 Living Room	Tested/Cleaned	12:59:52 PM	03/28/2023
Smoke Detector	5th IL side Room 514 Bedroom	Tested/Cleaned	12:59:11 PM	03/28/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	5th IL side Room 514 Bedroom	Tested/Cleaned	12:59:45 PM	03/28/2023
Smoke Detector	5th IL side Room 514 Living Room	Tested/Cleaned	12:58:34 PM	03/28/2023
Smoke Detector	5th IL side Room 515 Bedroom	Tested/Cleaned	12:56:58 PM	03/28/2023
Smoke Detector	5th IL side Room 515 Bedroom	Tested/Cleaned	12:57:18 PM	03/28/2023
Smoke Detector	5th IL side Room 515 Living Room	Tested/Cleaned	12:56:40 PM	03/28/2023
Smoke Detector	5th IL side Room 516 Bedroom	Tested/Cleaned	12:58:58 PM	03/28/2023
Smoke Detector	5th IL side Room 516 Living Room	Tested/Cleaned	12:58:20 PM	03/28/2023
Smoke Detector	5th IL side Room 517 Bedroom	Tested/Cleaned	12:53:57 PM	03/28/2023
Smoke Detector	5th IL side Room 517 Living Room	Tested/Cleaned	12:52:58 PM	03/28/2023
Smoke Detector	5th IL side Room 518 Bedroom	Tested/Cleaned	12:57:00 PM	03/28/2023
Smoke Detector	5th IL side Room 518 Living Room	Tested/Cleaned	12:55:52 PM	03/28/2023
Smoke Detector	5th IL side Room 519 Bedroom	Tested/Cleaned	12:54:02 PM	03/28/2023
Smoke Detector	5th IL side Room 519 Bedroom	Tested/Cleaned	12:54:15 PM	03/28/2023
Smoke Detector	5th IL side Room 519 Living Room	Tested/Cleaned	12:55:26 PM	03/28/2023
Smoke Detector	5th IL side Room 520 Bedroom	Tested/Cleaned	12:52:18 PM	03/28/2023
Smoke Detector	5th IL side Room 520 Bedroom	Tested/Cleaned	12:52:44 PM	03/28/2023
Smoke Detector	5th IL side Room 520 Living Room	Tested/Cleaned	12:51:38 PM	03/28/2023
Smoke Detector	5th IL side Room 521 Bedroom	Tested/Cleaned	12:49:32 PM	03/28/2023
Smoke Detector	5th IL side Room 521 Living Room	Tested/Cleaned	12:49:22 PM	03/28/2023
Smoke Detector	5th IL side Room 522 Bedroom	Tested/Cleaned	12:49:34 PM	03/28/2023
Smoke Detector	5th IL side Room 522 Living Room	Tested/Cleaned	12:49:17 PM	03/28/2023
Smoke Detector	5th IL side Room 523 Bedroom	Tested/Cleaned	12:46:34 PM	03/28/2023
Smoke Detector	5th IL side Room 523 Living Room	Tested/Cleaned	12:46:26 PM	03/28/2023
Smoke Detector	5th IL side Room 524 Bedroom	Tested/Cleaned	12:45:57 PM	03/28/2023
Smoke Detector	5th IL side Room 524 Living Room	Tested/Cleaned	12:45:50 PM	03/28/2023
Smoke Detector	5th IL side Room 525 Bedroom	Tested/Cleaned	12:46:15 PM	03/28/2023
Smoke Detector	5th IL side Room 525 Living Room	Tested/Cleaned	12:46:50 PM	03/28/2023
Smoke Detector	5th IL side Room 526 Bedroom	Tested/Cleaned	12:43:13 PM	03/28/2023
Smoke Detector	5th IL side Room 526 Living Room	Tested/Cleaned	12:42:55 PM	03/28/2023
Smoke Detector	5th IL side Room 527 Bedroom	Tested/Cleaned	12:45:01 PM	03/28/2023
Smoke Detector	5th IL side Room 527 Living Room	Tested/Cleaned	12:44:53 PM	03/28/2023
Smoke Detector	5th IL side Room 528 Bedroom	Tested/Cleaned	12:40:59 PM	03/28/2023
Smoke Detector	5th IL side Room 528 Living Room	Tested/Cleaned	12:40:21 PM	03/28/2023
Smoke Detector	5th IL side Room 529 Bedroom	Tested/Cleaned	12:42:38 PM	03/28/2023
Smoke Detector	5th IL side Room 529 Bedroom	Tested/Cleaned	12:43:08 PM	03/28/2023
Smoke Detector	5th IL side Room 529 Living Room	Tested/Cleaned	12:42:29 PM	03/28/2023
Smoke Detector	5th IL side Room 530 Living Room	Tested/Cleaned	12:38:31 PM	03/28/2023
Smoke Detector	5th IL side Room 531 Bedroom	Tested/Cleaned	12:43:56 PM	03/28/2023
Smoke Detector	5th IL side Room 531 Living Room	Tested/Cleaned	12:43:49 PM	03/28/2023
Smoke Detector	5th IL side Room 532 Bedroom	Tested/Cleaned	12:37:00 PM	03/28/2023
Smoke Detector	5th IL side Room 532 Living Room	Tested/Cleaned	12:38:04 PM	03/28/2023
Smoke Detector	5th IL side Room 533 Bedroom	Tested/Cleaned	12:36:22 PM	03/28/2023
Smoke Detector	5th IL side Room 533 Living Room	Tested/Cleaned	12:35:30 PM	03/28/2023
Smoke Detector	5th IL side Room 535 Bedroom	Tested/Cleaned	12:33:45 PM	03/28/2023
Smoke Detector	5th IL side Room 535 Living Room	Tested/Cleaned	12:33:34 PM	03/28/2023
Smoke Detector	5th IL side hallway by room 501	Tested/Cleaned	11:11:09 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 504	Tested/Cleaned	11:13:03 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 505	Tested/Cleaned	11:13:08 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 508	Tested/Cleaned	11:13:19 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 510	Tested/Cleaned	11:13:44 AM	03/24/2023

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	5th IL side hallway by room 513	Tested/Cleaned	11:13:55 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 516	Tested/Cleaned	11:14:17 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 517	Tested/Cleaned	11:14:33 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 520	Tested/Cleaned	11:14:44 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 521	Tested/Cleaned	11:14:56 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 524	Tested/Cleaned	11:19:20 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 526	Tested/Cleaned	11:19:41 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 528	Tested/Cleaned	11:21:54 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 530	Tested/Cleaned	11:22:45 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 533	Tested/Cleaned	11:24:40 AM	03/24/2023
Smoke Detector	5th IL side hallway by room 534	Tested/Cleaned	11:27:33 AM	03/24/2023
Smoke Detector	5th Top of stairwell 3 IL side	Tested/Cleaned	11:31:05 AM	03/24/2023
Smoke Detector	5th Top of stairwell 4 IL side	Tested/Cleaned	11:29:52 AM	03/24/2023
Smoke Detector	5th elevator lobby D	Tested/Cleaned	12:47:28 PM	04/06/2023
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	3rd Telephone/FACP	Tested	11:37:27 AM	04/12/2023
Communicator	2nd IL side Telephone Room by room 226	Tested	11:28:22 AM	04/12/2023
Indicating				
Horn/Strobe	2nd Total (42)	Tested	9:31:08 PM	03/30/2023
Horn/Strobe	3rd Total (28)	Tested	9:30:03 PM	03/30/2023
Horn/Strobe	4th Total (10)	Tested	3:18:57 PM	03/30/2023

Service Summary

Generated by: BuildingReports.com

Building: Magnolia Glen		
<i>The Service Summary section provides an overview of the services performed in this report.</i>		
Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Communicator	Tested	1
Horn/Strobe	Tested	3
Total		5
<i>Passed</i>		
Annunciator	Tested	2
Battery	Tested	9
Control Panel	Tested	1
Duct Detector	Tested	4
Heat Detector	Inspected	3
Heat Detector	Tested	28
Horn/Strobe	Tested	2
Power Supply	Tested	8
Pull Station	Tested	31
Smoke Detector	Inspected	2
Smoke Detector	Tested/Cleaned	549
Total		639
Grand Total		644

Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Magnolia Glen		Control Panel: 1 - Siemens XLS-MME-ADPT		
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>				
Type	Location	Comment	ScanID	Simulated
<i>Passed</i>				
Duct Detector				
Air Duct	3rd by room A303	Passed	22983382	
Air Duct	3rd by room A311	Passed	22983381	
Air Duct	5th by room 503	Passed	14244049	
Air Duct	5th by room 518	Passed	22983380	
Smoke Detector				
Elevator Recall	1st Elevator Equipment Room C	Passed	14244563	
Elevator Recall	1st Elevator Equipment Room D	Passed	14244580	
Elevator Recall	1st Elevator Lobby C	Passed	14244565	
Elevator Recall	1st elevator lobby D	Passed	14244394	
Elevator Recall	2nd Elevator Lobby C	Passed	14244442	
Elevator Recall	2nd elevator lobby D	Passed	14244545	
Elevator Recall	3rd Elevator Lobby C	Passed	14244088	
Elevator Recall	3rd elevator lobby D	Passed	14244449	
Elevator Recall	4th elevator lobby D	Passed	14244080	
Elevator Recall	5th elevator lobby D	Passed	14242703	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Magnolia Glen				Control Panel: 1 - Siemens XLS-MME-ADPT			
<p>The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</p>							
Battery							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Passed</i>							
Sealed Lead Acid	2nd IL side Telephone Room by room 226	7	12				
Sealed Lead Acid	2nd IL side Telephone Room by room 226	7	12				
Sealed Lead Acid	2nd IL side Telephone Room by room 226	7	12				
Sealed Lead Acid	3rd IL side FACP Room by room 332	7	12				7.0
Sealed Lead Acid	3rd IL side FACP Room by room 332 Bottom	7	12				7.9
Sealed Lead Acid	3rd IL side FACP Room by room 332 Too right	7	12				
Sealed Lead Acid	3rd IL side FACP Room by room 332 Top left	7	12				
Sealed Lead Acid	4th IL side Telephone Room by room 432	7	12				7.6
Sealed Lead Acid	5th IL side Mechanical Room by room 532	7	12				7.9
<i>Failed/Other</i>							
Sealed Lead Acid	3rd Telephone /FACP	35 bolt	12				
Power Supply							
Protection Type	Location	Rated Ah	Rated Volts	Charging Voltage			
<i>Passed</i>							
Breaker	2nd IL side Telephone Room by room 226	1	120				
Breaker	2nd IL side Telephone Room by room 226	1	120				
Breaker	3rd IL side FACP Room by room 332	3	120				
Breaker	3rd IL side FACP Room by room 332	3	120				
Breaker	3rd IL side FACP Room by room 332	3	120				
Breaker	3rd IL side FACP Room by room 332	3	120				

	332		
Breaker	4th IL side Telephone Room by room 432	1	120
Breaker	5th IL side Mechanical Room by room 532	1	120

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Magnolia Glen	Control Panel: 1 - Siemens XLS-MME-ADPT
-------------------------	--

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Annunciator	Control	0.31%	2
Battery	Control	1.55%	10
Communicator	Control	0.16%	1
Control Panel	Control	0.16%	1
Duct Detector	Initiating	0.62%	4
Heat Detector	Initiating	4.81%	31
Horn/Strobe	Indicating	0.78%	5
Power Supply	Control	1.24%	8
Pull Station	Initiating	4.81%	31
Smoke Detector	Initiating	85.56%	551

Type	Qty	Model #	Description	Install Date
------	-----	---------	-------------	--------------

In Service - 3 Years to 5 Years

DURACELL

Battery	1	DURA12-7F	Sealed Lead Acid	04/01/2020
---------	---	-----------	------------------	------------

DURACELL ULTRA

Battery	1	DURA12-7	Sealed Lead Acid	04/01/2020
---------	---	----------	------------------	------------

Battery	5	DURA12-7F	Sealed Lead Acid	04/01/2020
---------	---	-----------	------------------	------------

Battery	2	WKA12-7F	Sealed Lead Acid	04/01/2020
---------	---	----------	------------------	------------

Power Sonic

Battery	1	PS12350-NB	Sealed Lead Acid	10/01/2018
---------	---	------------	------------------	------------

In Service - 5 Years to 10 Years

Siemens

Annunciator	2	RCC-1	LCD Display	10/24/2016
-------------	---	-------	-------------	------------

Control Panel	1	XLS-MME-ADPT	Addressable	10/24/2016
---------------	---	--------------	-------------	------------

Heat Detector	28	FPT-11		10/24/2016
---------------	----	--------	--	------------

Heat Detector	3	FPT-11	Fixed Temperature	10/24/2016
---------------	---	--------	-------------------	------------

Horn/Strobe	1			10/24/2016
-------------	---	--	--	------------

Pull Station	31	MSI-10B	Single Action	10/24/2016
--------------	----	---------	---------------	------------

Smoke Detector	551	FP-11	Photoelectric	10/24/2016
----------------	-----	-------	---------------	------------

Wheelock

Horn/Strobe	4	NS4-24110W		10/24/2016
-------------	---	------------	--	------------

System Sensor

Duct Detector	3	DH100ACDCLP	Ionization	12/02/2015
---------------	---	-------------	------------	------------

Duct Detector	1	DH100ACDCLP	Photoelectric	12/02/2015
---------------	---	-------------	---------------	------------

In Service - 15 Years to 25 Years

Siemens				
Power Supply	1	PAD-3		12/02/2000
Fire-Lite				
Power Supply	5	FCPS-24F		10/24/2000
Siemens				
Power Supply	2	PAD-3		10/24/2000
Silent Knight				
Communicator	1	SK-5208	Digital Communicator	10/24/2000

Zone Address Report

Generated by: BuildingReports.com

Building: Magnolia Glen

Control Panel: 1 - Siemens
XLS-MME-ADPT

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 1				
01	Smoke Detector	1st AL side Room A106 Bed room	Photoelectric	14244793
02	Smoke Detector	1st AL side Room A106 Bedroom	Photoelectric	14244792
03	Smoke Detector	1st AL side Room A105 Living Room	Photoelectric	14244794
04	Smoke Detector	1st AL side Room A105 Bedroom	Photoelectric	14244795
06	Smoke Detector	1st AL side Room A103 Living Room	Photoelectric	14244797
07	Smoke Detector	1st AL side Room A102 Bedroom	Photoelectric	14244799
09	Smoke Detector	1st AL side Room A101 Living Room	Photoelectric	14244800
09	Smoke Detector	1st AL side Room A102 Living Room	Photoelectric	14244798
10	Smoke Detector	1st AL side Room A101 Living Room	Photoelectric	14244801
11	Smoke Detector	1st AL side Room A108 Living Room	Photoelectric	14244790
12	Smoke Detector	1st AL side Room A110 Living Room	Photoelectric	14244786
13	Smoke Detector	1st AL side Room A110 Bedroom	Photoelectric	14244787
15	Smoke Detector	1st AL side Room A109 Bedroom	Photoelectric	14244788
16	Smoke Detector	1st AL side Room A107 Living Room	Photoelectric	14244791
17	Smoke Detector	2nd AL side By Room A105	Photoelectric	14244576
18	Smoke Detector	2nd AL side By Room A104	Photoelectric	14244571
19	Smoke Detector	2nd AL side By Room A102	Photoelectric	14244573
20	Smoke Detector	2nd 1st Floor AL side Soiled Linen By A101	Photoelectric	72108677
21	Heat Detector	2nd 1st Floor AL side soiled utility		14244574
22	Heat Detector	1st AL side Laundry		14244572
23	Smoke Detector	1st AL side Electrical Room by A106	Photoelectric	37498866
24	Smoke Detector	2nd AL side By Trash Room	Photoelectric	14244569
25	Smoke Detector	2nd AL side By Room A110	Photoelectric	14244568
26	Smoke Detector	2nd AL side near front lobby By Room A110	Photoelectric	14244567
27	Smoke Detector	2nd AL side near front lobby By Room A109 At Fire Doors	Photoelectric	14244566
30	Smoke Detector	1st Elevator Equipment Room C	Photoelectric	14244563
31	Heat Detector	1st Elevator Equipment w C		14244564
32	Smoke Detector	1st AL side Front Lobby	Photoelectric	14244560
33	Smoke Detector	2nd AL side near cafe	Photoelectric	14244556
34	Smoke Detector	2nd AL side By Legacy Health Services	Photoelectric	14244555
35	Smoke Detector	2nd AL side By Staff Lounge near Receiving	Photoelectric	14244551
36	Smoke Detector	2nd AL side By stairwell 4 near Receiving	Photoelectric	14244549
37	Smoke Detector	2nd AL side By stairwell 4 near Receiving	Photoelectric	14244548
40	Pull Station	2nd AL side near stairwell 6	Single Action	14244577
41	Pull Station	2nd AL side Front entrance	Single Action	14244559

46	Smoke Detector	1st AL side Living/Lounge Area	Photoelectric	14244562
47	Pull Station	2nd Legacy Health Services	Single Action	29189783
59	Smoke Detector	1st Elevator Lobby C	Photoelectric	14244565
60	Smoke Detector	1st AL side Living/Lounge Area	Photoelectric	14244561

Zone/Circuit: 2

01	Heat Detector	2nd 1st Floor AL Kitchen	Fixed Temperature	14244552
02	Heat Detector	2nd 1st Floor AL Kitchen	Fixed Temperature	14244553
08	Smoke Detector	2nd AL side At room A204	Photoelectric	14244432
09	Smoke Detector	2nd AL side Room A209 Bedroom	Photoelectric	14244877
10	Smoke Detector	2nd AL side Room A209 Living Room	Photoelectric	14244876
11	Smoke Detector	2nd AL side Room A207 Living Room	Photoelectric	14244812
12	Smoke Detector	2nd AL side Room A206 Bedroom	Photoelectric	14244811
13	Smoke Detector	2nd AL side Room A206 Living Room	Photoelectric	14244810
16	Smoke Detector	2nd AL side Room A204 Living Room	Photoelectric	14244807
17	Smoke Detector	2nd AL side Room A203 Living Room	Photoelectric	14244806
18	Smoke Detector	2nd AL side Room A202 Bedroom	Photoelectric	14244805
19	Smoke Detector	2nd AL side Room A202 Living Room	Photoelectric	14244804
20	Smoke Detector	2nd AL side Room A201 Living Room	Photoelectric	14244802
21	Smoke Detector	2nd AL side Room A201 Bedroom	Photoelectric	14244803
22	Smoke Detector	2nd AL side Room A208 Living Room	Photoelectric	14244878
23	Smoke Detector	2nd AL side Room A210 Living Room	Photoelectric	14244874
24	Smoke Detector	2nd AL side Room A210 Bedroom	Photoelectric	14244875
31	Smoke Detector	2nd AL side stairwell 6	Photoelectric	14244430
32	Smoke Detector	2nd AL side At room A201	Photoelectric	14244434
33	Smoke Detector	2nd AL side Soiled Utility Room by room A201	Photoelectric	14244435
34	Heat Detector	2nd AL side Laundry		14244433
35	Smoke Detector	2nd AL side At room A208	Photoelectric	14244437
36	Smoke Detector	2nd AL side At room A209	Photoelectric	14244438
37	Smoke Detector	2nd AL side At stairwell 5	Photoelectric	14244439
38	Smoke Detector	2nd AL side At stairwell 5	Photoelectric	14244440
39	Smoke Detector	2nd Elevator Lobby C	Photoelectric	14244442
40	Smoke Detector	1st AL side Trash Room	Photoelectric	14244570
41	Smoke Detector	2nd AL side Trash room	Photoelectric	14244436
42	Heat Detector	2nd 1st Floor AL Kitchen	Fixed Temperature	29189785
43	Smoke Detector	2nd AL side In Dining At Kitchen Door	Photoelectric	29189784
44	Pull Station	2nd Hallway by stairwell 6 AL side	Single Action	14244431
45	Pull Station	2nd Hallway by stairwell 5 AL side	Single Action	14244441

Zone/Circuit: 3

05	Horn/Strobe	1st Total (49)		52545308
05	Smoke Detector	3rd FACP/Telephone Room	Photoelectric	14244453
05	Horn/Strobe	3rd Total (28)		68319041
05	Horn/Strobe	4th Total (10)		68319042
05	Horn/Strobe	5th Total (11)		68319043
06	Smoke Detector	3rd Electrical Room	Photoelectric	14244451
07	Smoke Detector	2nd IL side Telephone Room	Photoelectric	37498861
07	Battery	2nd IL side Telephone Room by room 226	Sealed Lead Acid	14244537
09	Smoke Detector	3rd AL side Room A309 Bedroom	Photoelectric	14244657
11	Smoke Detector	3rd AL side Room A307 Living Room	Photoelectric	14244669
12	Smoke Detector	3rd AL side Room A306 Bedroom	Photoelectric	14244660
13	Smoke Detector	3rd AL side Room A306 Living Room	Photoelectric	14244659

14	Smoke Detector	3rd AL side Room A305 Living room	Photoelectric	14244662
15	Smoke Detector	3rd AL side Room A305 Bedroom	Photoelectric	14244661
16	Smoke Detector	3rd AL side Room A304 Living room	Photoelectric	14244663
17	Smoke Detector	3rd AL side Room A303 Living room	Photoelectric	14244664
18	Smoke Detector	3rd AL side Room A302 Bedroom	Photoelectric	14244666
20	Smoke Detector	3rd AL side Room A301 Living room	Photoelectric	14244667
21	Smoke Detector	3rd AL side Room A301 Bedroom	Photoelectric	14244668
22	Smoke Detector	3rd AL side Room A308 Living Room	Photoelectric	14244658
23	Smoke Detector	3rd AL side Room A310 Living Room	Photoelectric	14244654
24	Smoke Detector	3rd AL side Room A310 Bedroom	Photoelectric	14244655
30	Smoke Detector	3rd AL side Stairwell 6	Photoelectric	14244429
31	Smoke Detector	3rd AL side At Room A305	Photoelectric	14244428
32	Smoke Detector	3rd AL side At Room A302	Photoelectric	14244096
33	Smoke Detector	3rd AL side Soiled Utility Room by A302	Photoelectric	14244426
34	Heat Detector	3rd AL side Laundry		14244095
35	Smoke Detector	3rd AL side At Room A303	Photoelectric	14244093
36	Smoke Detector	3rd AL side At Room A307	Photoelectric	14244091
37	Smoke Detector	3rd AL side At Room A309	Photoelectric	14244090
38	Smoke Detector	3rd AL side by stairwell 5 At Room A309	Photoelectric	14244089
39	Smoke Detector	3rd Elevator Lobby C	Photoelectric	14244088
40	Smoke Detector	3rd AL side Trash room near room A303	Photoelectric	14244092
43	Smoke Detector	3rd AL side Stairwell 5	Photoelectric	14244086
44	Pull Station	3rd Hallway by stairwell 6 AL side	Single Action	14244427
45	Pull Station	3rd Hallway by stairwell 5 AL side	Single Action	14244087

Zone/Circuit: 4

01	Smoke Detector	2nd AL side Room A219 Living Room	Photoelectric	14244860
02	Smoke Detector	2nd AL side Room A219 Bedroom	Photoelectric	14244861
03	Smoke Detector	2nd AL side Room A217 Living Room	Photoelectric	14244864
04	Smoke Detector	2nd AL side Room A215 Living Room	Photoelectric	14244866
05	Smoke Detector	2nd AL side Room A213 BedRoom	Photoelectric	14244869
06	Smoke Detector	2nd AL side Room A213 Living room	Photoelectric	14244868
07	Smoke Detector	2nd AL side Room A211 Bedroom	Photoelectric	14244873
09	Smoke Detector	2nd AL side Room A212 Living Room	Photoelectric	14244870
10	Smoke Detector	2nd AL side Room A212 Bedroom	Photoelectric	14244871
12	Smoke Detector	2nd AL side Room A216 Living Room	Photoelectric	14244865
13	Smoke Detector	2nd AL side Room A218 Bedroom	Photoelectric	14244863
14	Smoke Detector	2nd AL side Room A218 Living Room	Photoelectric	14244862
24	Smoke Detector	3rd AL side Room A319 Living Room	Photoelectric	14244226
25	Smoke Detector	3rd AL side Room A319 Bedroom	Photoelectric	14244225
26	Smoke Detector	3rd AL side Room A317 Living Room	Photoelectric	14244223
27	Smoke Detector	3rd AL side Room A315 Living Room	Photoelectric	14244221
28	Smoke Detector	3rd AL side Room A313 Bedroom	Photoelectric	14244219
29	Smoke Detector	3rd AL side Room A313 Living Room	Photoelectric	14244220
34	Smoke Detector	3rd AL side Room A314 Living Room	Photoelectric	14244222
35	Smoke Detector	3rd AL side Room A316 Living Room	Photoelectric	14244224
36	Smoke Detector	3rd AL side Room A318 Bedroom	Photoelectric	14244227
37	Smoke Detector	3rd AL side Room A318 Living Room	Photoelectric	14244228
47	Smoke Detector	2nd AL side At room A218	Photoelectric	14244447
48	Smoke Detector	2nd AL side At room A216	Photoelectric	14244446
49	Smoke Detector	2nd AL side At room A213	Photoelectric	14244444
50	Smoke Detector	2nd AL side At room A211	Photoelectric	14244443
51	Smoke Detector	3rd AL side At Room A311	Photoelectric	14244084
52	Smoke Detector	3rd AL side At Room A315	Photoelectric	14244083

53	Smoke Detector	3rd AL side At Room A317	Photoelectric	14244082
54	Smoke Detector	3rd AL side At Room A319	Photoelectric	14244081
55	Smoke Detector	2nd AL side At room A214	Photoelectric	14244445

Zone/Circuit: 5

1	Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Photoelectric	37498874
2	Smoke Detector	1st Storage room by Main Mechanical/Electrical Room	Photoelectric	37498873
03	Smoke Detector	1st Elevator Equipment Room D	Photoelectric	14244580
11	Smoke Detector	1st elevator lobby D	Photoelectric	14244394
13	Smoke Detector	1st Main Mechanical/Electrical Room	Photoelectric	66860927
13	Heat Detector	1st main mechanical/ electrical room		14244582
14	Smoke Detector	1st Main Mechanical/Electrical Room	Photoelectric	68318900
15	Heat Detector	1st main mechanical/ electrical room		14244584
16	Heat Detector	1st main mechanical/ electrical room		14244587
17	Heat Detector	1st mech room in corridor by fitness		14244605
18	Pull Station	1st Main Mechanical/Electrical Room	Single Action	14244589
26	Smoke Detector	1st Workshop hallway by Clean Linen	Photoelectric	14244395
27	Smoke Detector	1st Workshop hallway by kitchen	Photoelectric	14244396
28	Smoke Detector	1st Workshop hallway by Staff Lounge	Photoelectric	14244397
29	Pull Station	1st Workshop hallway by Staff Lounge	Single Action	14244398
30	Smoke Detector	1st Workshop hallway	Photoelectric	14244407
31	Heat Detector	1st bistro kitchen		14244403
32	Heat Detector	1st bistro kitchen		14244404
33	Heat Detector	1st bistro kitchen		14244399
34	Heat Detector	1st bistro kitchen		14244400
35	Heat Detector	1st bistro kitchen		14244401
36	Heat Detector	1st bistro kitchen		14244402
38	Smoke Detector	1st Kitchen by office	Photoelectric	14244406
39	Smoke Detector	1st Workshop hallway Mech room beside Dining Services Office	Photoelectric	37498868
40	Heat Detector	1st workshop hallway kitchen mech room beside office		14244592
41	Smoke Detector	1st Workshop hallway	Photoelectric	14244409
42	Smoke Detector	1st Workshop hallway	Photoelectric	14244410
43	Pull Station	1st Cafeteria dining room by exit	Single Action	14244417
44	Pull Station	1st Cafeteria dining room by exit	Single Action	14244416
45	Pull Station	1st Dining Room by exit	Single Action	14244415
46	Pull Station	1st The Bistro by exit	Single Action	14244414
47	Smoke Detector	1st Workshop Hallway	Photoelectric	14244411
48	Smoke Detector	1st Workshop Electrical Room	Photoelectric	37498884
49	Heat Detector	1st workshop maintenance office		14244599
50	Smoke Detector	1st Workshop	Photoelectric	14244412
51	Smoke Detector	1st Workshop Mechanical Room	Photoelectric	37498867
52	Heat Detector	1st workshop hallway mech room beside maintenance office		14244594
54	Smoke Detector	1st Workshop hallway	Photoelectric	14244408
57	Heat Detector	1st Elevator Equipment Room D		14244581

Zone/Circuit: 6

1	Smoke Detector	1st Elevator Lobby B	Photoelectric	14244413
2	Smoke Detector	1st Elevator Equipment Room B	Photoelectric	16486159
03	Heat Detector	1st Elevator Equipment B		16486158

09	Smoke Detector	1st IL side Trash room by 113	Photoelectric	14244295
10	Smoke Detector	1st Hallway by Fitness Center	Photoelectric	14244418
11	Smoke Detector	1st hallway by Fitness Center	Photoelectric	14244419
12	Smoke Detector	1st Corridor by Fitness Center	Photoelectric	14244420
13	Smoke Detector	1st Corridor by Fitness Center	Photoelectric	14244421
13	Smoke Detector	1st mech room in Corridor by Fitness Center	Photoelectric	37498885
14	Pull Station	1st Corridor by Fitness Center	Single Action	14244422
19	Smoke Detector	1st IL side hallway by pool	Photoelectric	14244425
20	Smoke Detector	1st Media Worship Center across from pool	Photoelectric	14244424
21	Pull Station	1st Chapel	Single Action	14244423
22	Smoke Detector	1st pool mechanical rm in pool area	Photoelectric	14244606
24	Heat Detector	1st IL side Laundry		14244297
25	Pull Station	1st Pool area	Single Action	66860928
26	Smoke Detector	1st Elevator Lobby A	Photoelectric	14244299
27	Smoke Detector	1st IL side fire doors by room by 113	Photoelectric	14244298
28	Smoke Detector	1st IL side fire doors by room by 113	Photoelectric	14244296
29	Smoke Detector	1st Elevator Equipment Room A	Photoelectric	14244608
30	Heat Detector	1st Elevator Equipment Room A		14244609
37	Smoke Detector	1st IL side hallway by room 111	Photoelectric	14244294
38	Smoke Detector	1st IL side hallway by room 109	Photoelectric	14244293
38	Smoke Detector	1st IL side hallway by room 109	Photoelectric	14244789
39	Smoke Detector	1st IL side hallway by room 107	Photoelectric	14244292
40	Smoke Detector	1st IL side hallway by room 105	Photoelectric	14244291
41	Smoke Detector	1st IL side Electrical Room by room 105	Photoelectric	37498888
42	Smoke Detector	1st IL side hallway by room 104	Photoelectric	14244290
42	Smoke Detector	1st IL side hallway by room 104	Photoelectric	14244796
43	Smoke Detector	1st IL side hallway by room 102	Photoelectric	14244289
44	Pull Station	1st IL side by room 102	Single Action	14244288
47	Smoke Detector	1st In Room IL/CR Across From Fitness Center In Left Closet	Photoelectric	14244601

Zone/Circuit: 7

1	Smoke Detector	1st IL side Room 113 Bedroom	Photoelectric	14244638
2	Smoke Detector	1st IL side Room 113 Living Room	Photoelectric	14244637
3	Smoke Detector	1st IL side Room 111 Living Room	Photoelectric	14244633
4	Smoke Detector	1st IL side Room 111 Bedroom	Photoelectric	14244634
5	Smoke Detector	1st IL side Room 109 Bedroom	Photoelectric	14244630
6	Smoke Detector	1st IL side Room 109 Living Room	Photoelectric	14244629
07	Smoke Detector	1st IL side Room 107 Bedroom	Photoelectric	14244626
08	Smoke Detector	1st IL side Room 107 Living Room	Photoelectric	14244624
09	Smoke Detector	1st IL side Room 107 Bedroom	Photoelectric	14244625
10	Smoke Detector	1st IL side Room 105 Bedroom	Photoelectric	14244622
11	Smoke Detector	1st IL side Room 105 Living Room	Photoelectric	14244621
12	Smoke Detector	1st IL side Room 104 Bedroom	Photoelectric	14244620
14	Smoke Detector	1st IL side Room 104 Living Room	Photoelectric	14244618
15	Smoke Detector	1st IL side Room 103 Bedroom	Photoelectric	14244617
16	Smoke Detector	1st IL side Room 103 Living Room	Photoelectric	14244616
17	Smoke Detector	1st IL side Room 102 Living Room	Photoelectric	14244613
18	Smoke Detector	1st IL side Room 102 Bedroom	Photoelectric	14244614
19	Smoke Detector	1st IL side Room 102 Bedroom	Photoelectric	14244615
20	Smoke Detector	1st IL side Room 101 Living Room	Photoelectric	14244611
22	Pull Station	2nd Front Lobby near stairwell 3	Single Action	14244526

23	Smoke Detector	1st IL side Room 106 Living Room	Photoelectric	14244623
24	Smoke Detector	1st IL side Room 108 Bedroom	Photoelectric	14244628
25	Smoke Detector	1st IL side Room 108 Living Room	Photoelectric	14244627
26	Smoke Detector	1st IL side Room 110 Living Room	Photoelectric	14244631
27	Smoke Detector	1st IL side Room 110 Bedroom	Photoelectric	14244632
28	Smoke Detector	1st IL side Room 112 Bedroom	Photoelectric	14244636
29	Smoke Detector	1st IL side Room 112 Living Room	Photoelectric	14244635
30	Pull Station	2nd Corridor near stairwell 4 by Receiving	Single Action	14244547
31	Smoke Detector	2nd elevator lobby D	Photoelectric	14244545
36	Smoke Detector	2nd IL side By Room 225	Photoelectric	14244533
37	Smoke Detector	2nd IL side By Room 223	Photoelectric	14244532
38	Smoke Detector	2nd IL side By Room 222	Photoelectric	14244531
39	Smoke Detector	2nd IL side By Room 220	Photoelectric	14244530
40	Smoke Detector	2nd IL side By Room 218	Photoelectric	14244529
41	Smoke Detector	2nd IL side By Room 214	Photoelectric	14244527
42	Smoke Detector	2nd Elevator Lobby B	Photoelectric	14244525
43	Smoke Detector	2nd Front Lobby near mailboxes	Photoelectric	14244524
44	Smoke Detector	2nd IL side Mechanical Room In Library	Photoelectric	37498894
45	Smoke Detector	2nd Front Lobby	Photoelectric	14244523
46	Smoke Detector	2nd Front Lobby At Main Desk	Photoelectric	14244510
47	Smoke Detector	2nd Front Lobby	Photoelectric	14244514
48	Smoke Detector	2nd Front Lobby near Copy Room	Photoelectric	14244517
49	Smoke Detector	2nd Front Lobby hallway near Conference Room	Photoelectric	14244519
50	Smoke Detector	2nd conference room mech closet behind front desk	Photoelectric	37499627
52	Smoke Detector	2nd Front Lobby	Photoelectric	14244287
53	Smoke Detector	2nd Front Lobby hallway near Human Resources	Photoelectric	14244511
55	Pull Station	2nd Front Lobby	Single Action	14244513
55	Smoke Detector	2nd Front Lobby hallway near Sales	Photoelectric	14244512
58	Pull Station	2nd By freight elevator near AL Kitchen	Single Action	14244546
60	Smoke Detector	2nd IL side Trash Room by room 214	Photoelectric	14244528

Zone/Circuit: 8

1	Smoke Detector	2nd IL side At Room IL/CA Near front lobby	Photoelectric	14244508
2	Smoke Detector	2nd IL side Mechanical Room In card table room	Photoelectric	37498893
3	Smoke Detector	2nd IL side Electrical Room In card table room	Photoelectric	37498892
04	Smoke Detector	2nd Elevator Lobby A	Photoelectric	14244500
6	Smoke Detector	2nd IL side Electrical/Mechanical Room by Salon	Photoelectric	37498891
7	Smoke Detector	2nd IL side At Room 213	Photoelectric	14244499
8	Smoke Detector	2nd IL side At Room 212	Photoelectric	14244497
9	Smoke Detector	2nd IL side At Room 210	Photoelectric	14244496
10	Smoke Detector	2nd IL side At Room 206	Photoelectric	14244495
11	Smoke Detector	2nd IL side Trash Room	Photoelectric	14244493
12	Smoke Detector	2nd IL side At Room 205	Photoelectric	14244494
13	Smoke Detector	2nd IL side By Room 201	Photoelectric	14244491
14	Pull Station	2nd Hallway by stairwell 1 IL Side	Single Action	14244492
21	Smoke Detector	2nd IL side Room 207 Bedroom	Photoelectric	14244748

26	Smoke Detector	2nd IL side Room 204 Bedroom	Photoelectric	14244649
27	Smoke Detector	2nd IL side Room 204 Bedroom	Photoelectric	14244648
29	Smoke Detector	2nd IL side Room 203 Bedroom	Photoelectric	14244646
30	Smoke Detector	2nd IL side Room 203 Living Room	Photoelectric	14244645
31	Smoke Detector	2nd IL side Room 202 Living Room	Photoelectric	14244642
33	Smoke Detector	3rd IL Side Telephone Room At Room 433	Photoelectric	14244073
34	Smoke Detector	2nd IL side Room 201 Living Room	Photoelectric	14244641
34	Smoke Detector	3rd IL Side Electrical Toom At Room 433	Photoelectric	14244077
35	Smoke Detector	2nd IL side Room 201 Bedroom	Photoelectric	14244640
36	Smoke Detector	2nd IL side Room 201 Bedroom	Photoelectric	14244639
37	Smoke Detector	2nd IL side Room 206 Living Room	Photoelectric	14244746
38	Smoke Detector	2nd IL side Room 208 Bedroom	Photoelectric	14244751
39	Smoke Detector	2nd IL side Room 208 Living Room	Photoelectric	14244750
40	Smoke Detector	2nd IL side Room 210 Living Room	Photoelectric	14244754
41	Smoke Detector	2nd IL side Room 210 Bedroom	Photoelectric	14244755
42	Smoke Detector	2nd IL side Room 212 Bedroom	Photoelectric	14244759
43	Smoke Detector	2nd IL side Room 212 Living Room	Photoelectric	14244758
53	Heat Detector	2nd IL side electrical/Mech room by Salon & Spa		54160088
53	Heat Detector	2nd IL side laundry		14244498
55	Smoke Detector	2nd Front Lobby	Photoelectric	29189782
55	Smoke Detector	2nd Front Lobby Above Light	Photoelectric	20163933

Zone/Circuit: 9

1	Smoke Detector	2nd IL side Room 226 Living Room	Photoelectric	14244785
2	Smoke Detector	2nd IL side Room 225 Bedroom	Photoelectric	14244784
4	Smoke Detector	2nd IL side Room 225 Bedroom	Photoelectric	29189788
5	Smoke Detector	2nd IL side Room 224 Living Room	Photoelectric	14244780
6	Smoke Detector	2nd IL side Room 224 Bedroom	Photoelectric	14244781
7	Smoke Detector	2nd IL side Room 221 Bedroom	Photoelectric	14244776
9	Smoke Detector	2nd IL side Room 221 Bed Room	Photoelectric	14244777
10	Smoke Detector	2nd IL side Room 219 Bedroom	Photoelectric	14244773
11	Smoke Detector	2nd IL side Room 219 Living Room	Photoelectric	14244772
12	Smoke Detector	2nd IL side Room 217 Living Room	Photoelectric	14244768
13	Smoke Detector	2nd IL side Room 217 Bed Room	Photoelectric	14244769
14	Smoke Detector	2nd IL side Room 215 Bedroom	Photoelectric	14244765
15	Smoke Detector	2nd IL side Room 215 Bedroom	Photoelectric	14244764
16	Smoke Detector	2nd IL side Room 214 Living Room	Photoelectric	14244762
17	Smoke Detector	2nd IL side Room 214 Bedroom	Photoelectric	14244763
18	Smoke Detector	2nd IL side Room 222 Bedroom	Photoelectric	14244814
19	Smoke Detector	2nd IL side Room 222 Living Room	Photoelectric	14244813
21	Smoke Detector	2nd IL side Room 220 Bed Room	Photoelectric	14244775
22	Smoke Detector	2nd IL side Room 220 Living Room	Photoelectric	14244774
23	Smoke Detector	2nd IL side Room 218 Bedroom	Photoelectric	14244770
24	Smoke Detector	2nd IL side Room 218 Bedroom	Photoelectric	14244771
25	Smoke Detector	2nd IL side Room 216 Bed Room	Photoelectric	14244767
26	Smoke Detector	2nd IL side Room 216 Living Room	Photoelectric	14244766
27	Pull Station	3rd Hallway by stairwell 4 IL side	Single Action	14244450
28	Smoke Detector	3rd IL side At stairwell 4	Photoelectric	14244448
29	Smoke Detector	3rd elevator lobby D	Photoelectric	14244449
34	Smoke Detector	3rd IL side At FACP room	Photoelectric	14244452
35	Smoke Detector	3rd IL side At room 331	Photoelectric	14244469
36	Smoke Detector	3rd IL side At room 329	Photoelectric	14244470

37	Smoke Detector	3rd IL side At room 326	Photoelectric	14244471
38	Smoke Detector	3rd IL side At room 324	Photoelectric	14244472
39	Smoke Detector	3rd IL side At room 323	Photoelectric	14244473
40	Smoke Detector	3rd IL side Trash Room At room 313	Photoelectric	14244483
40	Smoke Detector	3rd IL side Trash Room At room 321	Photoelectric	14244474
41	Smoke Detector	3rd Elevator Lobby B	Photoelectric	14244476
42	Pull Station	3rd Hallway by stairwell 3 IL side	Single Action	14244475
43	Smoke Detector	3rd IL side At Room 320	Photoelectric	14244477
44	Smoke Detector	3rd IL side At Room 317	Photoelectric	14244478
45	Smoke Detector	3rd IL side At Room 316	Photoelectric	14244479
46	Smoke Detector	3rd Elevator Lobby A	Photoelectric	14244481
47	Heat Detector	3rd IL side Laundry		14244480
48	Smoke Detector	3rd IL side At Room 313	Photoelectric	14244482
49	Smoke Detector	3rd IL side At Room 311	Photoelectric	14244484
50	Smoke Detector	3rd IL side At Room 309	Photoelectric	14244485
51	Smoke Detector	3rd IL side At Room 307	Photoelectric	14244486
52	Smoke Detector	3rd IL side At Room 305	Photoelectric	14244487
53	Smoke Detector	3rd IL side Electrical Room by room 304	Photoelectric	14244488
54	Pull Station	3rd Hallway by stairwell 1 IL side	Single Action	14244489
55	Smoke Detector	3rd IL side At Room 301	Photoelectric	14244490

Zone/Circuit: 10

3	Smoke Detector	3rd IL side Room A332 Bedroom	Photoelectric	14244855
4	Smoke Detector	3rd IL side Room A332 Living Room	Photoelectric	14244856
5	Smoke Detector	3rd IL side Room A332 Bedroom	Photoelectric	14244857
6	Smoke Detector	3rd IL side Room A331 Living Room	Photoelectric	14244853
7	Smoke Detector	3rd IL side Room A331 Bedroom	Photoelectric	14244854
8	Smoke Detector	3rd IL side Room A329 Bedroom	Photoelectric	14244735
10	Smoke Detector	3rd IL side Room A329 Bedroom	Photoelectric	29189787
11	Smoke Detector	3rd IL side Room A327 Bedroom	Photoelectric	14244732
12	Smoke Detector	3rd IL side Room A327 Living Room	Photoelectric	14244731
13	Smoke Detector	3rd IL side Room A325 Living Room	Photoelectric	14244727
14	Smoke Detector	3rd IL side Room A325 Bedroom	Photoelectric	14244728
15	Smoke Detector	3rd IL side Room A323 Bedroom	Photoelectric	14244724
16	Smoke Detector	3rd IL side Room A323 Living Room	Photoelectric	14244723
17	Smoke Detector	3rd IL side Room A321 Living Room	Photoelectric	14244719
18	Smoke Detector	3rd IL side Room A321 Bedroom	Photoelectric	14244720
19	Smoke Detector	3rd IL side Room A319 Bedroom	Photoelectric	14244713
20	Smoke Detector	3rd IL side Room A319 Living Room	Photoelectric	14244711
21	Smoke Detector	3rd IL side Room A319 Bedroom	Photoelectric	14244712
22	Smoke Detector	3rd IL side Room A315 Bedroom	Photoelectric	14244707
23	Smoke Detector	3rd IL side Room A315 Living Room	Photoelectric	14244706
24	Smoke Detector	3rd IL side Room A315 Bedroom	Photoelectric	14244708
25	Smoke Detector	3rd IL side Room A314 Bedroom	Photoelectric	14244703
26	Smoke Detector	3rd IL side Room A314 Bedroom	Photoelectric	14244702
27	Smoke Detector	3rd IL side Room A314 Living Room	Photoelectric	14244701
28	Smoke Detector	3rd IL side Room A316 Living Room	Photoelectric	14244705
29	Smoke Detector	3rd IL side Room A316 Bedroom	Photoelectric	14244704
30	Smoke Detector	3rd IL side Room A317 Living Room	Photoelectric	14244709
31	Smoke Detector	3rd IL side Room A317 Bedroom	Photoelectric	14244710
32	Smoke Detector	3rd IL side Room A318 Bedroom	Photoelectric	14244715
33	Smoke Detector	3rd IL side Room A318 Living Room	Photoelectric	14244714
37	Smoke Detector	3rd IL side Room A322 Living Room	Photoelectric	14244721
38	Smoke Detector	3rd IL side Room A322 Bedroom	Photoelectric	14244722

39	Smoke Detector	3rd IL side Room A324 Bedroom	Photoelectric	14244726
40	Smoke Detector	3rd IL side Room A324 Living Room	Photoelectric	14244725
41	Smoke Detector	3rd IL side Room 326 Living Room	Photoelectric	14244729
42	Smoke Detector	3rd IL side Room A326 Bedroom	Photoelectric	14244730
43	Smoke Detector	3rd IL side Room A328 Bedroom	Photoelectric	14244734
44	Smoke Detector	3rd IL side Room A328 Living Room	Photoelectric	14244733
45	Smoke Detector	3rd IL side Room A330 Living Room	Photoelectric	14244852

Zone/Circuit: 11

1	Pull Station	4th Hallway by stairwell 4 IL Side	Single Action	14244078
2	Smoke Detector	4th IL Side At Stairwell 4	Photoelectric	14244079
3	Smoke Detector	4th elevator lobby D	Photoelectric	14244080
04	Smoke Detector	4th IL side Trash Room by room 413	Photoelectric	14244057
8	Smoke Detector	4th IL side By Room 432	Photoelectric	14244072
9	Smoke Detector	4th IL side By Room 431	Photoelectric	14244071
10	Smoke Detector	4th IL side By Room 428	Photoelectric	14244070
11	Smoke Detector	4th IL side By Room 426	Photoelectric	14244069
12	Smoke Detector	4th IL side By Room 424	Photoelectric	14244068
13	Smoke Detector	4th IL side By Room 421	Photoelectric	14244066
15	Smoke Detector	4th Elevator Lobby B	Photoelectric	14244064
16	Pull Station	4th Hallway by stairwell 3 IL Side	Single Action	14244065
17	Smoke Detector	4th IL side By Room 420	Photoelectric	14244063
18	Smoke Detector	4th IL side By Room 417	Photoelectric	14244062
19	Smoke Detector	4th IL side By Room 415	Photoelectric	14244061
20	Smoke Detector	4th Elevator Lobby A	Photoelectric	14244059
21	Heat Detector	4th IL side Laundry		14244060
22	Smoke Detector	4th IL side By Room 413	Photoelectric	14244058
23	Smoke Detector	4th IL side By Room 411	Photoelectric	14244056
24	Smoke Detector	4th IL side By Room 409	Photoelectric	14244055
25	Smoke Detector	4th IL side By Room 406	Photoelectric	14244054
26	Smoke Detector	4th IL side By Room 405	Photoelectric	14244053
27	Smoke Detector	4th IL side Electrical room by room 404	Photoelectric	14244052
28	Pull Station	4th Hallway by stairwell 1 IL Side	Single Action	14244050
29	Smoke Detector	4th IL side By Room 401	Photoelectric	14244051
30	Smoke Detector	3rd IL side Room A313 Bedroom	Photoelectric	14244700
31	Smoke Detector	3rd IL side Room A313 Living Room	Photoelectric	14244699
32	Smoke Detector	3rd IL side Room 311 Living Room	Photoelectric	14244695
33	Smoke Detector	3rd IL side Room 311 Bedroom	Photoelectric	14244696
34	Smoke Detector	2nd IL side Electrical Room by room 226	Photoelectric	37498862
34	Smoke Detector	3rd IL side Room 309 Bedroom	Photoelectric	14244692
34	Smoke Detector	3rd IL side Room 320 Living Room	Photoelectric	14244716
35	Smoke Detector	3rd IL side Room 309 Living Room	Photoelectric	14244691
35	Smoke Detector	3rd IL side Room 320 Bedroom	Photoelectric	14244717
36	Smoke Detector	3rd IL side Room 307 Bedroom	Photoelectric	14244688
36	Smoke Detector	3rd IL side Room 320 Bedroom	Photoelectric	14244718
37	Smoke Detector	3rd IL side Room 307 Living Room	Photoelectric	14244686
38	Smoke Detector	3rd IL side Room 307 Bedroom	Photoelectric	14244687
39	Smoke Detector	3rd IL side Room 305 Bedroom	Photoelectric	14244684
40	Smoke Detector	3rd IL side Room 305 Living Room	Photoelectric	14244683
41	Smoke Detector	3rd IL side Room 304 Bedroom	Photoelectric	14244682
42	Smoke Detector	3rd IL side Room 304 Bedroom	Photoelectric	14244681
43	Smoke Detector	3rd IL side Room 304 Living Room	Photoelectric	14244680
44	Smoke Detector	3rd AL side Room 303 Bedroom	Photoelectric	14244679
45	Smoke Detector	3rd AL side Room 303 Living Room	Photoelectric	14244678

46	Smoke Detector	3rd IL side Room 302 Living Room	Photoelectric	14244677
47	Smoke Detector	3rd IL side Room 302 Bedroom	Photoelectric	14244675
48	Smoke Detector	3rd IL side Room 302 Bedroom	Photoelectric	14244676
49	Smoke Detector	3rd IL side Room 301 Living Room	Photoelectric	14244672
50	Smoke Detector	3rd IL side Room 301 Bedroom	Photoelectric	14244673
51	Smoke Detector	3rd IL side Room 301 Bedroom	Photoelectric	14244674
52	Smoke Detector	3rd IL side Room 306 Living Room	Photoelectric	14244685
53	Smoke Detector	3rd IL side Room 308 Bedroom	Photoelectric	14244690
54	Smoke Detector	3rd IL side Room 308 Living Room	Photoelectric	14244689
55	Smoke Detector	3rd IL side Room 310 Living Room	Photoelectric	14244693
56	Smoke Detector	3rd IL side Room 310 Bedroom	Photoelectric	14244694
57	Smoke Detector	3rd IL side Room 312 Bedroom	Photoelectric	14244698
58	Smoke Detector	3rd IL side Room 312 Living Room	Photoelectric	14244697

Zone/Circuit: 12

1	Smoke Detector	4th IL side Room 433 Living Room	Photoelectric	14244230
2	Smoke Detector	4th IL side Room 433 Bedroom	Photoelectric	14244229
3	Smoke Detector	4th IL side Room 432 Bedroom	Photoelectric	14244233
4	Smoke Detector	4th IL side Room 432 Living Room	Photoelectric	14244232
5	Smoke Detector	4th IL side Room 432 Bedroom	Photoelectric	14244231
8	Smoke Detector	4th IL side Room 429 Bedroom	Photoelectric	14244237
9	Smoke Detector	4th IL side Room 429 Living Room	Photoelectric	14244239
10	Smoke Detector	4th IL side Room 429 Bedroom	Photoelectric	14244238
11	Smoke Detector	4th IL side Room 427 Bedroom	Photoelectric	14244242
12	Smoke Detector	4th IL side Room 427 Living Room	Photoelectric	14244243
13	Smoke Detector	4th IL side Room 425 Bedroom	Photoelectric	14244244
14	Smoke Detector	4th IL side Electrical Room by room 421	Photoelectric	14244067
14	Smoke Detector	4th IL side Room 425 Living Room	Photoelectric	14244245
15	Smoke Detector	4th IL side Room 423 Bedroom	Photoelectric	14244248
16	Smoke Detector	4th IL side Room 423 Living Room	Photoelectric	14244249
17	Smoke Detector	4th IL side Room 421 Living Room	Photoelectric	14244253
18	Smoke Detector	4th IL side Room 421 Bedroom	Photoelectric	14244252
19	Smoke Detector	4th IL side Room 419 Bedroom	Photoelectric	14244260
20	Smoke Detector	4th IL side Room 419 Living Room	Photoelectric	14244261
21	Smoke Detector	4th IL side Room 419 Bedroom	Photoelectric	14244259
22	Smoke Detector	4th IL side Room 415 Bedroom	Photoelectric	14244264
23	Smoke Detector	4th IL side Room 415 Living Room	Photoelectric	14244266
24	Smoke Detector	4th IL side Room 415 Bedroom	Photoelectric	14244265
25	Smoke Detector	4th IL side Room 414 Bedroom	Photoelectric	14244270
26	Smoke Detector	4th IL side Room 414 Bedroom	Photoelectric	14244269
27	Smoke Detector	4th IL side Room 414 Living Room	Photoelectric	14244271
28	Smoke Detector	4th IL side Room 416 Living Room	Photoelectric	14244268
29	Smoke Detector	4th IL side Room 416 Bedroom	Photoelectric	14244267
30	Smoke Detector	4th IL side Room 417 Living Room	Photoelectric	14244263
31	Smoke Detector	4th IL side Room 417 Bedroom	Photoelectric	14244262
32	Smoke Detector	4th IL side Room 418 Bedroom	Photoelectric	14244257
33	Smoke Detector	4th IL side Room 418 Living Room	Photoelectric	14244258
34	Smoke Detector	4th IL side Room 420 Living Room	Photoelectric	14244256
35	Smoke Detector	4th IL side Room 420 Bedroom	Photoelectric	14244254
36	Smoke Detector	4th IL side Room 420 Bedroom	Photoelectric	14244255
37	Smoke Detector	4th IL side Room 422 Living Room	Photoelectric	14244251
38	Smoke Detector	4th IL side Room 422 Bedroom	Photoelectric	14244250
39	Smoke Detector	4th IL side Room 424 Bedroom	Photoelectric	14244246
40	Smoke Detector	4th IL side Room 424 Living Room	Photoelectric	14244247

41	Smoke Detector	4th IL side Room 426 Living room	Photoelectric	14244670
42	Smoke Detector	4th IL side Room 426 Bedroom	Photoelectric	14244671
43	Smoke Detector	4th IL side Room 428 Bedroom	Photoelectric	14244240
44	Smoke Detector	4th IL side Room 428 Living Room	Photoelectric	14244241
45	Smoke Detector	4th IL side Room 430 Living Room	Photoelectric	14244236
57	Smoke Detector	5th IL side Room 513 Living Room	Photoelectric	14244327
58	Smoke Detector	5th IL side Electrical Room by room 513	Photoelectric	68318899
58	Smoke Detector	5th IL side Room 513 Bedroom	Photoelectric	14244328

Zone/Circuit: 13

1	Smoke Detector	4th IL side room 413 Bedroom	Photoelectric	14244272
2	Smoke Detector	4th IL side room 413 Living room	Photoelectric	14244273
3	Smoke Detector	4th IL side room 411 Living room	Photoelectric	14244277
4	Smoke Detector	4th IL side room 411 Bedroom	Photoelectric	14244276
5	Smoke Detector	4th IL side room 409 Bedroom	Photoelectric	14244280
6	Smoke Detector	4th IL side room 409 Living room	Photoelectric	14244281
7	Smoke Detector	4th IL side room 407 Bedroom	Photoelectric	14244284
8	Smoke Detector	4th IL side room 407 Living room	Photoelectric	14244286
9	Smoke Detector	4th IL side room 407 Bedroom	Photoelectric	14244285
10	Smoke Detector	4th IL side room 405 Bedroom	Photoelectric	14244392
11	Smoke Detector	4th IL side room 405 Living room	Photoelectric	14244391
12	Smoke Detector	4th IL side room 404 Bedroom	Photoelectric	14244390
13	Smoke Detector	4th IL side room 404 Bedroom	Photoelectric	14244389
14	Smoke Detector	4th IL side room 404 Living room	Photoelectric	14244388
15	Smoke Detector	4th IL side room 403 Bedroom	Photoelectric	14244387
16	Smoke Detector	4th IL side room 403 Living room	Photoelectric	14244386
17	Smoke Detector	4th IL side room 402 Living room	Photoelectric	14244383
18	Smoke Detector	4th IL side room 402 Bedroom	Photoelectric	14244384
19	Smoke Detector	4th IL side room 402 Bedroom	Photoelectric	14244385
20	Smoke Detector	4th IL side room 401 Living room	Photoelectric	14244381
21	Smoke Detector	4th IL side room 401 Bedroom	Photoelectric	14244382
22	Smoke Detector	4th IL side room 401 Bedroom	Photoelectric	14244380
23	Smoke Detector	4th IL side room 406 Living room	Photoelectric	14244393
24	Smoke Detector	4th IL side room 408 Bedroom	Photoelectric	14244282
25	Smoke Detector	4th IL side room 408 Living room	Photoelectric	14244283
26	Smoke Detector	4th IL side room 410 Living room	Photoelectric	14244279
27	Smoke Detector	4th IL side room 410 Bedroom	Photoelectric	14244278
28	Smoke Detector	4th IL side room 412 Bedroom	Photoelectric	14244274
29	Smoke Detector	4th IL side room 412 Living room	Photoelectric	14244275
30	Smoke Detector	5th IL side Room 511 Living Room	Photoelectric	14244323
31	Smoke Detector	5th IL side Room 511 Bedroom	Photoelectric	14244324
33	Smoke Detector	5th IL side Room 507 Bedroom	Photoelectric	14244315
33	Smoke Detector	5th IL side Room 509 Living Room	Photoelectric	14244321
34	Smoke Detector	5th IL side Room 509 Bedroom	Photoelectric	14244322
35	Smoke Detector	5th IL side Room 507 Living Room	Photoelectric	14244314
36	Smoke Detector	5th IL side Room 506 Living Room	Photoelectric	14244313
36	Smoke Detector	5th IL side Room 507 Bedroom	Photoelectric	14244316
37	Smoke Detector	5th IL side Room 505 Bedroom	Photoelectric	14244312
38	Smoke Detector	5th IL side Room 505 Living Room	Photoelectric	14244311
39	Smoke Detector	5th IL side Room 504 Bedroom	Photoelectric	14244319
40	Smoke Detector	5th IL side Room 504 Bedroom	Photoelectric	14244320
41	Smoke Detector	5th IL side Room 504 Living Room	Photoelectric	14244310
42	Smoke Detector	5th IL side Room 503 Bedroom	Photoelectric	14244309
43	Smoke Detector	5th IL side Room 503 Living Room	Photoelectric	14244308

44	Smoke Detector	5th IL side Room 502 Living Room	Photoelectric	14244305
45	Smoke Detector	5th IL side Room 502 Bedroom	Photoelectric	14244306
47	Smoke Detector	5th IL side Room 501 Living Room	Photoelectric	14244303
48	Smoke Detector	5th IL side Room 501 Bedroom	Photoelectric	14244304
49	Smoke Detector	5th IL side Room 501 Bedroom	Photoelectric	20163939
51	Smoke Detector	5th IL side Room 508 Bedroom	Photoelectric	14244318
52	Smoke Detector	5th IL side Room 508 Living Room	Photoelectric	14244317
53	Smoke Detector	5th IL side Room 510 Living Room	Photoelectric	14244379
54	Smoke Detector	5th IL side Room 510 Bedroom	Photoelectric	14244378
55	Smoke Detector	5th IL side Room 512 Bedroom	Photoelectric	14244326
56	Smoke Detector	5th IL side Room 512 Living Room	Photoelectric	14244325

Zone/Circuit: 14

1	Smoke Detector	5th Top of stairwell 4 IL side	Photoelectric	14242706
2	Pull Station	5th Hallway by stairwell 4 IL side	Single Action	14242704
3	Smoke Detector	5th IL side hallway by room 534	Photoelectric	14242707
4	Smoke Detector	5th elevator lobby D	Photoelectric	14242703
7	Smoke Detector	5th IL side Mechanical Room by room 533	Photoelectric	14243950
11	Smoke Detector	5th IL side hallway by room 533	Photoelectric	14242708
12	Smoke Detector	5th IL side hallway by room 530	Photoelectric	14242709
13	Smoke Detector	5th IL side hallway by room 528	Photoelectric	14242710
14	Smoke Detector	5th IL side hallway by room 526	Photoelectric	14242711
15	Smoke Detector	5th IL side hallway by room 524	Photoelectric	14242712
16	Smoke Detector	5th IL side hallway by room 521	Photoelectric	14242713
17	Smoke Detector	5th IL side Electrical Room by room 521	Photoelectric	14244042
20	Smoke Detector	5th Elevator Lobby B	Photoelectric	14242714
21	Pull Station	5th Hallway by stairwell 3 IL side	Single Action	14242715
22	Smoke Detector	5th IL side hallway by room 520	Photoelectric	14242717
23	Smoke Detector	5th IL side hallway by room 517	Photoelectric	14242718
24	Smoke Detector	5th IL side hallway by room 516	Photoelectric	14242719
25	Smoke Detector	5th Elevator Lobby A	Photoelectric	14242720
26	Heat Detector	5th IL side Laundry		14242705
28	Smoke Detector	5th IL side hallway by room 513	Photoelectric	14242721
29	Smoke Detector	5th IL side hallway by room 510	Photoelectric	14242722
30	Smoke Detector	5th IL side hallway by room 508	Photoelectric	14242723
31	Smoke Detector	5th IL side hallway by room 505	Photoelectric	14242724
32	Smoke Detector	5th IL side Mechanical Room by room 504	Photoelectric	37498863
33	Smoke Detector	5th IL side hallway by room 504	Photoelectric	14242725
34	Smoke Detector	5th	Photoelectric	14244302
35	Pull Station	5th Hallway by stairwell 1 IL side	Single Action	14244300
36	Smoke Detector	5th IL side hallway by room 501	Photoelectric	14244301
37	Smoke Detector	5th IL side Room 530 Living Room	Photoelectric	14244364
38	Smoke Detector	5th IL side Room 528 Living Room	Photoelectric	14244362
39	Smoke Detector	5th IL side Room 528 Bedroom	Photoelectric	14244363
40	Smoke Detector	5th IL side Room 526 Bedroom	Photoelectric	14244356
41	Smoke Detector	5th IL side Room 526 Living Room	Photoelectric	14244355
42	Smoke Detector	5th IL side Room 524 Living Room	Photoelectric	14244353
43	Smoke Detector	5th IL side Room 524 Bedroom	Photoelectric	14244354
44	Smoke Detector	5th IL side Room 522 Bedroom	Photoelectric	14244352
45	Smoke Detector	5th IL side Room 522 Living Room	Photoelectric	14244351
46	Smoke Detector	5th IL side Room 520 Bedroom	Photoelectric	14244345
47	Smoke Detector	5th IL side Room 520 Bedroom	Photoelectric	14244346

48	Smoke Detector	5th IL side Room 520 Living Room	Photoelectric	14244344
49	Smoke Detector	5th IL side Room 518 Living Room	Photoelectric	14244342
50	Smoke Detector	5th IL side Room 518 Bedroom	Photoelectric	14244343
51	Smoke Detector	5th IL side Room 517 Bedroom	Photoelectric	14244338
52	Smoke Detector	5th IL side Room 517 Living Room	Photoelectric	14244337
53	Smoke Detector	5th IL side Room 516 Bedroom	Photoelectric	14244332
54	Smoke Detector	5th IL side Room 516 Living Room	Photoelectric	14244333
55	Smoke Detector	5th IL side Room 514 Living Room	Photoelectric	14244329
56	Smoke Detector	5th IL side Room 514 Bedroom	Photoelectric	14244330
57	Smoke Detector	5th IL side Room 514 Bedroom	Photoelectric	14244331
59	Smoke Detector	5th Top of stairwell 3 IL side	Photoelectric	14242716

Zone/Circuit: 15

3	Smoke Detector	5th IL side Room 535 Bedroom	Photoelectric	14244375
4	Smoke Detector	5th IL side Room 535 Living Room	Photoelectric	14244374
5	Smoke Detector	5th IL side Room 533 Living Room	Photoelectric	14244370
6	Smoke Detector	5th IL side Room 533 Bedroom	Photoelectric	14244371
7	Smoke Detector	5th IL side Room 532 Bedroom	Photoelectric	14244367
9	Smoke Detector	5th IL side Room 532 Living Room	Photoelectric	14244368
10	Smoke Detector	5th IL side Room 531 Living Room	Photoelectric	14244365
11	Smoke Detector	5th IL side Room 531 Bedroom	Photoelectric	14244366
12	Smoke Detector	5th IL side Room 529 Bedroom	Photoelectric	14244360
13	Smoke Detector	5th IL side Room 529 Living Room	Photoelectric	14244359
14	Smoke Detector	5th IL side Room 529 Bedroom	Photoelectric	14244361
15	Smoke Detector	5th IL side Room 527 Bedroom	Photoelectric	14244358
16	Smoke Detector	5th IL side Room 527 Living Room	Photoelectric	14244357
17	Smoke Detector	5th IL side Room 525 Living Room	Photoelectric	14244376
18	Smoke Detector	5th IL side Room 525 Bedroom	Photoelectric	14244377
19	Smoke Detector	5th IL side Room 523 Bedroom	Photoelectric	14244350
20	Smoke Detector	5th IL side Room 523 Living Room	Photoelectric	14244349
21	Smoke Detector	5th IL side Room 521 Living Room	Photoelectric	14244347
22	Smoke Detector	5th IL side Room 521 Bedroom	Photoelectric	14244348
23	Smoke Detector	5th IL side Room 519 Bedroom	Photoelectric	14244341
24	Smoke Detector	5th IL side Room 519 Living Room	Photoelectric	14244340
25	Smoke Detector	5th IL side Room 519 Bedroom	Photoelectric	14244339
26	Smoke Detector	5th IL side Room 515 Bedroom	Photoelectric	14244336
27	Smoke Detector	5th IL side Room 515 Living Room	Photoelectric	14244334
28	Smoke Detector	5th IL side Room 515 Bedroom	Photoelectric	14244335
28	Duct Detector	3rd by room A311	Ionization	22983381
29	Duct Detector	3rd by room A303	Ionization	22983382
30	Duct Detector	5th by room 518	Photoelectric	22983380
33	Duct Detector	5th by room 503	Ionization	14244049