PRINTED: 05/29/2018 FORM APPROVED

	of Health Service Reg	ulation		DUCD Montal H	FORM APPROVED
	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER	(X2) MULTIPI A. BUILDING	LE CONSTRUCTION DITOR - IVICINAL TI	(X3) DATE SURVEY COMPLETED
				JUN 08 2018	
MHL005-020		9. WNG		05/16/2018	
NAME OF P	ROVIDER OR SUPPLIER	STREET	ADDRESS, CITY, 81	TATE, ZIP CODE Lic. & Cert. Sect	ion
SUMMIT S	SUPPORT SERVICES O	r ashe, inc - ark	NG STREET ISON, NC 28640)	
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	
V 000	INITIAL COMMENTS	6	V 000	Von will find a	tachments
	An annual survey was completed on May 18, 2018. A deficiency was cited. This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disabilities.			A-Fregarding	FNESAG
				from Aug 15)	
V 736	27G .0303(c) Facility and Grounds Maintenance		V 738	and an estin	nate
	10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly			and an estin provided to summit / Remie to replace	Ard trong
	manner and shall be foodor.	sept free from offensive		the handicays	shower
E	This Rule is not met a Based on observation was not maintained in manner. The findings	and interviews, the facility a clean and attractive		Then again you the Arcis regulary 10 to 3	et anoth
3	Observation on 5/15/1 3:30PM through 4:30P	M revealed:		estimate for repairs (E) à	fter
b	athroom off of the Ilvii The shower walls and	shower was located in the ng room; floor were covered with a			Granght.
-	an colored tile; The shower head leak The floor of the showe	ed water; r and the bottom walls		again (hotton	OFE)S/10
w	vere covered with a bla ppeared unclean			on (F) May 17,	
-5	iterview on 5/15/18 wi She had tried to clean lany times;			our citation.	
-S	Staff #2 had used mult scrub brush had bee	lple types of cleaners, n used on the blackened		People will be estimates which	houseline
	Service Regulation ECTOR'S OR PROVIDER/SUI	PPLIER REPRESENTATIVE'S BIGNATURE		need to be app	(XO) DATE
E FORM			8639 W	The Arc. Starting	Topy to clay a
				Ala Por Clar	ADP

PRINTED: 05/29/2018 FORM APPROVED

Division	of Health Service Requ	lation			FORM AFFROVED				
STATEMENT OF DEFICIENCIES (X1) PRO AND PLAN OF CORRECTION IDEN		(X1) PROVIDER/SUPPLIER/CLIA		E CONSTRUCTION	(X9) DATE SURVEY				
		IDENTIFICATION NOWBER.	A BUILDING:		COMPLETED				
	MHL005-020		B. WNG	05/16/2018					
NAME OF F	PROVIDER OR SUPPLIER		DDRESS CITY ST	ATE ZIP CODE	00/10/2018				
342 LONG STREET									
SUMMIT SUPPORT SERVICES OF ASHE, INC - ARK JEFFERSON, NC 28640									
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE COMPLETE				
V 736	Continued From page	1	V 796						
	and dirty areas of the	shower;							
İ	-None of her attempts	to clean the shower were							
	successful; -The shower had been in this condition for a long								
	time.	.							
	Interview on 5/16/18 v	with the Executive Director							
	(ED) revealed:								
	 She acknowledged thunclean; 	e shower appeared		in 17					
	-The Facility Maintena								
	contacted the building	owner; ted the facility to obtain							
	estimates for repair of								
1									
				ž.					
		0							

bills/quotes

Page 1 of 1

A

From:
Subject:

bills/quotes

Date:

'Tue, August 15, 2017:11:19 am

To:

Good Morning

Hope you are doing well.....

Attached you will find a bill from Bare's Plumbing regarding repair of a valve on a toilet at the Ark (Ashe 1) Also attached you will quotes on requested improvements/repairs from at our facilities.

Has a decision been reached regarding the repair of the hot water heater at Ashe 1 yet?

Final thing-checked on the repair of the door on Apt. 1A at the 258 location.....to order the insets for both doors which involves new windows as well was \$379.00 from Lowes....a complete set of new doors were like \$479.00....which direction do you want him to go in?

Thanks

Summit Support Services Jefferson, NC 28640 336-846-4491 336-846-4927 (fax)

Attachments:

untitled-[1.1].plain

Size: 0.8 k

Type:text/plain

20170815110235601.pdf

Size:86 k

Type application/pdf

20170815110251071.pdf

Slze:59 k

Type application/pdf

RE: bills/quotes


Page 1 of 2

F


From:
Subject: RE: bills/quotes
Date: Thu August 17 2017 9:17 am
To:

Will get it on it Thanks

On Wed, August 16, 2017 9:26 am, > We have never gotten the quote for the plumbing for the tankless water > heater > [The Arc NC Logo] CPM(r), Property Manager > The Arc of North Carolina > 5509A West Friendly Avenue, Suite 101 > Greensboro, NC 27410 > 336-273-4404, Ext. 28 > 336-378-0758 FAX > 336-420-5080 Cell > Learn more about our advocacy and services at > www.arcnc.org<http://www.arcnc.org/> > IMPORTANT WARNING: This message is intended for the use of the person or > entity to which it is addressed and may contain information that is > privileged and confidential, the disclosure of which is governed by > applicable law. If you are not the intended recipient, or the employee or > agent responsible to deliver it to the intended recipient, you are hereby > notified that any disclosure, copyling or distribution of this information > is Strictly Prohlbited. If you have received this message by error, please > notify the sender immediately to arrange for return or destruction of > these documents. > [/src/compose.php?send_to=sssdawn@skybest.com] From: > Sent: Tuesday, August 15, 2017 11;20 AM > To: > Subject: bills/quotes > Good Morning . > Hope you are doing well.... > Attached you will find a bill from Bare's Plumbing regarding repair > of a valve on a toilet at the Ark (Ashe 1) > Also attached you will quotes on requested improvements/repairs from > John at our facilities. > Has a decision been reached regarding the repair of the hot water > heater at Ashe 1 yet? > Final thingchecked on the repair of the door on Apt. 1A at > the 268 location.....to order the Insets for both doors which







RE: Couple of issues

Page 1 of 2

E

From: Sublect:

RE: Couple of Issues

Date: To: Thu, May 10, 2018 2:36 pm

You will need to get me estimates of cost for remodeling the showers in the two bathrooms as well as an estimate for re-roofing the storage building. Thanks



CPM®, HCCP® | jpritchett@arcnc.org

Property Manager, The Arc of North Carolina 5509A West Friendly Avenue, Suite 101, Greensboro, NC 27410 Main 336,273,4404, ext. 28 | Mobile 336,420,5080| Fax 336,378,0758

Donate | Instagram | Facebook | Twitter | YouTube



The Arc is not an acronym. Always refer to us as The Arc (not The ARC and never ARC).

Confidentiality notice: This email and any attachments may contain confidential information intended solely for the addressee, if the reader of this message is not the intended recipient, any distribution, copying, or use of this email or its attachments is prohibited. If you received this message in error, please notify the sender immediately and delete this message. Thank you.

From: [/src/compose.php?send_to=sssdawn@skybeat.com]

Sent: Thursday, May 10, 2018 1:20 PM

To:

Subject: Couple of Issues

Hey

The roof on the storage shed at Ashe 1 has finally surrendered to the high winds and the abuse of mother nature. It has started to leak and has also started to break down. Can that building be re-roofed? Do I need to get estimates? How do we proceed?

On another note: Both client restrooms in Ashe 1 need some TLC. I know you and I had discussed the one handicap access restroom some time ago. Both restrooms are very outdated and are in need of renovation. The tile on the walls and floor are stained and are extremely hard to clean, and the sheetrock around the tollet has been chipped away during many numerous repairs...and looks pretty rough. So far the sanitation inspector hasn't binged us, but we do expect it......The restroom on the front of the house, the tile on the floor is like the other...stained and blemished. Believe it or not....according to everything I can find...this is the original stuff that was put in the restrooms when the house was built. I can find no records here that it has been replaced. What if anything can we do?

RE: Bathroom at Ashe 1

Page 1 of 2

From:

To:

Subject: Date:

RE: Bathroom at Ashe 1

Thu, May 17, 2018 2:17 pm

No. Just get us back to where we were, only better. Thanks!

CPM®, HCCP® | jpritchett@arcnc.org

Property Manager, The Arc of North Carolina 5509A West Friendly Avenue, Suite 101, Greensboro, NC 27410 Main 336.273.4404, ext. 28 | Mobile 336.420.5080| Fax 336.378.0758

Donate | Instagram | Facebook | Twitter | YouTube



The Arc is not an acronym. Always refer to us as The Arc (not The ARC and never ARC).

Confidentiality notice: This email and any attachments may contain confidential information intended solely for the addressee. If the reader of this message is not the intended recipient, any distribution, copying, or use of this email or Its attachments is prohibited. If you received this message in error, please notify the sender immediately and delete this message. Thank you.

[/src/compose.php?send_to=sssdawn@skybest.com]

Sent: Thursday, May 17, 2018 1:18 PM

Subject: Balhroom at Ashe 1

Hey

Just wanted you to know that in the past two days.....both group homes had a Construction Inspection with no Issues cited- that I was informed about anyway.....and on Tuesday the 15th we had a routine inspection from DHSR- who yesterday cited us for the restroom. I am still in process of getting estimates as we discussed previously. Is there any standard they need to see or follow when submitting estimates? Thanks.....

Summit Support Services Jefferson, NC 28640 336-846-4491 336-846-4927 (fax)

Attachments:

untitled-[1.1].plain Size: 1.8 k

SUMMIT SUPPORT SERVICES OF ASHE, INC.

Fax Transmittal Form

Volley Van Wy

FROM Lelen Clark

Organization Name/Dept: 745R

Pax number: 919-733-2757

Phone: 336-846-4491 Phone: 336-846-2741 Fax: 336-846-4927

Urgent For Review

Please Comment

Please Reply

Date sent: 6/1// Time sents 11:00,

Number of pages including cover page:

Comments:

In your letter you mentioned July 5 as

The information contained in this facsimile message is client privileged and confidential information intended only for the use of the individual or entity named above. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by telephone and return the original message to us at the below address via the U. S. Postal Service. Thank you.

Summit Support Services of Ashe is dedicated to providing a comprehensive range of opportunities and resources that encourages the intellectual, social, emotional, vocational, physical and spiritual growth necessary for each individual to reach his or her fullest potential as citizens of the community.

Summit Support Services of Ashe, Inc.

PO Box 381 Jefferson, NC 28640 Phone: 336-846-4491 Phone: 336-846-2741 336-846-4927