

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>MHL092-859</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>07/10/2018</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  <b>DESTINY FAMILY CARE HOME 2</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>1238 FAIRLANE ROAD CARY, NC 27511</b>
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p><b>INITIAL COMMENTS</b></p> <p>An annual survey was completed on 7/10/18. A deficiency was cited.</p> <p>The facility is licensed for a 10A NCAC 27G .5600C Supervised Living For Developmental Disability Adult.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT</p> <p>(b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors.</p> <p>(4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interview the facility failed to ensure water temperatures were maintained between 100-116 degrees Fahrenheit. The findings are:</p> <p>Observation on 7/10/18 of water temperatures at 11:30 AM in kitchen area was 128 degrees Fahrenheit.</p> <p>Observation on 7/10/18 of water temperatures in both clients bathrooms revealed temperatures between 127-128 degrees Fahrenheit.</p> <p>During interview the Qualified Professional stated: -Not aware the water temperature was running high.</p>	V 752		

Division of Health Service Regulation  
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ (X6) DATE \_\_\_\_\_

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>MHL092-859</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>07/10/2018</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  <b>DESTINY FAMILY CARE HOME 2</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>1238 FAIRLANE ROAD CARY, NC 27511</b>
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	Continued From page 1  -This home was just licensed at the end of March and assumed the water temperature was ok then. -Will follow up and have the water checked.	V 752		